# FS100L MAINTENANCE MANUAL

Upon receipt of the product and prior to initial operation, read these instructions thoroughly, and retain for future reference.

MOTOMAN INSTRUCTIONS

(FOR MEDIUM AND LARGE-SIZED MANIPULATORS) MOTOMAN-DDD INSTRUCTIONS FS100L INSTRUCTIONS FS100 OPERATOR'S MANUAL FS100L MAINTENANCE MANUAL

The FS100 OPERATOR'S MANUAL above is applicable to both FS100 and FS100L controllers.

YASKAWA ELECTRIC CORPORATION





- This manual explains maintenance procedures of the FS100L system. Read this manual carefully and be sure to understand its contents before handling the FS100L.
- General items related to safety are listed in Chapter 1: Safety of the FS100L INSTRUCTIONS. To ensure correct and safe operation, carefully read the FS100L Instructions before reading this manual.



- Some drawings in this manual are shown with the protective covers or shields removed for clarity. Be sure all covers and shields are replaced before operating this product.
- The drawings and photos in this manual are representative examples and differences may exist between them and the delivered product.
- YASKAWA may modify this model without notice when necessary due to product improvements, modifications, or changes in specifications. If such modification is made, the manual number will also be revised.
- If your copy of the manual is damaged or lost, contact a YASKAWA representative to order a new copy. The representatives are listed on the back cover. Be sure to tell the representative the manual number listed on the front cover.
- YASKAWA is not responsible for incidents arising from unauthorized modification of its products. Unauthorized modification voids your product's warranty.

# **Notes for Safe Operation**

Read this manual carefully before maintenance or inspection of the FS100L.

In this manual, the Notes for Safe Operation are classified as "DANGER", "WARNING", "CAUTION", "MANDATORY", or "PROHIBITED".







Indicates an imminent hazardous situation which, if not avoided, could result in death or serious injury to personnel.

Indicates a potentially hazardous situation which, if not avoided, could result in death or serious injury to personnel.

Indicates a potentially hazardous situation which, if not avoided, could result in minor or moderate injury to personnel and damage to equipment. It may also be used to alert against unsafe practices.

MANDATORY

Always be sure to follow explicitly the items listed under this heading.

Must never be performed.



Even items described as "CAUTION" may result in a serious accident in some situations.

At any rate, be sure to follow these important items.



To ensure safe and efficient operation at all times, be sure to follow all instructions, even if not designated as "DAN-GER", "WARNING" and "CAUTION".

# 

• Before operating the manipulator, check that servo power is turned OFF when the emergency stop button on the programming pendant is pressed.

When the servo power is turned OFF, the SERVO ON LED on the programing pendant is turned OFF.

Injury or damage to machinery may result if the emergency stop circuit cannot stop the manipulator during an emergency. The manipulator should not be used if the emergency stop button does not function.

Fig. : Emergency Stop Button



- In the case of not using the programming pendant, be sure to supply the emergency stop button on the equipment. Then before operating the manipulator, check to be sure that the servo power is turned OFF by pressing the emergency stop button.
   Connect the external emergency stop button to the 5-6 pin and 16-17 pin of the robot system signal connector (CN2).
- Upon shipment of the FS100L, this signal is connected by a jumper cable in the dummy connector. To use the signal, make sure to supply a new connector, and then input it.

If the signal is input with the jumper cable connected, it does not function, which may result in personal injury or equipment damage.

• Once the emergency stop button is released, clear the cell of all items which could interfere with the operation of the manipulator. Then turn the servo power ON.

Injury may result from unintentional or unexpected manipulator motion.

Fig. : Release of Emergency Stop Button



- Observe the following precautions when performing teaching operations within the manipulator's operating range:
  - Be sure to use a lockout device to the safeguarding when going inside. Also, display the sign that the operation is being performed inside the safeguarding and make sure no one closes the safeguarding.
  - View the manipulator from the front whenever possible.
  - Always follow the predetermined operating procedure.
  - Ensure that you have a safe place to retreat in case of emergency.

Improper or unintended manipulator operation may result in injury.



The emergency stop button is located on the programing pendant.



- Perform the following inspection procedures prior to teaching the manipulator. If problems are found, correct them immediately, and be sure that all other necessary tasks have been performed.
  - Check for problems in manipulator movement.
  - Check for damage to the insulation and sheathing of external wires.
- Return the programming pendant to a safe place after use.

If the programming pendant is inadvertently left on the manipulator, on a fixture, or on the floor, the manipulator or a tool may collide with the programming pendant during manipulator movement, which may result in personal injury or equipment damage.

• Read and understand the Explanation of Warning Labels in the FS100L Instructions before operating the manipulator.

# **Definition of Terms Used Often in This Manual**

The MOTOMAN is the YASKAWA industrial robot product.

The MOTOMAN usually consists of the manipulator, the FS100L controller, manipulator cables, the FS100L programming pendant (optional), and the FS100L programming pendant dummy connector (optional).

In this manual, the equipment is designated as follows:

Equipment	Manual Designation
FS100L controller	FS100L
FS100L programming pendant	Programming pendant
Cable between the manipulator and the controller	Manipulator Cable
FS100L programming pendant dummy connector	Programming pendant dummy connector

Descriptions of the programming pendant keys, buttons, and displays are shown as follows:

Equipment		Manual Designation
Programming Pendant	Character Keys	The keys which have characters printed on them are denoted with []. ex. [ENTER]
	Symbol Keys	The keys which have a symbol printed on them are not denoted with [] but depicted with a small picture.
		ex. PAGE key
		The Cursor is an exception, and a picture is not shown.
	Axis Keys Numeric Keys	"Axis Keys" and "Numeric Keys" are generic names for the keys for axis operation and number input.
	Keys pressed simultaneously	When two keys are to be pressed simultaneously, the keys are shown with a "+" sign between them,
		ex. SHIFT key 🛅 +COORD key 🔛
	Mode Key	Three kinds of modes that can be selected by the mode key are denoted as follows: REMOTE, PLAY, or TEACH
	Button	Three buttons on the upper side of the programming pendant are denoted as follows: HOLD button START button EMERGENCY STOP button
	Displays	The menu displayed in the programming pendant is denoted with { }. ex. {JOB}
PC Keyboard		The name of the key is denoted ex. Ctrl key on the keyboard

# **Description of the Operation Procedure**

In the explanation of the operation procedure, the expression "Select •••" means that the cursor is moved to the object item and the SELECT key is pressed, or that the item is directly selected by touching the screen.

# **Registered Trademark**

In this manual, names of companies, corporations, or products are trademarks, registered trademarks, or brand names for each company or corporation. The indications of (R) and  $^{TM}$  are omitted.

# **Explanation of Warning Labels**



F٤	S100	Contents	
1	Equipm	ent Configuration	
	1.1	Arrangement of Units and Circuit Boards	1-1
	1.2	Power Flow	1-2
	1.3	Signal Flow	1-3
2	Securit	y System	2-1
	2.1	Protection Through Security Mode Settings	2-1
		2.1.1 Security Mode	2-1
		2.1.1.1 Changing the Security Mode	2-5
		2.1.2 User ID 2.1.2.1 Changing a User ID	2-7 2-7
3	Mainter	nance and Inspections	
	3.1	Daily Inspections	
	3.2	Cooling Fan Inspections	
	3.3	Emergency Stop Button Inspections	
	3.4	Enable Switch Inspections	
	3.5	Battery Inspections	3-5
	3.6	Filter Inspection	
4	Prepara	ation before Replacing Parts	4-1
	4.1	Creating a Check Program	4-3
5	Replac	ing Parts	5-1
	5.1	Control Circuit Board Replacement	5-3
	5.2	Power Relay Circuit Board Replacement	5-8
	5.3	Circuit Board Rack Replacement	5-13
	5.4	Machine Safety Circuit Board Replacement	5-20
	5.5	User I/O Circuit Board and System Circuit I/O Board Replacement	5-23
	5.6	CPS Unit (JZNC-YPS01-E) Replacement	5-27
	5.7	Power Supply Contactor Unit (JZRCR-YPU31 □ -1) Replacement	5-29
	5.8	Brake Control Board (JZRCR-YBK01-2E) Replacement	5-31
	5.9	SERVO AMPLIFIER (SRDA-SDA	5-33
	5.10	Converter (SRDA-COA30A01A-E) Replacement	5-37
	5.11	Major Axes Control Circuit Board (SRDA-EAXA01A) Replacement	5-39
	5.12	2 Checking and Replacing Fuse	5-41

FS100		Contents	
	5.12.1	Power Supply Contactor Unit	5-41
	5.12.2	Brake Control Board	5-42
	5.12.3	Fuse Holder	5-43
	5.12.4	Major Axes Control Circuit Board (SRDA-EAXA01A)	5-44
5.1	3 Cooling	Fan Replacement	5-45
	5.13.1	Replacing Servo Cooling Fan	5-45
	5.13.2	Replacing Converter Cooling fan	5-46
	5.13.3	Replacing Regenerative Resistor Cooling Fan	5-47
	5.13.4	Replacing Cooling Fan for the Interior of the Controller	5-49
5.1	4 Battery	Replacement	5-50
5.1	5 Relay fo	or the Motor Cooling Fan Replacement	5-51
5.1	6 Filter Re	eplacement	5-52
5.1	7 Cable Ir	nlet Replacement	5-53
6 Recom	mended S	pare Parts	6-1
6.1	List of FS	S100L Accessories	6-1
6.2	Recomm	ended Spare Parts	6-3
7 Operat	ions After	Replacing Parts	7-1
7.1	Home Pc	osition Calibration	7-3
	7.1.1 H	Home Position Calibration	7-3
	7.1.2 (	Calibrating Operation	7-4
	7	1.2.1 Registering All Axes at One Time	7-4
	7	.1.2.2 Registering Individual Axes	7-6
	7	.1.2.3 Changing the Absolute Data	
	713 M	Manipulator Home Position	
7.2	Position	Deviation Check Using the Check Program	
7.3	Checking	g of the Check Program	7-12
	7.3.1 M	Notion of the Check Program	7-12
	7.3.2 (	Checking of the Check Point	7-12
	7.3.3 H	Home Position Data Correction	7-13
7.4	Setting th	ne Second Home Position	7-14
	7.4.1 F	Purpose of Position Check Operation	7-16
	7.4.2 F	Procedure for the Second Home Position Setting (Check Point)	7-18
	7.4.3 F	Procedure after the Alarm	

# FS100

#### Contents

8	System	Diagno	sis	8-1
	8.1	System	N Version	8-1
	8.2	Manipu	Ilator Model	8-1
	8.3	Input/C	output Status	8-2
		8.3.1	Universal Input 8.3.1.1 Universal Input Window 8.3.1.2 Universal Input Simple Window	8-2 8-2 8-2
		8.3.2	Universal Output	8-3 8-3 8-3 8-4
		8.3.3	Specific Input.         8.3.3.1       Specified Input Window.         8.3.3.2       Specific Input Simple Window.	8-5 8-5 8-5
		8.3.4	Specific Output8.3.4.1Specified Output Window8.3.4.2Specific Output Simple Window	8-6 8-6 8-6
		8.3.5	RIN Input 8.3.5.1 RIN Input Window	8-7 8-7
		8.3.6	<ul><li>Signal Number Search</li><li>8.3.6.1 Direct Search on the Universal/Specified Input/Output Window</li><li>8.3.6.2 Search from the Menu</li></ul>	8-8 8-9 8-10
		8.3.7	<ul><li>Relay Number Search</li><li>8.3.7.1 Direct Search on the Universal/Specified Input/Output Window</li><li>8.3.7.2 Search from the Menu</li></ul>	8-11 8-12 8-13
		8.3.8	<ul><li>Modification of the Signal Name</li><li>8.3.8.1 Direct Modification on the Universal/Specified Input/Output Window .</li><li>8.3.8.2 Modification from the Menu</li></ul>	8-14 8-14 8-15
	8.4	System	n Monitoring Time Display	8-16
		8.4.1	System Monitoring Time Display Window	8-16
		8.4.2	Individual Window of the System Monitoring Time Display	8-17
		8.4.3	Clearing the System Monitoring Time Display	8-18
	8.5	Alarm I	History	8-19
		8.5.1	Alarm History Window	8-19
		8.5.2	Clearing the Alarm History	8-20
	8.6	I/O Me	ssage History	8-21
		8.6.1	I/O Message History Window 8.6.1.1 Search	8-21 8-21
		8.6.2	Clearing the I/O Message History	8-22

FS100	)		Contents	
	8.7	Position Data Wh	en Power is Turned ON/OFF	
		8.7.1 Power Of	V/OFF Position Window	8-23
	8.8	Current Position		8-24
		8.8.1 Current F	osition Window	8-24
	8.9	Servo Monitoring.		8-25
		8.9.1 Servo Mo	nitor Window	8-25
		8.9.1.1 C	hanging the Monitor Items	8-26
		8.9.1.2 C	Clearing Maximum Torque Data	8-28
9 Ala	ırm			9-1
	9.1	Outline of Alarm		9-1
	9.2	Alarm Display		9-2
		9.2.1 Displayin	g and Releasing Alarm	9-2
		9.2.1.1 F	eleasing Alarms	9-2
		9.2.2 Special A	larm Display	9-3
	9.3	Display of Alarm [	Details	9-4
		9.3.1 Paramete	r	9-4
		9.3.2 Display of	f Alarm Detail Window	9-4
		9.3.3 Transitior	of Alarm Detail Window	9-6
	9.4	Alarm Message L	st	9-7
10 E	rror .			
	10.1	Error Message		
		10.1.1 System	and General Operation	
		10.1.2 Editing		
		10.1.3 Job Def	ned Data	
		10.1.4 External	Memory Equipment	
		10.1.5 Concurr	ent I/O	
		10.1.6 Mainten	ance Mode	
	10.2	Particular Error	Nessage	
		10.2.1 Messag	9	
		10.2.1.1	Fatal Error	
		10.2.1.2	Application Transaction Error	
		10.2.1.3	Uther Errors	
		10.2.2 When th	e Error is Indicated	
		10.2.2.1	Fatal Error	
		10.2.2.2	Application Transaction Error	
		10.2.2.3		

FS1	00			Contents							
11	LED In	dicator o	on Each	Circuit Board	l					1 <sup>.</sup>	1-1
	11.1	6 LED-	Spot Ind	licator on the	Main CPU	Circuit Bo	ard (CPU	201R)		1′	1-2
	11.2	7-Segn	nent LED	D Indicator or	the Main C	CPU Circui	it Board (	CPU201F	R)	1′	1-3
		11.2.1	Status	of 7-Segmen	t LED Indic	ator at Err	or Occuri	ence		1′	1-4
		11.2.2	Status	of 7-Segmen	t LED Indic	ator at Co	ntrol Pow	er Start-u	ıp (one d	igit) 1 <sup>-</sup>	1-5
		11.2.3	Status	of 7-Segmen	t LED Indic	ator at Ha	rdware E	rror Occu	rrence	1 <i>′</i>	1-5
		11.2.4	Status	of 7-Segmen	t LED Indic	ator at Ala	rm Occu	rrence		1′	1-6
	11.3	LED In	dicator o	on Machine S	afety Board	I (SF2300I	R)			1 <i>′</i>	1-7
	11.4	7-Segn	nent LED	D Indicator or	SERVO co	ontrol circu	uit board (	(EAXA)		1′	1-8
		11.4.1	Status and SEF Power S	of 7-Segmen RVO Control Supply System	t LED Indic Board Com	ator at Err municatior	or Occuri n System	ence in tl or	ne Main (	CPU 1 <sup>7</sup>	1-8
		11.4.2	Status	of 7-Segmen	t LED Indic	ator at Fat	tal Error C	Occurrenc	:е	1 <i>′</i>	1-9
		11.4.3	Status	of 7-Segmen	t LED Indic	ator at Co	ntrol Pow	er Start-u	ıp (One [	Digit) 11-	·11
12	Trouble	shooting	g Methoo	ds When an A	Alarm Mass	age Is Not	t Displaye	ed		12	2-1

- 1 Equipment Configuration
- 1.1 Arrangement of Units and Circuit Boards

# **1** Equipment Configuration

# 1.1 Arrangement of Units and Circuit Boards

Fig. 1-1: Arrangement of Units and Circuit Boards



- 1 Equipment Configuration
- 1.2 Power Flow



# 1.2 Power Flow

- 1 Equipment Configuration
- 1.3 Signal Flow

1.3 Signal Flow



- 2 Security System
- 2.1 Protection Through Security Mode Settings

# 2 Security System

#### 2.1 Protection Through Security Mode Settings

The FS100L modes setting are protected by a security system. The system allows operation and modification of settings according to operator clearance. Be sure operators have the correct level of training for each level to which they are granted access.

#### 2.1.1 Security Mode

There are three security modes. Editing mode and management mode require a user ID. The user ID consists of numbers and letters, and contains no less than 4 and no more than 8 characters. (Significant numbers and signs: "0 to 9", "-", ".".

Security Mode	Explanation
Operation Mode	This mode allows basic operation of the robot (stopping, starting, etc.) for people operating the robot work on the line.
Editing Mode	This mode allows the operator to teach and edit jobs and robot settings.
Management Mode	This mode allows those authorized to set up and maintain robot system: parameters, system time and modifying user IDs.

Table 2-1: Security Mode Descriptions

- 2 2.1 Security System Protection Through Security Mode Settings

Main Menu	Sub Menu	Allowed Secu	rity Mode
		DISPLAY	EDIT
JOB	JOB	Operation	Edit
	SELECT JOB	Operation	Operation
	CREATE NEW JOB <sup>1)</sup>	Edit	Edit
	MASTER JOB	Operation	Edit
	JOB CAPACITY	Operation	-
	CYCLE	Operation	Operation
VARIABLE	BYTE	Operation	Edit
	INTEGER	Operation	Edit
	DOUBLE	Operation	Edit
	REAL	Operation	Edit
	STRING	Operation	Edit
	POSITION (ROBOT)	Operation	Edit
	POSITION (BASE)	Operation	Edit
	POSITION (ST)	Operation	Edit
	LOCAL VARIABLE <sup>1)</sup>	Operation	-
IN/OUT	EXTERNAL INPUT	Operation	Edit
	EXTERNAL OUTPUT	Operation	Edit
	UNIVERSAL INPUT	Operation	Operation
	UNIVERSAL OUTPUT	Operation	Operation
	SPECIFIC INPUT	Operation	-
	SPECIFIC OUTPUT	Operation	-
	RIN	Operation	-
	REGISTER	Operation	Management
	AUXILIARY RELAY	Operation	-
	CONTROL INPUT	Operation	-
	PSEUDO INPUT SIG	Operation	Management
	NETWORK INPUT	Operation	-
	NETWORK OUTPUT	Operation	-
	ANALOG OUTPUT	Operation	-
	TERMIMAL	Operation	-
	LADDER PROGRAM	Management	Management
	I/O ALARM	Management	Management
	I/O MESSAGE	Management	Management
	I/O SIMULATION LIST	Operation	Operation

Table 2-2: Menu & Security Mode (Sheet 1 of 3)

1) Displayed in the teach mode only.

- 2 2.1 Security System Protection Through Security Mode Settings

Main Menu	Sub Menu	Allowed Secu	rity Mode
		DISPLAY	EDIT
ROBOT	CURRENT POSITION	Operation	-
	COMMAND POSITION	Operation	-
	SERVO MONITOR	Management	-
	WORK HOME POS	Operation	Edit
	SECOND HOME POS	Operation	Edit
	DROP AMOUNT	Management	Management
	POWER ON/OFF POS	Operation	-
	TOOL	Edit	Edit
	INTERFERENCE	Management	Management
	SHOCK SENS LEVEL	Operation	Edit
	USER COORDINATE	Edit	Edit
	HOME POSITION	Management	Management
	MANIPULATOR TYPE	Management	-
	ANALOG MONITOR	Management	Management
	OVERRUN	Edit	Edit
	LIMIT RELEASE	Edit	Edit
	ARM CONTROL	Management	Management
	SHIFT VALUE	Operation	-
	MANUAL BRAKE RELEASE	Operation	Operation
	HAND VIBRATION CONTROL	Operation	Management
SYSTEM INFO	VERSION	Operation	-
	MONITORING TIME	Operation	Management
	ALARM HISTORY	Operation	Management
	I/O MSG HISTORY	Operation	Management
	NETWORK SERVICE	Management	-
	USER DEFINITION MENU	Operation	Operation
	SECURITY	Operation	Operation
EXTERNAL	LOAD	Edit	-
MEMORY	SAVE	Operation	-
	VERIFY	Operation	-
	DELETE	Operation	-
	DEVICE	Operation	Operation
	FOLDER	Edit	Management

Table 2-2: Menu & Security Mode (Sheet 2 of 3)

2 2.1 Security System Protection Through Security Mode Settings

Main Menu	Sub Menu	Allowed Secu	rity Mode
		DISPLAY	EDIT
PARAMETER	S1CxG	Management	Management
	S2C	Management	Management
	S3C	Management	Management
	S4C	Management	Management
	A1P	Management	Management
	RS	Management	Management
	S1E	Management	Management
	S2E	Management	Management
	S3E	Management	Management
	S4E	Management	Management
	S5E	Management	Management
	S6E	Management	Management
	S7E	Management	Management
	S8E	Management	Management
SETUP	TEACHING COND	Edit	Edit
	OPERATE COND	Management	Management
	OPERATE ENABLE	Management	Management
	FUNCTION ENABLE	Management	Management
	JOG COND	Management	Management
	PLAYBACK COND	Management	Management
	FUNCTION COND	Management	Management
	DISPLAYING COLOR COND	Management	Management
	DATE/TIME	Management	Management
	GRP COMBINATION	Management	Management
	RESERVE JOB NAME	Edit	Edit
	USER ID	Edit	Edit
	SET SPEED	Management	Management
	KEY ALLOCATION	Management	Management
	JOG KEY ALLOC	Edit	Management
	RES. START (CNCT)	Management	Management
	AUTO BACK SET	Management	Management
	WRONG DATA LOG	Edit	Management
	ENERGY SAVING FUNCTION	Edit	Management
	ENCODER MAINTENANE	Edit	Management
DISPLAY	CHANGE FONT	Operation	Operation
SETUP	CHANGE BUTTON	Operation	Operation
	INITIALIZE LAYOUT	Operation	Operation
	CHANGE WINDOW PATTERN	Operation	Operation
GENERAL	GENERAL DIAG	Operation	Edit

 Table 2-2: Menu & Security Mode (Sheet 3 of 3)

- 2 Security System
- 2.1 Protection Through Security Mode Settings

#### 2.1.1.1 Changing the Security Mode

- 1. Select {SYSTEM INFO} under the main menu.
  - The sub menu appears.



- 2. Select {SECURITY}.
  - The selection window of security mode appears.

DATA	EDIT	DISPLAY	UTILITY	1. 🛛 🖬 😣 🐻 📑	•
SECURITY					
MODE	FDI	TING MODE	6		

- 2 Security System
- 2.1 Protection Through Security Mode Settings
- 3. Press [SELECT] and select "SECURITY MODE".

MODE	OPE	RATION MOD	E		
	EDI	TING MODE AGEMENT MO			

- 4. Input the user ID.
  - The user ID input window appears.





- 5. Press [ENTER].
  - The input user ID is compared with the user ID of the selected security mode. When the correct user ID is entered, the security mode is changed.

- 2 Security System
- 2.1 Protection Through Security Mode Settings

#### 2.1.2 User ID

User ID is requested when Editing Mode or Management Mode is operated.

User ID must be between 4 characters and 8, and they must be numbers and symbols. ("0 to 9", "-" and ".")

#### 2.1.2.1 Changing a User ID

In order to change the user ID, the FS100 must be in Editing Mode or Management Mode. Higher security modes can make changes the user ID of to lower security modes.

- 1. Select {SETUP} under the main menu.
  - The sub menu appears.



- 2. Select {USER ID}.
  - The USER ID window appears.

DATA	EDIT	DISPLAY	UTRATY 10 🗷 📶 🐋 🐻 寻 🎋	
SER ID		,	·	
EDITING	MODE	******		
MANAGEM	ENT MODE	******		

- 2 Security System
- 2.1 Protection Through Security Mode Settings
- 3. Select the desired ID.
  - The character input line appears, and the message "Input current ID no. (4 to 8 digits)" is shown.

DĂTĂ	EDIT	DISPLAY	UTILITY	io 🗷 🖌	<b>⊛</b> @⊒	( <del>b</del> )
USER ID						
EDITING	MODE					
HAMACEN	Pas	sword				
Weinerst M	CINI MULIE	******				
_		-			_	_
-						

- 4. Input current ID and press [ENTER].
  - When the correct user ID is entered, a new ID is requested to be input. "Input new ID no.(4 to 8 digits)" appears.

SER ID		,	
EDITING MANAGEM	MODE ENT MODE	sword= ********	

- 5. Input new ID and press [ENTER].
  - User ID is changed.

- 3 Maintenance and Inspections
- 3.1 Daily Inspections

# 3 Maintenance and Inspections

Operator's manual for daily inspection and parts replacement are explained in this section. Be sure to read and understand this instruction before operating the FS100L.

To ensure correct and safe operation, carefully read the FS100L INSTRUCTIONS (RE-CTO-A219).



# 3.1 Daily Inspections



- 3 Maintenance and Inspections
- 3.1 Daily Inspections

Carry out the	following	inspections.
---------------	-----------	--------------

Inspection Equipment	Inspection Item	Method	Inspection	Comments
FS100L Controller exterior	Check for damages and cracks	Check visually	As required	Check for damages and loose connectors
Power supply cable	Check for damages or connections.	Check visually	As required	Check for damages and loose connectors
Manipulator cable (between the FS100L and the manipulator)	Check for damages or connections.	Check visually	As required	Check for damages and loose connectors
Cover mounting screws	Check for defect or loose of the screws	Use screw driver	As required	Tighten loose screws
Cooling fan	Check the operation	Check visually	As required	When the power is turned ON
Emergency stop button <sup>1)</sup> (programming pendant)	Check the operation	By activating the button	Before the manipulator operation	When the SERVO is turned ON
Enable switch (programming pendant)	Check the operation	By activating the switch	Before the manipulator operation	During the teach mode
Battery (for the system)	Message indication Check LED lights	Check visually	As required	
Filter	Check if there are any dirt and the dust clogging on the filter	Check visually	As for every three months	For IP40 specification (optional)

1 Be sure to confirm that the SERVO can be turned OFF by pressing the external emergency button when the programming pendant is not used.

The external emergency button is prepared by the user.

- 3 Maintenance and Inspections
- 3.2 Cooling Fan Inspections

# 3.2 Cooling Fan Inspections

Inspect the cooling fans as required. A defective fan can cause the FS100L to malfunction because of excessive high temperatures inside.

The interior circulation fan and cooling fan normally operate while the power is turned ON. Check if the fans are operating correctly by visual inspection and by feeling air moving into the air inlet and from the outlet. Especially there are two each servo cooling fans and regenerative resistor cooling fans in FS100L. Confirm those fans are working normally. It is able to confirm by feeling the air coming from the whole air outlet, which is located in the lower left side of the back view. Please confirm the all of the fans are working normally if feel the air is not coming from the whole area.







When the message of the "Cooling fan in YPS power supply stopped. Exchange fan" is displayed, it may be caused by the error occurrence at the cooling fan (JZNC-YZU01-E) inside CPS unit (JZNC-YPS01-E).

When the message of the "Cooling fan in YPS unit stopped, replace cooling fan" is displayed, carry out an inspection and the replacement of the cooling fan in the CPS unit as soon as possible.

- 3 Maintenance and Inspections
- 3.3 Emergency Stop Button Inspections

#### 3.3 Emergency Stop Button Inspections

The emergency stop button is located on the programming pendant. Before operating the manipulator, confirm that the SERVO power is ON/ OFF by pressing the emergency stop button after the SERVO is ON.

• Be sure to confirm that the SERVO can be turned OFF by pressing the external emergency button when the programming pendant is not used.

The external emergency button is prepared by the user.

#### 3.4 Enable Switch Inspections

The programing pendant is equipped with a three-position enable switch. Perform the following operations to confirm that the enable switch is firmly operated.

(1) Set the Mode key on the programming pendant to "TEACH".

Mode key with a switch



(2) Press [SERVO ON READY] on the programming pendant. Then [SERVO ON] lamp blinks.



(3) When the enable switch is grasped lightly, the servo power is turned ON.

When the enable switch is grasped firmly or released, the servo power is turned OFF.

If the [SERVO ON] lamp does not blink in previous operation (2), check the following:



• The emergency stop button on the programming pendant is pressed.

- The emergency stop signal is externally input.
- An alarm is occurring.

- 3 Maintenance and Inspections
- 3.5 Battery Inspections

#### 3.5 Battery Inspections

The FS100L has a battery that backs up the important program files for user data in the CMOS memory.

When a battery is weakened to be replaced, a message "Memory battery weak" appears on the programming pendant display.

Confirm this message is not appeared on the display.

Refer to *chapter 5.14 "Battery Replacement" at page 5-50* for the battery replacement.

When the programming pendant is not used, be sure to confirm, from the LED audit window on the FS100L front panel, that the battery alarm LED of the CPU unit (CPU-201R) is not lit up.



- 3 Maintenance and Inspections
- 3.6 Filter Inspection

#### 3.6 Filter Inspection

There are filters on the air outlets and inlets for IP40 specification (optional). When the filter has dirt and the dust clogging, the temperature in the controller will increase, and it may cause a harmful effect on the internal devices. Inspect the filter every three months and replace the filter as needed. Also replace the filter every six months regularly.



For the filter for air outlets, It is necessary for the inside of the filter of the back and the left side of the controller to be checked by removing a cover.

#### Scheduling of the inspection and replacement for the filters

Inspection	Replacement
Every three months	Every six months





# 4 Preparation before Replacing Parts

• Before operating the manipulator, check that servo power is turned OFF when the emergency stop button on the programming pendant is pressed.
When the servo power is turned OFF, the SERVO ON LED on the programing pendant is turned OFF.
Injury or damage to machinery may result if the emergency stop circuit cannot stop the manipulator during an emergency. The manipulator should not be used if the emergency stop button does not function.
<ul> <li>In the case of not using the programming pendant, be sure to supply the emergency stop button on the equipment. Then before operating the manipulator, check to be sure that the servo power is turned OFF by pressing the emergency stop button. Connect the external emergency stop button to the 5-6 pin and 16- 17 pin of the robot system signal connector (CN2).</li> </ul>
<ul> <li>Upon shipment of the FS100L, this signal is connected by a jumper cable in the dummy connector. To use the signal, make sure to supply a new connector, and then input it.</li> </ul>
If the signal is input with the jumper cable connected, it does not function, which may result in personal injury or equipment damage.
<ul> <li>Observe the following precautions when performing teaching operations within the manipulator's operating range:</li> </ul>
<ul> <li>Be sure to use a lockout device to the safeguarding when going inside. Also, display the sign that the operation is being performed inside the safeguarding and make sure no one closes the safeguarding.</li> </ul>
<ul> <li>View the manipulator from the front whenever possible.</li> </ul>
<ul> <li>Always follow the predetermined operating procedure.</li> </ul>
<ul> <li>Ensure that you have a safe place to retreat in case of emergency.</li> </ul>
Improper or unintended manipulator operation may result in injury.
<ul> <li>Confirm that no person is present in the manipulator's operating range and that you are in a safe location before:</li> </ul>
<ul> <li>Turning ON the power for the FS100L.</li> </ul>
<ul> <li>Moving the manipulator with the programming pendant.</li> </ul>
Injury may result if anyone enters the manipulator's operating range during operation. Always press an emergency stop button immediately if there are problems. The emergency stop button is located on the programing pendant.

4



The following flowchart shows the operations for replacing parts.



This chapter describes how to create a check program as a preparation for replacing parts. The check program is a program to check the position deviation. If positions are deviated, home position calibration is required. For the calibration, this program data is used to correct the home position data. In the following cases particularly, the home position calibration using the check program is needed. Be sure to create a check program referring to *chapter 4.1 "Creating a Check Program" at page 4-3*.

- Change in the combination of the manipulator and FS100L
- · Replacement of the motor or absolute encoder
- Clearing stored memory (by replacement of main CPU board, weak battery, etc.)
- Home position deviation caused by hitting the manipulator against a workpiece, etc.

- 4 Preparation before Replacing Parts
- 4.1 Creating a Check Program

#### 4.1 Creating a Check Program

To check position deviation whenever necessary, create a program in which a check point is taught (the job for the check point). In the job for the check point, teach two points; one as a check point and the other as the point to approach the check point. This program checks for any deviation between the tool tip position and the check point.



Fig. 4-1: <Enlarged View>



# 5 Replacing Parts



Failure to observe this warning may result in electric shock.



#### 5 Replacing Parts

It is necessary to open a panel to the each unit and the board of the FS100L in order to replace the new ones. The panels which need to be opened are shown at *table 5-1 "Replacement Units and to Open and Shut Panels"*.

Before replace the units and the boards, make sure which panels need to be opened.

Replacement parts	To open and shut panels	
Control circuit board (JEPMC-CP3201R-E)	Front panel	
Power relay circuit board (JEPMC-PSD3007R-E)		
Circuit board rack (JEPMC-BUB3008R-E)		
Machine safety circuit board (JAPMC-SF2300R-E)		
User I/O circuit board (JAPMC-IO2308R-E)		
System I/O circuit board (JAPMC-IO2308R-ET1)		
Battery		
Servo cooling fan		
CPS unit (JZNC-YPS01-E)	Back panel	
Power supply contactor unit (JZRCR-YPU31-1)		
Brake control board (JANCD-YBK01-2E)		
Converter (SRDA-COA30A01A-E)		
Servo amplifier (SRDA-SDA 🗌 🖓 A01A-E)	Top panel	
Major axes control circuit board (SRDA-EAXA01A)		
Converter cooling fan		
Fuse holder	Left panel	
Cooling fan inside the controller		
Relay for a motor cooling fan		
Regenerative resistor cooling fan	Right panel	

Table 5-1: Replacement Units and to Open and Shut Panels



When it needs to be opened the top panel of stacking FS100L, unstack the controllers to replace the units and the boards to open the top panel of FS100L.

- 5 Replacing Parts
- 5.1 Control Circuit Board Replacement

### 5.1 Control Circuit Board Replacement

(JEPMC-CP3201R-E is abbreviated as CPU-201R)



Before replacing the board, save the important data, such as the parameter, to a USB storage device, and then turn the power supply OFF.




- 5 Replacing Parts
- 5.1 Control Circuit Board Replacement

## **Replacement Procedures**

1. Remove two screws on the upper and loosen two screws on the lower of the front panel, and then remove the front panel.



2. Remove all connected cables to the each board in the CPU unit. Also disconnect a battery lead extension cable connector, which is connected to the battery on the bottom of the controller, and remove a clamp, which is fixing extension cable.



- 5 Replacing Parts
- 5.1 Control Circuit Board Replacement
- 3. Loosen two fixed screws of the base mounting the CPU unit.



- 4. Hold the CPU unit itself, and remove the CPU unit as pulling them from the controller.
- 5. Remove the fixing jig from the DIN rail.
- 6. To unlock, depress a DIN rail fixed lock which is located in lower spot of the power relay circuit board and the control circuit board. (two places)



- 5 Replacing Parts
- 5.1 Control Circuit Board Replacement
- 7. Unlock both upper and lower locations of the power relay circuit board and the control circuit board.



8. After unlocking, move the power relay circuit board and the control circuit board to the left side of the DIN rail. Separate the power relay circuit board, the control circuit board and the circuit board rack, and then remove the control circuit board from the DIN rail.



9. Remove the battery lead extension cable which is connected to the control circuit board, and then connect it to the new control circuit board.



If the battery lead extension cable is not connected in proper way, it may lose a new saving data. Be sure to proper connectivity with the new board.



- 5 Replacing Parts
- 5.1 Control Circuit Board Replacement
- 10. After connecting the battery lead extension cable, install the new control circuit board to the DIN rail, and then assemble it with the circuit board rack. Lock the boards for both upper and lower locations. Assemble the control panel and the power relay circuit board as well, and lock the boards for both upper and lower locations.



11. Force up the DIN rail fixed lock which is located lower spot of the power relay circuit board and the control circuit board, and fasten it to the DIN rail. Align the right edge of the circuit board rack and the edge of the DIN rail, and reinstall the fixing jig. Fasten the CPU unit to the DIN rail.



- 12. Hook the base mounting the CPU unit to the inserted style brackets and the fixing screws, and fasten the screws. (two places)
- 13. Reinstall all cables to the CPU unit. Be sure not to forget connecting the battery on the bottom of the controller and the grounding wire to the power relay circuit board.
- 14. Reinstall the front panel, and tighten four screws.

- 5 Replacing Parts
- 5.2 Power Relay Circuit Board Replacement

## 5.2 Power Relay Circuit Board Replacement

(JEPMC-PSD3007R-E)



Before replacing the board, and save the important data, such as the parameter, to a USB storage device, and then turn the power supply OFF.





- 5 Replacing Parts
- 5.2 Power Relay Circuit Board Replacement

### Replacement Procedures

1. Remove two screws on the upper and loosen two screws on the lower of the front panel, and then remove the front panel.



2. Remove all connected cables to the each board in the CPU unit. Also disconnect a battery lead extension cable connector, which is connected to the battery on the bottom of the controller, and remove a clamp, which is fixing extension cable.



- 5 Replacing Parts
- 5.2 Power Relay Circuit Board Replacement
- 3. Loosen two fixed screws of the base mounting the CPU unit.



- 4. Hold the CPU unit itself, and remove the CPU unit as pulling them from the controller.
- 5. Remove the fixing jig from the DIN rail.
- 6. To unlock, depress a DIN rail fixed lock which is located in lower spot of the power relay circuit board. (one place)



- 5 Replacing Parts
- 5.2 Power Relay Circuit Board Replacement
- 7. Unlock both upper and lower locations of the power relay circuit board.



8. After unlocking, move the power relay circuit board to the left side of the DIN rail. Separate the power relay circuit board and the control circuit board, and then remove the power relay circuit board from the DIN rail.



9. Install the new power relay circuit board to the DIN rail. Assemble it with the control circuit board, and lock the boards. (Lock the boards for both upper and lower locations.)

#### Power relay circuit board



- 5 Replacing Parts
- 5.2 Power Relay Circuit Board Replacement
- 10. Force up the DIN rail fixed lock which is located lower spot of the power relay circuit board, and fasten it to the DIN rail. Align the right edge of the circuit board rack and the edge of the DIN rail, and reinstall the fixing jig. Fasten the CPU unit to the DIN rail.



- 11. Hook the base mounting the CPU unit to inserted style brackets and the fixing screws, and fasten the screws. (two places)
- 12. Reinstall all cables to the CPU unit. Be sure not to forget connecting the battery on the bottom of the controller and the grounding wire to the power relay circuit board.
- 13. Reinstall the front panel, and tighten four screws.

- 5 Replacing Parts
- 5.3 Circuit Board Rack Replacement

# 5.3 Circuit Board Rack Replacement

(JEPMC-BUB3008R-E is abbreviated as MBU-B08R)



Before replacing the board, save the important data, such as the parameter, to a USB storage device, and then turn the power supply OFF.





- 5 Replacing Parts
- 5.3 Circuit Board Rack Replacement

#### **Replacement Procedures**

1. Remove two screws on the upper and loosen two screws on the lower of the front panel, and then remove the front panel.



2. Remove all connected cables to the each board in the CPU unit. Also disconnect a battery lead extension cable connector, which is connected to the battery on the bottom of the controller, and remove a clamp, which is fixing extension cable.



- 5 Replacing Parts
- 5.3 Circuit Board Rack Replacement
- 3. Loosen two fixed screws of the base mounting the CPU unit.



- 4. Hold the CPU unit itself, and remove the CPU unit as pulling them from the controller.
- 5. To unlock, depress a DIN rail fixed lock which is located in lower spot of the circuit board rack. (two places)



- 5 Replacing Parts
- 5.3 Circuit Board Rack Replacement
- 6. Unlock both upper and lower locations of the control circuit board.



7. After unlocking, move the circuit board rack to the right side of the DIN rail. Separate the control circuit board and the circuit board rack, and then remove the circuit board rack from the DIN rail.



8. In order to remove the board and the cover on the rack, take out a tool for removing the front cover from the left side of the rack.



- 5 **Replacing Parts**
- 5.3 **Circuit Board Rack Replacement**
- 9. Insert the tool into the depressed area which is fixing the front cover, and unlock the cover.

\*The tool should be used as follows.



Removing the front cover of the machine safety circuit board. (two depressing areas)



Removing the user I/O circuit board or the system I/O circuit board. (one depressing area)

\*As for the rack with an optional board, follow the same procedures to open the front cover of the optional board.

10. Remove all boards which are attached to the rack, after removing the front cover, and replace the rack.

\*Pull straight the boards along by the rail.



- 5 Replacing Parts
- 5.3 Circuit Board Rack Replacement
- 11. After replacing the rack, reinstall the boards on the new rack. Insert the boards straight along by the rail which are located in the top and bottom on the rack. Each board should be reinstalled where it used to be. Special attention for the user input/output board (JAPMC-IO2308R-E) and the system input/output board (JAPMC-IO2308R-ET1) for installation.



Remove the boards and reinstall them again, when the boards does not smoothly move into the rack.

Avoid excessive pressure during the replacement. It may cause a damage or a failure to the boards. Special attention for the replacement.



The guide for inserting the boards (Rails)

- 12. After installing the boards, reinstall the front covers. Put the tool for removing the front cover away into the left side of the rack.
  \*To install the front cover, insert the bottom of the cover first which makes installation easier. After installation, make sure the cover is not loosen.
- 13. Install the rack to the DIN rail. Assemble it with the control circuit board, and lock the board. (Lock the board for both upper and lower locations.)



- 5 Replacing Parts
- 5.3 Circuit Board Rack Replacement
- 14. Force up the DIN rail fixed lock which is located lower spot on the rack, and fasten it to the DIN rail. Align the right edge of the circuit board rack and the edge of the DIN rail.



- 15. Hook the base which mounting the CPU unit to the inserted style brackets and the fixing screws, and fasten the screws. (two places)
- 16. Reinstall all cables to the CPU unit. Be sure not to forget connecting the battery on the bottom of the controller and the grounding wire to the power relay circuit board.
- 17. Reinstall the front panel, and tighten four screws.

- 5 Replacing Parts
- 5.4 Machine Safety Circuit Board Replacement

## 5.4 Machine Safety Circuit Board Replacement

(JAPMC-SF2300R-E is abbreviated as SF2300R)



Before replacing the board, turn the power supply OFF.



#### Replacement Procedures

1. Remove two screws on the upper and loosen two screws on the lower of the front panel, and then remove the front panel.



2. Remove all connected cables to the machine safety circuit board.

- 5 Replacing Parts
- 5.4 Machine Safety Circuit Board Replacement
- 3. Take out a tool for removing the front cover from the left side of the rack.



 Insert the tool into the depressed area which is fixing the front cover of the machine safety circuit board, and unlock the cover.
 \*The tool should be used as follows.



- Removing the front cover of the machine safety circuit board.
   (2 depressing areas)
- 5. Remove the machine safety circuit board, after removing the front cover.
  - \*Pull straight the board along by the rail.



- 5 Replacing Parts
- 5.4 Machine Safety Circuit Board Replacement
- Install the new machine safety circuit board on the rack.
   \*Insert the board straight along by the rails which are located in the top and the bottom on the rack.



Remove the board and reinstall it again when the board does not smoothly move into the rack.

Avoid excessive pressure during the replacement. It may cause a damage or a failure to the boards. Special attention for the replacement.



The guide for inserting the boards (Rails)

- After installing the board, reinstall the front cover. Put the tool for removing the front cover away into the left side of the rack.
   \*To install the front cover, insert the bottom of the cover first, which makes installation easier. After installation, make sure the cover is not loosen.
- Reinstall all cables to the machine safety circuit board.
   \*Be sure to attach the CN1 short circuit connector which is located on the top.
- 9. Reinstall the front panel, and tighten four screws.

- 5 Replacing Parts
- 5.5 User I/O Circuit Board and System Circuit I/O Board Replacement

# 5.5 User I/O Circuit Board and System Circuit I/O Board Replacement

User I/O circuit board: (JAPMC-IO2308R-E) System I/O circuit board: (JAPMC-IO2308R-ET1)







- 5 Replacing Parts
- 5.5 User I/O Circuit Board and System Circuit I/O Board Replacement

## **Replacement Procedures**

1. Remove two screws on the upper and loosen two screws on the lower of the front panel, and then remove the front panel.



- 2. Remove the attached cables on CN1, CN2 and CN3 of I/O board.
- 3. Take out a tool for removing the front cover from the left side of the rack.



- 5 Replacing Parts
- 5.5 User I/O Circuit Board and System Circuit I/O Board Replacement
- 4. Insert the tool into the depressed area which is fixing the front cover, and unlock the cover.

\*The tool should be used as follows.



5. After removing the cover, remove the I/O board. \*Pull straight the board along by the rail.





Pull straight the board from the rack. If it does not, it may cause a damage or a failure to the board and the rack. Special attention for the replacement

- 5 Replacing Parts
- 5.5 User I/O Circuit Board and System Circuit I/O Board Replacement
- 6. Install the new I/O board along by the rail to deeply inside of the rack.





Remove the board and reinstall it again when the board does not smoothly move into the rack.

Avoid excessive pressure during the replacement. It may cause a damage or a failure to the boards. Special attention for the replacement.

7. After installing the I/O board, reinstall the front cover. Put the tool for removing the front cover away into the left side of the rack.

\*To install the front cover, insert the bottom of the cover first, which makes installation easier. After installation, make sure the cover is not loosen.

- 8. Reinstall all cables to the I/O board.
- 9. Reinstall the front panel, and tighten four screws.

- 5 Replacing Parts
- 5.6 CPS Unit (JZNC-YPS01-E) Replacement

# 5.6 CPS Unit (JZNC-YPS01-E) Replacement



• After turning OFF the power supply, wait at least 5 minutes before replacing a control power supply. Do not touch any terminals during this period. Confirm all monitor lights are turned OFF.

Failure to observe this caution may result in electric shock or injury.

#### Replacement Procedure

1. Loosen six screws on the back panel, and then remove the back panel.



- 2. Disconnect all cables which connected to the CPS unit.
- 3. Loosen upper screws (2 places) fixing the CPS unit to the controller.
- 4. Remove the CPS unit from the controller by holding up the unit.
- 5. Insert the lower part flange of the new CPS unit into the inserted style bracket.
- 6. Tighten upper screws.
- 7. Connect all disconnected cables.
- 8. Reinstall the back panel, and tighten six screws.

- 5 **Replacing Parts**
- 5.6 CPS Unit (JZNC-YPS01-E) Replacement



# Fig. 5-1: CPS Unit (JZNC-YPS01-E)

- 5 Replacing Parts
- 5.7 Power Supply Contactor Unit (JZRCR-YPU31 □ -1) Replacement
- 5.7 Power Supply Contactor Unit (JZRCR-YPU31 □ -1) Replacement



## Replacement Procedure

1. Loosen six screws on the back panel, and then remove the back panel.



2. Disconnect all the cables connected to the power supply contactor unit.

\*The following connectors are not necessarily disconnected since they are to connected inside the unit.

CN610, CN611, CN612

(Disconnect the grounding wire screwed to the front side of the unit.)

- 3. Loosen upper and lower side screws (4 places) fixing the power supply contactor unit to the controller.
- 4. Remove the power supply contactor unit from the controller by holding up the upper and lower side.
  \*Do not hold the board only, but hold it together with the unit since it may cause damages to the board or injury.
- 5. Hook the new power supply contactor unit to the screws in the controller (4 places).
  \*Do not hold the board only, but hold it together with the unit since it may cause damages to the board or injury.
- 6. Tighten upper and lower side screws (4 places) firmly to fix the power supply contactor unit.

- 5 Replacing Parts
- 5.7 Power Supply Contactor Unit (JZRCR-YPU31 1) Replacement
- 7. Connect all the disconnected cables. (Connect the grounding wire firmly.)
- 8. Reinstall the back panel, and tighten six screws.
- Fig. 5-2: Configuration of Power Supply Contactor Unit (JZRCR-YPU31 □ -1)



- 5 Replacing Parts
- 5.8 Brake Control Board (JZRCR-YBK01-2E) Replacement

## 5.8 Brake Control Board (JZRCR-YBK01-2E) Replacement



#### Replacement Procedure

1. Loosen six screws on the back panel, and then remove the back panel.



- Disconnect the cable connectors from the brake control board.
   \*Do not disconnect jumper wiring connectors at CN404 yet. (Disconnect the grounding wire which screwed to the front side of the board.)
- 3. Loosen upper side screws (2 places) fixing the brake control board to the controller.
- 4. Remove the brake control board from the controller by holding up the board.
- 5. Hook the new cotrol brake control board to the inserted style bracket.
- 6. Tighten upper side screws (2 places) to fix the brake control board.
- 7. Disconnect CN404 jumper wiring connectors from the removed brake control board and connect them to CN404 on the new brake control board.
- 8. Connect all the disconnected cables. (Connect the grounding wire firmly.)
- 9. Reinstall the back panel, and tighten six screws.

- 5 Replacing Parts
- 5.8 Brake Control Board (JZRCR-YBK01-2E) Replacement





5 Replacing Parts

5.9 SERVO AMPLIFIER (SRDA-SDA 
A01A-E) Replacement

## 5.9 SERVO AMPLIFIER (SRDA-SDA DA1A-E) Replacement



 After turning OFF the power supply, wait at least 5 minutes before replacing a SERVO AMPLIFIER. Do not touch any terminals during this period.

Failure to observe this warning may result in electric shock.

#### Replacement Procedure

- 1. Turn OFF the breaker and the primary power supply and wait at least 5 minutes before replacement. Do not touch any terminals during this period.
- 2. Remove screws (8 places) on the top panel, and then remove the top panel.



Top View

- 3. Verify that the converter charge lamp (red LED) is unlit.
- 4. Disconnect all the cables, which are shown in below, connected externally to the major axis control circuit board.
  - (1) Converter control signal connector (CN507)
  - (2) Control power supply connector for the converter (CN510)
  - (3) Safety unit I/F connector (CN511)
  - (4) Brake control signal connector (CN513)
  - (5) Control power supply input connector (CN509)
  - (6) Control communication connector (CN515)
  - (7) Encoder signal connector (CN508)
  - (8) Direct-in connector (CN514)
- 5. Unscrew four EAXA base fixing screws.
- 6. Open the EAXA base.
- 7. Disconnect all the cables from the servo amplifier to be replaced.

- 5 Replacing Parts
- 5.9 SERVO AMPLIFIER (SRDA-SDA 
  A01A-E) Replacement
- Remove screws fixing the amplifier.
   \*Servo amplifier for SRDA-SDA14A01A-E, SRDA-SDA21A01A-E
   : Remove upper right and lower left screws (2 places).

\*Servo amplifier for SRDA-SDA35A01A-E, SRDA-SDA71A01A-E : Remove IPM fixing screws (2 places) besides the four corners screws (4 places).

- 9. Mount thermal sheet to the new servo amplifier. (Refer to Thermal Sheet Mounting Instruction)
- 10. Mount the new servo amplifier.
- 11. Connect all the disconnected cables to the new servo amplifier.
- 12. Tighten four EAXA base fixing screws.
- 13. Connect all the disconnected cables to the SERVOPACK.
- 14. Reinstall the top panel, and tighten eight screws.
- Fig. 5-4: SERVOPACK



5 Replacing Parts

5.9 SERVO AMPLIFIER (SRDA-SDA 
A01A-E) Replacement









- 5 Replacing Parts
- 5.9 SERVO AMPLIFIER (SRDA-SDA 
  A01A-E) Replacement

"Thermal sheet mounting instruction"

Affix the thermal sheet to the bottom of the amplifier along the grooves.

- •Servo amplifier : SRDA-SDA14A01A-E, SRDA-SDA21A01A-E Affix the thermal sheet to the bottom of the amplifier along its grooves.
- •Servo amplifier : SRDA-SDA35A01A-E, SRDA-SDA71A01A-E

True up the edges of the IPM frame and its grooves that are at the bottom of the amplifier, then affix the thermal sheet along the edge.



Fig. 5-7: Thermal Sheet Mounting Instruction

- 5 Replacing Parts
- 5.10 Converter (SRDA-COA30A01A-E) Replacement

## 5.10 Converter (SRDA-COA30A01A-E) Replacement



#### Replacement Procedure

- 1. Turn OFF the breaker and the primary power supply and wait at least 5 minutes before replacement. Do not touch any terminals during this period.
- 2. Loosen six screws on the back panel, and then remove the back panel.



- 3. Verify that the converter charge lamp (red LED) is unlit.
- 4. Disconnect all the cables connected externally to the converter, and also disconnect the grounding wire which fixing with the screws to the converter.
- 5. Loosen lower two screws and remove upper two screws fixing the converter.
- 6. Hold the top grip and lift it to pull out the converter.
- Install the new converter and reconnect the connectors in the reverse order of the removing procedure. (Connect the grounding wire firmly.)

- 5 Replacing Parts
- 5.10 Converter (SRDA-COA30A01A-E) Replacement
- 8. Reinstall the back panel, and tighten six screws.





- 5 Replacing Parts
- 5.11 Major Axes Control Circuit Board (SRDA-EAXA01A) Replacement

## 5.11 Major Axes Control Circuit Board (SRDA-EAXA01A) Replacement



#### Replacement Procedure

1. Remove screws (8 places) on the top panel, and then remove the top panel.





- 2. Disconnect all the cables connected to the major axes control circuit board.
- 3. Remove A screws. (6 places)
- 4. Remove the EAXA cover.
- 5. Remove hexagon threaded spacers (6 places) fixing A screws.
- 6. Remove B screws (8 places).
- 7. Remove the major axes control circuit board from the SERVOPACK.
- 8. Install the new circuit board to the SERVOPACK in the reverse order of the removing procedure.
- 9. Set the rotary switch to the same value as the removed circuit board's rotary switch.
- 10. Reinstall the EAXA cover.
- 11. Connect all the disconnected cables in the step 2.
- 12. Reinstall the top panel, and tighten eight screws.
- 5 Replacing Parts
- 5.11 Major Axes Control Circuit Board (SRDA-EAXA01A) Replacement



Fig. 5-9: Major Axes Control Circuit Board Replacement Procedure

- 5 Replacing Parts
- 5.12 Checking and Replacing Fuse

## 5.12 Checking and Replacing Fuse

#### 5.12.1 Power Supply Contactor Unit

The types of fuses on the power supply contactor unit (JZRCR-YPU31  $\Box$  -1) are as follows.

Parts No.	Fuse Name	Specification
1FU, 2FU	AC Control Power Supply Fuse	0218010P 250V,10A, Time Lag Fuse (LITTEL)
3FU,4FU	AC Cooling Fan Fuse	GP25, 2.5A, 250V (Daito Communication Apparatus Co., Ltd.)

Fig. 5-10: Replacement Fuse of the Power Supply Contactor Unit



If the fuse is blown, replace it with the same type of fuse (supplied or spare parts).



- 5 Replacing Parts
- 5.12 Checking and Replacing Fuse

#### 5.12.2 Brake Control Board

The types of fuses on the brake control board (JANCD-YBK01-2E) are as follows.

Parts No.	Fuse Name	Specification
F1	Brake Power Supply Fuse for External Axis	02173.15P, 250V,3.15A, Rapid Cut Fuse (LITTEL)

Fig. 5-11: Replacement Fuse of I/O Unit (JZNC-YIU01-2E)



If the fuse is blown, replace it with the same type of fuse (supplied or spare parts).



- 5 Replacing Parts
- 5.12 Checking and Replacing Fuse

#### 5.12.3 Fuse Holder

There are following fuses on the left side of FS100L.

Parts No.	Name	Specification
F11	DC Control Power Supply Fuse	0312010.MXP, 250V, 10A Rapid Cut Fuse (LITTEL)
F12	PP Power Supply Fuse	0312001.MXP, 250V, 1A Rapid Cut Fuse(LITTEL)
F13	System I/O power supply fuse	0312.300MXP, 250V, 0.3A Rapid Cut Fuse (LITTEL)
F14	User I/O power supply fuse	0312001.MXP, 250V, 1A Rapid Cut Fuse (LITTEL)



If the fuse seems to be blown, remove it and perform the continuity check by a tester. If the fuse is blown, replace it with the same type of fuse (supplied or spare parts).



- 5 Replacing Parts
- 5.12 Checking and Replacing Fuse

### 5.12.4 Major Axes Control Circuit Board (SRDA-EAXA01A)

There is a following fuse in the major axes control circuit board.

\*A exchangeable fuse is mounted in the board of which revision number is later than REV.C.

Parts No.	Name	Specification
F1	PG power supply fuse	HM10 250V, 1A Daito Communication Apparatus Co., Ltd.



If the fuse is blown, replace it with the same type of fuse (supplied or spare parts).



- 5 Replacing Parts
- 5.13 Cooling Fan Replacement

## 5.13 Cooling Fan Replacement



Turn OFF the power before replacing the cooling fan.

#### 5.13.1 Replacing Servo Cooling Fan

#### Replacement Procedures

- 1. Remove two screws on the upper, and loosen two screws on the lower of the front panel, and then remove the front panel.
- 2. Remove screws (2 places) fixing the fan and the fan-guard.
- 3. Disconnect a plug code and the grounding wire connected to the fan.
- 4. Remove the fan from the controller.
- 5. Connect the plug code and the grounding wire to the new fan. (Connect the plug code firmly to fill the gap, and also connect the grounding wire firmly.)
- 6. Install the new fan to the controller. Tighten with the fan guard. Install the fan to the direction where the fan can absorb an air against the inside of the controller. (In other words, install the label side of the fan toward the inside of the controller.)
- 7. Reinstall the front panel, and tighten four screws.



- 5 Replacing Parts
- 5.13 Cooling Fan Replacement

#### 5.13.2 Replacing Converter Cooling fan

#### Replacement Procedures

- 1. Remove screws (8 places) on the top panel, and then remove the top panel.
- 2. Loosen screws (4 places) fixing the fan base.
- 3. Remove the fan base then disconnect a plug code and the grounding wire from the fan.
- 4. Remove screws fixing the fan (2places), and remove the fan from the fan base.
- Install the new fan to the fan base. Install the fan to the direction where the fan can absorb an air against the converter. (In other words, install the label side of the fan toward the converter.)
- Connect the plug code and the grounding wire to the new fan. (Connect the plug code firmly to fill the gap, and also connect the grounding wire firmly.)
- 7. Reinstall the fan base with the new fan to the controller.
- 8. Reinstall the top panel, and tighten eight screws.



(with the top panel)

(without the top panel)

- 5 Replacing Parts
- 5.13 Cooling Fan Replacement

#### 5.13.3 Replacing Regenerative Resistor Cooling Fan



#### Replacement Procedures

- 1. Loosen screws (4 places) on the right panel, and then remove the right panel.
- 2. Disconnect all connected cables from the regenerative resistor box. (Also disconnect the fixed grounding wire.)
- 3. Remove the screws (4places) on the plate fixing the regenerative resistor box.



Right View (with the right panel)

Right View (without the right panel)

4. Move the regenerative resistor box forward, and take it out from FS100L.



<u>Front View</u> (Remove the regenerative resistor box)

- 5 Replacing Parts
- 5.13 Cooling Fan Replacement
- 5. Remove screws (2places) fixing the fan.
- 6. Disconnect the plug code and the grounding wire from the fan.
- 7. Remove the fan from the regenerative resistor box.
- 8. Connect the plug code and the grounding wire to the new fan. (Connect the plug code firmly to fill the gap, and also connect the grounding wire firmly.)
- 9. Install the new fan to the regenerative resistor box.
  Install the fan to the direction where the fan can absorb an air against the inside of the regenerative resistor box.
  (In other words, install the label side of the fan toward the inside of the regenerative resistor box.)
- 10. Install the regenerative resistor box to the FS100L, and move the box backwards to FS100L.

Reinstall the plate, and tighten four screws.



Right View (without the right panel)

- 11. Connect all cables to the regenerative resistor box. (Connect the grounding wire firmly.)
- 12. Reinstall the right panel, and tighten four screws.

- 5 Replacing Parts
- 5.13 Cooling Fan Replacement

#### 5.13.4 Replacing Cooling Fan for the Interior of the Controller

#### Replacement Procedures

- 1. Loosen screws (6 places) on the left panel, and then remove the left panel.
- 2. Remove screws (2 places) fixing the fan.
- 3. Disconnect a plug code and the grounding wire connected to the fan.
- 4. Remove the fan from the controller.
- 5. Connect the plug code and the grounding wire to the new fan. (Connect the plug code firmly to fill the gap, and also connect the grounding wire firmly.)
- Install the new fan to the controller. Install the fan to the direction where the fan can absorb an air against the inside of the controller. (In other words, install the label side of the fan toward the inside of the controller.)
- 7. Reinstall the left panel, and tighten six screws.



(with the left panel)

(without the left panel)

- 5 Replacing Parts
- 5.14 Battery Replacement

## 5.14 Battery Replacement

The battery must be replaced as soon as the battery alarm occurred. Please be sure to replace it within 1 hour after the power is turned OFF.

(When the programming pendant is used, a message to ask battery replacement appears on its window.

Also, the timing can be confirmed by the lighting-up of the battery alarm LED on the control circuit board. (CPU-201R)



Before replacing the battery, save the important data to a USB storage device, such as the parameter, and turn the power supply OFF.

#### Replacement Procedures

- 1. Remove two screws on the upper, and loosen two screws on the lower of the front panel, and then remove the front panel.
- Loosen a strap which tighten the battery on the bottom of the controller, and remove the battery.
   In case of the difficulty, remove the cable connected to the machine safety circuit board (JAPMC-SF2300R-E) first, and remove the battery.



Connector of the battery lead extension cable

- 3. Remove the connector of the battery lead extension cable, and remove the battery. Please do not pull the extension cable strongly, and do not use the excessive power to remove the battery.
- 4. Connect the new battery to the battery lead extension cable.
- 5. Fix the battery with the strap on the bottom of the controller. Fasten the strap till the 5th hole of it. If disconnect the cable to the machine safety circuit board, connect the cable again.



Although the CMOS memory is backed up by super capacitor, the battery must be replaced as soon as the message "Memory battery weak" appears.

The job data and other data may be lost if the message "Memory battery weak" appears and the breaker is turned OFF for more than 1 hours.

- 5 Replacing Parts
- 5.15 Relay for the Motor Cooling Fan Replacement

#### 5.15 Relay for the Motor Cooling Fan Replacement

All robots do not have the relay for the motor cooling fan. To confirm having the relay, refer to *chapter 6.2 "Recommended Spare Parts" at page 6-3.* 

#### Replacement Procedures

- 1. Loosen screws (6 places) on the left panel, and then remove the left panel.
- 2. Remove the relay from the relay socket.
- 3. Install the new relay to the relay socket.
- 4. Reinstall the left panel, and tighten six screws.



Left View (with the left panel)



Left View (without the left panel)

- 5 Replacing Parts
- 5.16 Filter Replacement

## 5.16 Filter Replacement

With the IP40 optional, there are filters on the air inlet/outlet as follows.

- Front panel ① : HB1301077-1
- Front panel ② : HB1301077-2
- Left panel ① : HB1301077-3
- Left panel ② : HB1301077-4
- Back panel ① : HB1301077-5
- Back panel ② : HB1301077-6



#### **Replacement Procedures**

- 1. Open a latch on the filter by pulling.
- 2. Remove the filter cover, and replace the filter.
- 3. Install the filter cover , and close the latch.

- 5 Replacing Parts
- 5.17 Cable Inlet Replacement

## 5.17 Cable Inlet Replacement

When replace the connected cables to FS100L, replace the cable inlet as well if a gap of the cable inlet becomes wider by deformed gasket of the front panel.

#### Replacement Procedures

- 1. Remove fixed screws (4 places) of the cable inlet, and remove the cable inlet.
- 2. Insert the cable into the new cable inlet, and tighten the four screws.



- 6 Recommended Spare Parts
- 6.1 List of FS100L Accessories

## 6.1 List of FS100L Accessories

Accessories of FS100L are as follows.

No.	Name	Dimensions	Model	Manufacturer	Qty
1	AC Control Power Supply Fuse		0218010P (10A 250V)	LITTEL	2
2	AC Cooling Fan Fuse		GP25 (2.5A 250V)	Daito Communication Apparatus Co., Ltd.	2
3	Brake Power Supply Fuse for External Axis		02173.15P (3.15A 250V)	LITTEL	1
4	DC Control Power Supply Fuse		0312010.MXP (10A 250V)	LITTEL	1
5	PP Power Supply Fuse User I/O Power Supply Fuse		0312001.MXP (1A 250V)	LITTEL	2
6	System I/O Power Supply Fuse		0312.300 MXP (0.3A 250V)	LITTEL	1
7	PG Power Supply Fuse		HM10 1A 250V	Daito Communication Apparatus Co., Ltd.	1
8	WAGO Connector Wiring Tool		734-230	WAGO	1
9	Power Supply Connector		09 14 003 2701	HARTING	1
	Carrier Hood		09 14 001 0311	HARTING	1
	Hood (Screw in hood)	1	19 14 001 0402	HARTING	1
	Cable Clamp	01	19 00 000 5194	HARTING	1
	Tool for Power Supply Connector	<b>S</b>	09 99 000 0313	HARTING	1

## Recommended Spare Parts List of FS100L Accessories 6

6.1

No.	Name	Dimensions	Model	Manufacturer	Qty
10	PP Hook		HB0402252-1	Yaskawa Electric Corporation	1

- 6 Recommended Spare Parts
- 6.2 Recommended Spare Parts

It is recommended that the following parts and components be kept in stock as spare parts for the FS100L. The spare parts list for the FS100L is shown below.

To buy the spare parts which are ranked B or C, inform the manufacturing number (or order number) of FS100L to Yaskawa representative.

Product performance can not be guaranteed when using spare parts from any company other than Yaskawa. The spare parts are ranked as follows:

- Rank A: Expendable and frequently replaced parts
- Rank B: Boards and sub-units
- Rank C: Units



For replacing parts in Rank B or Rank C, contact your Yaskawa representative.

6.2 Recommended Spare Parts

Rank	Parts	Name	Туре	Manufacturer	Spare	Qty	Remarks
	No.				Parts	per	
						Unit	
A	1	Battery	BR-1/2AA 3.0V	PANASONIC	1	1	
Α	2	CPS Unit	JZNC-YZU01-E	Yaskawa Electric	1	1	
		Cooling Fan		Corporation			
A	3	Interior Circulation Fan	4715MS-22T-B50-B00	Minebea Co., Ltd	6	6	
A	4	AC Control Power supply Fuse	0218010P (10A 250V)	LITTEL	2	2	
A	5	AC Cooling Fan Fuse	GP25 (2.5A 250V)	Daito Communication Apparatus Co., Ltd.	2	2	
A	6	Brake Power Supply Fuse for External Axis	02173.15P (3.15A 250V)	LITTEL	1	1	
A	7	DC Control Power Supply Fuse	0312010.MXP (10A 250V)	LITTEL	1	1	
A	8	PP Power Supply Fuse User I/O power Supply Fuse	0312001.MXP (1A 250V)	LITTEL	2	2	
A	9	System I/O Power Supply fuse	0312.300 MXP (0.3A 250V)	LITTEL	1	1	
A	10	PG Power Supply Fuse	HM10 (1A 250V)	Daito Communication Apparatus Co., Ltd.	1	1	
A	11	Relay for Motor Cooling Fan	LY2N-D2 DC24V	OMRON	1	1	
С	12	Converter	SRDA-COA30A01A-E	Yaskawa Electric Corporation	1	1	
В	13	Servo Amplifier 1, 2, 3	SRDA-SDA71A01A-E	Yaskawa Electric Corporation	1	3	
В	14	Servo Amplifier 4	SRDA-SDA35A01A-E	Yaskawa Electric Corporation	1	1	
В	15	Major Axes Control Circuit Board	SRDA-EAXA01A	Yaskawa Electric Corporation	1	1	
В	16	Power Relay Circuit Board	JEPMC-PSD3007R-E	Yaskawa Electric Corporation	1	1	
В	17	Control Circuit Board	JEPMC-CP3201R-E	Yaskawa Electric Corporation	1	1	
В	18	Circuit Board Rack	JEPMC-BUB3008R-E	Yaskawa Electric Corporation	1	1	
В	19	Machine Safety Circuit Board	JAPMC-SF2300R-E	Yaskawa Electric Corporation	1	1	
В	20	User I/O Circuit board	JAPMC-IO2308R-E	Yaskawa Electric Corporation	1	1	
В	21	System I/O Circuit board	JAPMC-SF2300R-ET1	Yaskawa Electric Corporation	1	1	
В	22	Brake Control Board	JANCD-YBK01-2E	Yaskawa Electric Corporation	1	1	

Table 6-1: Recommended Spare Parts List of FS100L for MPL100, MPL160, MPL300

- Recommended Spare Parts Recommended Spare Parts 6
- 6.2

Rank	Parts No.	Name	Туре	Manufacturer	Spare Parts	Qty per	Remarks
						Unit	
С	23	Power Supply Contractor Unit	JZRCR-YPU31C-1	Yaskawa Electric Corporation	1	1	
С	24	CPS Unit	JZNC-YPS01-E	Yaskawa Electric Corporation	1	1	
С	25	Programming Pendant	JZRCR-YPP03-1	Yaskawa Electric Corporation	1	1	With Cable (8M)

Table 6-1: Recommended Spare Parts List of FS100L for MPL100, MPL160, MPL300

6.2 Recommended Spare Parts

Rank	Parts No.	Name	Туре	Manufacturer	Spare Parts	Qty per	Remarks
						Unit	
A	1	Battery	BR-1/2AA 3.0V	PANASONIC	1	1	
Α	2	CPS Unit	JZNC-YZU01-E	Yaskawa Electric	1	1	
		Cooling Fan		Corporation			
A	3	Interior Circulation Fan	4715MS-22T-B50-B00	Minebea Co., Ltd	6	6	
A	4	AC Control Power supply Fuse	0218010P (10A 250V)	LITTEL	1	1	
A	5	AC Cooling Fan Fuse	GP25 (2.5A 250V)	Daito Communication Apparatus Co., Ltd.	2	2	
A	6	Brake Power Supply Fuse for External Axis	02173.15P (3.15A 250V)	LITTEL	1	1	
A	7	DC Control Power Supply Fuse	0312010.MXP (10A 250V)	LITTEL	1	1	
A	8	PP Power Supply Fuse User I/O power Supply Fuse	0312001.MXP (1A 250V)	LITTEL	2	2	
A	9	System I/O Power Supply fuse	0312.300 MXP (0.3A 250V)	LITTEL	1	1	
A	10	PG Power Supply Fuse	HM10 (1A 250V)	Daito Communication Apparatus Co., Ltd.	1	1	
С	11	Converter	SRDA-COA30A01A-E	Yaskawa Electric Corporation	1	1	
В	12	Servo Amplifier 1, 2	SRDA-SDA71A01A-E	Yaskawa Electric Corporation	1	2	
В	13	Servo Amplifier 3	SRDA-SDA35A01A-E	Yaskawa Electric Corporation	1	1	
В	14	Servo Amplifier 4, 5, 6	SRDA-SDA14A01A-E	Yaskawa Electric Corporation	1	3	
В	15	Major Axes Control Circuit Board	SRDA-EAXA01A	Yaskawa Electric Corporation	1	1	
В	16	Power Relay Circuit Board	JEPMC-PSD3007R-E	Yaskawa Electric Corporation	1	1	
В	17	Control Circuit Board	JEPMC-CP3201R-E	Yaskawa Electric Corporation	1	1	
В	18	Circuit Board Rack	JEPMC-BUB3008R-E	Yaskawa Electric Corporation	1	1	
В	19	Machine Safety Circuit Board	JAPMC-SF2300R-E	Yaskawa Electric Corporation	1	1	
В	20	User I/O Circuit board	JAPMC-IO2308R-E	Yaskawa Electric Corporation	1	1	
В	21	System I/O Circuit board	JAPMC-SF2300R-ET1	Yaskawa Electric Corporation	1	1	
В	22	Brake Control Board	JANCD-YBK01-2E	Yaskawa Electric Corporation	1	1	

Table 6-2: Recommended Spare Parts List of FS100L for MH50, MPL80

- Recommended Spare Parts Recommended Spare Parts 6
- 6.2

Rank	Parts No.	Name	Туре	Manufacturer	Spare Parts	Qty per	Remarks
С	23	Power Supply Contractor Unit	JZRCR-YPU31C-1	Yaskawa Electric Corporation	1	1	
С	24	CPS Unit	JZNC-YPS01-E	Yaskawa Electric Corporation	1	1	
С	25	Programming Pendant	JZRCR-YPP03-1	Yaskawa Electric Corporation	1	1	With Cable (8M)

Table 6-2: Recommended Spare Parts List of FS100L for MH50, MPL80

6.2 Recommended Spare Parts

Rank	Parts No.	Name	Туре	Manufacturer	Spare Parts	Qty per	Remarks
						Unit	
A	1	Batterv	BR-1/2AA 3.0V	PANASONIC	1	1	
Α	2	CPS Unit	JZNC-YZU01-E	Yaskawa Electric	1	1	
		Cooling Fan		Corporation			
А	3	Interior	4715MS-22T-B50-B00	Minebea Co., Ltd	6	6	
		Circulation Fan					
A	4	AC Control Power supply Fuse	0218010P (10A 250V)	LITTEL	2	2	
A	5	AC Cooling Fan Fuse	GP25 (2.5A 250V)	Daito Communication Apparatus Co., Ltd.	2	2	
A	6	Brake Power Supply Fuse for External Axis	02173.15P (3.15A 250V)	LITTEL	1	1	
A	7	DC Control Power Supply Fuse	0312010.MXP (10A 250V)	LITTEL	1	1	
A	8	PP Power Supply Fuse User I/O power Supply Fuse	0312001.MXP (1A 250V)	LITTEL	2	2	
A	9	System I/O Power Supply fuse	0312.300 MXP (0.3A 250V)	LITTEL	1	1	
A	10	PG Power Supply Fuse	HM10 (1A 250V)	Daito Communication Apparatus Co., Ltd.	1	1	
С	11	Converter	SRDA-COA30A01A-E	Yaskawa Electric Corporation	1	1	
В	12	Servo Amplifier 1, 2, 3	SRDA-SDA71A01A-E	Yaskawa Electric Corporation	1	3	
В	13	Servo Amplifier 4	SRDA-SDA35A01A-E	Yaskawa Electric Corporation	1	1	
В	14	Servo Amplifier 5, 6	SRDA-SDA21A01A-E	Yaskawa Electric Corporation	1	2	
В	15	Major Axes Control Circuit Board	SRDA-EAXA01A	Yaskawa Electric Corporation	1	1	
В	16	Power Relay Circuit Board	JEPMC-PSD3007R-E	Yaskawa Electric Corporation	1	1	
В	17	Control Circuit Board	JEPMC-CP3201R-E	Yaskawa Electric Corporation	1	1	
В	18	Circuit Board Rack	JEPMC-BUB3008R-E	Yaskawa Electric Corporation	1	1	
В	19	Machine Safety Circuit Board	JAPMC-SF2300R-E	Yaskawa Electric Corporation	1	1	
В	20	User I/O Circuit board	JAPMC-IO2308R-E	Yaskawa Electric Corporation	1	1	
В	21	System I/O Circuit board	JAPMC-SF2300R-ET1	Yaskawa Electric Corporation	1	1	
В	22	Brake Control Board	JANCD-YBK01-2E	Yaskawa Electric Corporation	1	1	

Table 6-3: Recommended Spare Parts List of FS100L for MH165, MH200

- Recommended Spare Parts Recommended Spare Parts 6
- 6.2

Rank	Parts No.	Name	Туре	Manufacturer	Spare Parts	Qty per Unit	Remarks
С	23	Power Supply Contractor Unit	JZRCR-YPU31C-1	Yaskawa Electric Corporation	1	1	
С	24	CPS Unit	JZNC-YPS01-E	Yaskawa Electric Corporation	1	1	
С	25	Programming Pendant	JZRCR-YPP03-1	Yaskawa Electric Corporation	1	1	With Cable (8M)

Table 6-3: Recommended Spare Parts List of FS100L for MH165, MH200

6.2 Recommended Spare Parts

Rank	Parts	Name	Туре	Manufacturer	Spare	Qty	Remarks
	No.				Parts	per	
						Unit	
A	1	Battery	BR-1/2AA 3.0V	PANASONIC	1	1	
A	2	CPS Unit	JZNC-YZU01-E	Yaskawa Electric	1	1	
		Cooling Fan		Corporation			
A	3	Interior Circulation Fan	4715MS-22T-B50-B00	Minebea Co., Ltd	6	6	
A	4	AC Control Power supply Fuse	0218010P (10A 250V)	LITTEL	2	2	
A	5	AC Cooling Fan Fuse	GP25 (2.5A 250V)	Daito Communication Apparatus Co., Ltd.	2	2	
A	6	Brake Power Supply Fuse for External Axis	02173.15P (3.15A 250V)	LITTEL	1	1	
A	7	DC Control Power Supply Fuse	0312010.MXP (10A 250V)		1	1	
A	8	PP Power Supply Fuse User I/O power Supply Fuse	0312001.MXP (1A 250V)	LITTEL	2	2	
A	9	System I/O Power Supply fuse	0312.300 MXP (0.3A 250V)		1	1	
A	10	PG Power Supply Fuse	HM10 (1A 250V)	Daito Communication Apparatus Co., Ltd.	1	1	
С	11	Converter	SRDA-COA30A01A-E	Yaskawa Electric Corporation	1	1	
В	12	Servo Amplifier 1, 2, 3	SRDA-SDA71A01A-E	Yaskawa Electric Corporation	1	3	
В	13	Servo Amplifier 4, 5, 6	SRDA-SDA35A01A-E	Yaskawa Electric Corporation	1	3	
В	14	Major Axes Control Circuit Board	SRDA-EAXA01A	Yaskawa Electric Corporation	1	1	
В	15	Power Relay Circuit Board	JEPMC-PSD3007R-E	Yaskawa Electric Corporation	1	1	
В	16	Control Circuit Board	JEPMC-CP3201R-E	Yaskawa Electric Corporation	1	1	
В	17	Circuit Board Rack	JEPMC-BUB3008R-E	Yaskawa Electric Corporation	1	1	
В	18	Machine Safety Circuit Board	JAPMC-SF2300R-E	Yaskawa Electric Corporation	1	1	
В	19	User I/O Circuit board	JAPMC-IO2308R-E	Yaskawa Electric Corporation	1	1	
В	20	System I/O Circuit board	JAPMC-SF2300R-ET1	Yaskawa Electric Corporation	1	1	
В	21	Brake Control Board	JANCD-YBK01-2E	Yaskawa Electric Corporation	1	1	

Table 6-4: Recommended Spare Parts List of FS100L for MH215, MH250

- Recommended Spare Parts Recommended Spare Parts 6
- 6.2

Rank	Parts	Name	Туре	Manufacturer	Spare	Qty	Remarks
	No.				Parts	per	
						Unit	
В	22	Power Supply Contractor Unit	JZRCR-YPU31C-1	Yaskawa Electric Corporation	1	1	
С	23	CPS Unit	JZNC-YPS01-E	Yaskawa Electric Corporation	1	1	
С	24	Programming Pendant	JZRCR-YPP03-1	Yaskawa Electric Corporation	1	1	With Cable (8M)

Table 6-4: Recommended Spare Parts List of FS100L for MH215, MH250

6.2 Recommended Spare Parts

Rank Parts		Name	Туре	Manufacturer	Spare	Qty	Remarks
	No.				Parts	per	
						Unit	
А	1	Battery	BR-1/2AA 3.0V	PANASONIC	1	1	
A	2	CPS Unit Cooling Fan	JZNC-YZU01-E	Yaskawa Electric Corporation	1	1	
A	3	Interior Circulation Fan	4715MS-22T-B50-B00	Minebea Co., Ltd	6	6	
A	4	AC Control Power supply Fuse	0218010P (10A 250V)	LITTEL	2	2	
A	5	AC Cooling Fan Fuse	GP25 (2.5A 250V)	Daito Communication Apparatus Co., Ltd.	2	2	
A	6	Brake Power Supply Fuse for External Axis	02173.15P (3.15A 250V)	LITTEL	1	1	
A	7	DC Control Power Supply Fuse	0312010.MXP (10A 250V)		1	1	
A	8	PP Power Supply Fuse User I/O power Supply Fuse	0312001.MXP (1A 250V)		2	2	
A	9	System I/O Power Supply fuse	0312.300 MXP (0.3A 250V)	LITTEL	1	1	
A	10	PG Power Supply Fuse	HM10 (1A 250V)	Daito Communication Apparatus Co., Ltd.	1	1	
С	11	Converter	SRDA-COA30A01A-E	Yaskawa Electric Corporation	1	1	
В	12	Servo Amplifier 1, 2, 3	SRDA-SDA71A01A-E	Yaskawa Electric Corporation	1	3	
В	13	Servo Amplifier 4, 5, 6	SRDA-SDA14A01A-E	Yaskawa Electric Corporation	1	3	
В	14	Major Axes Control Circuit Board	SRDA-EAXA01A	Yaskawa Electric Corporation	1	1	
В	15	Power Relay Circuit Board	JEPMC-PSD3007R-E	Yaskawa Electric Corporation	1	1	
В	16	Control Circuit Board	JEPMC-CP3201R-E	Yaskawa Electric Corporation	1	1	
В	17	Circuit Board Rack	JEPMC-BUB3008R-E	Yaskawa Electric Corporation	1	1	
В	18	Machine Safety Circuit Board	JAPMC-SF2300R-E	Yaskawa Electric Corporation	1	1	
В	19	User I/O Circuit board	JAPMC-IO2308R-E	Yaskawa Electric Corporation	1	1	
В	20	System I/O Circuit board	JAPMC-SF2300R-ET1	Yaskawa Electric Corporation	1	1	
В	21	Brake Control Board	JANCD-YBK01-2E	Yaskawa Electric Corporation	1	1	

Table 6-5: Recommended Spare Parts List of FS100L for MPK50, MH80

- 6 Recommended Spare Parts Recommended Spare Parts
- 6.2

Rank	Parts No.	Name	Туре	Manufacturer	Spare Parts	Qty per Unit	Remarks
В	22	Power Supply Contractor Unit	JZRCR-YPU31C-1	Yaskawa Electric Corporation	1	1	
С	23	CPS Unit	JZNC-YPS01-E	Yaskawa Electric Corporation	1	1	
С	24	Programming Pendant	JZRCR-YPP03-1	Yaskawa Electric Corporation	1	1	With Cable (8M)

Table 6-5: Recommended Spare Parts List of FS100L for MPK50, MH80

6.2 Recommended Spare Parts

Rank	Parts No.	Name	Туре	Manufacturer	Spare Parts	Qty per Unit	Remarks
A	1	Filter	HB1301077	Yaskawa Electric Corporation	2	1	
A	2	Cable Inlet	HB1370647	Yaskawa Electric Corporation	1	1	

Table 6-6: Recommended Spare Parts List of Optional IP40

## 7 Operations After Replacing Parts

7



7

٠

٠



on a fixture, or on the floor, the manipulator or a tool may collide with the programming pendant during manipulator movement, which may result in personal injury or equipment damage.

#### 7 Operations After Replacing Parts

7.1 Home Position Calibration

## 7.1 Home Position Calibration

#### 7.1.1 Home Position Calibration

Teaching and playback are not possible before home position calibration is complete.



In a system with two or more manipulators, the home position of all the manipulators must be calibrated before starting teaching or playback.

Set the security mode to the management mode to perform home position calibration.

Home position calibration is an operation in which the home position and absolute encoder position coincide. Although this operation is performed prior to shipment at the factory, the following cases require this operation to be performed again.

- Change in the combination of the manipulator and FS100L
- Replacement of the motor or absolute encoder
- Clearing stored memory (by replacement of main CPU board, weak battery, etc.)
- Home position deviation caused by hitting the manipulator against a workpiece, etc.

To calibrate the home position, use the axis keys to calibrate the mark for the home position on each axis so that the manipulator can take its posture for the home position. There are two operations for home position calibration:

- All the axes can be moved at the same time
- Axes can be moved individually

If the absolute data of the home position is already known, set the absolute data again after completing home position registration.

#### **Home Position**

The home position is the position with the pulse value "0" for each axis. See *chapter 7.1.3 "Manipulator Home Position" at page 7-10.* 

- 7 Operations After Replacing Parts
- 7.1 Home Position Calibration

## 7.1.2 Calibrating Operation

- 7.1.2.1 Registering All Axes at One Time
  - 1. Select {ROBOT} under the main menu.
  - 2. Select {HOME POSITION}.
    - The HOME POSITIONING window appears.

DATA	EDIT	DISPLAY	UTILITY	12 🖻 📶 🛛	Þ
HOME POST	TONING	APSOLUTE	DATA		
RT :S L U R B T	00000		* * * * *		

3. Select {DISPLAY} under the menu,

or select "PAGE" to display the selection window for the control group,

```
or press page key
```

- The pull-down menu appears.

DATA	EDIT	DISPLAY	UTILITY	12 🗷 📶 🛚	1 🐻 📮 👆	Þ
HOME POST	FIONING SELECT	RUBUT1				
R1 :S L	0	STATION				
U R	00		*			
1 B	00		*			
			1	PAGE		
Main Men	1 Simp	te Benu			-	-

- 7 Operations After Replacing Parts
- 7.1 Home Position Calibration

EDIT	DISPLAY	UTILITY	12 🕑 📶 😣	10 L (†	Þ
TIONING	ARSOLUTE	DATA			
00000		*			
		RS	1:ROBOT1 1:STATION1		
	FRIT	EDIT DISPLAY	FEGIT DISPLAY UTFLITY FICKING SELECT ASSOLUTE DATA SELECT ASSOL	FEAT DISPLAY UTFLITY 12 2 1 2	FOIT DISPLAY UTLATY 12 2 10 2 10 4

- 4. Select the desired control group.
- 5. Select {EDIT} under the menu.
  - The pull-down menu appears.

HOME POST	SELECT ALL	OUTE	DATA		
RT :S L U R B T	00000		*		

- 6. Select {SELECT ALL AXES}.
  - The confirmation dialog box appears.

DATA	EDIT	DISPLAY	UTILITY	12 🗷 📶	🚳 🚾 🖳 👆	Þ
HOME POST	FIONING SELECT	ABSOLUTE	DATA			
R1 :S		-	*			
UR	1		*			
-8 T		Crea	te home	position?		
		YES		NO		
	_				_	
						1
	_	-		The	_	_
Maln Men	u Simp	le Benu				

- 7. Select "YES".
  - Displayed position data of all axes are registered as home position.
     When "NO" is selected, the registration will be canceled.

- 7 Operations After Replacing Parts
- 7.1 Home Position Calibration
- 7.1.2.2 Registering Individual Axes
  - 1. Select {ROBOT} under the main menu.
  - 2. Select {HOME POSITION}.
  - 3. Select the desired control group.
    - Perform steps 3 and 4 which have been described in chapter 7.1.2.1 "Registering All Axes at One Time" at page 7-4 to select the desired control group.
  - 4. Select the axis to be registered.

DATA	EDIT	DISPLAY	UTILITY	12 🖻 📶 🚳 🐻	🖳 🖨  🖻
HOME POST	TIONING SELECT	ABSOLUTE	DATA		
R1 :S	00	-53	97165		
UR			*		
B	00	53	99349		
	0		-		
				PAGE	
Maln Men	u Sim	le Menu			

- The confirmation dialog box appears.

DATA	EDIT	DISPLAY	UTILITY	12 🗷 📶	🕲 🐻 🖳 👆	Þ
HOME POST	TIONING	ADSOLUTE	DATA			
R1 :S L U R	000	70	97165 21630 * *	_	-	
BŢ		Crea	te home	position?		
				Free		
Waln Men	u Sing	le Benu				

- 5. Select "YES".
  - Displayed position data of the axis are registered as home position.
     When "NO" is selected, the registration will be canceled.

- 7 Operations After Replacing Parts
- 7.1 Home Position Calibration

#### 7.1.2.3 Changing the Absolute Data

To change the absolute data of the axis when home position calibration is completed, perform the following:

- 1. Select {ROBOT} under the main menu.
- 2. Select {HOME POSITION}.
- 3. Select the desired control group.
  - Perform steps 3 and 4 which have been described in "Registering All Axes at One Time" to select the desired control group
- 4. Select the absolute data to be registered.
  - The number can now be entered.

DATA	EDIT	DISPLAY	UTILITY	12 2 10 00	۱	Þ
HOME POST	FIONING SELECT	ABSOLUTE	DATA			
R1 :S L U R B T	00000	703 -53218 -565 -565 -565 -553 -553 -11640	271651 20 21430 39240 99349 99803			
		-		1848	)	
Main Menu	2 Sinp	le Benu				

- 5. Enter the absolute data using the numeric keys.
- 6. Press [ENTER].
  - Absolute data are modified.

- 7 Operations After Replacing Parts
- 7.1 Home Position Calibration

#### 7.1.2.4 Clearing Absolute Data

- 1. Select {ROBOT} under the main menu.
- 2. Select {HOME POSITION}.
  - Perform steps 2, 3, and 4 which have been described in "Registering All Axes at One Time" to display the HOME POSITIONING window and select the desired control group.
- 3. Select {DATA} under the menu.
  - The pull-down menu appears.

DATA	EDIT	DISPLAY	UTILITY	12 🗷 📶 🚳	10 L (†	Þ
CLEAR ALL D	ATA ECI	ABSOLUTE	DATA			
L	00	-532	97165 21630			
UR	000	-562	21430 39240			
I. B	00	11640	99349			
				PAGE		
Maln Menu	s Sing	le Henu				

- 4. Select {CLEAR ALL DATA}.
  - The confirmation dialog box appears.

DATA	EDIT	DISPLAY	UTILITY	12 🛃 🖬 🕏		Þ
HOME POST	TIONING SELECT	ABSOLUTE	DATA			
R1 :S L U R B T	0000	70 -53 -56 55	97165 21630 21430 89240			
		Clear data? YES NO				
				Pre		
Na)n Nen	u Sing	le Henu	-			-
- Operations After Replacing Parts Home Position Calibration 7
- 7.1
- 5. Select "YES".
  - The all absolute data are cleared. When "NO" is selected, the operation will be canceled.

DATA	EDIT	DISPLAY	UTILITY	12 🗹 📶 🚳 🐻 寻	
HOME POST	TIONING SELECT	ABSOLUTE	DATA		
R1 :S L U R 8 T	00000		* * *		
_			_		_

7 Operations After Replacing Parts

7.1 Home Position Calibration

### 7.1.3 Manipulator Home Position

With the MOTOMAN-MH165, the home position is as follows.





Other manipulator models have different positions. Always consult the documentation for the correct manipulator model.

- 7 Operations After Replacing Parts
- 7.2 Position Deviation Check Using the Check Program

# 7.2 Position Deviation Check Using the Check Program

Use the check program to check if positions are deviated with the following procedure.

1. Call up the check program in which the check point is taught (the job for) and operate the manipulator at low speed.



- 2. Check the tool tip position.
  - If it points the check point exactly as shown in the following figure, there is no deviation from the positions. Proceed to *chapter 7.4* "Setting the Second Home Position" at page 7-14.
  - If not, there is a deviation. When the motor or encoder, etc. was replaced, move the corresponding axis only, when the stored memory was cleared or the manipulator was hit against a workpiece, move all axes, to the check point by joint motion. Then, proceed to *chapter 7.3.3 "Home Position Data Correction" at page 7-13*.



### 7 Operations After Replacing Parts

7.3 Checking of the Check Program

# 7.3 Checking of the Check Program

# 7.3.1 Motion of the Check Program

Call up the check program in which the check point is taught (the job for avoiding the position deviation) and operate the manipulator at low speed.



#### 7.3.2 Checking of the Check Point

Check the deviation in to the check point. If the tool tip position is deviated, there is a deviation.

When the motor or encoder, etc. was replaced, move the corresponding axis only, when the stored memory was cleared or the manipulator was hit against a workpiece, move all axes, to the check point by joint motion.



- 7 Operations After Replacing Parts
- 7.3 Checking of the Check Program

# 7.3.3 Home Position Data Correction

When there is a deviation from the positions, correct the home position data with the following procedure.

- 1. Check the values of the following pulses.
  - If there is no deviation, the following two values coincide. Then, proceed to *chapter 7.4* "Setting the Second Home Position" at page 7-14.
  - If there is a deviation, execute the following procedures to correct it.
  - (1) Command position pulse of the check point which was taught in advance

#### **Displaying the Command Position Pulse**

- I) Select {ROBOT} under the main menu.
- II) Select {COMMAND POSITION}.
- (2) Current position pulse where the manipulator (tool tip) was moved to the check point after performing the check program

#### **Displaying the Current Position Pulse**

- I) Select {ROBOT} under the main menu.
- II) Select {CURRENT POSITION}.
- 2. Calculate the difference between the command position pulse and the current position pulse.

The difference pulse = Command position pulse – Current position pulse

- 3. On the HOME POSITIONING window, add the difference pulse value to the absolute data of the axis whose motor or encoder, etc. was replaced.
- 4. Modify the home position data by following the procedures described in *chapter 7.1.2.3 "Changing the Absolute Data" at page 7-7* in chapter 7.1.2.
- 5. Confirm that the command position pulse and the current position pulse coincide.
  - The home position data have been corrected.
  - Proceed to chapter.

- 7 Operations After Replacing Parts
- 7.4 Setting the Second Home Position

# 7.4 Setting the Second Home Position



• Be aware of safety hazards when performing the position confirmation of the second home position (check point).

Abnormality of the PG system may be a cause for alarm. The manipulator may operate in an unexpected manner, and there is a risk of damage to equipment or injury to personnel.

• Before operating the manipulator, check that the SERVO ON lamp goes out when the emergency stop button on the programming pendant is pressed.

Injury or damage to machinery may result if the manipulator cannot be stopped in case of an emergency.

- In the case of not using the programming pendant, be sure to supply the emergency stop button on the equipment. Then before operating the manipulator, check to be sure that the servo power is turned OFF by pressing the emergency stop button.
   Connect the external emergency stop button to the 5-6 pin and 16-17 pin of the robot system signal connector (CN2).
- Upon shipment of the FS100L, this signal is connected by a jumper cable in the dummy connector. To use the signal, make sure to supply a new connector, and then input it.

If the signal is input with the jumper cable connected, it does not function, which may result in personal injury or equipment damage.

- Observe the following precautions when performing teaching operations within the manipulator's operating range:
  - Be sure to use a lockout device to the safeguarding when going inside. Also, display the sign that the operation is being performed inside the safeguarding and make sure no one closes the safeguarding.
  - View the manipulator from the front whenever possible.
  - Always follow the predetermined operating procedure.
  - Ensure that you have a safe place to retreat in case of emergency.

Improper or unintended manipulator operation may result in injury.

- Prior to performing the following operations, be sure that no one is in the manipulator's operating range, and be sure that you are in a safe place when:
  - Turning ON the FS100L power.
  - Moving the manipulator with the programming pendant.

Injury may result from contact with the manipulator if persons enter the manipulator's operating range.

Always press the emergency stop button immediately if there are problems.

Emergency stop button is attached on the programming pendant.

- 7 Operations After Replacing Parts
- 7.4 Setting the Second Home Position



- 7 Operations After Replacing Parts
- 7.4 Setting the Second Home Position

#### 7.4.1 Purpose of Position Check Operation

If the absolute number of rotation detected at power supply ON does not match the data stored in the absolute encoder the last time the power supply was turned OFF, an alarm is issued when the FS100L power is turned ON.

There are two possible causes of this alarm:

- Error in the PG system
- The manipulator was moved after the power supply was turned OFF.

If there is an error with the PG system, the manipulator may stall when playback is started. If the absolute data allowable range error alarm has occurred, playback and test runs will not function and the position must be checked.



- 7 Operations After Replacing Parts
- 7.4 Setting the Second Home Position

### 1. Position Check

After the "OUT OF RANGE (ABSO DATA)" alarm occurs, move to the second home position using the axis keys and perform the position confirmation. Playback, test runs, and FWD operation will not function unless "CONFIRM POSITION" is performed.

### 2. Pulse Difference Check

The pulse number at the second home position is compared with that at the current position. If the difference is within the allowable range, playback is enabled. If not, the alarm occurs again.

- The allowable range pulse is the number of pulses per rotation of the motor (PPR data).
- The initial value of the second home position is the home position (where all axes are at pulse 0). The second home position can be changed. For details, refer to *chapter 7.4.2 "Procedure for the Second Home Position Setting (Check Point)" at page 7-18*.

#### 3. Alarm Occurrence

If the alarm occurs again, there may be an error in the PG system. Check the system. After adjusting the erroneous axis, calibrate the home position of the axis, then check the position again.

- Home position calibration of all the axes at the same time enables playback operations without having to check the position.
  Sometimes in a system with a manipulator that has no brake, it
  - Sometimes in a system with a manipulator that has no brake, it is possible to enable playback without position checking after the alarm occurs. However, as a rule, always perform "COMFIRM POSITION".

Under the above special conditions, the manipulator moves as

OTE

follows:

After starting, the manipulator moves at low speed (1/10 of the maximum speed) to the step indicated by the cursor.

If it is stopped and restarted during this motion, the low speed setting is retained until the step at cursor is reached. Regardless of cycle setting, the manipulator stops after the cursor step is reached.

Starting the manipulator again then moves it at the programmed speed and cycle of the job.

- 7 Operations After Replacing Parts
- 7.4 Setting the Second Home Position

#### 7.4.2 Procedure for the Second Home Position Setting (Check Point)

Apart from the "home position" of the manipulator, the second home position can be set up as a check point for absolute data. Use the following steps to set the specified point.

If two or more manipulators or stations are controlled by one FS100L, the second home position must be set for each manipulator or station.

- 1. Select {ROBOT} under the main menu.
- 2. Select {SECOND HOME POS}.
  - The SECOND HOME POS window appears.
     The message "Available to move to and modify specified point" is shown.

DATA	EDIT	DISPLAY	UTILITY	12 🗹 🖬 😣 🛅 寻 👘	Þ
SECOND HO	VE POS SPECIFIED	e	DOENT	DIFFERENCE	
R1 /S	0		n	0	
INT IS	0		0	ů	
ii.	0		0	0	
R	Ũ		0	Ő	
8	0		0	0	
T	0		0	0	
					_
				PAGE	
Halo Hea	I Sland	a Hanu	Inclick	In the mount to and modify approlition	nalat

- 3. Press the page key , or select "PAGE" to display the selection window for the control group.
  - The group axes by which the second home position is set is selected when there are two or more group axes.

DATA	EDIT	DISPLAY	UTILITY	12 🗷 📶 😣 🔟 🖳 (	•
SECOND HO	VE POS SPECIFIED	e	RENT	DIFFERENCE	
R1 :S	0	U.	0	0	
L	0		0	0	
U	0		0	U	
R	0		0	0	
8	0		0	0	
T	0		0	0	
				I:ROBOTI I:STATIONI	
				(FROM	
Maln Men	u Simpl	e Benu	Avai)ab	le to move to and modify specif	led point

- 4. Press the axis keys.
  - Move the manipulator to the new second home position.
- 5. Press [MODIFY] and [ENTER].
  - The second home position is changed.

- 7 Operations After Replacing Parts
- 7.4 Setting the Second Home Position

# 7.4.3 Procedure after the Alarm



Abnormality of the PG system may be cause for alarm. The manipulator may operate in an unexpected manner, and there is a risk of damage to equipment or injury to personnel.

If the "OUT OF RANGE (ABSO DATA)" alarm occurs, perform the followings

- Reset the alarm
- Turn Servo power ON

and confirm the second home position. After the confirmation, if the PG system is found to be the cause of the alarm, perform the necessary operation, such as replacing the PG, etc.

The robot current position data when turning main power supply OFF and ON can be confirmed in "POWER ON/OFF POS" window.



Refer to *chapter 8.7 "Position Data When Power is Turned ON/OFF" at page 8-23* for details on the "POWER ON/OFF POS" window.

- 1. Select {ROBOT} under the main menu.
- 2. Select {SECOND HOME POS}.
  - The SECOND HOME POS window appears.

DATA	EOIT	DISPLAY	UTILITY	12 🗷 📶 😣 🔟 🖳 👆	Þ
SECOND HC	ME POS SPECIFIED	C	RENT	DIFFERENCE	
R1 :S	0		0	0	
L	0		0	0	
P	0		0	0	
8	0		ŭ	0	
T	0		0	0	
				PAGE	
Main Mer	u Simpl	e Henu	Availat	le to move to and modify specified p	oint

#### 7 Operations After Replacing Parts

- 7.4 Setting the Second Home Position
- 3. Press the page key

or select "PAGE" to display the selection window for the control group.

 The group axes by which the second home position is set is selected when there are two or more group axes.



- 4. Press [FWD].
  - TCP moves to the second home position. The robot moving speed is set as selected manual speed.
- 5. Select {DATA} under the menu.
- 6. Select {CONFIRM POSITION}.
  - The message "Home position checked" is shown.
     Pulse data of the second home position and current pulse data are compared. If the compared error is in allowed range, playback operation can be done.

If the error is beyond the allowed range, the alarm occurs again.

- 8 System Diagnosis
- 8.1 System Version

# 8 System Diagnosis

# 8.1 System Version

It is possible to check the system CPU version information as follows.

- 1. Select {SYSTEM INFO} under the main menu.
- 2. Select {VERSION}.
  - The VERSION window appears.

DATA	EDIT	DISPLAY	UTILITY	1. 2 📶 🙁 🐻 📑 🦣	Þ
VERSION I	NECMATION				
SYSTEM	: CS0.74.9	7 (JP/US)-0	10		
PARAMETER	: 2.32 • MOULE-EA				
APPL 1	: GENERAL				
LANGUAGE	: 0.74-00	-00/ 0.74-0	00-00		
CDU	EVETEN DO	DOOT DOU			
CPU-201R	0.74.97	B.22	0.10		
YPP01	0.71-00	0.55-00	1.02		
1FM3L#0	0.73-99	0.10			
_		_	_		_
	Tur				_
Main Men	u Simpl	e Menu			

# 8.2 Manipulator Model

- 1. Select {ROBOT} under the main menu.
- 2. Select {MANIPULATOR TYPE}.
  - The ROBOT AXIS CONFIG window appears.

DATA	EDIT	DISPLAY	UTILITY	10 🖻 📶 🚳 🐻 🗔 👆
ROBUT AXIS	CONFIG GURATION			
R1 :MCMH5 S1 :UNIV-	-E4* 001 2 000	1_1111 0_0011		
		-		
Nain Nenu	Siap	le Benu		

- 8 System Diagnosis
- 8.3 Input/Output Status

# 8.3 Input/Output Status

#### 8.3.1 Universal Input

The status of input signal which is referred to by input instruction of a job can be confirmed.

#### 8.3.1.1 Universal Input Window

- 1. Select {IN/OUT} under the main menu.
- 2. Select {UNIVERSAL INPUT}.
  - The UNIVERSAL INPUT window appears.

DATA	EDIT	DISPLAY	UTILITY	12 🗷 📶 🧐	a 🐻 🖳 🤚	Þ
UNIVERSAL GROUP IN#0002 IN#0003 IN#0003 IN#0003 IN#0006 IN#00007 IN#00007 IN#0008	INPUT 100010 #00010 #00012 #00013 #00014 #00015 #00016 #00017		00:HEX.			
				PAGE		
Majn Menu	e Slavli	- Menu				

#### 8.3.1.2 Universal Input Simple Window

- 1. Select {IN/OUT} under the main menu.
- 2. Select {UNIVERSAL INPUT}.
  - The UNIVERSAL INPUT window appears.
- 3. Select {SIMPLE} from the pull-down menu of {DISPLAY}.
  - The UNIVERSAL INPUT simple window appears.

DATA	EDIT	DISPLAY	UTILITY	12 🗷 📶 ط 🛅 🖳 🁌	
UNIVERSAL	INPUT				
LOGICAL N	0. 7654 32	10			
#0001X	0000_00	000			
#0002X	0000_00	000			
#0003X	0000_00	00			
#0004X	0000_00	000			
#0005X	0000_00	000			
#0006X	0000_00	000			
#0007X	0000_00	000			
#0008X	0000_00	000			
#0009X	0000_00	000			
#0010X	0000_00	000			
#0011X	0000_00	000			
#0012X	0000_00	000			
#0013X	0000_00	000			
#0014X	0000_00	000			
#0015X	0000_00	000			
	T	- T			-
Main Men	u Slow	In Mena			

- 8 System Diagnosis
- 8.3 Input/Output Status

# 8.3.2 Universal Output

The status of the output signal set by the output instruction can be confirmed and modified.

- 8.3.2.1 Universal Output Window
  - 1. Select {IN/OUT} under the main menu.
  - 2. Select {UNIVERSAL OUTPUT}.
    - The UNIVERSAL OUTPUT window appears.

DATA	EDIT	DISPLAY	UTILITY	12 🗹 📶 🟍 🐻 🖳 👘	Þ
UNIVERSAL GROUP OUT#0002 OUT#0002 OUT#0003 OUT#0005 OUT#0006 OUT#0006 OUT#0008	001F07 06#001 #10010 C #10011 C #10012 C #10013 C #10014 C #10015 C #10016 C #10017 C	O:DEC.	00:HEX.		
				PAGE	
Ma)n Menu	Sleet.	r Mera			

- 8.3.2.2 Universal Output Simple Window
  - 1. Select {IN/OUT} under the main menu.
  - 2. Select {UNIVERSAL OUTPUT}.
    - The UNIVERSAL OUTPUT window appears.
  - 3. Select {SIMPLE} from the pull-down menu of {DISPLAY}.
    - The UNIVERSAL OUTPUT simple window appears.

DATA	EDIT	DISPLAY	UTILITY	12 🗷 📶 😣 🔟 🖳 👆
UNIVERSAL	OUTPUT			
LOGICAL N	<ol> <li>7654 3.</li> </ol>	210		
#1001X	0000_0	000		
#1002X	0000_0	000		
#1003X	0000_0	000		
#1004X	0000_00	000		
#1005X	0000_0	000		
#1006X	0000 0	000		
#1007X	0000 0	000		
#1008X	0000 0	000		
#1009X	0000 0	000		
#1010X	0000 0	000		
#1011X	0000 0	000		
#1012X	0000 0	000		
#1013X	0000 00	000		
#1014X	0000_0	000		
#1015X	0000 00	nac		
110100			-	
	-		1	
11-1-2 Hora		to the second	-	the second s

- 8 System Diagnosis
- 8.3 Input/Output Status

#### 8.3.2.3 Modifying the Output Status

The status of universal output signal can be changed by the operation below.

- 1. Select the desired output signal number.
  - Select the status of the desired output signal, "O" or "●" in the UNIVERSAL OUTPUT window.
- 2. Press INTER LOCK key 🐨 + [SELECT].
  - The status is changed. (•: ON status, O: OFF status)

DATA	EDIT	DISPLAY	UTILITY	12 🗹 😖 📾 📑 👆	Þ
UNIVERSAL GROUP OUT#0001 OUT#0002 OUT#0003 OUT#0005 OUT#0005 OUT#0006 OUT#0008	CUTEUT CG#001 #10010 C #10011 C #10012 C #10013 C #10014 C #10016 C #10016 C	SELEC.	033HEX.		
Main Menu		Moral		PAGE	_



The status of universal output signal can be changed only when the mode is set to the teach mode.

- 8 System Diagnosis
- 8.3 Input/Output Status

# 8.3.3 Specific Input

- 8.3.3.1 Specified Input Window
  - 1. Select {IN/OUT} under the main menu.
  - 2. Select {SPECIFIED INPUT}.
    - The SPECIFIED INPUT window appears.

FOLE IED	NPET				
GROUP		OFDEC.	00:HEX.		
SIN#0001	#40010 C	SYSTEM	ALM REQ		
SIN#0002	#40011 〇	SYSTEM	MSG REO		
SIN#0003	#40012 O	USER AL	M REQ		
SIN#0004	#40013 O	USER MS	G RED		
SIN#0005	#40014 Q	ALM/ERF	RESET		
SIN#0006	#40015 O	0			
SIN#0007	#40016 C	SPEED L	IMIT		
SIN#0008	#40017 O	0			
_		-		0405	-
				PAGE	

- 8.3.3.2 Specific Input Simple Window
  - 1. Select {IN/OUT} under the main menu.
  - 2. Select {SPECIFIED INPUT}.
    - The SPECIFIED INPUT window appears.
  - 3. Select {SIMPLE} from the pull-down menu of {DISPLAY}.
    - The SPECIFIC INPUT simple window appears.

UNTH	cult	DIGPLAT	uncin		
SPECIFIC	INPUT				
LOGICAL N	1. 7654 321	0			
#4001X	0000_000	0			
#4002X	0000_0000	0			
#4003X	0000_000	10			
#4004X	0000_0000	0			
#4005X	1000_000	0.			
#4006X	0000 0000	0			
#4007X	0000_000	0			
#4008X	0000 000	0			
#4009X	0000 0000	0			
#4010X	0000 0000	0			
#4011X	0000 000	0			
#4012X	0000 000	0			
#4013X	000 000	0			
#4014X	000 000	0			
#4015X	0000 000	in in			
	0000 000		-		-
				_	

- 8 System Diagnosis
- 8.3 Input/Output Status

### 8.3.4 Specific Output

- 8.3.4.1 Specified Output Window
  - 1. Select {IN/OUT} under the main menu.
  - 2. Select {SPECIFIED OUTPUT}.
    - The SPECIFIED OUTPUT window appears.

DATA	EDIT	DISPLAY	UTILITY	12 🗷 📶 😣 ն	
GROUP		O:DEC.	00:HEX.		
SOUT#000 SOUT#000	12 #50011 C	MINOR A	ALM OCCUR		
SOUT#000 SOUT#000	04 #50013 C	DUSER AL	M OCCUR		
SOUT#000 SOUT#000	07 #50016 C	ENCOR I	GIRY MEAK GIRY MEAK		
				PAGE	
Main Men	a Sine	r Menu			

- 8.3.4.2 Specific Output Simple Window
  - 1. Select {IN/OUT} under the main menu.
  - 2. Select {SPECIFIED OUTPUT}.
    - The SPECIFIED OUTPUT window appears.
  - 3. Select {SIMPLE} from the pull-down menu of {DISPLAY}.
    - The SPECIFIC OUTPUT simple window appears.

DATA	EDIT	DISPLAY	UTILITY	12 🗹 📶 😣	個日 🗄
SPECIFIC (	UTPUT				
LOGICAL N	1. 7654 3210				
#5001X	0000_0000	1			
#5002X	0000_0000				
#5003X	0000_0000				
#5004X	0000_0000				
¥5005X	0000_1010				
#5006X	0000_0000				
45007X	0000_1000				
75008X	0000_0000				
75009X	0000_0000				
45010X	0000_0000				
5011X	0000_0000				
\$5012X	0000_0000				
5013X	0000_0000				
5014X	0000_0000				
\$5015X	0000_0000				
_					1
-	7	-			
Hain Hen	a Sleete	depai			

- 8 System Diagnosis
- 8.3 Input/Output Status

# 8.3.5 RIN Input

- 8.3.5.1 RIN Input Window
- 1. Select {IN/OUT} under the main menu.
- 2. Select {RIN}.
  - The RIN window appears.

DATA	1	EDIT	DISPLAY	UTILITY	12 🗷 📶 🐋	🐻 🖳 (†
RIN#001 RIN#002 RIN#003 RIN#004	0000	DIRECT DIRECT DIRECT DIRECT	INT (SERVO) IN2 (SERVO) IN3 (SERVO) IN4 (SERVO)			_
RIN#005 RIN#006	000	DIRECT	IN5 (SERVO) IN5 (SERVO) IN6 (SERVO)			
Main Me	inu	Sinp	le Benu			

- 8 System Diagnosis
- 8.3 Input/Output Status

### 8.3.6 Signal Number Search

A search can be made for a signal number of a universal input, universal output, system input, and system output.

	DATA	EDIT	DISPLAY	UTILITY	12 🗹 🖬 😣 🔟 🖳 👆	Þ
Signal num <u>ber</u>	UNIVERSAL CROUP IN#0001 IN#0003 IN#0003 IN#0003 IN#0007 IN#0008	INFUT 190010 400010 400012 400013 400013 400014 400015 400017 400017		00:HEX.		
					PAGE	
	Main Menu	1 Simple	Nenu			

A search for the signal number can be made in the following two ways.

- Direct search on the UNIVERSAL/SPECIFIED INPUT/OUTPUT window
- Search from the menu

- 8 System Diagnosis
- 8.3 Input/Output Status
- 8.3.6.1 Direct Search on the Universal/Specified Input/Output Window
  - 1. Move the cursor to a signal number in the UNIVERSAL/SPECIFIED INPUT/OUTPUT window, and press [SELECT].
    - Numeric values can now be entered.

DATA	EDIT	DISPLAY	UTILITY	122108000	Þ
UNIVERSAL GROUP IN#0002 IN#0003 IN#0004 IN#0006 IN#0006 IN#0008	INFOT IE#0010 #00010 #00012 #00012 #00013 #00014 #00015 #00016 #00017		00:HEX.		
		-		19£	

- 2. Enter the signal number to be searched.
  - Type the signal number in the number input line.
- 3. Press [ENTER] to start the search.
  - The page where the signal number exists appears.

DATA	EDIT	DISPLAY	UTILITY	12 🗷 📶 🤞	s 🐻 🖳 👆	Þ
UNIVERSAL GROUP	INPUT 1G#00	6 <u>0:DEC.</u>	00:HEX.			
IN#0042 IN#0043 IN#0044 IN#0044 IN#0045 IN#0046 IN#0047 IN#0048	#00080 #00061 #00062 #00063 #00064 #00065 #00086 #00067	0000000				
				PAGE		
Main Men	a Sie	In Menu				

- 8 System Diagnosis
- 8.3 Input/Output Status

#### 8.3.6.2 Search from the Menu

- 1. Select {EDIT} under the menu in the UNIVERSAL/SPECIFIED INPUT/ OUTPUT window.
  - The pull-down menu appears.

DATA	EDIT	DISPLA	IT II III	.1TY 12	2 🖌 😣 🔟	📑 (†)	Þ
UNIVERSAL GROUP	SEARCH SIC	NAL :D	EC. 00:H	EX.			
1N#0009 1N#0010	SEARCH REL	AY		-			
IN#0012 IN#0013	RENAME						
IN#0014 IN#0015 IN#0016	SELECT ALL	SIN C		_			
	SELECT ALL	PHY					
	10 Simulat SEARCH	ion					
					PAGE		
Main Menu	Sin	le Benu	Ju Tu	rn on serva	power		

2. Select {SEARCH SIGNAL NO.}.

- Numeric values can now be entered.

DATA	EDIT	DISPLAY	UTILITY	12 🗷 📶	∞@₽(	•
UNI VERSAL GROUP	INPUT IG#00	1 0:DEC.	00:HEX.			
1140002	#00010 #00011			_		
IN#0003 IN#0004 IN#0005	#00012 #00013			_		
1N#0006 1N#0007	#00015 #00016			_		
IN#0008	#00017					
_					_	_
		-		(P)C		
Main Menu	e Slée	in Menu				

3. Enter the signal number to be searched.

- Type the signal number in the number input line.

- 4. Press [ENTER] to start the search.
  - The page where the signal number exists appears.

- 8 System Diagnosis
- 8.3 Input/Output Status

### 8.3.7 Relay Number Search

A search can be made for a relay number of a universal input, universal output, system input, and system output.

DATA	EDIT	DISPLAY	UTILITY	12 🗷 📶 😣 🔟 寻 👆	Þ
UNI VERSAL GROUP	INPUT IG#001	0:DEC.	00:HEX.		
IN#0001 IN#0002 IN#0003 IN#0004 IN#0005 IN#0006 IN#0007 IN#0008	#00010 #00011 #00012 #00013 #00014 #00015 #00016 #00017	0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0			
				PAGE	
Main Men	1 Simple	a Nenu			

A search for the relay number can be made in the following two ways.

- Direct search on the UNIVERSAL/SPECIFIED INPUT/OUTPUT window
- Search from the menu

- 8 System Diagnosis
- 8.3 Input/Output Status
- 8.3.7.1 Direct Search on the Universal/Specified Input/Output Window
  - 1. Move the cursor to a relay number in the UNIVERSAL/SPECIFIED INPUT/OUTPUT window, and press [SELECT].
    - Numeric values can now be entered.

DATA	EDIT	DISPLAY	UTILITY	12 🗷 📶 😣 🐻 🖳 👘	Þ
UNIVERSAL GROUP	INPUT IG#001	0:DEC.	00:HEX.		
IN#0001 IN#0003 IN#0003 IN#0004 IN#0005 IN#0006 IN#0007 IN#0008	#00011 #00012 #00013 #00014 #00015 #00016 #00017	00000000			
				IPhée	
Main Menu	Slopt	r Menu			

- 2. Enter the relay number to be searched.
  - Type the relay number in the number input line.
- 3. Press [ENTER] to start the search.
  - The page where the relay number exists appears.

DATA	EDIT	DISPLAY	UTILITY	12 🗷 📶 🤘	a 🐻 🖳 👆	Þ
UNIVERSAL	INPUT IG#00	5 O:DEC.	00:HEX.			
IN#0033	#00050	0				
IN#0034	#00051					
IN#0035	#00052					
IN#0036	#00053					
1110037	800054					
10#0038	#00055					
11/1/0033	#00056					
1140040	BOOMAN L					
						_
				0405	1	
				PAGE	-	
Train and	T					
Main Men	a Slav	n Mona				

- 8 System Diagnosis
- 8.3 Input/Output Status
- 8.3.7.2 Search from the Menu
  - 1. Select {EDIT} under the menu in the UNIVERSAL/SPECIFIED INPUT/ OUTPUT window.
    - The pull-down menu appears.

	EDIT	DISPLAY	UTILITY	12 🖻 🖢	1 😪 🐻 🖳	۲	Þ
UNIVERSAL GROUP	SEARCH SIGNAL	:DEC.	00:HEX.				
1N#0033 1N#0034 1N#0035	SEARCH RELAY NO.	000		-			
1N#0036 1N#0037	RENAME	000	_				
1N#0039 1N#0040	SELECT ALL SIN	000	_	_			
	SELECT ALL PHY						
	10 Simulation SEARCH						

- 2. Select {SEARCH RELAY SIGNAL NO.}.
  - Numeric values can now be entered.

DATA	EDIT	DISPLAY	UTILITY	122108000	Þ
UNIVERSAL GROUP IN#0001 IN#0002 IN#0003 IN#0004 IN#0006 IN#0006 IN#0008	INPOT 16#00 #00012 #00013 #00014 #00015 #00016 #00017		00:HEX.		
Halo Hear		In Hera		Phile	

- 3. Enter the relay number to be searched.
  - Type the relay number in the number input line.
- 4. Press [ENTER] to start the search.
  - The page where the relay number exists appears.

- 8 System Diagnosis
- 8.3 Input/Output Status

#### 8.3.8 Modification of the Signal Name

The name of the universal input or output signal can be modified.



The name can be modified in the following two ways.

- Direct modification on the UNIVERSAL/SPECIFIED INPUT/OUTPUT window.
- Modification from the menu
- 8.3.8.1 Direct Modification on the Universal/Specified Input/Output Window
  - 1. Move the cursor to the signal name to be modified in the UNIVERSAL/ SPECIFIED INPUT/OUTPUT window, and press [SELECT].
    - The window for character input appears.
  - 2. Enter the signal name.
  - 3. Press [ENTER].
    - New signal name is registered.

DATA	EDIT	DISPLAY	UTILITY	12 🗷 📶 😣 🛍	Þ
UNIVERSAL GROUP	INPUT IG#001	O:DEC.	00:HEX.		
1N#0001 1N#0002 1N#0003 1N#0003 1N#0005 1N#0006 1N#0006 1N#0008	#00010 #00011 #00012 #00013 #00014 #00015 #00016 #00017	00000000	IEST		
				PAGE	
Main Menu	e Sierie	Wepe			

- 8 System Diagnosis
- 8.3 Input/Output Status
- 8.3.8.2 Modification from the Menu
  - 1. Move the cursor to the signal name to be modified in the UNIVERSAL/ SPECIFIED INPUT/OUTPUT window.
  - 2. Select {EDIT} under the menu.
    - The pull-down menu appears.

UNIVERSAL	SEARCH SIG	NAL	:DEC.	00:HEX.			
IN#0033 1N#0034	SEARCH REL	AY	000				
IN#0035 IN#0036 IN#0037	RENAME		00	-	-		
1N#0038 1N#0039	SELECT ALL	SIM	000		_		
TMHODHO	SELECT ALL	PHY	0.1				
	10 Simulat SEARCH	ion					
						PAGE	

- 3. Select {RENAME}.
  - The window for character input appears.
- 4. Enter the signal name.
- 5. Press [ENTER].
  - New signal name is registered.

DATA	EDIT	DISPLAY	UTILITY	12 🗷 📶 🕻	ه 🗐 📑 🍓	Þ
UNIVERSAL GROUP	INPUT IG#001	O:DEC.	00:HEX.			
IN#0001 IN#0002 IN#0003 IN#0004 IN#0005 IN#0006 IN#0006 IN#0007 IN#0008	#00010 #00011 #00012 #00013 #00014 #00015 #00016 #00017	000000000000000000000000000000000000000	IESI			
	and the second second	-				

- 8 System Diagnosis
- 8.4 System Monitoring Time Display

# 8.4 System Monitoring Time Display

# 8.4.1 System Monitoring Time Display Window

The status of system operation, e.g. power ON time, can be checked.

- 1. Select {SYSTEM INFO}.
- 2. Select {MONITORING TIME}.

- The SYS MONITORING TIME window appears.



### **1. CONTROL POWER TIME**

Displays the cumulative time that the main power supply has been ON.

#### 2. SERVO POWER TIME

Displays the cumulative time that the servo power supply has been ON.

#### 3. PLAYBACK TIME

Displays the cumulative time during which playback was executed.

# 4. MOVING TIME

Displays the cumulative time that the manipulator was in motion.

### 5. OPERATING TIME

Displays the cumulative time spent in operation.

- 8 System Diagnosis
- 8.4 System Monitoring Time Display

# 8.4.2 Individual Window of the System Monitoring Time Display

If the page key is pressed, or "PAGE" is selected to display the selection window for the system monitoring time display, the servo power time, playback time, moving time, and each-application operating time by each control group are individually displayed.

DATA	EOIT	DISPLAY	UTILITY	12 2 4	1 😪 🐻 🖳	<del>6</del> [	2
SERVO POWE	R TIME		2000/19/19	17:12 ~)			
DODOT?		1: 6'2	000/12/10	17,12)			
AUDUIZ		1: 6'2	7	17-10 - 0			
STATIONI		1: 6'2	2008/12/18 7	17:13 ~)			
	-	DIOD IN		08.1211		Res. E	
PLAVBACK T	EUT	DISPLAT	unum	1 U2 🖻 Z		<b>T</b> L	-
R0B0T1	1mc	10000	2008/12/18	17:13~)			
ROBOT2		0.0	2008/12/18	17:13 ~)			
STATIONI		0:0	2008/12/18	17:13 ~)			
		1 0:0 1	1				
		1	1				
DATA	EDIT	DISPLAY	UTILITY			( <del>1)</del>	
ROBOT1	Æ		2008/12/18	17:13~)	-		-
ROBOT2		0: 0'	0 2008/12/18	17:13 ~)			
STATIONI		0: 0'	0 2008/12/18	17:13 ~)			
		0:0'	Ū				
DATA	EDIT	DISPLAY	UTILITY	122	M 😣 🔟 🖳	( <del>)</del>	D
OPERATING	TIME		2002/12/12	17:12)			
ALLI		0: 0'	0	inita (%)			



The total time of each control group here is not always the same as the time in the SYS MONITORING TIME window because these windows show time as seen from the individual control group.

- 8 System Diagnosis
- 8.4 System Monitoring Time Display

#### 8.4.3 Clearing the System Monitoring Time Display

The moving time and operating time can be cleared and set back to 0 by following procedure. These operations can be performed in the SYS MONITORING TIME window, or in the individual windows.

- 1. Select the time to be cleared.
  - The confirmation dialog box appears.



- 2. Select "YES".
  - The cumulative time value at the cursor line is reset to 0, and a new time measurement begins.



- 8 System Diagnosis
- 8.5 Alarm History

# 8.5 Alarm History

### 8.5.1 Alarm History Window

The alarm history can be confirmed in the alarm history window. There are five types of alarm history windows: the "MAJOR ALARM" window, the "MINOR ALARM" window, the "USER ALARM (SYSTEM)" window, the "USER ALARM (USER)" window, and the "OFF-LINE ALARM" window. Each window shows the alarm code and the date and time.

- 1. Select {SYSTEM INFO} under the main menu.
- 2. Select {ALARM HISTORY}.
  - The alarm history window appears.

DATA	EDIT	DISPLAY	UTILITY	12 🗷 📶 🛛	Þ
MAJOR ALARI	DATE	CLOCK			
001 1105	2011/06/11	13:22			
002 1105	2011/06/11	13121			
003 1105	2011/06/11	13:20			
004 1105	2011/06/11	13:18			
005 1105	2011/06/11	13:15			
007 1105	2011/06/11	13:14			
SYSTEM ERR	OR(SERVO)				
1.1000	[5151]			0001 0.0000	
J: YOUN	KISI		L	:0001 5:0000	
				PAGE	
Main Menu	Simple	Benu.			

- 3. Press the page key is to change the window, or select "PAGE" to display the selection window for the alarm windows.
  - Each time the page key is pressed, the window changes
     "MAJOR ALARM"→"MINOR ALARM"→"USER
     ALARM(SYSTEM)"→"USER ALARM(USER)"→"OFF-LINE
     ALARM".

DATA	4	EDIT	DISPLAY	UTILITY	12 🗷 📶 🏟 🔟 寻 👌	Þ
MAJOR	ALAR	DATE	CLOCK			
001	1105	2011/06/1	1 13:22			
002	1105	2011/06/1	1 13:21			
003	1105	2011/06/1	1 13:20			
004	1105	2011/06/1	1 13:18			
005	1105	2011/06/1	1 13:17			
006	1105	2011/06/1	1 13:15			
007	1105	2011/06/1	1 13:14			
SYSTE	em err J: Voon	0R(SERVO) [5151] R1S1			AJOR ALARM INOR ALARM SER ALARM(SYSTEM) SER ALARM(USER) FF-LINE ALARM	
	_		_		Prez.	
Ha)r	900a	Simple	Benu			

- 8 System Diagnosis
- 8.5 Alarm History

#### 8.5.2 Clearing the Alarm History

The history of the minor alarms and the user alarms (system and user) can be cleared.

- 1. Display the alarm history window to be cleared.
- 2. Select {DATA} under the menu.
  - The pull-down menu "CLEAR HISTORY" appears.

DATA	EDIT	DISPLAY	UTILITY	12 🗹 📶 🚳 🐻 🖳 👆	Þ
CLEAR HISTORY	DATE	CLOCK			
001 7011	11/06/14	13:29			
002 4311	2011/06/14	13:25			
003 4511	2011/06/14	12:55			
004 4328	2011/06/14	12:54			
005 4511	2011/06/14	12:53			
006 4311	2011/06/14	12:53			
007 4511	2011/06/13	08:51			
008 4311	2011/06/13	08:50			
009 4311	2011/06/13	08:45			
010 4311	2011/06/11	21:58			
OUT OF RANG	E(DROP-VAL) [RIS1] RIS1	E)	ì	:0001 \$:0000	
				PAGE	
Main Menu	Simple	Benu	-		

- 3. Select {CLEAR HISTORY}.
  - The confirmation dialog box appears.

DATA	EDIT	DISPLAY	UTILITY	12 🗷 📶 6	100	Þ
MINOR ALARS	DATE	ei nev				
001 4311	2011/06/1	4 13:29				
002 4311	2011/06/1	4 13:25				
003 4511	2011/06/1	4 12:55				
005 4611	2011/06/1	4 12:54			_	
005 4311			Initial	ize?		
007 4511						
008 4311						
009 4311		1 Inte	1			
010 4311		YES		NU		
OUT OF RAN	[ <mark>RI</mark> SI] RISI	LULY	ì	:0001 S:0000		
				€r€		
Maln Menu	Simpl	e Benu				

- 4. Select "YES".
  - The alarm history displayed is reset.

- 8 System Diagnosis
- 8.6 I/O Message History

# 8.6 I/O Message History

#### 8.6.1 I/O Message History Window

The I/O message history can be confirmed in the I/O MESSAGE HISTORY window.

The I/O MESSAGE HISTORY window shows the date and time, job name, line number, and step number of the I/O message that appeared on the window.

- 1. Select {SYSTEM INFO} under the main menu.
- 2. Select {I/O MSG HISTORY}
  - The I/O MESSAGE HISTORY window appears.

DATA	EDIT	DISPLAY	UTILITY	12 🗹 🐱 🐻 🖳 👆
O MESSAC	E HISTORY			
0001 ME	SSAGE1			
0002 ME	SSAGE2			
0003 ME	SSAGE3			
0004				
0005				
0006				
0007				
0008				
0009				
0010				
0011				
0012				
0013				
TE/TIME	:2011/06/1	4 13:18		
TEST			L:00	03 S:0003
_		_	-	

Press [SELECT], and numeric values can now be entered. Input the history number, and press [ENTER]. The search for the input history number begins, and the I/O message that appeared on the window is displayed.

#### 8.6.1.1 Search

Use the following operation to search for the I/O message history.

- 1. Select {EDIT} under the menu.
- 2. Select {SEARCH}.
  - The character input line appears.
- 3. Enter the history No.
- 4. Press [ENTER].
  - The search for the input history number begins, and the I/O message is displayed.

- 8 System Diagnosis
- 8.6 I/O Message History

# 8.6.2 Clearing the I/O Message History

- Use the following operation to clear the I/O message history.
- 1. Select {DATA} under the menu.
- 2. Select {CLEAR HISTORY}.
  - The confirmation dialog box appears.

DATA	EDIT	DISPLAY	UTILITY	12 🗹 🖬 🚳 🛅 🗔 (	Ð
/O MESSA	GE HISTORY				
	ESSAGE1				
0002 M	ESSAGE3				
0004	2001020				
0005					
0006	24	-	Initial	1702	
0008			initiai	120:	
0009					
0010		T. Junio	-		
0011		YES		NO	
0013	-				
ATE/TIM	E:2011/08/	4 13:18			
: TEST		10110	L:00	03 S:0003	
_		-			_
	T	Г	-		-
Main Men	u Sim	ale Menu			

- 3. Select "YES".
  - The displayed I/O message history is cleared.

- 8 System Diagnosis
- 8.7 Position Data When Power is Turned ON/OFF

# 8.7 Position Data When Power is Turned ON/OFF

### 8.7.1 Power ON/OFF Position Window

The Power ON/OFF position window shows the position of the manipulator when the power was turned OFF the last time, the current position of the manipulator when power was later turned ON, and the amount of difference between the two positions.

When alarm 4107, "OUT OF RANGE (ABSO DATA)" occurs, the error value of the faulty axes can be verified in this window.

- 1. Select {ROBOT} under the main menu.
- 2. Select {POWER ON/OFF POS}.
  - The POWER ON/OFF POSITION window appears.



- 8 System Diagnosis
- 8.8 Current Position

# 8.8 Current Position

### 8.8.1 Current Position Window

- 1. Select {ROBOT} under the main menu.
- 2. Select {CURRENT POSITION} under the sub menu.
  - The CURRENT POSITION window appears.

DATA	EDIT	DISPLAY	UTILITY	12 🗷 🖬 ਖ਼	) 🐻 📑 🤚	Þ
CURRENT PO	PULSE		DÖ			
R1 :S	0					
R	0					
1 I	0					
			_		-	_
				PAGE		
Naln Sen	i Sing	le Benu				

- 3. Select the types of coordinates to be displayed.
  - The pull-down menu appears.

DATA	EDIT	DISPLAY	UTILITY	12 🗷 📶 😣	個日 🖣	D
CURRENT P COORDINAT	OSTITION E PULSE	TOOL : (	0			
PULSE	0					
USER	0					
L B	0					
		-		的图		
Nain Nen	u Simp	le Henu				

- 4. Select the desired coordinate system.
  - The type of coordinates being displayed is changed.

DATA	EDIT	DISPLAY	UTILITY	12 🗷 📶 😣	圖艮 🖣	Þ
CURRENT P	OSTITION TE BASE	TCCL:00				
R1 :X Y Z < R0BDT T FRONT UP FLTP	479.500 mm 0.000 mm 350.000 mm YPE > S< 180 R< 180 I< 180	Rx Ry Rz	180.0000 -90.0000 0.0000	deg. deg. deg.		
				PAGE	1	
Maln Mer	nu Simple	Henu.				
## 8 System Diagnosis

8.9 Servo Monitoring

## 8.9 Servo Monitoring

## 8.9.1 Servo Monitor Window

The servo monitor window shows the servo-related data of each axis.

Monitor Items	Description
FEEDBACK PULSE	Feedback position (actual position) of each axis "0" at the home position
ERROR PULSE	Difference between the command position and the feedback position of each axis
SPEED DEVIATION	Difference between the command speed and the feedback speed of each axis
SPEED INST	Speed reference of each axis
FEEDBACK SPEED	Feedback speed (actual speed) of each axis
TORQUE SPEC	Torque reference of each axis
MAX. TORQUE	Keeps the maximum value of the torque reference of each axis. "0" when the maximum torque is cleared or the control power supply is turned ON or OFF
ENCODER ROTATE SUM	Accumulated number of encoder rotation when the control power supply of each axis is turned ON
IN 1 TURN POSITION	Position after one rotation of the encoder when the control power supply of each axis is turned ON
MOTOR ABSOLUTE	Absolute value of the motor is calculated by adding the position in one rotation to the sum of the accumulated rotations when the control power supply of each axis is turned ON.
ENCODER TEMPERATURE	Encoder temperature of each axis

- 8 System Diagnosis
- 8.9 Servo Monitoring

## 8.9.1.1 Changing the Monitor Items

- 1. Set the security mode to the management mode.
- 2. Select {ROBOT} under the main menu.
- 3. Select {SERVO MONITOR}.
  - The SERVO MONITOR window appears.

DATA	EDIT	DISPLAY UTILITY	12 🗹 🖬 🚳 🛅 📑 👘
servo mo	NETOR FEELBACK PULSE	TOROLE SPEC	
R1 :S	300	.0	
L	-632	0	
U	596	0	
R	676	0	
8	716	0	
T	697	0	
\$1 :1	-31984	0	
2	0	Ð	

- 4. Select {DISPLAY} under the menu.
  - The pull-down menu appears.
     MONITOR ITEM 1 is the data on the left, and MONITOR ITEM 2 is the data on the right

DATA	EDIT	DISPLAY	TILITY	12 🗹 🖬 🚳 🛅 📑 👘
SERVO MONI	TUR DONE PLL SE	MONITOR ITEM	SPEC	
R1 :S	NUCCE POLICE		0	
U	1.1	NONLIGH TIENS	0	
R		0	0	
I	6	0	0	
\$1 :1		D	0	
2		0	.0.	

- 8 System Diagnosis
- 8.9 Servo Monitoring
- 5. Select MONITOR ITEM 1 or 2, and view the sub-menu choices by the cursor key.
  - The sub-menu choices appear.

DATA	EDIT	DISPLAY	UTD	LITY	12 2	1 😒 🔟 🕞 👘
SERVO MONI T	tór Orque spec	FEEDRACK PU	SE	ENCOD	ER BOTATE	
KI :S U	RI :S L U R B	ERROR PULSE		IN I POSIT	TURN LUN	
R B		SPEED DEVIATION		HOTOR	ABSOLUTE	
\$1 :1 2		SPEED INST		ENCOD	ER TEMP.	
2	FEEDBACK SPE	EED				
		TORQUE SPEC				
		NAX TORQUE				

- 6. Select a menu.
  - The type of monitor-related information is changed.

DATA	EDIT	DISPLAY UTILITY	12 🗹 📶 🚳 🐻 寻 👆
servo m	ONLITOR SPEED INST	TOROLE SPEC	
R1 :S	-3	.0	
L	1	0	
U	0	0	
R	0	0	
8	-3	0	
T	11	0	
S1 :1	-2	0	
2	2	0	

- 8 System Diagnosis
- 8.9 Servo Monitoring

## 8.9.1.2 Clearing Maximum Torque Data

The data for the maximum torque can be cleared when the maximum torque-related information is being displayed.

- 1. Select {DATA} under the menu.
  - The clear max torque window appears

DATA	EDIT	DISPLAY	UTILITY	12 🗹 🖬 🚳 🛅 📑 👘
LEAR MAX	ROLE	π	ROLE SPEC	
11-10	1		.0	
L	179		0	
U	2		0	
R	12		0	
8	2		0	
T	2		0	
\$1 :1	0		0	
2	0		Ð	

- 2. Select {MAX. TORQUE}.
  - The maximum torque data is cleared.

DATA	EDIT	DISPLAY	UTILITY	12 🗷 📶 🚳 🐻 🖳 👆
SERVO MO	NETOR MAX TORCUE	π	ROLE SPEC	
R1 :S	).	)	.0	
L	(	)	0	
U	(	)	0	
R	(	)	0	
8	ſ	3	.0	
T	Ĩ	1	0	
\$1 :1	i i	1	0	
2	i	<u>.</u>	0	

- 9 Alarm
- 9.1 Outline of Alarm

# 9 Alarm

## 9.1 Outline of Alarm

When an alarm of level 0 to 3 (major alarm) occurs, the servo power supply is turned OFF.

Alarm Code	Alarm Level	Alarm Reset Method
0000	Level 0 (Major alarm) (Off line alarm: Initial diagnosis/ Hardware diagnosis alarm)	It is not possible to reset by "RESET" under the ALARM win- dow or the system input signal (Alarm reset). Turn OFF the main power supply and correct the cause of the alarm. Then turn ON the main power supply again.
1000 to 3000	Level 1 to 3 (Major alarm)	It is not possible to reset by "RESET" under the ALARM win- dow or the system input signal (Alarm reset). Turn OFF the main power supply and correct the cause of the alarm. Then turn ON the main power supply again.
4000 to 8000	Level 4 to 8 (Minor alarm)	After correcting the cause, it is possible to reset by "RESET" under the ALARM window or the system input signal (Alarm reset).
9000	Level 9 (Minor alarm) (I/O alarm)	After correcting the cause for which the system input signal for the system or user alarm request turns ON, it is possible to reset by "RESET" under the ALARM win- dow or the system input signal (Alarm reset).

#### 9 Alarm

9.2 Alarm Display

## 9.2 Alarm Display

#### 9.2.1 Displaying and Releasing Alarm

If an alarm occurs during operation, the manipulator stops immediately and the ALARM window appears on the programming pendant indicating that the machine was stopped by an alarm.



If more than one alarm occurs simultaneously, all the alarms are displayed.

Scroll the viewing area with the cursor to view the alarm that is not currently displayed on the viewing area.

The following operations are available in the alarm status: window change, mode change, alarm reset, and emergency stop. If the window is changed to another window during alarm occurrence, the ALARM window can be shown again by selecting {SYSTEM INFO} under the main menu and then selecting {ALARM}.

#### 9.2.1.1 Releasing Alarms

Alarms are classified by minor and major alarms.

Minor Alarms

Select "RESET" on the ALARM window to release alarms. Or, turn ON the system signal "ALARM RESET" when using an external input signal (system input).

Major Alarms

If a severe alarm such as hardware failure occurs, servo power is automatically shut OFF and the manipulator stops. Turn OFF the main power supply, remove the cause of the alarm, and then turn ON the power supply again.

- 9 Alarm
- 9.2 Alarm Display

9.2.2	Special	Alarm	Display
-------	---------	-------	---------

(1) Sub Data

Sub data such as data for the axis where the alarm occurred, may also be displayed for some alarms.

- Decimal data Without signs: 0 to 65535 With signs: -32768 to 32767
- Binary data The alarm occurrence data becomes "1". With 8 bits: 0000\_0001 With 16 bits: 00000001\_00000001
- Axis data The axis where the alarm occurred is highlighted. With robot axis: Robots 1 [SUURBT] With base axis: Base 1 [12]
  With station axis: Stations 1 to 3 [123]
- XYZ coordinate data The coordinates where the alarm occurred are highlighted.
   X Y Z IX Ty Tz ]
- 123 data The data for which the alarm occurred is highlighted.
   [123]
- Control group data The control group where the alarm occurred is highlighted.

[R1 R2 S1 S2 S3 ]

(2) Independent Control Function (Optional)

In the independent control function (multi-task job), the tasks that were being done when the alarm occurred are also displayed.

TASK#0: Master-task job

- TASK#1: Sub-task1 job (SUB1)
- TASK#2: Sub-task2 job (SUB2)
- TASK#3: Sub-task3 job (SUB3)
- TASK#4: Sub-task4 job (SUB4)
- TASK#5: Sub-task5 job (SUB5)

- 9 Alarm
- 9.3 Display of Alarm Details

## 9.3 Display of Alarm Details

Alarm details displaying function indicates the alarm contents breakdown on the alarm window.

Press [Select] after moving the cursor to the subject alarm on the alarm window to display its "content", "cause" and "measure".

Skip displaying the alarm window to directly display this breakdown window is possible by specifying the parameter when an alarm occurs.

### 9.3.1 Parameter

S2C406 Alarm Details Direct Display 0: Invalid / 1: Valid

### 9.3.2 Display of Alarm Detail Window

	Page			
Alarm No.	1	Alarm explanation		
DATA E ALARM DETAIL: ALARM 4328 SERVO TRACKI ROBOTI [SL ALARM CONTENT The axis devia	DIT O DISPLAY UTI 1/3 NG ERROR URBT] ated from the specifie	d position and motion pa	3 O (*) D	Alarm title Same as alarm window data. (Ordinary window) Alarm content
allowable rans Sub Code: Sign CAUSE	se. hifies the axis in whi	ch the alarm occurred		{Right/Left} button
Interference e	error		•	Cause
MEASURE Remove the int	terference of robot.			● ● Measure
	RETURN	RESET	PAGE	
Main Menu	Simple Menu			
	{Return} buttor	n {Retset} button	{Page} butte	on

#### Page

Displays

the page number of the alarm whose detail window is currently displayed / the total alarm number occurred coincidentally.

Alarm No.

Displays the alarm number with decimal 4 digit.

Sub data

Displays the subcode number defined to each alarm.

#### Alarm content

Displays the content of the alarm.

- 9 Alarm
- Display of Alarm Details 9.3

**{Right/Left} button** This button appears when there can be several "cause"s and "measure"s to one alarm. Press this to right/left ward to alternate the "cause" and the "measure".

Cause Displays the cause of an alarm.

#### Measure

Displays the recovery method from the alarming state.

#### {Reset}button

Press this button to reset the alarm.

#### {Page} button

Press this button to display the page number inputting area.

This area appears when several alarms occur at a time.

- 9 Alarm
- 9.3 Display of Alarm Details

### 9.3.3 Transition of Alarm Detail Window



- 9 Alarm
- 9.4 Alarm Message List

## 9.4 Alarm Message List



Alarm	Alarm Name	Sub	Meaning	Cause	Remedy	
Number		Code				
20	CPU COMMUNICATION ERROR	1	No response was sent from the Main CPU board when the control power turned ON.	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
				Main CPU board failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the Main CPU board. Save the CMOS.BIN before replace the board to be safe. Replace the Main CPU board, and then Please execute the update. And, please load CMOS.BIN.</li> </ul>	
		50	No response was sent from the servo board #1 when the control power turned ON. At this time, the FS100L may judge it as signal input such as external hold wrong. However, it is caused by the communication error with Servo control circuit board #1. Therefore, execute the following measures first of all.	Setting error	(1)Check the following settings. • Control group settings in maintenance mode • The EAXA board rotary switch setting (0) of the corresponding node number (SV#1)	9. Alarm 9.4 Alarm Messa
				Connection failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, check the connection and insertion of the following cables and connectors.</li> <li>The cable of EAXA board connector CN515,CN509</li> <li>The cable of CPU-201R board connector CN1/2</li> <li>The cable of YPS unit CN155</li> </ul>	ae List
				Servo control circuit board failure	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, replace the EAXA board. Save the CMOS.BIN before replace the board to be safe.	
				Main CPU board failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the Main CPU board. Save the CMOS.BIN before replace the board to be safe. Replace the Main CPU board, and then Please execute the update. And, please load CMOS.BIN.</li> </ul>	
21	COMMUNICATION ERROR (SERVO)	50	The communications CPU for the Servo control circuit board #1 detected an error when the control power turned ON.	Setting error	<ul> <li>(1)Check the following settings.</li> <li>Control group settings in maintenance mode</li> <li>The EAXA board rotary switch setting (0) of the corresponding node number (SV#1)</li> </ul>	
				Connection failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, check the connection and insertion of the following cables and connectors.</li> <li>The cable of EAXA board connector CN515,CN509</li> <li>The cable of CPU-201R board connector CN1/2</li> <li>The cable of YPS unit CN155</li> </ul>	

Alarm Number	Alarm Name	Sub Code	Meaning	Cause	Remedy
				Servo control circuit board failure	<ul><li>(1)Turn the power OFF then back ON.</li><li>(2)If the alarm occurs again, replace the EAXA board. Save the CMOS.BIN before replace the board to be safe.</li></ul>
				Main CPU board failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the Main CPU board. Save the CMOS.BIN before replace the board to be safe. Replace the Main CPU board, and then Please execute the update. And, please load CMOS.BIN.</li> </ul>
30	ROM ERROR	1	The CPU-201R system program is damaged.	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		50	The system program of Servo control circuit board #1 is damaged.	Software operation error occurred	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).
				Servo control circuit board failure	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, replace the EAXA board. Save the CMOS.BIN before replace the board to be safe.
60	COMMUNICATION ERROR (I/O MODULE)	0	The IO module board connected with 0th serial bus exists.	Software operation error occurred	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).
				Main CPU board failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the Main CPU board. Save the CMOS.BIN before replace the board to be safe. Replace the Main CPU board, and then Please execute the update. And, please load CMOS.BIN.</li> </ul>
		1	An error was detected in communications with the I/O module board connected with 1st serial bus when the control power turned ON.	Setting error	<ul> <li>(1)Check the following settings.</li> <li>The switch setting which specifies slot numbers of each I/O module</li> <li>I/O module settings in maintenance mode</li> </ul>
				Connection failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, check the connection and insertion of the following cables and connectors.</li> <li>The M II communications cable which I/O module of the corresponding node number</li> <li>(In case of M II communications last station) Terminator</li> <li>24V power of the corresponding I/O module</li> </ul>
				Board failure (I/O module)	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the following board. Save the CMOS.BIN before replace the board to be safe.</li> <li>Corresponding I/O module</li> </ul>

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy
Number		Code			
				Main CPU board failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the Main CPU board. Save the CMOS.BIN before replace the board to be safe. Replace the Main CPU board, and then Please execute the update. And, please load CMOS.BIN.</li> </ul>
		2	An error was detected in communications with the I/O module board connected with 2nd serial bus when the control power turned ON.	Setting error	<ul> <li>(1)Check the following settings.</li> <li>The switch setting which specifies slot numbers of each I/O module</li> <li>I/O module settings in maintenance mode</li> </ul>
				Connection failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, check the connection and insertion of the following cables and connectors.</li> <li>The M II communications cable which I/O module of the corresponding node number</li> <li>(In case of M II communications last station) Terminator</li> <li>24V power of the corresponding I/O module</li> </ul>
				Board failure (I/O module)	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the following board. Save the CMOS.BIN before replace the board to be safe.</li> <li>Corresponding I/O module</li> </ul>
				Main CPU board failure	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, replace the Main CPU board. Save the CMOS.BIN before replace the board to be safe. Replace the Main CPU board, and then Please execute the update. And, please load CMOS.BIN.
		3	An error was detected in communications with the I/O module board connected with 3rd serial bus when the control power turned ON.	Setting error	<ul> <li>(1)Check the following settings.</li> <li>The switch setting which specifies slot numbers of each I/O module</li> <li>I/O module settings in maintenance mode</li> </ul>
				Connection failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, check the connecting or inserting state of the following cables or connectors.</li> <li>The M II communications cable which I/O module of the corresponding node number</li> <li>(In case of M II communications last station) Terminator</li> <li>24V power of the corresponding I/O module</li> </ul>
				Board failure (I/O module)	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the following board. Save the CMOS.BIN before replace the board to be safe.</li> <li>Corresponding I/O module</li> </ul>

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy	
Number		Code				
				Main CPU board failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the Main CPU board. Save the CMOS.BIN before replace the board to be safe. Replace the Main CPU board, and then Please execute the update. And, please load CMOS.BIN.</li> </ul>	
		4	An error was detected in communications with the I/O module board connected with 4th serial bus when the control power turned ON.	Setting error	<ul> <li>(1)Check the following settings.</li> <li>The switch setting which specifies slot numbers of each I/O module</li> <li>I/O module settings in maintenance mode</li> </ul>	
				Connection failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, check the connecting or inserting state of the following cables or connectors.</li> <li>The M II communications cable which I/O module of the corresponding node number</li> <li>(In case of M II communications last station) Terminator</li> <li>24V power of the corresponding I/O module</li> </ul>	9. Alarm 9.4 Alarm
				Board failure (I/O module)	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the following board. Save the CMOS.BIN before replace the board to be safe.</li> <li>Corresponding I/O module</li> </ul>	Message
				Main CPU board failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the Main CPU board. Save the CMOS.BIN before replace the board to be safe. Replace the Main CPU board, and then Please execute the update. And, please load CMOS.BIN.</li> </ul>	List
		5	An error was detected in communications with the I/O module board connected with 5th serial bus when the control power turned ON.	Setting error	<ul> <li>(1)Check the following settings.</li> <li>The switch setting which specifies slot numbers of each I/O module</li> <li>I/O module settings in maintenance mode</li> </ul>	
				Connection failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, check the connecting or inserting state of the following cables or connectors.</li> <li>The M II communications cable which I/O module of the corresponding node number</li> <li>(In case of M II communications last station) Terminator</li> <li>24V power of the corresponding I/O module</li> </ul>	
				Board failure (I/O module)	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the following board. Save the CMOS.BIN before replace the board to be safe.</li> <li>Corresponding I/O module</li> </ul>	

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy	
Number		Code				
				Main CPU board failure	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, replace the Main CPU board. Save the CMOS.BIN before replace the board to be safe. Replace the Main CPU board, and then Please execute the update. And, please load CMOS.BIN.	
		6	An error was detected in communications with the I/O module board connected with 6th serial bus when the control power turned ON.	Setting error	<ul> <li>(1)Check the following settings.</li> <li>The switch setting which specifies slot numbers of each I/O module</li> <li>I/O module settings in maintenance mode</li> </ul>	
				Connection failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, check the connecting or inserting state of the following cables or connectors.</li> <li>The M II communications cable which I/O module of the corresponding node number</li> <li>(In case of M II communications last station) Terminator</li> <li>24V power of the corresponding I/O module</li> </ul>	9. Alarm 9.4 Alarm
				Board failure (I/O module)	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the following board. Save the CMOS.BIN before replace the board to be safe.</li> <li>Corresponding I/O module</li> </ul>	Message
				Main CPU board failure	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, replace the Main CPU board. Save the CMOS.BIN before replace the board to be safe. Replace the Main CPU board, and then Please execute the update. And, please load CMOS.BIN.	List
		7	An error was detected in communications with the I/O module board connected with 7th serial bus when the control power turned ON.	Setting error	<ul> <li>(1)Check the following settings.</li> <li>The switch setting which specifies slot numbers of each I/O module</li> <li>I/O module settings in maintenance mode</li> </ul>	
				Connection failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, check the connecting or inserting state of the following cables or connectors.</li> <li>The M II communications cable which I/O module of the corresponding node number</li> <li>(In case of M II communications last station) Terminator</li> <li>24V power of the corresponding I/O module</li> </ul>	
				Board failure (I/O module)	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the following board. Save the CMOS.BIN before replace the board to be safe.</li> <li>Corresponding I/O module</li> </ul>	

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy
Number		Code			
				Main CPU board failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the Main CPU board. Save the CMOS.BIN before replace the board to be safe. Replace the Main CPU board, and then Please execute the update. And, please load CMOS.BIN.</li> </ul>
		8	An error was detected in communications with the I/O module board connected with 8th serial bus when the control power turned ON.	Setting error	<ul> <li>(1)Check the following settings.</li> <li>The switch setting which specifies slot numbers of each I/O module</li> <li>I/O module settings in maintenance mode</li> </ul>
				Connection failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, check the connecting or inserting state of the following cables or connectors.</li> <li>The M II communications cable which I/O module of the corresponding node number</li> <li>(In case of M II communications last station) Terminator</li> <li>24V power of the corresponding I/O module</li> </ul>
				Board failure (I/O module)	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the following board. Save the CMOS.BIN before replace the board to be safe.</li> <li>Corresponding I/O module</li> </ul>
				Main CPU board failure	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, replace the Main CPU board. Save the CMOS.BIN before replace the board to be safe. Replace the Main CPU board, and then Please execute the update. And, please load CMOS.BIN.
100	COMMUNICATION ERROR (servo#1)	1	The error was detected during the check of the serial communication watchdog data. Counter value received from Servo control circuit board is invalid.	Setting error	<ul> <li>(1)Check the following settings.</li> <li>Control group settings in maintenance mode</li> <li>The EAXA board rotary switch setting (0) of the corresponding node number (SV#1)</li> </ul>
				Connection failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, check the connection and insertion of the following cables and connectors.</li> <li>The cable of EAXA board connector CN515</li> <li>The cable of CPU-201R board connector CN1/2</li> </ul>
				Servo control circuit board failure	<ul><li>(1)Turn the power OFF then back ON.</li><li>(2)If the alarm occurs again, replace the EAXA board. Save the CMOS.BIN before replace the board to be safe.</li></ul>
				Main CPU board failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the Main CPU board. Save the CMOS.BIN before replace the board to be safe. Replace the Main CPU board, and then Please execute the update. And, please load CMOS.BIN.</li> </ul>

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy
Number		Code			
		2	The error was detected during the check of the number of the serial communications. Counter value received from Servo control circuit board is off by one cycle.	Setting error	<ul> <li>(1)Check the following settings.</li> <li>Control group settings in maintenance mode</li> <li>The EAXA board rotary switch setting (0) of the corresponding node number (SV#1)</li> </ul>
				Connection failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, check the connection and insertion of the following cables and connectors.</li> <li>The cable of EAXA board connector CN515</li> <li>The cable of CPU-201R board connector CN1/2</li> </ul>
				Servo control circuit board failure	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, replace the EAXA board. Save the CMOS.BIN before replace the board to be safe.
				Main CPU board failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the Main CPU board. Save the CMOS.BIN before replace the board to be safe. Replace the Main CPU board, and then Please execute the update. And, please load CMOS.BIN.</li> </ul>
200	MEMORY ERROR (PARAMETER FILE)	0	The RC parameter is damaged.	Data error	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, initialize the appropriate data in maintenance mode, and then load the data saved in the external memory device.</li> </ul>
				Main CPU board failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the Main CPU board. Save the CMOS.BIN before replace the board to be safe. Replace the Main CPU board, and then Please execute the update. And, please load CMOS.BIN.</li> </ul>
		1	The RO parameter is damaged.	Data error	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, initialize the appropriate data in maintenance mode, and then load the data saved in the external memory device.</li> </ul>
				Main CPU board failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the Main CPU board. Save the CMOS.BIN before replace the board to be safe. Replace the Main CPU board, and then Please execute the update. And, please load CMOS.BIN.</li> </ul>
		2	The SV parameter is damaged.	Data error	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, initialize the appropriate data in maintenance mode, and then load the data saved in the external memory device.</li> </ul>
				Main CPU board failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the Main CPU board. Save the CMOS.BIN before replace the board to be safe. Replace the Main CPU board, and then Please execute the update. And, please load CMOS.BIN.</li> </ul>
		3	The SVM parameter is damaged.	Data error	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, initialize the appropriate data in maintenance mode, and then load the data saved in the external memory device.</li> </ul>

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy	
Number		Code				
				Main CPU board failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the Main CPU board. Save the CMOS.BIN before replace the board to be safe. Replace the Main CPU board, and then Please execute the update. And, please load CMOS.BIN.</li> </ul>	
		4	The SC parameter is damaged.	Data error	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, initialize the appropriate data in maintenance mode, and then load the data saved in the external memory device.</li> </ul>	
				Main CPU board failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the Main CPU board. Save the CMOS.BIN before replace the board to be safe. Replace the Main CPU board, and then Please execute the update. And, please load CMOS.BIN.</li> </ul>	ю ч
		5	The SD parameter is damaged.	Data error	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, initialize the appropriate data in maintenance mode, and then load the data saved in the external memory device.</li> </ul>	4 <u>2</u> 2
				Main CPU board failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the Main CPU board. Save the CMOS.BIN before replace the board to be safe. Replace the Main CPU board, and then Please execute the update. And, please load CMOS.BIN.</li> </ul>	arm Mes:
		6	The CIO parameter is damaged.	Data error	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, initialize the appropriate data in maintenance mode, and then load the data saved in the external memory device.	sane L
				Main CPU board failure	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, replace the Main CPU board. Save the CMOS.BIN before replace the board to be safe. Replace the Main CPU board, and then Please execute the update. And, please load CMOS.BIN.	<u>N</u>
		7	The FD parameter is damaged.	Data error	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, initialize the appropriate data in maintenance mode, and then load the data saved in the external memory device.</li> </ul>	
				Main CPU board failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the Main CPU board. Save the CMOS.BIN before replace the board to be safe. Replace the Main CPU board, and then Please execute the update. And, please load CMOS.BIN.</li> </ul>	
		8	The AP parameter is damaged.	Data error	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, initialize the appropriate data in maintenance mode, and then load the data saved in the external memory device.</li> </ul>	
				Main CPU board failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the Main CPU board. Save the CMOS.BIN before replace the board to be safe. Replace the Main CPU board, and then Please execute the update. And, please load CMOS.BIN.</li> </ul>	
		9	The RS parameter is damaged.	Data error	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, initialize the appropriate data in maintenance mode, and then load the data saved in the external memory device.</li> </ul>	

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy
Number		Code			
				Main CPU board failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the Main CPU board. Save the CMOS.BIN before replace the board to be safe. Replace the Main CPU board, and then Please execute the update. And, please load CMOS.BIN.</li> </ul>
		10	The SE parameter is damaged.	Data error	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, initialize the appropriate data in maintenance mode, and then load the data saved in the external memory device.</li> </ul>
				Main CPU board failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the Main CPU board. Save the CMOS.BIN before replace the board to be safe. Replace the Main CPU board, and then Please execute the update. And, please load CMOS.BIN.</li> </ul>
		11	The SVC parameter is damaged.	Data error	<ul><li>(1)Turn the power OFF then back ON.</li><li>(2)If the alarm occurs again, initialize the appropriate data in maintenance mode, and then load the data saved in the external memory device.</li></ul>
				Main CPU board failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the Main CPU board. Save the CMOS.BIN before replace the board to be safe. Replace the Main CPU board, and then Please execute the update. And, please load CMOS.BIN.</li> </ul>
		12	The AMC parameter is damaged.	Data error	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, initialize the appropriate data in maintenance mode, and then load the data saved in the external memory device.</li> </ul>
				Main CPU board failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the Main CPU board. Save the CMOS.BIN before replace the board to be safe. Replace the Main CPU board, and then Please execute the update. And, please load CMOS.BIN.</li> </ul>
		13	The SVP parameter is damaged.	Data error	<ul><li>(1)Turn the power OFF then back ON.</li><li>(2)If the alarm occurs again, initialize the appropriate data in maintenance mode, and then load the data saved in the external memory device.</li></ul>
				Main CPU board failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the Main CPU board. Save the CMOS.BIN before replace the board to be safe. Replace the Main CPU board, and then Please execute the update. And, please load CMOS.BIN.</li> </ul>
		14	The MF parameter is damaged.	Data error	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, initialize the appropriate data in maintenance mode, and then load the data saved in the external memory device.</li> </ul>
				Main CPU board failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the Main CPU board. Save the CMOS.BIN before replace the board to be safe. Replace the Main CPU board, and then Please execute the update. And, please load CMOS.BIN.</li> </ul>
		15	The SVS parameter is damaged.	Data error	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, initialize the appropriate data in maintenance mode, and then load the data saved in the external memory device.</li> </ul>

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy
Number		Code			
				Main CPU board failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the Main CPU board. Save the CMOS.BIN before replace the board to be safe. Replace the Main CPU board, and then Please execute the update. And, please load CMOS.BIN.</li> </ul>
210	MEMORY ERROR (SYSTEM CONFIG-DATA)		The system configuration information data are damaged.	Main CPU board failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the Main CPU board. Save the CMOS.BIN before replace the board to be safe. Replace the Main CPU board, and then Please execute the update. And, please load CMOS.BIN.</li> </ul>
220	MEMORY ERROR (JOB MNG DATA)	0	The management data of job files are damaged.	Data error	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, initialize the job file in maintenance mode, and then load the data (job, variable data, Robot calibration data) saved in the external memory device.
				Main CPU board failure	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, replace the Main CPU board. Save the CMOS.BIN before replace the board to be safe. Replace the Main CPU board, and then Please execute the update. And, please load CMOS.BIN.
		1	The job files are damaged.	Data error	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, initialize the job file in maintenance mode, and then load the data (job, variable data, Robot calibration data) saved in the external memory device.
				Main CPU board failure	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, replace the Main CPU board. Save the CMOS.BIN before replace the board to be safe. Replace the Main CPU board, and then Please execute the update. And, please load CMOS.BIN.
		2	The management data of position data files are damaged.	Data error	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, initialize the job file in maintenance mode, and then load the data (job, variable data, Robot calibration data) saved in the external memory device.</li> </ul>
				Main CPU board failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the Main CPU board. Save the CMOS.BIN before replace the board to be safe. Replace the Main CPU board, and then Please execute the update. And, please load CMOS.BIN.</li> </ul>
		3	Memory and play back file is damaged.	Data error	<ul><li>(1)Turn the power OFF then back ON.</li><li>(2)If the alarm occurs again, initialize the appropriate data in maintenance mode, and then load the data saved in the external memory device.</li></ul>
				Main CPU board failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the Main CPU board. Save the CMOS.BIN before replace the board to be safe. Replace the Main CPU board, and then Please execute the update. And, please load CMOS.BIN.</li> </ul>
230	MEMORY ERROR (LADDER PRG FILE)		The CIO ladder file is damaged.	Data error	<ul><li>(1)Turn the power OFF then back ON.</li><li>(2)If the alarm occurs again, initialize the appropriate data in maintenance mode, and then load the data saved in the external memory device.</li></ul>

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy
Number		Code			
				Main CPU board failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the Main CPU board. Save the CMOS.BIN before replace the board to be safe. Replace the Main CPU board, and then Please execute the update. And, please load CMOS.BIN.</li> </ul>
290	MEMORY ERROR (NETWORK SETUP)		The network setting file is damaged.	Data error	<ul><li>(1)Turn the power OFF then back ON.</li><li>(2)If the alarm occurs again, initialize the appropriate data in maintenance mode, and then set the network again.</li></ul>
				Main CPU board failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the Main CPU board. Save the CMOS.BIN before replace the board to be safe. Replace the Main CPU board, and then Please execute the update. And, please load CMOS.BIN.</li> </ul>
300	VERIFY ERROR (SYSTEM CONFIG-DATA)	2	CIO parameter error.	Setting error	<ul><li>(1)Check the following settings.</li><li>I/O module settings in maintenance mode</li></ul>
				Main CPU board failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the Main CPU board. Save the CMOS.BIN before replace the board to be safe. Replace the Main CPU board, and then Please execute the update. And, please load CMOS.BIN.</li> </ul>
		4	Axis-related parameter error.	Setting error	(1)Check the following settings.       Control group settings in maintenance mode       Control group settings in maintenance mode
				Main CPU board failure	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, replace the Main CPU board. Save the CMOS.BIN before replace the board to be safe. Replace the Main CPU board, and then Please execute the update. And, please load CMOS.BIN.
		5	Sensor-use parameter error.	Setting error	<ul><li>(1)Check the following settings.</li><li>The optional board setting in maintenance mode</li></ul>
				Main CPU board failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the Main CPU board. Save the CMOS.BIN before replace the board to be safe. Replace the Main CPU board, and then Please execute the update. And, please load CMOS.BIN.</li> </ul>
		7	The set optional functions are different from those of the mounted optional board.	Setting error	<ul><li>(1)Check the following settings.</li><li>The optional board setting in maintenance mode</li></ul>
				Main CPU board failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the Main CPU board. Save the CMOS.BIN before replace the board to be safe. Replace the Main CPU board, and then Please execute the update. And, please load CMOS.BIN.</li> </ul>
		8	IO type error (combination impossible to coexist).	Setting error	<ul><li>(1)Check the following settings.</li><li>I/O module settings in maintenance mode</li></ul>

<u>9</u>.

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy
Number		Code			
				Main CPU board failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the Main CPU board. Save the CMOS.BIN before replace the board to be safe. Replace the Main CPU board, and then Please execute the update. And, please load CMOS.BIN.</li> </ul>
301	VERIFY ERROR (OVERRUN INPUT SET)		subcode: Control group Parameter specification and OT signal information are wrong	Setting error	<ul><li>(1)Check the following settings.</li><li>Connection settings (OT) in maintenance mode</li></ul>
310	VERIFY ERROR (CMOS MEMORY)	0	The CMOS memory version is different from its initial setting.	Setting error	<ul><li>(1)Check the following settings.</li><li>Set the security mode to MANAGEMENT MODE.</li><li>Data rebuild in maintenance mode</li></ul>
				Main CPU board failure	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, replace the Main CPU board. Save the CMOS.BIN before replacing the board to be safe. After replacing the Main CPU board, upgrade the system with the version same as the collected board and load CMOS.BIN.
		1	The CRC data in CMOS memory and the CRC data calculated by the system software are inconsistent	Setting error	<ul><li>(1)Check the following settings.</li><li>Set the security mode to MANAGEMENT MODE.</li><li>Data rebuild in maintenance mode</li></ul>
				Main CPU board failure	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, replace the Main CPU board. Save the CMOS.BIN before replacing the board to be safe. After replacing the Main CPU board, upgrade the system with the version same as the collected board and load CMOS.BIN.
320	VERIFY ERROR (I/O MODULE)	1	The I/O module connected to the serial bus #1 is different from the function of the set I/O module.	Setting error	<ul> <li>(1)Check the following settings.</li> <li>The rotary switch setting which specifies slot numbers of each I/O module</li> <li>I/O module settings in maintenance mode</li> </ul>
				Connection failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, check the connecting or inserting state of the following cables or connectors.</li> <li>The M II communications cable which I/O module of the corresponding node number</li> <li>(In case of M II communications last station) Terminator</li> <li>24V power of the corresponding I/O module</li> </ul>
				Board failure (I/O module)	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the following board. Save the CMOS.BIN before replace the board to be safe.</li> <li>Corresponding IO module</li> </ul>
				Main CPU board failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the Main CPU board. Save the CMOS.BIN before replace the board to be safe. Replace the Main CPU board, and then Please execute the update. And, please load CMOS.BIN.</li> </ul>

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy
Number		Code			
		2	The I/O module connected to the serial bus #2 is different from the function of the set I/O module.	Setting error	<ul> <li>(1)Check the following settings.</li> <li>The rotary switch setting which specifies slot numbers of each I/O module</li> <li>I/O module settings in maintenance mode</li> </ul>
				Connection failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, check the connecting or inserting state of the following cables or connectors.</li> <li>The M II communications cable which I/O module of the corresponding node number</li> <li>(In case of M II communications last station) Terminator</li> <li>24V power of the corresponding I/O module</li> </ul>
				Board failure (I/O module)	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the following board. Save the CMOS.BIN before replace the board to be safe.</li> <li>Corresponding IO module</li> </ul>
				Main CPU board failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the Main CPU board. Save the CMOS.BIN before replace the board to be safe. Replace the Main CPU board, and then Please execute the update. And, please load CMOS.BIN.</li> </ul>
		3	The I/O module connected to the serial bus #3 is different from the function of the set I/O module.	Setting error	<ul> <li>(1)Check the following settings.</li> <li>The rotary switch setting which specifies slot numbers of each I/O module</li> <li>I/O module settings in maintenance mode</li> </ul>
				Connection failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, check the connecting or inserting state of the following cables or connectors.</li> <li>The M II communications cable which I/O module of the corresponding node number</li> <li>(In case of M II communications last station) Terminator</li> <li>24V power of the corresponding I/O module</li> </ul>
				Board failure (I/O module)	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the following board. Save the CMOS.BIN before replace the board to be safe.</li> <li>•Corresponding IO module</li> </ul>
				Main CPU board failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the Main CPU board. Save the CMOS.BIN before replace the board to be safe. Replace the Main CPU board, and then Please execute the update. And, please load CMOS.BIN.</li> </ul>
		4	The I/O module connected to the serial bus #4 is different from the function of the set I/O module.	Setting error	<ul> <li>(1)Check the following settings.</li> <li>The rotary switch setting which specifies slot numbers of each I/O module</li> <li>I/O module settings in maintenance mode</li> </ul>

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy
Number		Code			
				Connection failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, check the connecting or inserting state of the following cables or connectors.</li> <li>The M II communications cable which I/O module of the corresponding node number</li> <li>(In case of M II communications last station) Terminator</li> <li>24V power of the corresponding I/O module</li> </ul>
				Board failure (I/O module)	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the following board. Save the CMOS.BIN before replace the board to be safe.</li> <li>•Corresponding IO module</li> </ul>
				Main CPU board failure	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, replace the Main CPU board. Save the CMOS.BIN before replace the board to be safe. Replace the Main CPU board, and then Please execute the update. And, please load CMOS.BIN.
		5	The I/O module connected to the serial bus #5 is different from the function of the set I/O module.	Setting error	(1)Check the following settings.       ■         • The rotary switch setting which specifies slot numbers of each I/O module       ■         • I/O module settings in maintenance mode       ■
				Connection failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, check the connecting or inserting state of the following cables or connectors.</li> <li>The M II communications cable which I/O module of the corresponding node number</li> <li>(In case of M II communications last station) Terminator</li> <li>24V power of the corresponding I/O module</li> </ul>
				Board failure (I/O module)	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the following board. Save the CMOS.BIN before replace the board to be safe.</li> <li>•Corresponding IO module</li> </ul>
				Main CPU board failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the Main CPU board. Save the CMOS.BIN before replace the board to be safe. Replace the Main CPU board, and then Please execute the update. And, please load CMOS.BIN.</li> </ul>
		6	The I/O module connected to the serial bus #6 is different from the function of the set I/O module.	Setting error	<ul> <li>(1)Check the following settings.</li> <li>The rotary switch setting which specifies slot numbers of each I/O module</li> <li>I/O module settings in maintenance mode</li> </ul>

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy
Number		Code			
				Connection failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, check the connecting or inserting state of the following cables or connectors.</li> <li>The M II communications cable which I/O module of the corresponding node number</li> <li>(In case of M II communications last station) Terminator</li> <li>24V power of the corresponding I/O module</li> </ul>
				Board failure (I/O module)	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the following board. Save the CMOS.BIN before replace the board to be safe.</li> <li>Corresponding IO module</li> </ul>
				Main CPU board failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the Main CPU board. Save the CMOS.BIN before replace the board to be safe. Replace the Main CPU board, and then Please execute the update. And, please load CMOS.BIN.</li> </ul>
		7	The I/O module connected to the serial bus #7 is different from the function of the set I/O module.	Setting error	<ul> <li>(1)Check the following settings.</li> <li>The rotary switch setting which specifies slot numbers of each I/O module</li> <li>I/O module settings in maintenance mode</li> </ul>
				Connection failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, check the connecting or inserting state of the following cables or connectors.</li> <li>The M II communications cable which I/O module of the corresponding node number</li> <li>(In case of M II communications last station) Terminator</li> <li>24V power of the corresponding I/O module</li> </ul>
				Board failure (I/O module)	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the following board. Save the CMOS.BIN before replace the board to be safe.</li> <li>Corresponding IO module</li> </ul>
				Main CPU board failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the Main CPU board. Save the CMOS.BIN before replace the board to be safe. Replace the Main CPU board, and then Please execute the update. And, please load CMOS.BIN.</li> </ul>
		8	The I/O module connected to the serial bus #8 is different from the function of the set I/O module.	Setting error	<ul> <li>(1)Check the following settings.</li> <li>The rotary switch setting which specifies slot numbers of each I/O module</li> <li>I/O module settings in maintenance mode</li> </ul>

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy
Number		Code			
				Connection failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, check the connecting or inserting state of the following cables or connectors.</li> <li>The M II communications cable which I/O module of the corresponding node number</li> <li>(In case of M II communications last station) Terminator</li> <li>24V power of the corresponding I/O module</li> </ul>
				Board failure (I/O module)	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, replace the following board. Save the CMOS.BIN before replace the board to be safe. •Corresponding IO module
				Main CPU board failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the Main CPU board. Save the CMOS.BIN before replace the board to be safe. Replace the Main CPU board, and then Please execute the update. And, please load CMOS.BIN.</li> </ul>
330	VERIFY ERROR (APPLICATION)			Main CPU board failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the Main CPU board. Save the CMOS.BIN before replace the board to be safe. Replace the Main CPU board, and then Please execute the update. And, please load CMOS.BIN.</li> </ul>
390	VERIFY ERROR (SEGMENT CLOCK)		Illegal instruction cycle is set.	Setting error	(1)Reset the alarm, and then try again. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).
				Main CPU board failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the Main CPU board. Save the CMOS.BIN before replace the board to be safe. Replace the Main CPU board, and then Please execute the update. And, please load CMOS.BIN.</li> </ul>
400	PARAMETER TRANSMISSION ERROR	50	An error occurred during the parameter/file transfer to the 1st Servo control circuit board.	Setting error	<ul> <li>(1)Check the following settings.</li> <li>Control group settings in maintenance mode</li> <li>The Servo control circuit board rotary switch setting (0) of the corresponding node number (SV#1)</li> </ul>
				Connection failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, check the connection and insertion of the following cables and connectors.</li> <li>The cable of EAXA board connector CN515</li> <li>The cable of CPU-201R board connector CN1/2</li> </ul>
				Servo control circuit board failure	<ul><li>(1)Turn the power OFF then back ON.</li><li>(2)If the alarm occurs again, replace the EAXA board. Save the CMOS.BIN before replace the board to be safe.</li></ul>

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy
Number		Code			
				Main CPU board failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the Main CPU board. Save the CMOS.BIN before replace the board to be safe. Replace the Main CPU board, and then Please execute the update. And, please load CMOS.BIN.</li> </ul>
		51	An error occurred during the parameter/file transfer to the 2nd Servo control circuit board.	Setting error	<ul> <li>(1)Check the following settings.</li> <li>Control group settings in maintenance mode</li> <li>The Servo control circuit board rotary switch setting (1) of the corresponding node number (SV#2)</li> </ul>
				Connection failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, check the connection and insertion of the following cables and connectors.</li> <li>The cable of EAXA board connector CN515</li> <li>The cable of CPU-201R board connector CN1/2</li> </ul>
				Servo control circuit board failure	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, replace the EAXA board. Save the CMOS.BIN before replace the board to be safe.
				Main CPU board failure	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, replace the Main CPU board. Save the CMOS.BIN before replace the board to be safe. Replace the Main CPU board, and then Please execute the update. And, please load CMOS.BIN.
410	MODE CHANGE ERROR	50	An error occurred during startup sequence processing with the servo CPU of 1st Servo control circuit board, and the system did not startup normally.	Setting error	<ul> <li>(1)Check the following settings.</li> <li>Control group settings in maintenance mode</li> <li>The Servo control circuit board rotary switch setting (0) of the corresponding node number (SV#1)</li> </ul>
				Connection failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, check the connection and insertion of the following cables and connectors.</li> <li>The cable of EAXA board connector CN515</li> <li>The cable of CPU-201R board connector CN1/2</li> </ul>
				Servo control circuit board failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the EAXA board. Save the CMOS.BIN before replace the board to be safe.</li> </ul>
				Main CPU board failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the Main CPU board. Save the CMOS.BIN before replace the board to be safe. Replace the Main CPU board, and then Please execute the update. And, please load CMOS.BIN.</li> </ul>
500	SEGMENT PROC NOT READY			Setting error	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy
Number		Code			
				Main CPU board failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the Main CPU board. Save the CMOS.BIN before replace the board to be safe. Replace the Main CPU board, and then Please execute the update. And, please load CMOS.BIN.</li> </ul>
510	SOFTWARE VERSION UNMATCH	50	1st Servo control circuit board's interface version is not corresponding to Main CPU board	Main CPU board failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the Main CPU board. Save the CMOS.BIN before replace the board to be safe. Replace the Main CPU board, and then Please execute the update. And, please load CMOS.BIN.</li> </ul>
		51	2nd Servo control circuit board's interface version is not corresponding to Main CPU board	Main CPU board failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the Main CPU board. Save the CMOS.BIN before replace the board to be safe. Replace the Main CPU board, and then Please execute the update. And, please load CMOS.BIN.</li> </ul>
520	AXIS LIMIT OVER	0		Setting error	<ul><li>(1)Check the following settings.</li><li>Control group settings in maintenance mode</li></ul>
				Main CPU board failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the Main CPU board. Save the CMOS.BIN before replace the board to be safe. Replace the Main CPU board, and then Please execute the update. And, please load CMOS.BIN.</li> </ul>
710	LADDER INITIALIZE ERROR			Data error	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, initialize the appropriate data in maintenance mode, and then load the data saved in the external memory device.
				Main CPU board failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the Main CPU board. Save the CMOS.BIN before replace the board to be safe. Replace the Main CPU board, and then Please execute the update. And, please load CMOS.BIN.</li> </ul>
720	LADDER PROGRAM ERROR	1	An error was found in the relay No. specification.	Data error	<ul><li>(1)Turn the power OFF then back ON.</li><li>(2)If the alarm occurs again, initialize the appropriate data in maintenance mode, and then load the data saved in the external memory device.</li></ul>
				Main CPU board failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the Main CPU board. Save the CMOS.BIN before replace the board to be safe. Replace the Main CPU board, and then Please execute the update. And, please load CMOS.BIN.</li> </ul>
		2	An error was found in the register No. specification.	Data error	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, initialize the appropriate data in maintenance mode, and then load the data saved in the external memory device.</li> </ul>
				Main CPU board failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the Main CPU board. Save the CMOS.BIN before replace the board to be safe. Replace the Main CPU board, and then Please execute the update. And, please load CMOS.BIN.</li> </ul>
		3	An incorrect instruction was set.	Data error	<ul><li>(1)Turn the power OFF then back ON.</li><li>(2)If the alarm occurs again, initialize the appropriate data in maintenance mode, and then load the data saved in the external memory device.</li></ul>

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy	
Number		Code				
				Main CPU board failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the Main CPU board. Save the CMOS.BIN before replace the board to be safe. Replace the Main CPU board, and then Please execute the update. And, please load CMOS.BIN.</li> </ul>	
		4	Output register is used redundantly.	Data error	<ul><li>(1)Turn the power OFF then back ON.</li><li>(2)If the alarm occurs again, initialize the appropriate data in maintenance mode, and then load the data saved in the external memory device.</li></ul>	
				Main CPU board failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the Main CPU board. Save the CMOS.BIN before replace the board to be safe. Replace the Main CPU board, and then Please execute the update. And, please load CMOS.BIN.</li> </ul>	9.9
		5	Output relay is used redundantly.	Data error	<ul><li>(1)Turn the power OFF then back ON.</li><li>(2)If the alarm occurs again, initialize the appropriate data in maintenance mode, and then load the data saved in the external memory device.</li></ul>	4 2
				Main CPU board failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the Main CPU board. Save the CMOS.BIN before replace the board to be safe. Replace the Main CPU board, and then Please execute the update. And, please load CMOS.BIN.</li> </ul>	arm Mes
		6	Unconnected relay exists.	Data error	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, initialize the appropriate data in maintenance mode, and then load the data saved in the external memory device.</li> </ul>	sage Li
				Main CPU board failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the Main CPU board. Save the CMOS.BIN before replace the board to be safe. Replace the Main CPU board, and then Please execute the update. And, please load CMOS.BIN.</li> </ul>	st
		7	The STR instructions are overused.	Data error	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, initialize the appropriate data in maintenance mode, and then load the data saved in the external memory device.</li> </ul>	
				Main CPU board failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the Main CPU board. Save the CMOS.BIN before replace the board to be safe. Replace the Main CPU board, and then Please execute the update. And, please load CMOS.BIN.</li> </ul>	
		8	The AND-STR instructions are overused.	Data error	<ul><li>(1)Turn the power OFF then back ON.</li><li>(2)If the alarm occurs again, initialize the appropriate data in maintenance mode, and then load the data saved in the external memory device.</li></ul>	
				Main CPU board failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the Main CPU board. Save the CMOS.BIN before replace the board to be safe. Replace the Main CPU board, and then Please execute the update. And, please load CMOS.BIN.</li> </ul>	
		9	A syntax error was found in the CNT instruction.	Data error	<ul><li>(1)Turn the power OFF then back ON.</li><li>(2)If the alarm occurs again, initialize the appropriate data in maintenance mode, and then load the data saved in the external memory device.</li></ul>	

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy	
Number		Code				
				Main CPU board failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the Main CPU board. Save the CMOS.BIN before replace the board to be safe. Replace the Main CPU board, and then Please execute the update. And, please load CMOS.BIN.</li> </ul>	
		10	The head of the block starts with an instruction other than the STR instruction.	Data error	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, initialize the appropriate data in maintenance mode, and then load the data saved in the external memory device.</li> </ul>	
				Main CPU board failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the Main CPU board. Save the CMOS.BIN before replace the board to be safe. Replace the Main CPU board, and then Please execute the update. And, please load CMOS.BIN.</li> </ul>	مق
		11	Excessive machine codes	Data error	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, initialize the appropriate data in maintenance mode, and then load the data saved in the external memory device.	<u>^</u> ≥
				Main CPU board failure	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, replace the Main CPU board. Save the CMOS.BIN before replace the board to be safe. Replace the Main CPU board, and then Please execute the update. And, please load CMOS.BIN.	arm Arm Moe
		12	The last instruction is not the END instruction.	Data error	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, initialize the appropriate data in maintenance mode, and then load the data saved in the external memory device.	222
				Main CPU board failure	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, replace the Main CPU board. Save the CMOS.BIN before replace the board to be safe. Replace the Main CPU board, and then Please execute the update. And, please load CMOS.BIN.	1
		13	An error was found in the PART instruction.	Data error	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, initialize the appropriate data in maintenance mode, and then load the data saved in the external memory device.</li> </ul>	
				Main CPU board failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the Main CPU board. Save the CMOS.BIN before replace the board to be safe. Replace the Main CPU board, and then Please execute the update. And, please load CMOS.BIN.</li> </ul>	
		14	An error was found in the GOUT instruction.	Data error	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, initialize the appropriate data in maintenance mode, and then load the data saved in the external memory device.</li> </ul>	
				Main CPU board failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the Main CPU board. Save the CMOS.BIN before replace the board to be safe. Replace the Main CPU board, and then Please execute the update. And, please load CMOS.BIN.</li> </ul>	
		15	The No. of operand is incorrect.	Data error	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, initialize the appropriate data in maintenance mode, and then load the data saved in the external memory device.</li> </ul>	

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy
Number		Code			
				Main CPU board failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the Main CPU board. Save the CMOS.BIN before replace the board to be safe. Replace the Main CPU board, and then Please execute the update. And, please load CMOS.BIN.</li> </ul>
		16	The constant value is incorrect.	Data error	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, initialize the appropriate data in maintenance mode, and then load the data saved in the external memory device.</li> </ul>
				Main CPU board failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the Main CPU board. Save the CMOS.BIN before replace the board to be safe. Replace the Main CPU board, and then Please execute the update. And, please load CMOS.BIN.</li> </ul>
		17	The step capacity exceeds the memory capacity.	Data error	<ul><li>(1)Turn the power OFF then back ON.</li><li>(2)If the alarm occurs again, initialize the appropriate data in maintenance mode, and then load the data saved in the external memory device.</li></ul>
				Main CPU board failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the Main CPU board. Save the CMOS.BIN before replace the board to be safe. Replace the Main CPU board, and then Please execute the update. And, please load CMOS.BIN.</li> </ul>
		18	The number of operation instructions exceed the permissible value.	Data error	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, initialize the appropriate data in maintenance mode, and then load the data saved in the external memory device.</li> </ul>
				Main CPU board failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the Main CPU board. Save the CMOS.BIN before replace the board to be safe. Replace the Main CPU board, and then Please execute the update. And, please load CMOS.BIN.</li> </ul>
		19	A syntax error was found in the CNT instruction or TMR instruction.	Data error	<ul><li>(1)Turn the power OFF then back ON.</li><li>(2)If the alarm occurs again, initialize the appropriate data in maintenance mode, and then load the data saved in the external memory device.</li></ul>
				Main CPU board failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the Main CPU board. Save the CMOS.BIN before replace the board to be safe. Replace the Main CPU board, and then Please execute the update. And, please load CMOS.BIN.</li> </ul>
		20	A syntax error was found in the JMP-LABEL instructions.	Data error	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, initialize the appropriate data in maintenance mode, and then load the data saved in the external memory device.</li> </ul>
				Main CPU board failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the Main CPU board. Save the CMOS.BIN before replace the board to be safe. Replace the Main CPU board, and then Please execute the update. And, please load CMOS.BIN.</li> </ul>
		21	The label of JMP destination does not exist.	Data error	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, initialize the appropriate data in maintenance mode, and then load the data saved in the external memory device.</li> </ul>

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy	
Number		Code				
				Main CPU board failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the Main CPU board. Save the CMOS.BIN before replace the board to be safe. Replace the Main CPU board, and then Please execute the update. And, please load CMOS.BIN.</li> </ul>	
790	MEMORY BATTERY WEAK		Main CPU board battery is weakening.	Connection failure	(1)Confirm that the battery is appropriately connected to the main CPU board.	
				Connection failure	(1)Replace the battery in accordance with the instructions in FS100L MAINTENANCE MANUAL.	
820	CNTR01R HARDWARE ERR		subcode: Option board. Numberx100 + factor factor: 1 ROM ERR 2 RAM ERR 3 CPU ERR 4 SHARED MEMORY ERR 5 CNTR ASIC ERR	CNTR01R board failure	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, replace the CNTR01R board. Save the CMOS.BIN before replacing the board to be safe.	9. Alarm
821	CNTR01R SOFTWARE ERR		subcode: Option board. Number×100 + factor factor: 1 WDG TIMEOVER 2 ADDRESS ERR(READ) EXCEPTION 3 ADDRESS ERR(WRITE) EXCEPTION 4 UNJUST INST EXCEPTION 5 UNJUST SLOT EXCEPTION	CNTR01R board failure	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, replace the CNTR01R board. Save the CMOS.BIN before replacing the board to be safe.	
822	CNTR01R WDG ERR	100	A Watchdog err was detected in the Option #1 board.	CNTR01R board failure	<ul><li>(1)Turn the power OFF then back ON.</li><li>(2)If the alarm occurs again, replace the CNTR01R board. Save the CMOS.BIN before replacing the board to be safe.</li></ul>	
		200	A Watchdog err was detected in the Option #2 board.	CNTR01R board failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the CNTR01R board. Save the CMOS.BIN before replacing the board to be safe.</li> </ul>	
		300	A Watchdog err was detected in the Option #3 board.	CNTR01R board failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the CNTR01R board. Save the CMOS.BIN before replacing the board to be safe.</li> </ul>	
		400	A Watchdog err was detected in the Option #4 board.	CNTR01R board failure	<ul><li>(1)Turn the power OFF then back ON.</li><li>(2)If the alarm occurs again, replace the CNTR01R board. Save the CMOS.BIN before replacing the board to be safe.</li></ul>	

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy	
Number		Code				
		500	A Watchdog err was detected in the Option #5 board.	CNTR01R board failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the CNTR01R board. Save the CMOS.BIN before replacing the board to be safe.</li> </ul>	
		600	A Watchdog err was detected in the Option #6 board.	CNTR01R board failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the CNTR01R board. Save the CMOS.BIN before replacing the board to be safe.</li> </ul>	
		700	A Watchdog err was detected in the Option #7 board.	CNTR01R board failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the CNTR01R board. Save the CMOS.BIN before replacing the board to be safe.</li> </ul>	
		800	A Watchdog err was detected in the Option #8 board.	CNTR01R board failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the CNTR01R board. Save the CMOS.BIN before replacing the board to be safe.</li> </ul>	9.4
910	CPU ERROR (CPU-201R)	1	An error was detected in the CPU.	Main CPU board failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the Main CPU board. Save the CMOS.BIN before replace the board to be safe. Replace the Main CPU board, and then Please execute the update. And, please load CMOS.BIN.</li> </ul>	Alarm I
920	BUS ERROR (CPU-201R)	1	The JL chip does not operate normally.	Main CPU board failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the Main CPU board. Save the CMOS.BIN before replace the board to be safe. Replace the Main CPU board, and then Please execute the update. And, please load CMOS.BIN.</li> </ul>	Message
950	CPU ERROR (servo#1)		An error was detected in the CPU of servo board #1.	Connection failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, check the connection and insertion of the following cables and connectors.</li> <li>The cable of EAXA board connector CN515</li> <li>The cable of CPU-201R board connector CN1/2</li> </ul>	List
				Servo control circuit board failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the EAXA board. Save the CMOS.BIN before replace the board to be safe.</li> </ul>	
				Main CPU board failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the Main CPU board. Save the CMOS.BIN before replace the board to be safe. Replace the Main CPU board, and then Please execute the update. And, please load CMOS.BIN.</li> </ul>	
990	SYSTEM ERROR (Main CPU)	1	Power Lost Signal Error	Main CPU board failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the Main CPU board. Save the CMOS.BIN before replace the board to be safe. Replace the Main CPU board, and then Please execute the update. And, please load CMOS.BIN.</li> </ul>	
1000	ROM ERROR (Main CPU)			Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
1020	MotoPlus application load error	1	Num of the Application files on the YCP01 CF is over the limit.	Setting error	Set the number of application file "*.OUT" to be within the defined value. (Delete unnecessary files from the MotoPlus menu of the maintenance mode.)	

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy	
Number		Code				
		2	Insufficient memory space. At the loading time, remaining CPU memory is less than 2Mbyte (Stipulated memory size for MotoPlus).	Setting error	Memory to work MotoPlus application is insufficient under the combination of current system configuration and its optional function. If the alarm occurs again, save the CMOS.BIN in maintenance mode and contact your Yaskawa representative about occurrence status (operating procedure).	
		3	MotoPlus application folder "/ Application"cannot be found.	Setting error	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the CPU-201R board. Save the CMOS.BIN before replace the board to be safe. Replace the CPU-201R board, and then Please execute the update. And, please load CMOS.BIN.</li> </ul>	
		4	Memory size (Code area + static variable area) required by MotoPlus Application is over the limit(2Mbyte).	Setting error	Check that if the object file name is too long or inappropriate letters are used.	9. 9.4
		5		Setting error	Check that symbols such as undefined functions or constants, which are provided from the system side, are included in the application program.	Alar Alar
		6		Setting error	<ul> <li>(1)Check the definition of static variable in the MotoPlus application program is correct or not.</li> <li>(2)Check the MotoPlus application programs so that they are set within the specified values.</li> <li>(3)Check that the object files are appropriately created.</li> </ul>	m m Message
		7	API library initialization failure because of Insufficient system memory to load MotoPlusAPI library	Setting error	Memory to work MotoPlus application is insufficient under the combination of current system configuration and its optional function. If the alarm occurs again, save the CMOS.BIN in maintenance mode and contact your Yaskawa representative about occurrence status (operating procedure).	List
		8	User root task "mpUsrRoot()" not included in the application	Setting error	Confirm that mpUsRoot() is described in the application program.	
		9	User root task generation failure	Setting error	Memory to work MotoPlus application is insufficient under the combination of current system configuration and its optional function. If the alarm occurs again, save the CMOS.BIN in maintenance mode and contact your Yaskawa representative about occurrence status (operating procedure).	
		10	RAM-Disk generation failure	Setting error	Memory to work MotoPlus application is insufficient under the combination of current system configuration and its optional function. If the alarm occurs again, save the CMOS.BIN in maintenance mode and contact your Yaskawa representative about occurrence status (operating procedure).	
		11	MotoPlus application process generation failure	Setting error	Check that the object file is appropriately created.	
		12	application file "*.VXE" in the controller exceeded the specified value	Setting error	Set the number of application file "*.VXE" to be within the defined value. (Delete unnecessary files from the MotoPlus menu of the maintenance mode.)	

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy	
Number		Code				
		13	Failure to install the driver to communicate between MotoPlus application and the system.	Setting error	Memory to work MotoPlus application is insufficient under the combination of current system configuration and its optional function. If the alarm occurs again, save the CMOS.BIN in maintenance mode and contact your Yaskawa representative about occurrence status (operating procedure).	
1021	MotoPlus SRAM File is not initialized		Despite MotoPlus function is activated SRAM file drive is not initialized. Causes are 1) The file is destroyed. 2) MotoPlus function has been activated by the means other than operation of MotoPlus in maintenance mode.	Setting error	Deactivate the MotoPlus function then activate it again in Maintenance mode.	
1030	MEMORY ERROR (PARAMETER FILE)	0	RCD, RCxG parameter error	Data error	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, initialize the appropriate parameter file in maintenance mode, and then load the parameter file saved in the external memory device.</li> </ul>	
				Main CPU board failure	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, replace the Main CPU board. Save the CMOS.BIN before replace the board to be safe. Replace the Main CPU board, and then Please execute the update. And, please load CMOS.BIN.	
		1	ROxG parameter error	Data error	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, initialize the appropriate parameter file in maintenance mode, and then load the parameter file saved in the external memory device.</li> </ul>	
				Main CPU board failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the Main CPU board. Save the CMOS.BIN before replace the board to be safe. Replace the Main CPU board, and then Please execute the update. And, please load CMOS.BIN.</li> </ul>	
		2	SVD, SVxG parameter error	Data error	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, initialize the appropriate parameter file in maintenance mode, and then load the parameter file saved in the external memory device.</li> </ul>	
				Main CPU board failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the Main CPU board. Save the CMOS.BIN before replace the board to be safe. Replace the Main CPU board, and then Please execute the update. And, please load CMOS.BIN.</li> </ul>	
		3	SVMxG parameter error	Data error	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, initialize the appropriate parameter file in maintenance mode, and then load the parameter file saved in the external memory device.</li> </ul>	
Alarm	Alarm Name	Sub	Meaning	Cause	Remedy	
--------	------------	------	---	------------------------	--	----------------
Number		Code				
				Main CPU board failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the Main CPU board. Save the CMOS.BIN before replace the board to be safe. Replace the Main CPU board, and then Please execute the update. And, please load CMOS.BIN.</li> </ul>	
		4	S1CxG, S2C, S3C, S4C parameter error	Data error	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, initialize the appropriate parameter file in maintenance mode, and then load the parameter file saved in the external memory device.</li> </ul>	
				Main CPU board failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the Main CPU board. Save the CMOS.BIN before replace the board to be safe. Replace the Main CPU board, and then Please execute the update. And, please load CMOS.BIN.</li> </ul>	9. 9.4
		5	S1D, S2D, S3D, S4D parameter error	Data error	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, initialize the appropriate parameter file in maintenance mode, and then load the parameter file saved in the external memory device.</li> </ul>	Alarm Alarm
				Main CPU board failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the Main CPU board. Save the CMOS.BIN before replace the board to be safe. Replace the Main CPU board, and then Please execute the update. And, please load CMOS.BIN.</li> </ul>	Message
		6	CIO parameter error	Data error	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, initialize the appropriate parameter file in maintenance mode, and then load the parameter file saved in the external memory device.</li> </ul>	List
				Main CPU board failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the Main CPU board. Save the CMOS.BIN before replace the board to be safe. Replace the Main CPU board, and then Please execute the update. And, please load CMOS.BIN.</li> </ul>	
		7	FD parameter error	Data error	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, initialize the appropriate parameter file in maintenance mode, and then load the parameter file saved in the external memory device.</li> </ul>	
				Main CPU board failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the Main CPU board. Save the CMOS.BIN before replace the board to be safe. Replace the Main CPU board, and then Please execute the update. And, please load CMOS.BIN.</li> </ul>	
		8	A1P, A2P,, A8P parameter error	Data error	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, initialize the appropriate parameter file in maintenance mode, and then load the parameter file saved in the external memory device.</li> </ul>	

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy	
Number		Code				
				Main CPU board failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the Main CPU board. Save the CMOS.BIN before replace the board to be safe. Replace the Main CPU board, and then Please execute the update. And, please load CMOS.BIN.</li> </ul>	
		9	RS parameter error	Data error	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, initialize the appropriate parameter file in maintenance mode, and then load the parameter file saved in the external memory device.</li> </ul>	
				Main CPU board failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the Main CPU board. Save the CMOS.BIN before replace the board to be safe. Replace the Main CPU board, and then Please execute the update. And, please load CMOS.BIN.</li> </ul>	9.4
		10	S1E, S2E,, S8E parameter error	Data error	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, initialize the appropriate parameter file in maintenance mode, and then load the parameter file saved in the external memory device.</li> </ul>	Alarm Alarm
				Main CPU board failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the Main CPU board. Save the CMOS.BIN before replace the board to be safe. Replace the Main CPU board, and then Please execute the update. And, please load CMOS.BIN.</li> </ul>	Message
		11	SVCxB parameter error	Data error	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, initialize the appropriate parameter file in maintenance mode, and then load the parameter file saved in the external memory device.	List
				Main CPU board failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the Main CPU board. Save the CMOS.BIN before replace the board to be safe. Replace the Main CPU board, and then Please execute the update. And, please load CMOS.BIN.</li> </ul>	
		12	AMCxG parameter error	Data error	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, initialize the appropriate parameter file in maintenance mode, and then load the parameter file saved in the external memory device.</li> </ul>	
				Main CPU board failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the Main CPU board. Save the CMOS.BIN before replace the board to be safe. Replace the Main CPU board, and then Please execute the update. And, please load CMOS.BIN.</li> </ul>	
		13	SVPxG parameter error	Data error	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, initialize the appropriate parameter file in maintenance mode, and then load the parameter file saved in the external memory device.</li> </ul>	

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy	
Number		Code				
				Main CPU board failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the Main CPU board. Save the CMOS.BIN before replace the board to be safe. Replace the Main CPU board, and then Please execute the update. And, please load CMOS.BIN.</li> </ul>	
		14	MFxG parameter error	Data error	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, initialize the appropriate parameter file in maintenance mode, and then load the parameter file saved in the external memory device.</li> </ul>	
				Main CPU board failure	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, replace the Main CPU board. Save the CMOS.BIN before replace the board to be safe. Replace the Main CPU board, and then Please execute the update. And, please load CMOS.BIN.	9 <u>9</u>
		15	SVSxG parameter error	Data error	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, initialize the appropriate parameter file in maintenance mode, and then load the parameter file saved in the external memory device.	Alarm Alarm
				Main CPU board failure	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, replace the Main CPU board. Save the CMOS.BIN before replace the board to be safe. Replace the Main CPU board, and then Please execute the update. And, please load CMOS.BIN.	Message
		16	RExG parameter error	Data error	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, initialize the appropriate parameter file in maintenance mode, and then load the parameter file saved in the external memory device.	u ist
				Main CPU board failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the Main CPU board. Save the CMOS.BIN before replace the board to be safe. Replace the Main CPU board, and then Please execute the update. And, please load CMOS.BIN.</li> </ul>	
1031	MEMORY ERROR (MOTION1)	0	"GET FILE" instruction, "SET FILE" instruction execution target file	Data error	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, initialize the appropriate data in maintenance mode, and then load the data saved in the external memory device.</li> </ul>	
		1	Home position calibration file	Data error	<ul><li>(1)Turn the power OFF then back ON.</li><li>(2)If the alarm occurs again, initialize the appropriate data in maintenance mode, and then load the data saved in the external memory device.</li></ul>	
		2	Tool file	Data error	<ul><li>(1)Turn the power OFF then back ON.</li><li>(2)If the alarm occurs again, initialize the appropriate data in maintenance mode, and then load the data saved in the external memory device.</li></ul>	
		3	User coordinates file	Data error	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, initialize the appropriate data in maintenance mode, and then load the data saved in the external memory device.</li> </ul>	

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy	
Number		Code				
		4	Robot calibration file	Data error	<ul><li>(1)Turn the power OFF then back ON.</li><li>(2)If the alarm occurs again, initialize the appropriate data in maintenance mode, and then load the data saved in the external memory device.</li></ul>	-
		5	Tool calibration file	Data error	<ul><li>(1)Turn the power OFF then back ON.</li><li>(2)If the alarm occurs again, initialize the appropriate data in maintenance mode, and then load the data saved in the external memory device.</li></ul>	-
		7	Home position correction data file	Data error	<ul><li>(1)Turn the power OFF then back ON.</li><li>(2)If the alarm occurs again, initialize the appropriate data in maintenance mode, and then load the data saved in the external memory device.</li></ul>	-
		8	Conveyor calibration file	Data error	<ul><li>(1)Turn the power OFF then back ON.</li><li>(2)If the alarm occurs again, initialize the appropriate data in maintenance mode, and then load the data saved in the external memory device.</li></ul>	9.4
		9	Arm and tool interference prevention file	Data error	<ul><li>(1)Turn the power OFF then back ON.</li><li>(2)If the alarm occurs again, initialize the appropriate data in maintenance mode, and then load the data saved in the external memory device.</li></ul>	Alarr Alarr
		34	Conveyor condition file	Data error	<ul><li>(1)Turn the power OFF then back ON.</li><li>(2)If the alarm occurs again, initialize the appropriate data in maintenance mode, and then load the data saved in the external memory device.</li></ul>	n n Mess
		35	Press characteristics file	Data error	<ul><li>(1)Turn the power OFF then back ON.</li><li>(2)If the alarm occurs again, initialize the appropriate data in maintenance mode, and then load the data saved in the external memory device.</li></ul>	age Lis
		36	Servo float condition file	Data error	<ul><li>(1)Turn the power OFF then back ON.</li><li>(2)If the alarm occurs again, initialize the appropriate data in maintenance mode, and then load the data saved in the external memory device.</li></ul>	¥
		42	Anticipation OT# output file	Data error	<ul><li>(1)Turn the power OFF then back ON.</li><li>(2)If the alarm occurs again, initialize the appropriate data in maintenance mode, and then load the data saved in the external memory device.</li></ul>	
		43	Anticipation OG# output file	Data error	<ul><li>(1)Turn the power OFF then back ON.</li><li>(2)If the alarm occurs again, initialize the appropriate data in maintenance mode, and then load the data saved in the external memory device.</li></ul>	
		45	Form cut file	Data error	<ul><li>(1)Turn the power OFF then back ON.</li><li>(2)If the alarm occurs again, initialize the appropriate data in maintenance mode, and then load the data saved in the external memory device.</li></ul>	
		47	Linear servo float condition file	Data error	<ul><li>(1)Turn the power OFF then back ON.</li><li>(2)If the alarm occurs again, initialize the appropriate data in maintenance mode, and then load the data saved in the external memory device.</li></ul>	
		48	Macro definition file	Data error	<ul><li>(1)Turn the power OFF then back ON.</li><li>(2)If the alarm occurs again, initialize the appropriate data in maintenance mode, and then load the data saved in the external memory device.</li></ul>	

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy	
Number		Code				
		53	Job registration table	Data error	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, initialize the appropriate data in maintenance mode, and then load the data saved in the external memory device.</li> </ul>	
		62	Linear scale condition file	Data error	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, initialize the appropriate data in maintenance mode, and then load the data saved in the external memory device.</li> </ul>	
		64	Conveyor condition auxiliary file	Data error	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, initialize the appropriate data in maintenance mode, and then load the data saved in the external memory device.</li> </ul>	
		67	Palletizing condition file	Data error	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, initialize the appropriate data in maintenance mode, and then load the data saved in the external memory device.</li> </ul>	9.4 9.4
		69	Mastering registration position	Data error	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, initialize the appropriate data in maintenance mode, and then load the data saved in the external memory device.</li> </ul>	Alarn Alarn
1050	SET-UP PROCESS ERROR (SYSCON)	1	Motion instruction setup incomplete.	Main CPU board failure	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, replace the Main CPU board. Save the CMOS.BIN before replace the board to be safe. Replace the Main CPU board, and then Please execute the update. And, please load CMOS.BIN.	n n Messag
				Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	je List
		2	Online error	Main CPU board failure	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, replace the Main CPU board. Save the CMOS.BIN before replace the board to be safe. Replace the Main CPU board, and then Please execute the update. And, please load CMOS.BIN.	
				Software operation error occurred	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).	
1051	SET-UP PROCESS ERROR (MOTION)	1	Unable to properly activate the servo control	Servo control circuit board failure	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, replace the EAXA board. Save the CMOS.BIN before replace the board to be safe.	
				Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		2	The position data of when the power supply was turned OFF cannot be transmitted to the servo control section	Servo control circuit board failure	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, replace the EAXA board. Save the CMOS.BIN before replace the board to be safe.	

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy
Number		Code			
				Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		3	The servo control section cannot receive the position data of when the power supply was turned OFF	Servo control circuit board failure	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, replace the EAXA board. Save the CMOS.BIN before replace the board to be safe.
				Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		7	Unable to send a request to prepare a feedback pulse	Servo control circuit board failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the EAXA board. Save the CMOS.BIN before replace the board to be safe.</li> </ul>
				Software operation error occurred	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).
		8	Unable to prepare a feedback pulse	Servo control circuit board failure	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, replace the EAXA board. Save the CMOS.BIN before replace the board to be safe.
				Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		9	Unable to send a request to initialize the arithmetic section (ARITH)	Main CPU board failure	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, replace the CPU-201R board. Save the CMOS.BIN and then replace the board. After replacing the board, upgrade the software with the version which is same as the one saved in the former CPU-201R board.
				Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		10	Unable to initialize ARITH	Main CPU board failure	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, replace the CPU-201R board. Save the CMOS.BIN and then replace the board. After replacing the board, upgrade the software with the version which is same as the one saved in the former CPU-201R board.
				Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy	
Number		Code				
		11	Unable to send a request to prepare the current position	Main CPU board failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the CPU-201R board. Save the CMOS.BIN and then replace the board. After replacing the board, upgrade the software with the version which is same as the one saved in the former CPU-201R board.</li> </ul>	
				Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		12	Unable to prepare the current position	Main CPU board failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the CPU-201R board. Save the CMOS.BIN and then replace the board. After replacing the board, upgrade the software with the version which is same as the one saved in the former CPU-201R board.</li> </ul>	9. 9.4
				Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	Alarm Alarm
1052	SET-UP PROCESS ERROR (MotomanSync)			Setting error	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	Message
1053	SYSTEM ERROR (EVENT)		subcode 1 to 8: Signifies the internal software error at event process.	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	List
1100	SYSTEM ERROR		subcode C, B, F : subcode of unknown alarm	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
				RAM software data error	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
1101	SYSTEM ERROR (MAN- MACHINE MECHA)		subcode 0 to 6: Internal control error in software	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
1102	SYSTEM ERROR (MAN-MACHINE APPLI)		subcode 0 to 526: Internal control error in software	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy
Number		Code			
1103	SYSTEM ERROR (EVENT)			Software operation error occurred	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).
1104	SYSTEM ERROR (CIO)		subcode 1000_0000: I/O module setting error	Connection failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, check the connecting or inserting state of the following cables or connectors.</li> <li>·IO module cable of the corresponding slot.</li> <li>·24V power of the corresponding IO module.</li> </ul>
				Setting error	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the error occurs again, set the I/O module again in maintenance mode.</li> <li>(3)If the error occurs again though the previous measures were executed, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
				Main CPU board failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the Main CPU board. Save the CMOS.BIN before replace the board to be safe. Replace the Main CPU board, and then Please execute the update. And, please load CMOS.BIN.</li> </ul>
		15	Communication period with the motion part is inappropriate.	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
				Servo control circuit board failure	<ul><li>(1)Turn the power OFF then back ON.</li><li>(2)If the alarm occurs again, replace the EAXA, EAXB board. Save the CMOS.BIN before replacing the board to be safe.</li></ul>
		21	A task request was sent to an axis in the alarm status.	Software operation error occurred	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).
				Servo control circuit board failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the EAXA, EAXB board. Save the CMOS.BIN before replacing the board to be safe.</li> </ul>
		30	The linear servo float does not support the manipulator type specified in the RC parameter at calculation for servo-float-related parameters.	Software operation error occurred	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).
		37	The manipulator (B-axis) passed the singular point while the linear servo float was ON.	Setting error	(1)Check the following settings. Correct the job so that the manipulator (B-axis) does not pass the singular point while the linear servo float is ON.

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy	
Number		Code				
		47	The alarm number is illegal.	Software operation error occurred	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).	
		49	Parameter modified while the servo float is ON.	Setting error	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).	
		128	The dynamics calculation process did not complete within the time set on the scheduling table.	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	9. 9.4
				Servo control circuit board failure	<ul><li>(1)Turn the power OFF then back ON.</li><li>(2)If the alarm occurs again, replace the EAXA, EAXB board. Save the CMOS.BIN before replacing the board to be safe.</li></ul>	Aları Aları
		135	General08ms process dose not complete within the time set by the scheduling table.	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	m m Messa
				Servo control circuit board failure	<ul><li>(1)Turn the power OFF then back ON.</li><li>(2)If the alarm occurs again, replace the EAXA, EAXB board. Save the CMOS.BIN before replacing the board to be safe.</li></ul>	ge List
		151	The averaging time is not an even number. (times)	Software operation error occurred	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).	
		160	The interface with the microprogram dose not complete within the time set by the scheduling table.	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
				Servo control circuit board failure	<ul><li>(1)Turn the power OFF then back ON.</li><li>(2)If the alarm occurs again, replace the EAXA, EAXB board. Save the CMOS.BIN before replacing the board to be safe.</li></ul>	
		161	Receive data area overflow	Data error	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).	
		1000	The check item number of SVD parameter is unmatched.	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy
Number		Code			
		1001	The check item number of SV parameter is unmatched.	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		1002	The check item number of SVM parameter is unmatched.	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		1003	The check item number of SVP parameter is unmatched.	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		1004	The check item number of AMC parameter is unmatched.	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		1005	The check item number of MFG parameter is unmatched.	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		1006	The check item number of MFA parameter is unmatched.	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		1007	The check item number of SVC parameter is unmatched.	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		2500	JL077 detects ground fault, but the converter doesn't inform it.	Connection failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, check the connection and insertion of the following cables and connectors.</li> <li>EAXA01-CN507,510</li> <li>EAXB01-CN531,532,533</li> <li>Converter-CN551,553</li> <li>EX1SV(External axis servo pack)-CN591,592</li> <li>(3)If the alarm repeatedly occurs, check if all the cables above are correctly connected.</li> </ul>
		4001	Execution of motion command did not complete within a certain time period. (The last three digits expresses the command code.)	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy	
Number		Code				
		4002	Execution of motion command did not complete within a certain time period. (The last three digits expresses the command code.)	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		4003	Execution of motion command did not complete within a certain time period. (The last three digits expresses the command code.)	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		4004	Execution of motion command did not complete within a certain time period. (The last three digits expresses the command code.)	Software operation error occurred	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).	, <u>.</u>
		4005	Execution of motion command did not complete within a certain time period. (The last three digits expresses the command code.)	Software operation error occurred	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).	Alarm
		4006	Execution of motion command did not complete within a certain time period. (The last three digits expresses the command code.)	Software operation error occurred	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).	•
		4007	Execution of motion command did not complete within a certain time period. (The last three digits expresses the command code.)	Software operation error occurred	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).	
		4008	Execution of motion command did not complete within a certain time period. (The last three digits expresses the command code.)	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		4009	Execution of motion command did not complete within a certain time period. (The last three digits expresses the command code.)	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		4010	Execution of motion command did not complete within a certain time period. (The last three digits expresses the command code.)	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		4011	Execution of motion command did not complete within a certain time period. (The last three digits expresses the command code.)	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy
Number		Code			
		4012	Execution of motion command did not complete within a certain time period. (The last three digits expresses the command code.)	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		4013	Execution of motion command did not complete within a certain time period. (The last three digits expresses the command code.)	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		4014	Execution of motion command did not complete within a certain time period. (The last three digits expresses the command code.)	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		4015	Execution of motion command did not complete within a certain time period. (The last three digits expresses the command code.)	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		4016	Execution of motion command did not complete within a certain time period. (The last three digits expresses the command code.)	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		4017	Execution of motion command did not complete within a certain time period. (The last three digits expresses the command code.)	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		4018	Execution of motion command did not complete within a certain time period. (The last three digits expresses the command code.)	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		4019	Execution of motion command did not complete within a certain time period. (The last three digits expresses the command code.)	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		4020	Execution of motion command did not complete within a certain time period. (The last three digits expresses the command code.)	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		4021	Execution of motion command did not complete within a certain time period. (The last three digits expresses the command code.)	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy	
Number		Code				
		4022	Execution of motion command did not complete within a certain time period. (The last three digits expresses the command code.)	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		4023	Execution of motion command did not complete within a certain time period. (The last three digits expresses the command code.)	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		4024	Execution of motion command did not complete within a certain time period. (The last three digits expresses the command code.)	Software operation error occurred	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).	, <u>.</u>
		4025	Execution of motion command did not complete within a certain time period. (The last three digits expresses the command code.)	Software operation error occurred	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).	Alarm
		4026	Execution of motion command did not complete within a certain time period. (The last three digits expresses the command code.)	Software operation error occurred	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).	•
		4027	Execution of motion command did not complete within a certain time period. (The last three digits expresses the command code.)	Software operation error occurred	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).	
		4028	Execution of motion command did not complete within a certain time period. (The last three digits expresses the command code.)	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		4029	Execution of motion command did not complete within a certain time period. (The last three digits expresses the command code.)	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		4030	Execution of motion command did not complete within a certain time period. (The last three digits expresses the command code.)	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		4031	Execution of motion command did not complete within a certain time period. (The last three digits expresses the command code.)	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy
Number		Code			
		4032	Execution of motion command did not complete within a certain time period. (The last three digits expresses the command code.)	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		4033	Execution of motion command did not complete within a certain time period. (The last three digits expresses the command code.)	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		4034	Execution of motion command did not complete within a certain time period. (The last three digits expresses the command code.)	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		4035	Execution of motion command did not complete within a certain time period. (The last three digits expresses the command code.)	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		4036	Execution of motion command did not complete within a certain time period. (The last three digits expresses the command code.)	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		4037	Execution of motion command did not complete within a certain time period. (The last three digits expresses the command code.)	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		4038	Execution of motion command did not complete within a certain time period. (The last three digits expresses the command code.)	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		4039	Execution of motion command did not complete within a certain time period. (The last three digits expresses the command code.)	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		4040	Execution of motion command did not complete within a certain time period. (The last three digits expresses the command code.)	Software operation error occurred	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).
		4041	Execution of motion command did not complete within a certain time period. (The last three digits expresses the command code.)	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy	
Number		Code				
		4042	Execution of motion command did not complete within a certain time period. (The last three digits expresses the command code.)	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		4043	Execution of motion command did not complete within a certain time period. (The last three digits expresses the command code.)	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		4044	Execution of motion command did not complete within a certain time period. (The last three digits expresses the command code.)	Software operation error occurred	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).	9
		4045	Execution of motion command did not complete within a certain time period. (The last three digits expresses the command code.)	Software operation error occurred	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).	Alarm
		4046	Execution of motion command did not complete within a certain time period. (The last three digits expresses the command code.)	Software operation error occurred	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).	
		4047	Execution of motion command did not complete within a certain time period. (The last three digits expresses the command code.)	Software operation error occurred	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).	
		4048	Execution of motion command did not complete within a certain time period. (The last three digits expresses the command code.)	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		4049	Execution of motion command did not complete within a certain time period. (The last three digits expresses the command code.)	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		4050	Execution of motion command did not complete within a certain time period. (The last three digits expresses the command code.)	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		4051	Execution of motion command did not complete within a certain time period. (The last three digits expresses the command code.)	Software operation error occurred	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).	

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy
Number		Code			
		4052	Execution of motion command did not complete within a certain time period. (The last three digits expresses the command code.)	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		4053	Execution of motion command did not complete within a certain time period. (The last three digits expresses the command code.)	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		4054	Execution of motion command did not complete within a certain time period. (The last three digits expresses the command code.)	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		4055	Execution of motion command did not complete within a certain time period. (The last three digits expresses the command code.)	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		4056	Execution of motion command did not complete within a certain time period. (The last three digits expresses the command code.)	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		4057	Execution of motion command did not complete within a certain time period. (The last three digits expresses the command code.)	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		4058	Execution of motion command did not complete within a certain time period. (The last three digits expresses the command code.)	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		4059	Execution of motion command did not complete within a certain time period. (The last three digits expresses the command code.)	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		4060	Execution of motion command did not complete within a certain time period. (The last three digits expresses the command code.)	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		4061	Execution of motion command did not complete within a certain time period. (The last three digits expresses the command code.)	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy	
Number		Code				
		4062	Execution of motion command did not complete within a certain time period. (The last three digits expresses the command code.)	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		4063	Execution of motion command did not complete within a certain time period. (The last three digits expresses the command code.)	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		4064	Execution of motion command did not complete within a certain time period. (The last three digits expresses the command code.)	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	9. 9.4
		4065	Execution of motion command did not complete within a certain time period. (The last three digits expresses the command code.)	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	Alarm Alarm
		4066	Execution of motion command did not complete within a certain time period. (The last three digits expresses the command code.)	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	Message
		4067	Execution of motion command did not complete within a certain time period. (The last three digits expresses the command code.)	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	List
		4068	Execution of motion command did not complete within a certain time period. (The last three digits expresses the command code.)	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		4069	Execution of motion command did not complete within a certain time period. (The last three digits expresses the command code.)	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		4070	Execution of motion command did not complete within a certain time period. (The last three digits expresses the command code.)	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		4071	Execution of motion command did not complete within a certain time period. (The last three digits expresses the command code.)	Software operation error occurred	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).	

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy
Number		Code			
		4072	Execution of motion command did not complete within a certain time period. (The last three digits expresses the command code.)	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		4073	Execution of motion command did not complete within a certain time period. (The last three digits expresses the command code.)	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		4074	Execution of motion command did not complete within a certain time period. (The last three digits expresses the command code.)	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		4075	Execution of motion command did not complete within a certain time period. (The last three digits expresses the command code.)	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		4076	Execution of motion command did not complete within a certain time period. (The last three digits expresses the command code.)	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		4077	Execution of motion command did not complete within a certain time period. (The last three digits expresses the command code.)	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		4078	Execution of motion command did not complete within a certain time period. (The last three digits expresses the command code.)	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		4079	Execution of motion command did not complete within a certain time period. (The last three digits expresses the command code.)	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		4080	Execution of motion command did not complete within a certain time period. (The last three digits expresses the command code.)	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		4081	Execution of motion command did not complete within a certain time period. (The last three digits expresses the command code.)	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy	
Number		Code				
		4082	Execution of motion command did not complete within a certain time period. (The last three digits expresses the command code.)	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		4083	Execution of motion command did not complete within a certain time period. (The last three digits expresses the command code.)	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		4084	Execution of motion command did not complete within a certain time period. (The last three digits expresses the command code.)	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	9. 9.4
		4085	Execution of motion command did not complete within a certain time period. (The last three digits expresses the command code.)	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	Alarm Alarm
		4086	Execution of motion command did not complete within a certain time period. (The last three digits expresses the command code.)	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	Message
		4087	Execution of motion command did not complete within a certain time period. (The last three digits expresses the command code.)	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	List
		4088	Execution of motion command did not complete within a certain time period. (The last three digits expresses the command code.)	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		4089	Execution of motion command did not complete within a certain time period. (The last three digits expresses the command code.)	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		4090	Execution of motion command did not complete within a certain time period. (The last three digits expresses the command code.)	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		4091	Execution of motion command did not complete within a certain time period. (The last three digits expresses the command code.)	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy
Number		Code			
		4092	Execution of motion command did not complete within a certain time period. (The last three digits expresses the command code.)	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		4093	Execution of motion command did not complete within a certain time period. (The last three digits expresses the command code.)	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		4094	Execution of motion command did not complete within a certain time period. (The last three digits expresses the command code.)	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		4095	Execution of motion command did not complete within a certain time period. (The last three digits expresses the command code.)	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		4096	Execution of motion command did not complete within a certain time period. (The last three digits expresses the command code.)	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		4097	Execution of motion command did not complete within a certain time period. (The last three digits expresses the command code.)	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		4098	Execution of motion command did not complete within a certain time period. (The last three digits expresses the command code.)	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		4099	Execution of motion command did not complete within a certain time period. (The last three digits expresses the command code.)	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		4100	Execution of motion command did not complete within a certain time period. (The last three digits expresses the command code.)	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		4101	Execution of motion command did not complete within a certain time period. (The last three digits expresses the command code.)	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy
Number		Code			
		4102	Execution of motion command did not complete within a certain time period. (The last three digits expresses the command code.)	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		4103	Execution of motion command did not complete within a certain time period. (The last three digits expresses the command code.)	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		4104	Execution of motion command did not complete within a certain time period. (The last three digits expresses the command code.)	Software operation error occurred	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).
		4105	Execution of motion command did not complete within a certain time period. (The last three digits expresses the command code.)	Software operation error occurred	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).
		4106	Execution of motion command did not complete within a certain time period. (The last three digits expresses the command code.)	Software operation error occurred	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).
		4107	Execution of motion command did not complete within a certain time period. (The last three digits expresses the command code.)	Software operation error occurred	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).
		4108	Execution of motion command did not complete within a certain time period. (The last three digits expresses the command code.)	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		4109	Execution of motion command did not complete within a certain time period. (The last three digits expresses the command code.)	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		4110	Execution of motion command did not complete within a certain time period. (The last three digits expresses the command code.)	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		4111	Execution of motion command did not complete within a certain time period. (The last three digits expresses the command code.)	Software operation error occurred	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy
Number		Code			
		4112	Execution of motion command did not complete within a certain time period. (The last three digits expresses the command code.)	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		4113	Execution of motion command did not complete within a certain time period. (The last three digits expresses the command code.)	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		4114	Execution of motion command did not complete within a certain time period. (The last three digits expresses the command code.)	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		4115	Execution of motion command did not complete within a certain time period. (The last three digits expresses the command code.)	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		4116	Execution of motion command did not complete within a certain time period. (The last three digits expresses the command code.)	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		4117	Execution of motion command did not complete within a certain time period. (The last three digits expresses the command code.)	Software operation error occurred	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).
		4118	Execution of motion command did not complete within a certain time period. (The last three digits expresses the command code.)	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		4119	Execution of motion command did not complete within a certain time period. (The last three digits expresses the command code.)	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		4120	Execution of motion command did not complete within a certain time period. (The last three digits expresses the command code.)	Software operation error occurred	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).
		4121	Execution of motion command did not complete within a certain time period. (The last three digits expresses the command code.)	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy	
Number		Code				
		4122	Execution of motion command did not complete within a certain time period. (The last three digits expresses the command code.)	Software operation error occurred	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).	
		4123	Execution of motion command did not complete within a certain time period. (The last three digits expresses the command code.)	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		4124	Execution of motion command did not complete within a certain time period. (The last three digits expresses the command code.)	Software operation error occurred	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).	, <u>.</u>
		4125	Execution of motion command did not complete within a certain time period. (The last three digits expresses the command code.)	Software operation error occurred	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).	Alarm
		4126	Execution of motion command did not complete within a certain time period. (The last three digits expresses the command code.)	Software operation error occurred	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).	•
		4127	Execution of motion command did not complete within a certain time period. (The last three digits expresses the command code.)	Software operation error occurred	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).	
		4128	Execution of motion command did not complete within a certain time period. (The last three digits expresses the command code.)	Software operation error occurred	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).	
		4129	Execution of motion command did not complete within a certain time period. (The last three digits expresses the command code.)	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		4130	Execution of motion command did not complete within a certain time period. (The last three digits expresses the command code.)	Software operation error occurred	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).	
		4131	Execution of motion command did not complete within a certain time period. (The last three digits expresses the command code.)	Software operation error occurred	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).	

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy
Number		Code			
		4132	Execution of motion command did not complete within a certain time period. (The last three digits expresses the command code.)	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		4133	Execution of motion command did not complete within a certain time period. (The last three digits expresses the command code.)	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		4134	Execution of motion command did not complete within a certain time period. (The last three digits expresses the command code.)	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		4135	Execution of motion command did not complete within a certain time period. (The last three digits expresses the command code.)	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		4136	Execution of motion command did not complete within a certain time period. (The last three digits expresses the command code.)	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		4137	Execution of motion command did not complete within a certain time period. (The last three digits expresses the command code.)	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		4138	Execution of motion command did not complete within a certain time period. (The last three digits expresses the command code.)	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		4139	Execution of motion command did not complete within a certain time period. (The last three digits expresses the command code.)	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		4140	Execution of motion command did not complete within a certain time period. (The last three digits expresses the command code.)	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		4141	Execution of motion command did not complete within a certain time period. (The last three digits expresses the command code.)	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy
Number		Code			
		4142	Execution of motion command did not complete within a certain time period. (The last three digits expresses the command code.)	Software operation error occurred	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).
		4143	Execution of motion command did not complete within a certain time period. (The last three digits expresses the command code.)	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		4144	Execution of motion command did not complete within a certain time period. (The last three digits expresses the command code.)	Software operation error occurred	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).
		4145	Execution of motion command did not complete within a certain time period. (The last three digits expresses the command code.)	Software operation error occurred	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).
		4146	Execution of motion command did not complete within a certain time period. (The last three digits expresses the command code.)	Software operation error occurred	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).
		4147	Execution of motion command did not complete within a certain time period. (The last three digits expresses the command code.)	Software operation error occurred	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).
		4148	Execution of motion command did not complete within a certain time period. (The last three digits expresses the command code.)	Software operation error occurred	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).
		4149	Execution of motion command did not complete within a certain time period. (The last three digits expresses the command code.)	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		4150	Execution of motion command did not complete within a certain time period. (The last three digits expresses the command code.)	Software operation error occurred	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).
		4151	Execution of motion command did not complete within a certain time period. (The last three digits expresses the command code.)	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy
Number		Code			
		4152	Execution of motion command did not complete within a certain time period. (The last three digits expresses the command code.)	Software operation error occurred	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).
		4153	Execution of motion command did not complete within a certain time period. (The last three digits expresses the command code.)	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		4154	Execution of motion command did not complete within a certain time period. (The last three digits expresses the command code.)	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		4155	Execution of motion command did not complete within a certain time period. (The last three digits expresses the command code.)	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		4156	Execution of motion command did not complete within a certain time period. (The last three digits expresses the command code.)	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		4157	Execution of motion command did not complete within a certain time period. (The last three digits expresses the command code.)	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		4158	Execution of motion command did not complete within a certain time period.(The last three digits expresses the command code.)	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		4159	Execution of motion command did not complete within a certain time period.(The last three digits expresses the command code.)	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		4600	The connection number of a external brake is wrong.	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
				Servo control circuit board failure	<ul><li>(1)Turn the power OFF then back ON.</li><li>(2)If the alarm occurs again, replace the EAXA, EAXB board. Save the CMOS.BIN before replacing the board to be safe.</li></ul>
		5111	The weaken field control parameter is incorrect. (The last digit expresses the physical axis number.)	Setting error	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy
Number		Code			
		5112	The weaken field control parameter is incorrect. (The last digit expresses the physical axis number.)	Setting error	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		5113	The weaken field control parameter is incorrect. (The last digit expresses the physical axis number.)	Setting error	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		5114	The weaken field control parameter is incorrect. (The last digit expresses the physical axis number.)	Setting error	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).
		5115	The weaken field control parameter is incorrect. (The last digit expresses the physical axis number.)	Setting error	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		5116	The weaken field control parameter is incorrect. (The last digit expresses the physical axis number.)	Setting error	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).
		5117	The weaken field control parameter is incorrect. (The last digit expresses the physical axis number.)	Setting error	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).
		5118	The weaken field control parameter is incorrect. (The last digit expresses the physical axis number.)	Setting error	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		5119	The weaken field control parameter is incorrect. (The last digit expresses the physical axis number.)	Setting error	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		5121	The weaken field control parameter is incorrect. (The last digit expresses the physical axis number.)	Setting error	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		5122	The weaken field control parameter is incorrect. (The last digit expresses the physical axis number.)	Setting error	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy
Number		Code			
		5123	The weaken field control parameter is incorrect. (The last digit expresses the physical axis number.)	Setting error	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		5124	The weaken field control parameter is incorrect. (The last digit expresses the physical axis number.)	Setting error	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		5125	The weaken field control parameter is incorrect. (The last digit expresses the physical axis number.)	Setting error	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		5126	The weaken field control parameter is incorrect. (The last digit expresses the physical axis number.)	Setting error	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		5127	The weaken field control parameter is incorrect. (The last digit expresses the physical axis number.)	Setting error	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		5128	The weaken field control parameter is incorrect. (The last digit expresses the physical axis number.)	Setting error	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		5129	The weaken field control parameter is incorrect. (The last digit expresses the physical axis number.)	Setting error	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		5131	The weaken field control parameter is incorrect. (The last digit expresses the physical axis number.)	Setting error	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		5132	The weaken field control parameter is incorrect. (The last digit expresses the physical axis number.)	Setting error	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		5133	The weaken field control parameter is incorrect. (The last digit expresses the physical axis number.)	Setting error	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy
Number		Code			
		5134	The weaken field control parameter is incorrect. (The last digit expresses the physical axis number.)	Setting error	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		5135	The weaken field control parameter is incorrect. (The last digit expresses the physical axis number.)	Setting error	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		5136	The weaken field control parameter is incorrect. (The last digit expresses the physical axis number.)	Setting error	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).
		5137	The weaken field control parameter is incorrect. (The last digit expresses the physical axis number.)	Setting error	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).
		5138	The weaken field control parameter is incorrect. (The last digit expresses the physical axis number.)	Setting error	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).
		5139	The weaken field control parameter is incorrect. (The last digit expresses the physical axis number.)	Setting error	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).
		5141	The weaken field control parameter is incorrect. (The last digit expresses the physical axis number.)	Setting error	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		5142	The weaken field control parameter is incorrect. (The last digit expresses the physical axis number.)	Setting error	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		5143	The weaken field control parameter is incorrect. (The last digit expresses the physical axis number.)	Setting error	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		5144	The weaken field control parameter is incorrect. (The last digit expresses the physical axis number.)	Setting error	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy
Number		Code			
		5145	The weaken field control parameter is incorrect. (The last digit expresses the physical axis number.)	Setting error	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		5146	The weaken field control parameter is incorrect. (The last digit expresses the physical axis number.)	Setting error	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		5147	The weaken field control parameter is incorrect. (The last digit expresses the physical axis number.)	Setting error	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		5148	The weaken field control parameter is incorrect. (The last digit expresses the physical axis number.)	Setting error	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		5149	The weaken field control parameter is incorrect. (The last digit expresses the physical axis number.)	Setting error	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		5151	The weaken field control parameter is incorrect. (The last digit expresses the physical axis number.)	Setting error	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		5152	The weaken field control parameter is incorrect. (The last digit expresses the physical axis number.)	Setting error	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		5153	The weaken field control parameter is incorrect. (The last digit expresses the physical axis number.)	Setting error	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		5154	The weaken field control parameter is incorrect. (The last digit expresses the physical axis number.)	Setting error	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		5155	The weaken field control parameter is incorrect. (The last digit expresses the physical axis number.)	Setting error	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy	
Number		Code				
		5156	The weaken field control parameter is incorrect. (The last digit expresses the physical axis number.)	Setting error	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		5157	The weaken field control parameter is incorrect. (The last digit expresses the physical axis number.)	Setting error	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		5158	The weaken field control parameter is incorrect. (The last digit expresses the physical axis number.)	Setting error	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).	o o o
		5159	The weaken field control parameter is incorrect. (The last digit expresses the physical axis number.)	Setting error	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).	Alarm
		5161	The weaken field control parameter is incorrect. (The last digit expresses the physical axis number.)	Setting error	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).	
		5162	The weaken field control parameter is incorrect. (The last digit expresses the physical axis number.)	Setting error	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).	, - ; - ; -
		5163	The weaken field control parameter is incorrect. (The last digit expresses the physical axis number.)	Setting error	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		5164	The weaken field control parameter is incorrect. (The last digit expresses the physical axis number.)	Setting error	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		5165	The weaken field control parameter is incorrect. (The last digit expresses the physical axis number.)	Setting error	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		5166	The weaken field control parameter is incorrect. (The last digit expresses the physical axis number.)	Setting error	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).	

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy
Number		Code			
		5167	The weaken field control parameter is incorrect. (The last digit expresses the physical axis number.)	Setting error	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		5168	The weaken field control parameter is incorrect. (The last digit expresses the physical axis number.)	Setting error	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		5169	The weaken field control parameter is incorrect. (The last digit expresses the physical axis number.)	Setting error	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		5201	The weaken field control parameter is incorrect. (The last digit expresses the physical axis number.)	Setting error	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		5202	The weaken field control parameter is incorrect. (The last digit expresses the physical axis number.)	Setting error	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		5203	The weaken field control parameter is incorrect. (The last digit expresses the physical axis number.)	Setting error	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		5204	The weaken field control parameter is incorrect. (The last digit expresses the physical axis number.)	Setting error	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		5205	The weaken field control parameter is incorrect. (The last digit expresses the physical axis number.)	Setting error	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		5206	The weaken field control parameter is incorrect. (The last digit expresses the physical axis number.)	Setting error	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		5207	The weaken field control parameter is incorrect. (The last digit expresses the physical axis number.)	Setting error	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy
Number		Code			
		5208	The weaken field control parameter is incorrect. (The last digit expresses the physical axis number.)	Setting error	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		5209	The weaken field control parameter is incorrect. (The last digit expresses the physical axis number.)	Setting error	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		5301	The weaken field control parameter is incorrect. (The last digit expresses the physical axis number.)	Setting error	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		5302	The weaken field control parameter is incorrect. (The last digit expresses the physical axis number.)	Setting error	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).
		5303	The weaken field control parameter is incorrect. (The last digit expresses the physical axis number.)	Setting error	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).
		5304	The weaken field control parameter is incorrect. (The last digit expresses the physical axis number.)	Setting error	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).
		5305	The weaken field control parameter is incorrect. (The last digit expresses the physical axis number.)	Setting error	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		5306	The weaken field control parameter is incorrect. (The last digit expresses the physical axis number.)	Setting error	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		5307	The weaken field control parameter is incorrect. (The last digit expresses the physical axis number.)	Setting error	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		5308	The weaken field control parameter is incorrect. (The last digit expresses the physical axis number.)	Setting error	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy
Number		Code			
		5309	The weaken field control parameter is incorrect. (The last digit expresses the physical axis number.)	Setting error	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		5401	The weaken field control parameter is incorrect. (The last digit expresses the physical axis number.)	Setting error	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		5402	The weaken field control parameter is incorrect. (The last digit expresses the physical axis number.)	Setting error	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		5403	The weaken field control parameter is incorrect. (The last digit expresses the physical axis number.)	Setting error	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		5404	The weaken field control parameter is incorrect. (The last digit expresses the physical axis number.)	Setting error	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		5405	The weaken field control parameter is incorrect. (The last digit expresses the physical axis number.)	Setting error	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		5406	The weaken field control parameter is incorrect. (The last digit expresses the physical axis number.)	Setting error	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		5407	The weaken field control parameter is incorrect. (The last digit expresses the physical axis number.)	Setting error	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		5408	The weaken field control parameter is incorrect. (The last digit expresses the physical axis number.)	Setting error	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		5409	The weaken field control parameter is incorrect. (The last digit expresses the physical axis number.)	Setting error	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy	
Number		Code				
		5501	The weaken field control parameter is incorrect. (The last digit expresses the physical axis number.)	Setting error	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		5502	The weaken field control parameter is incorrect. (The last digit expresses the physical axis number.)	Setting error	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		5503	The weaken field control parameter is incorrect. (The last digit expresses the physical axis number.)	Setting error	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).	9 <u>9</u>
		5504	The weaken field control parameter is incorrect. (The last digit expresses the physical axis number.)	Setting error	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).	Alarm
		5505	The weaken field control parameter is incorrect. (The last digit expresses the physical axis number.)	Setting error	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).	Message
		5506	The weaken field control parameter is incorrect. (The last digit expresses the physical axis number.)	Setting error	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).	
		5507	The weaken field control parameter is incorrect. (The last digit expresses the physical axis number.)	Setting error	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		5508	The weaken field control parameter is incorrect. (The last digit expresses the physical axis number.)	Setting error	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		5509	The weaken field control parameter is incorrect. (The last digit expresses the physical axis number.)	Setting error	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		6101	Calculation results of the weaken field control parameter is incorrect. (The last digit expresses the physical axis number.)	Setting error	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).	

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy	
Number		Code				
		6102	Calculation results of the weaken field control parameter is incorrect. (The last digit expresses the physical axis number.)	Setting error	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		6103	Calculation results of the weaken field control parameter is incorrect. (The last digit expresses the physical axis number.)	Setting error	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		6104	Calculation results of the weaken field control parameter is incorrect. (The last digit expresses the physical axis number.)	Setting error	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	9. Ala 9.4 Ala
		6105	Calculation results of the weaken field control parameter is incorrect. (The last digit expresses the physical axis number.)	Setting error	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	rm rm Messag
		6106	Calculation results of the weaken field control parameter is incorrect. (The last digit expresses the physical axis number.)	Setting error	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	e List
		6107	Calculation results of the weaken field control parameter is incorrect. (The last digit expresses the physical axis number.)	Setting error	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		6108	Calculation results of the weaken field control parameter is incorrect. (The last digit expresses the physical axis number.)	Setting error	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		6109	Calculation results of the weaken field control parameter is incorrect. (The last digit expresses the physical axis number.)	Setting error	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
Alarm	Alarm Name	Sub	Meaning	Cause	Remedy	
--------	------------	------	--	---------------	---	---------------------
Number		Code				
		6201	Calculation results of the weaken field control parameter is incorrect. (The last digit expresses the physical axis number.)	Setting error	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		6202	Calculation results of the weaken field control parameter is incorrect. (The last digit expresses the physical axis number.)	Setting error	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		6203	Calculation results of the weaken field control parameter is incorrect. (The last digit expresses the physical axis number.)	Setting error	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	9. Alai 9.4 Alai
		6204	Calculation results of the weaken field control parameter is incorrect. (The last digit expresses the physical axis number.)	Setting error	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	rm Messag
		6205	Calculation results of the weaken field control parameter is incorrect. (The last digit expresses the physical axis number.)	Setting error	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	e List
		6206	Calculation results of the weaken field control parameter is incorrect. (The last digit expresses the physical axis number.)	Setting error	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		6207	Calculation results of the weaken field control parameter is incorrect. (The last digit expresses the physical axis number.)	Setting error	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		6208	Calculation results of the weaken field control parameter is incorrect. (The last digit expresses the physical axis number.)	Setting error	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy	
Number		Code				
		6209	Calculation results of the weaken field control parameter is incorrect. (The last digit expresses the physical axis number.)	Setting error	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		6401	Calculation results of the weaken field control parameter is incorrect. (The last digit expresses the physical axis number.)	Setting error	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		6402	Calculation results of the weaken field control parameter is incorrect. (The last digit expresses the physical axis number.)	Setting error	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	9. Ala 9.4 Ala
		6403	Calculation results of the weaken field control parameter is incorrect. (The last digit expresses the physical axis number.)	Setting error	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	rm Messag
		6404	Calculation results of the weaken field control parameter is incorrect. (The last digit expresses the physical axis number.)	Setting error	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	le List
		6405	Calculation results of the weaken field control parameter is incorrect. (The last digit expresses the physical axis number.)	Setting error	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		6406	Calculation results of the weaken field control parameter is incorrect. (The last digit expresses the physical axis number.)	Setting error	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).	
		6407	Calculation results of the weaken field control parameter is incorrect. (The last digit expresses the physical axis number.)	Setting error	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy
Number		Code			
		6408	Calculation results of the weaken field control parameter is incorrect. (The last digit expresses the physical axis number.)	Setting error	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		6409	Calculation results of the weaken field control parameter is incorrect. (The last digit expresses the physical axis number.)	Setting error	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		6501	Calculation results of the weaken field control parameter is incorrect. (The last digit expresses the physical axis number.)	Setting error	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		6502	Calculation results of the weaken field control parameter is incorrect. (The last digit expresses the physical axis number.)	Setting error	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		6503	Calculation results of the weaken field control parameter is incorrect. (The last digit expresses the physical axis number.)	Setting error	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		6504	Calculation results of the weaken field control parameter is incorrect. (The last digit expresses the physical axis number.)	Setting error	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		6505	Calculation results of the weaken field control parameter is incorrect. (The last digit expresses the physical axis number.)	Setting error	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		6506	Calculation results of the weaken field control parameter is incorrect. (The last digit expresses the physical axis number.)	Setting error	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy	
Number		Code				
		6507	Calculation results of the weaken field control parameter is incorrect. (The last digit expresses the physical axis number.)	Setting error	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).	
		6508	Calculation results of the weaken field control parameter is incorrect. (The last digit expresses the physical axis number.)	Setting error	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).	
		6509	Calculation results of the weaken field control parameter is incorrect. (The last digit expresses the physical axis number.)	Setting error	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).	9. Ala 9.4 Ala
		7201	Interpolation cycle is shorter than the set value. (The last digit expresses the physical axis of the alarm occurrence.)	Software operation error occurred	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).	rm Messag
		7202	Interpolation cycle is shorter than the set value. (The last digit expresses the physical axis of the alarm occurrence.)	Software operation error occurred	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).	e List
		7203	Interpolation cycle is shorter than the set value. (The last digit expresses the physical axis of the alarm occurrence.)	Software operation error occurred	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).	
		7204	Interpolation cycle is shorter than the set value. (The last digit expresses the physical axis of the alarm occurrence.)	Software operation error occurred	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).	
		7205	Interpolation cycle is shorter than the set value. (The last digit expresses the physical axis of the alarm occurrence.)	Software operation error occurred	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).	

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy
Number		Code			
		7206	Interpolation cycle is shorter than the set value. (The last digit expresses the physical axis of the alarm occurrence.)	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		7207	Interpolation cycle is shorter than the set value. (The last digit expresses the physical axis of the alarm occurrence.)	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		7208	Interpolation cycle is shorter than the set value. (The last digit expresses the physical axis of the alarm occurrence.)	Software operation error occurred	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).
		7209	Interpolation cycle is shorter than the set value. (The last digit expresses the physical axis of the alarm occurrence.)	Software operation error occurred	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).
1200	HIGH TEMPERATURE (IN CNTL BOX)			The temperature rises in the controller	If the LED (OHT) on the YPS power unit lights up, wait until the inside of the controller has got cool and then turn the power OFF then back ON.
				Connection failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, check the connection of the following cable.</li> <li>YPS-CN159</li> <li>MAKER LIO board (TYPE:LIO-08RT1) -CN1</li> </ul>
				YPS unit failure	<ul><li>(1)Turn the power OFF then back ON.</li><li>(2)If the alarm occurs again, replace the following unit.</li><li>YPS unit</li></ul>
1204	COMMUNICATION ERROR (OPTION MODULE)		The communication error slot (Serial-bus-connected Option module communication station No.) is displayed by the bit. 0: correct / 1: incorrect	Connection failure	Check the connecting or inserting state of the followings. •Option modules of the corresponding slot. •Option module cables of the corresponding slot.
				IO module failure	Replace the I/O module of the corresponding station number.
				Power supply broken	Replace the 24V power supply supplied to the I/O module of the corresponding station number.
				Main CPU board broken	Save the CMOS.BIN file. Replace the Main CPU board, and then load the saved CMOS.BIN file.
1220	LAN COMMUNICATION PARAMETER ERROR	1	Incorrect setting of the IP address which is used in the Ethernet function.	Setting error	<ul><li>(1)Check the following settings.</li><li>IP address setting of network in maintenance mode</li></ul>

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy	
Number		Code				
		2	Incorrect setting of the sub net mask which is used in the Ethernet function.	Setting error	<ul><li>(1)Check the following settings.</li><li>Sub net mask of network in maintenance mode</li></ul>	
		3	Incorrect setting of the default gateway which is used in the Ethernet function.	Setting error	<ul><li>(1)Check the following settings.</li><li>Default gateway of network in maintenance mode</li></ul>	
		4	Incorrect setting of the host address which is used in the Ethernet function.	Setting error	<ul><li>(1)Check the following settings.</li><li>Server (host) of network in maintenance mode</li></ul>	
		70	Incorrect setting of the host name which is used in the Ethernet function.	Setting error	<ul><li>(1)Check the following settings.</li><li>Host name of network in maintenance mode</li></ul>	9. 9.4
		75	Incorrect setting of the domain which is used in the Ethernet function.	Setting error	<ul><li>(1)Check the following settings.</li><li>Domain name of network in maintenance mode</li></ul>	Alarn Alarn
1221	ETHERNET INITIAL PROCESS ERROR	1	An error occurred in the device initialization process of the Ethernet function.	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	n n Messag
				Main CPU board failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the CPU-201R board. Save the CMOS.BIN before replace the board to be safe. Replace the CPU-201R board, and then Please execute the update. And, please load CMOS.BIN.</li> </ul>	je List
		2	An error occurred in the IP address setting process of the Ethernet function.	Setting error	<ul><li>(1)Check the following settings.</li><li>IP address setting of network in maintenance mode"</li></ul>	
				Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
				Main CPU board failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the CPU-201R board. Save the CMOS.BIN before replace the board to be safe. Replace the CPU-201R board, and then Please execute the update. And, please load CMOS.BIN.</li> </ul>	
		3	An error occurred in the sub net mask setting process of the Ethernet function.	Setting error	<ul><li>(1)Check the following settings.</li><li>Sub net mask of network in maintenance mode</li></ul>	
				Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy
Number		Code			
				Main CPU board failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the CPU-201R board. Save the CMOS.BIN before replace the board to be safe. Replace the CPU-201R board, and then Please execute the update. And, please load CMOS.BIN.</li> </ul>
		4	An error occurred in the default gateway setting process of the Ethernet function.	Setting error	<ul><li>(1)Check the following settings.</li><li>Default gateway of network in maintenance mode</li></ul>
				Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
				Main CPU board failure	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, replace the CPU-201R board. Save the CMOS.BIN before replace the board to be safe. Replace the CPU-201R board, and then Please execute the update. And, please load CMOS.BIN.
		5	An error occurred in the host name setting process of the Ethernet function.	Setting error	<ul><li>(1)Check the following settings.</li><li>Server (host) of network in maintenance mode</li></ul>
				Software operation error occurred	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).
				Main CPU board failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the CPU-201R board. Save the CMOS.BIN before replace the board to be safe. Replace the CPU-201R board, and then Please execute the update. And, please load CMOS.BIN.</li> </ul>
		6	An error occurred in the MAC address getting process of the Ethernet function.	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
				Main CPU board failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the CPU-201R board. Save the CMOS.BIN before replace the board to be safe. Replace the CPU-201R board, and then Please execute the update. And, please load CMOS.BIN.</li> </ul>
		20	An error occurred in the Web server task creating process of the Ethernet function.	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
				Main CPU board failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the CPU-201R board. Save the CMOS.BIN before replace the board to be safe. Replace the CPU-201R board, and then Please execute the update. And, please load CMOS.BIN.</li> </ul>

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy
Number		Code			
		21	An error occurred in the FTP server task creating process of the Ethernet function.	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
				Main CPU board failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the CPU-201R board. Save the CMOS.BIN before replace the board to be safe. Replace the CPU-201R board, and then Please execute the update. And, please load CMOS.BIN.</li> </ul>
		22	An error occurred in the FTP client task creating process of the Ethernet function.	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
				Main CPU board failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the CPU-201R board. Save the CMOS.BIN before replace the board to be safe. Replace the CPU-201R board, and then Please execute the update. And, please load CMOS.BIN.</li> </ul>
		30	An error occurred in the semaphore generation process for access exclusion of the Ethernet function.	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
				Main CPU board failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the CPU-201R board. Save the CMOS.BIN before replace the board to be safe. Replace the CPU-201R board, and then Please execute the update. And, please load CMOS.BIN.</li> </ul>
		50	An error occurred in the Web server task management ID getting process of the Ethernet function.	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
				Main CPU board failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the CPU-201R board. Save the CMOS.BIN before replace the board to be safe. Replace the CPU-201R board, and then Please execute the update. And, please load CMOS.BIN.</li> </ul>
		51	An error occurred in the FTP server task management ID getting process of the Ethernet function.	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
				Main CPU board failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the CPU-201R board. Save the CMOS.BIN before replace the board to be safe. Replace the CPU-201R board, and then Please execute the update. And, please load CMOS.BIN.</li> </ul>

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy
Number		Code			
1301	COMMUNICATION ERROR (SERVO)	0	Communication status error	Connection failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, check the connection and insertion of the following cables and connectors.</li> <li>EAXA01-CN515</li> <li>CPU-201R-CN1</li> </ul>
				Circuit board failure (YPU unit)	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2) If the alarm occurs again, check the LED of the YPS01 power unit: If any of the following red LED indications; +5V or +24V, FAN, OHT has lighten up, replace the YPS01 power unit.</li> </ul>
				Servo control circuit board failure	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, replace the EAXA, EAXB board. Save the CMOS.BIN before replacing the board to be safe.9
				Main CPU board failure	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, replace the CPU-201R board. Save the CMOS.BIN before replace the board to be safe. Replace the CPU-201R board, and then Please execute the update. And, please load CMOS.BIN.
		1	Watchdog timer error	Connection failure	(1)Turn the power OFF then back ON.       Construction         (2)If the alarm occurs again, check the connection and insertion of the following cables and connectors.       So the construction of the following cables and connectors.         • EAXA01-CN515       Construction         • CPU-201R-CN1       Construction
				Circuit board failure (YPU unit)	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2) If the alarm occurs again, check the LED of the YPS01 power unit: If any of the following red LED indications; +5V or +24V, FAN, OHT has lighten up, replace the YPS01 power unit.</li> </ul>
				Servo control circuit board failure	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, replace the EAXA, EAXB board. Save the CMOS.BIN before replacing the board to be safe.
				Main CPU board failure	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, replace the CPU-201R board. Save the CMOS.BIN before replace the board to be safe. Replace the CPU-201R board, and then Please execute the update. And, please load CMOS.BIN.
		2	JL0101 alarm	Connection failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, check the connection and insertion of the following cables and connectors.</li> <li>EAXA01-CN515</li> <li>CPU-201R-CN1</li> </ul>
				Circuit board failure (YPU unit)	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2) If the alarm occurs again, check the LED of the YPS01 power unit: If any of the following red LED indications; +5V or +24V, FAN, OHT has lighten up, replace the YPS01 power unit.</li> </ul>

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy
Number		Code			
				Servo control circuit board failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the EAXA, EAXB board. Save the CMOS.BIN before replacing the board to be safe.</li> </ul>
				Main CPU board failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the CPU-201R board. Save the CMOS.BIN before replace the board to be safe. Replace the CPU-201R board, and then Please execute the update. And, please load CMOS.BIN.</li> </ul>
		3	Communication status error	Connection failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, check the connection and insertion of the following cables and connectors.</li> <li>EAXA01-CN515</li> <li>CPU-201R-CN1</li> </ul>
				Circuit board failure (YPU unit)	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2) If the alarm occurs again, check the LED of the YPS01 power unit: If any of the following red LED indications; +5V or +24V, FAN, OHT has lighten up, replace the YPS01 power unit.</li> </ul>
				Servo control circuit board failure	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, replace the EAXA, EAXB board. Save the CMOS.BIN before replacing the board to be safe.
				Main CPU board failure	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, replace the CPU-201R board. Save the CMOS.BIN before replace the board to be safe. Replace the CPU-201R board, and then Please execute the update. And, please load CMOS.BIN.
		4	Data consistency error	Connection failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, check the connection and insertion of the following cables and connectors.</li> <li>EAXA01-CN515</li> <li>CPU-201R-CN1</li> </ul>
				Circuit board failure (YPU unit)	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2) If the alarm occurs again, check the LED of the YPS01 power unit: If any of the following red LED indications; +5V or +24V, FAN, OHT has lighten up, replace the YPS01 power unit.</li> </ul>
				Servo control circuit board failure	<ul><li>(1)Turn the power OFF then back ON.</li><li>(2)If the alarm occurs again, replace the EAXA, EAXB board. Save the CMOS.BIN before replacing the board to be safe.</li></ul>
				Main CPU board failure	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, replace the CPU-201R board. Save the CMOS.BIN before replace the board to be safe. Replace the CPU-201R board, and then Please execute the update. And, please load CMOS.BIN.

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy	
Number		Code				
				Software operation error occurred	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).	
		0110	The communications loop back value of the robot interface board (CPU-201R) communications is incorrect. (Communication loop back)	Connection failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, check the connection and insertion of the following cables and connectors.</li> <li>EAXA01-CN515</li> <li>CPU-201R -CN1</li> </ul>	
				YPS unit failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2) If the alarm occurs again, check the LED of the YPS01 power unit: If any of the following red LED indications; +5V or +24V, FAN, OHT has lighten up, replace the YPS01 power unit.</li> </ul>	9.4
				Servo control circuit board failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the EAXA, EAXB board. Save the CMOS.BIN before replacing the board to be safe</li> </ul>	Alarm Alarm
				CPU-201R board failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the CPU-201R board. Save the CMOS.BIN before replace the board to be safe. Replace the CPU-201R board, and then Please execute the update. And, please load CMOS.BIN.</li> </ul>	Message
1303	ARITHMETIC ERROR (SERVO)		The data [X] indicates the generation process. 10000: Observer control 20000: High-precision path control 30000: Dynamics 40000: Disturbance observer control 50000: Dislocation detect The data [_YYY_] indicates the alarm contents. The data [Z] indicates the physical axis number.	Tool file setting error	(1)Check the following settings. Reexamine the tool file setting. (Check the units of mass and center of gravity, positive/negative signs.)	List
				Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
				Motor load error	(1)Check the followings. Overload is applied to the manipulator. Correct the tools, the work pieces, and the drive condition.	
1304	EX-AXIS BOARD NOT INSTALLED			Setting error	(1)Check the following settings. Check the parameter setting of external axis selection.	

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy
Number		Code			
				Connection failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, check the connection and insertion of the following cables and connectors.</li> <li>EAXA01-CNAX-EAXB01</li> </ul>
				Servo control circuit board failure	<ul><li>(1)Turn the power OFF then back ON.</li><li>(2)If the alarm occurs again, replace the EAXB board. Save the CMOS.BIN before replace the board to be safe.</li></ul>
				Servo control circuit board failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the EAXA board. Save the CMOS.BIN before replace the board to be safe.</li> </ul>
1306	AMPLIFIER TYPE MISMATCH		subcode: Signifies the axis in which the alarm occurred	Setting error	<ul> <li>(1)Check the following settings.</li> <li>Check the current capacity of the amplifier before/after replacement by the model described in board.</li> <li>When the external axis is mounted, check if there is no difference between the amplifier selected at configuration and the amplifier that is actually mounted. Reference parameter: after SVPxG232</li> </ul>
				Connection failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, check the connection and inserting state of the following cables and connectors.</li> <li>EAXA01-CN501-506</li> <li>EAXB01-CN531,532,533</li> <li>Amplifier -CN581,582</li> <li>EX1SV(External axis servo pack) -CN591,592,595</li> <li>SGDM -CN1</li> </ul>
				Module failure (amplifier)	<ul><li>(1)Turn the power OFF then back ON.</li><li>(2)If the alarm occurs again, replace the amplifier.</li></ul>
				Servo control circuit board failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the EAXA, EAXB board. Save the CMOS.BIN before replacing the board to be safe.</li> </ul>
1307	ENCODER TYPE MISMATCH		subcode: Signifies the axis in which the alarm occurred	Setting error	<ul> <li>(1)Check the following settings.</li> <li>Check the motor type before and after the replacement.</li> <li>When the external axis is mounted, check if there is no difference between the motor selected at configuration and the motor that is actually mounted.</li> </ul>
				Connection failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, check the connection and inserting state of the following cables and connectors.</li> <li>[Robot axis]</li> <li>Cables between encoders</li> <li>EAXA-CN508</li> <li>[External axis]</li> <li>Cables between encoders</li> <li>EAXB-CN534,535,536</li> </ul>

<u>9</u>.

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy	
Number		Code				
				Module failure (encoder)	<ul><li>(1)Turn the power OFF then back ON.</li><li>(2)If the alarm occurs again, replace the encoder.</li></ul>	
				Servo control circuit board failure	<ul><li>(1)Turn the power OFF then back ON.</li><li>(2)If the alarm occurs again, replace the EAXA, EAXB board. Save the CMOS.BIN before replacing the board to be safe.</li></ul>	
				Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
1308	CONVERTER TYPE MISMATCH		subcode: Signifies the converter in which the alarm occurred	Setting error	<ul> <li>(1)Check the following settings.</li> <li>Check the current capacity of the amplifier before/after replacement by the model described in board.</li> <li>When the external axis is mounted, check if there is no difference between the converter selected at configuration and the converter that is actually mounted. Reference parameter: after SVCxB060 ~</li> </ul>	9. Alarr 9.4 Alarr
				Connection failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, check the connection and insertion of the following cables and connectors.</li> <li>EAXA01-CN507,510</li> <li>EAXB01-CN531,532,533</li> <li>Converter-CN551,553</li> <li>EX1SV(External axis servo pack)-CN591,592</li> </ul>	n n Message List
				Converter unit failure	<ul><li>(1)Turn the power OFF then back ON.</li><li>(2)If the alarm occurs again, replace the Converter unit.</li></ul>	
				Servo control circuit board failure	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, replace the EAXA, EAXB board. Save the CMOS.BIN before replacing the board to be safe.	
				Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
1309	HARDWARE ERROR (CONVERTER)		subcode: Signifies the converter physical number in which the alarm occurred	Module failure (converter)	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, replace the converter.	
1310	CHARGE ERROR (CONVERTER)		subcode: Signifies the converter physical number in which the alarm occurred	Module failure (converter)	<ul><li>(1)Turn the power OFF then back ON.</li><li>(2)If the alarm occurs again, replace the converter.</li></ul>	
				Primary power failure	Check if the primary power supply voltage does not drop with a tester, and so on.	

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy
Number		Code			
1311	A/D DETECTION ERROR (CONVERTER)		subcode: Signifies the converter physical number in which the alarm occurred	Converter unit failure	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, replace the converter.
1312	ID ERROR (CONVERTER)		subcode: Signifies the converter in which the alarm occurred	Module failure (converter)	<ul><li>(1)Turn the power OFF then back ON.</li><li>(2)If the alarm occurs again, replace the converter.</li></ul>
1321	BRAKE BOARD ERROR			Connection failure	Check the connection of wiring around the brake circuit board.
1322	BRAKE BOARD STICKING			Connection failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, check the connection and insertion of the following cables and connectors.</li> <li>NBP - CN14 ~ AXA-CN514</li> <li>YBP-CN413 ~ AXA-CN514</li> </ul>
				Module failure (brake)	<ul><li>(1)Turn the power OFF then back ON.</li><li>(2)If the alarm occurs again, replace the Brake power supply unit (NBP or YBP).</li></ul>
1325	COMMUNICATION ERROR (ENCODER)		subcode: Signifies the axis in which the alarm occurred	Connection failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, check the connection and inserting state of the following cables and connectors.</li> <li>[Robot axis]</li> <li>Cables between encoders</li> <li>EAXA-CN508</li> <li>[External axis]</li> <li>Cables between encoders</li> <li>EAXB-CN534,535,536</li> </ul>
				Module failure (encoder)	<ul><li>(1)Turn the power OFF then back ON.</li><li>(2)If the alarm occurs again, replace the encoder.</li></ul>
				Servo control circuit board failure	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, replace the EAXA,EAXB board. Save the CMOS.BIN before replace the board to be safe.
1326	DEFECTIVE ENCODER ABSOLUTE DATA		subcode: Signifies the axis in which the alarm occurred	Connection failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, check the connection and insertion of the following cables and connectors.</li> <li>EAXA01-CN508</li> <li>EAXB01-CN534,535,536</li> </ul>
				Module failure (encoder)	<ul><li>(1)Check the following settings.</li><li>Replace the defective motor (encoder).</li><li>Check the position after the alarm.</li></ul>
				Servo control circuit board failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the EAXA,EAXB board. Save the CMOS.BIN before replace the board to be safe.</li> </ul>

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy	
Number		Code				
				External environment	<ul> <li>(1)Check the following settings.</li> <li>Check the grounding condition of Manipulator.</li> <li>Check whether it is installed into the strong magnetic field.</li> <li>Check the position after the alarm.</li> </ul>	
1327	ENCODER OVER SPEED		subcode: Signifies the axis in which the alarm occurred	Connection failure	(1)Turn the power OFF then back ON.         (2)If the alarm occurs again, check the connection and inserting state of the following cables and connectors.         [Robot axis]         • Cables between encoders         • EAXA-CN508         [External axis]         • Cables between encoders         • EAXB-CN534,535,536	9. <i>1</i> 9.4 <i>1</i>
				Encoder failure	Replace the defective motor (encoder).	A a
				Servo control circuit board failure	(1)Check the following settings. Check whether to find error in the brake slip and the brake control relay.	rm M
1328	DEFECTIVE ENCODER		subcode: Signifies the axis in which the alarm occurred	Connection failure	(1)Turn the power OFF then back ON.       (2)         (2)If the alarm occurs again, check the connection and inserting state of the following cables and connectors.       (2)         [Robot axis]       • Cables between encoders       (2)         • CASHES between encoders       (2)         • EAXB-CN534,535,536       (2)	essage List
				Module failure (encoder)	<ul><li>(1)Turn the power OFF then back ON.</li><li>(2)If the alarm occurs again, replace the encoder.</li></ul>	
				Servo control circuit board failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the EAXA,EAXB board. Save the CMOS.BIN before replace the board to be safe.</li> </ul>	
1329	DEFECTIVE SERIAL ENCODER COMMAND		subcode: Signifies the axis in which the alarm occurred	Connection failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, check the connection and inserting state of the following cables and connectors.</li> <li>[Robot axis]</li> <li>Cables between encoders</li> <li>EAXA-CN508</li> <li>[External axis]</li> <li>Cables between encoders</li> <li>EAXB-CN534,535,536</li> </ul>	
				Module failure (encoder)	<ul><li>(1)Turn the power OFF then back ON.</li><li>(2)If the alarm occurs again, replace the encoder.</li></ul>	

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy
Number		Code			
				Servo control circuit board failure	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, replace the EAXA,EAXB board. Save the CMOS.BIN before replace the board to be safe.
1330	MICRO PROGRAM TRANSMIT ERROR		subcode: Signifies the axis in which the alarm occurred	Servo control circuit board failure	<ul><li>(1)Turn the power OFF then back ON.</li><li>(2)If the alarm occurs again, replace the EAXA,EAXB board. Save the CMOS.BIN before replace the board to be safe.</li></ul>
1335	ENCODER NOT RESET		subcode: Signifies the axis in which the alarm occurred	Connection failure	(1)Turn the power OFF then back ON.         (2)If the alarm occurs again, check the connection and insertion of the following cables and connectors.         [Robot axis]         • Cable between encoders         • EAXA-CN508         [External axis]         • Cable between encoders         • EAXB-CN0531,532,533
				Battery failure	[Robot axis]       Image: Constraint of the manipulator.         Replace the battery inside the manipulator.       Image: Constraint of the manipulator.         [External axis]       Image: Constraint of the manipulator.         Check the voltage of external axis battery.       Image: Constraint of the manipulator.
				Connection failure	(1)Check the battery cables.(2)Replace the battery cables if it is damaged.
				Module failure (encoder)	<ul><li>(1)Turn the power OFF then back ON.</li><li>(2)If the alarm occurs again, replace the encoder.</li></ul>
				Servo control circuit board failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the EAXA,EAXB board. Save the CMOS.BIN before replace the board to be safe.</li> </ul>
1343	COMMUNICATION ERROR (CONVERTER)	101	Communication status error (The first digit shows the converter No.)	Connection failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, check the connection and insertion of the following cables and connectors.</li> <li>EAXA01-CN507,510</li> <li>EAXB01-CN531,532,533</li> <li>Converter-CN551,553</li> <li>EX1SV(External axis servo pack)-CN591,592</li> </ul>
				Module failure (converter)	<ul><li>(1)Turn the power OFF then back ON.</li><li>(2)If the alarm occurs again, replace the converter.</li></ul>
				Servo control circuit board failure	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, replace the EAXA, EAXB board. Save the CMOS.BIN before replacing the board to be safe.

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy	
Number		Code				
		201	Communication status error (The first digit shows the converter No.)	Connection failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, check the connection and insertion of the following cables and connectors.</li> <li>EAXA01-CN507,510</li> <li>EAXB01-CN531,532,533</li> <li>Converter-CN551,553</li> <li>EX1SV(External axis servo pack)-CN591,592</li> </ul>	
				Module failure (converter)	<ul><li>(1)Turn the power OFF then back ON.</li><li>(2)If the alarm occurs again, replace the converter.</li></ul>	
				Servo control circuit board failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the EAXA, EAXB board. Save the CMOS.BIN before replacing the board to be safe.</li> </ul>	9. 9.4
		301	Communication status error (The first digit shows the converter No.)	Connection failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, check the connection and insertion of the following cables and connectors.</li> <li>EAXA01-CN507,510</li> <li>EAXB01-CN531,532,533</li> <li>Converter-CN551,553</li> <li>EX1SV(External axis servo pack)-CN591,592</li> </ul>	Alarm Alarm Messag
				Module failure (converter)	<ul><li>(1)Turn the power OFF then back ON.</li><li>(2)If the alarm occurs again, replace the converter.</li></ul>	le Lis
				Servo control circuit board failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the EAXA, EAXB board. Save the CMOS.BIN before replacing the board to be safe.</li> </ul>	4
		401	Communication status error (The first digit shows the converter No.)	Connection failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, check the connection and insertion of the following cables and connectors.</li> <li>EAXA01-CN507,510</li> <li>EAXB01-CN531,532,533</li> <li>Converter-CN551,553</li> <li>EX1SV(External axis servo pack)-CN591,592</li> </ul>	
				Module failure (converter)	<ul><li>(1)Turn the power OFF then back ON.</li><li>(2)If the alarm occurs again, replace the converter.</li></ul>	
				Servo control circuit board failure	<ul><li>(1)Turn the power OFF then back ON.</li><li>(2)If the alarm occurs again, replace the EAXA, EAXB board. Save the CMOS.BIN before replacing the board to be safe.</li></ul>	

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy
Number		Code			
		501	Communication status error (The first digit shows the converter No.)	Connection failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, check the connection and insertion of the following cables and connectors.</li> <li>EAXA01-CN507,510</li> <li>EAXB01-CN531,532,533</li> <li>Converter-CN551,553</li> <li>EX1SV(External axis servo pack)-CN591,592</li> </ul>
				Module failure (converter)	<ul><li>(1)Turn the power OFF then back ON.</li><li>(2)If the alarm occurs again, replace the converter.</li></ul>
				Servo control circuit board failure	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, replace the EAXA, EAXB board. Save the CMOS.BIN before replacing the board to be safe.
		601	Communication status error (The first digit shows the converter No.)	Connection failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, check the connection and insertion of the following cables and connectors.</li> <li>EAXA01-CN507,510</li> <li>EAXB01-CN531,532,533</li> <li>Converter-CN551,553</li> <li>EX1SV(External axis servo pack)-CN591,592</li> </ul>
				Module failure (converter)	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, replace the converter.
				Servo control circuit board failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the EAXA, EAXB board. Save the CMOS.BIN before replacing the board to be safe.</li> </ul>
		102	Command time-out (The first digit shows the converter No.)	Connection failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, check the connection and insertion of the following cables and connectors.</li> <li>EAXA01-CN507,510</li> <li>EAXB01-CN531,532,533</li> <li>Converter-CN551,553</li> <li>EX1SV(External axis servo pack)-CN591,592</li> </ul>
				Module failure (converter)	<ul><li>(1)Turn the power OFF then back ON.</li><li>(2)If the alarm occurs again, replace the converter.</li></ul>
				Servo control circuit board failure	<ul><li>(1)Turn the power OFF then back ON.</li><li>(2)If the alarm occurs again, replace the EAXA, EAXB board. Save the CMOS.BIN before replacing the board to be safe.</li></ul>
				Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy
Number		Code			
		202	Command time-out (The first digit shows the converter No.)	Connection failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, check the connection and insertion of the following cables and connectors.</li> <li>EAXA01-CN507,510</li> <li>EAXB01-CN531,532,533</li> <li>Converter-CN551,553</li> <li>EX1SV(External axis servo pack)-CN591,592</li> </ul>
				Module failure (converter)	<ul><li>(1)Turn the power OFF then back ON.</li><li>(2)If the alarm occurs again, replace the converter.</li></ul>
				Servo control circuit board failure	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, replace the EAXA, EAXB board. Save the CMOS.BIN before replacing the board to be safe.
				Software operation error occurred	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).
		302	Command time-out (The first digit shows the converter No.)	Connection failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, check the connection and insertion of the following cables and connectors.</li> <li>EAXA01-CN507,510</li> <li>EAXB01-CN531,532,533</li> <li>Converter-CN551,553</li> <li>EX1SV(External axis servo pack)-CN591,592</li> </ul>
				Module failure (converter)	<ul><li>(1)Turn the power OFF then back ON.</li><li>(2)If the alarm occurs again, replace the converter.</li></ul>
				Servo control circuit board failure	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, replace the EAXA, EAXB board. Save the CMOS.BIN before replacing the board to be safe.
				Software operation error occurred	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).
		402	Command time-out (The first digit shows the converter No.)	Connection failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, check the connection and insertion of the following cables and connectors.</li> <li>EAXA01-CN507,510</li> <li>EAXB01-CN531,532,533</li> <li>Converter-CN551,553</li> <li>EX1SV(External axis servo pack)-CN591,592</li> </ul>
				Module failure (converter)	<ul><li>(1)Turn the power OFF then back ON.</li><li>(2)If the alarm occurs again, replace the converter.</li></ul>

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy
Number		Code			
				Servo control circuit board failure	<ul><li>(1)Turn the power OFF then back ON.</li><li>(2)If the alarm occurs again, replace the EAXA, EAXB board. Save the CMOS.BIN before replacing the board to be safe.</li></ul>
				Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		502	Command time-out (The first digit shows the converter No.)	Connection failure	(1)Turn the power OFF then back ON.         (2)If the alarm occurs again, check the connection and insertion of the following cables and connectors.         • EAXA01-CN507,510         • EAXB01-CN531,532,533         • Converter-CN551,553         • EX1SV(External axis servo pack)-CN591,592
				Module failure (converter)	<ul><li>(1)Turn the power OFF then back ON.</li><li>(2)If the alarm occurs again, replace the converter.</li></ul>
				Servo control circuit board failure	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, replace the EAXA, EAXB board. Save the CMOS.BIN before replacing the board to be safe.
				Software operation error occurred	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).
		602	Command time-out (The first digit shows the converter No.)	Connection failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, check the connection and insertion of the following cables and connectors.</li> <li>EAXA01-CN507,510</li> <li>EAXB01-CN531,532,533</li> <li>Converter-CN551,553</li> <li>EX1SV(External axis servo pack)-CN591,592</li> </ul>
				Module failure (converter)	<ul><li>(1)Turn the power OFF then back ON.</li><li>(2)If the alarm occurs again, replace the converter.</li></ul>
				Servo control circuit board failure	<ul><li>(1)Turn the power OFF then back ON.</li><li>(2)If the alarm occurs again, replace the EAXA, EAXB board. Save the CMOS.BIN before replacing the board to be safe.</li></ul>
				Software operation error occurred	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy	
Number		Code				
		103	Sent buffer FULL (The first digit shows the converter No.)	Connection failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, check the connection and insertion of the following cables and connectors.</li> <li>EAXA01-CN507,510</li> <li>EAXB01-CN531,532,533</li> <li>Converter-CN551,553</li> <li>EX1SV(External axis servo pack)-CN591,592</li> </ul>	
				Module failure (converter)	<ul><li>(1)Turn the power OFF then back ON.</li><li>(2)If the alarm occurs again, replace the converter.</li></ul>	
				Servo control circuit board failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the EAXA, EAXB board. Save the CMOS.BIN before replacing the board to be safe.</li> </ul>	9.4 9.4
				Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	Alarm Alarm I
		203	Sent buffer FULL (The first digit shows the converter No.)	Connection failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, check the connection and insertion of the following cables and connectors.</li> <li>EAXA01-CN507,510</li> <li>EAXB01-CN531,532,533</li> <li>Converter-CN551,553</li> <li>EX1SV(External axis servo pack)-CN591,592</li> </ul>	Message List
				Module failure (converter)	<ul><li>(1)Turn the power OFF then back ON.</li><li>(2)If the alarm occurs again, replace the converter.</li></ul>	
				Servo control circuit board failure	<ul><li>(1)Turn the power OFF then back ON.</li><li>(2)If the alarm occurs again, replace the EAXA, EAXB board. Save the CMOS.BIN before replacing the board to be safe.</li></ul>	
				Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		303	Sent buffer FULL (The first digit shows the converter No.)	Connection failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, check the connection and insertion of the following cables and connectors.</li> <li>EAXA01-CN507,510</li> <li>EAXB01-CN531,532,533</li> <li>Converter-CN551,553</li> <li>EX1SV(External axis servo pack)-CN591,592</li> </ul>	
				Module failure (converter)	<ul><li>(1)Turn the power OFF then back ON.</li><li>(2)If the alarm occurs again, replace the converter.</li></ul>	

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy
Number		Code			
				Servo control circuit board failure	<ul><li>(1)Turn the power OFF then back ON.</li><li>(2)If the alarm occurs again, replace the EAXA, EAXB board. Save the CMOS.BIN before replacing the board to be safe.</li></ul>
				Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		403	Sent buffer FULL (The first digit shows the converter No.)	Connection failure	(1)Turn the power OFF then back ON.         (2)If the alarm occurs again, check the connection and insertion of the following cables and connectors.         • EAXA01-CN507,510         • EAXB01-CN531,532,533         • Converter-CN551,553         • EX1SV(External axis servo pack)-CN591,592
				Module failure (converter)	<ul><li>(1)Turn the power OFF then back ON.</li><li>(2)If the alarm occurs again, replace the converter.</li></ul>
				Servo control circuit board failure	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, replace the EAXA, EAXB board. Save the CMOS.BIN before replacing the board to be safe.
				Software operation error occurred	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).
		503	Sent buffer FULL (The first digit shows the converter No.)	Connection failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, check the connection and insertion of the following cables and connectors.</li> <li>EAXA01-CN507,510</li> <li>EAXB01-CN531,532,533</li> <li>Converter-CN551,553</li> <li>EX1SV(External axis servo pack)-CN591,592</li> </ul>
				Module failure (converter)	<ul><li>(1)Turn the power OFF then back ON.</li><li>(2)If the alarm occurs again, replace the converter.</li></ul>
				Servo control circuit board failure	<ul><li>(1)Turn the power OFF then back ON.</li><li>(2)If the alarm occurs again, replace the EAXA, EAXB board. Save the CMOS.BIN before replacing the board to be safe.</li></ul>
				Software operation error occurred	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy
Number		Code			
		603	Sent buffer FULL (The first digit shows the converter No.)	Connection failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, check the connection and insertion of the following cables and connectors.</li> <li>EAXA01-CN507,510</li> <li>EAXB01-CN531,532,533</li> <li>Converter-CN551,553</li> <li>EX1SV(External axis servo pack)-CN591,592</li> </ul>
				Module failure (converter)	<ul><li>(1)Turn the power OFF then back ON.</li><li>(2)If the alarm occurs again, replace the converter.</li></ul>
				Servo control circuit board failure	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, replace the EAXA, EAXB board. Save the CMOS.BIN before replacing the board to be safe.
				Software operation error occurred	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).
		104	CRC-16 error (The first digit shows the converter No.)	Connection failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, check the connection and insertion of the following cables and connectors.</li> <li>EAXA01-CN507,510</li> <li>EAXB01-CN531,532,533</li> <li>Converter-CN551,553</li> <li>EX1SV(External axis servo pack)-CN591,592</li> </ul>
				Module failure (converter)	<ul><li>(1)Turn the power OFF then back ON.</li><li>(2)If the alarm occurs again, replace the converter.</li></ul>
				Servo control circuit board failure	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, replace the EAXA, EAXB board. Save the CMOS.BIN before replacing the board to be safe.
				Software operation error occurred	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).
		204	CRC-16 error (The first digit shows the converter No.)	Connection failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, check the connection and insertion of the following cables and connectors.</li> <li>EAXA01-CN507,510</li> <li>EAXB01-CN531,532,533</li> <li>Converter-CN551,553</li> <li>EX1SV(External axis servo pack)-CN591,592</li> </ul>
				Module failure (converter)	<ul><li>(1)Turn the power OFF then back ON.</li><li>(2)If the alarm occurs again, replace the converter.</li></ul>

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy
Number		Code			
				Servo control circuit board failure	<ul><li>(1)Turn the power OFF then back ON.</li><li>(2)If the alarm occurs again, replace the EAXA, EAXB board. Save the CMOS.BIN before replacing the board to be safe.</li></ul>
				Software operation error occurred	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).
		304	CRC-16 error (The first digit shows the converter No.)	Connection failure	(1)Turn the power OFF then back ON.         (2)If the alarm occurs again, check the connection and insertion of the following cables and connectors.         • EAXA01-CN507,510         • EAXB01-CN531,532,533         • Converter-CN551,553         • EX1SV(External axis servo pack)-CN591,592
				Module failure (converter)	<ul><li>(1)Turn the power OFF then back ON.</li><li>(2)If the alarm occurs again, replace the converter.</li></ul>
				Servo control circuit board failure	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, replace the EAXA, EAXB board. Save the CMOS.BIN before replacing the board to be safe.
				Software operation error occurred	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).
		404	CRC-16 error (The first digit shows the converter No.)	Connection failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, check the connection and insertion of the following cables and connectors.</li> <li>EAXA01-CN507,510</li> <li>EAXB01-CN531,532,533</li> <li>Converter-CN551,553</li> <li>EX1SV(External axis servo pack)-CN591,592</li> </ul>
				Module failure (converter)	<ul><li>(1)Turn the power OFF then back ON.</li><li>(2)If the alarm occurs again, replace the converter.</li></ul>
				Servo control circuit board failure	<ul><li>(1)Turn the power OFF then back ON.</li><li>(2)If the alarm occurs again, replace the EAXA, EAXB board. Save the CMOS.BIN before replacing the board to be safe.</li></ul>
				Software operation error occurred	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy
Number		Code			
		504	CRC-16 error (The first digit shows the converter No.)	Connection failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, check the connection and insertion of the following cables and connectors.</li> <li>EAXA01-CN507,510</li> <li>EAXB01-CN531,532,533</li> <li>Converter-CN551,553</li> <li>EX1SV(External axis servo pack)-CN591,592</li> </ul>
				Module failure (converter)	<ul><li>(1)Turn the power OFF then back ON.</li><li>(2)If the alarm occurs again, replace the converter.</li></ul>
				Servo control circuit board failure	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, replace the EAXA, EAXB board. Save the CMOS.BIN before replacing the board to be safe.
				Software operation error occurred	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).
		604	CRC-16 error (The first digit shows the converter No.)	Connection failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, check the connection and insertion of the following cables and connectors.</li> <li>EAXA01-CN507,510</li> <li>EAXB01-CN531,532,533</li> <li>Converter-CN551,553</li> <li>EX1SV(External axis servo pack)-CN591,592</li> </ul>
				Module failure (converter)	<ul><li>(1)Turn the power OFF then back ON.</li><li>(2)If the alarm occurs again, replace the converter.</li></ul>
				Servo control circuit board failure	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, replace the EAXA, EAXB board. Save the CMOS.BIN before replacing the board to be safe.
				Software operation error occurred	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).
		105	Error code received (The first digit shows the converter No)	Connection failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, check the connection and insertion of the following cables and connectors.</li> <li>EAXA01-CN507,510</li> <li>EAXB01-CN531,532,533</li> <li>Converter-CN551,553</li> <li>EX1SV(External axis servo pack)-CN591,592</li> </ul>
				Module failure (converter)	<ul><li>(1)Turn the power OFF then back ON.</li><li>(2)If the alarm occurs again, replace the converter.</li></ul>

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy	
Number		Code				
				Servo control circuit board failure	<ul><li>(1)Turn the power OFF then back ON.</li><li>(2)If the alarm occurs again, replace the EAXA, EAXB board. Save the CMOS.BIN before replacing the board to be safe.</li></ul>	
				Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		205	Error code received (The first digit shows the converter No)	Connection failure	(1)Turn the power OFF then back ON.         (2)If the alarm occurs again, check the connection and insertion of the following cables and connectors.         • EAXA01-CN507,510         • EAXB01-CN531,532,533         • Converter-CN551,553         • EX1SV(External axis servo pack)-CN591,592	9. Al 9.4 Al
				Module failure (converter)	<ul><li>(1)Turn the power OFF then back ON.</li><li>(2)If the alarm occurs again, replace the converter.</li></ul>	arm arm 1
				Servo control circuit board failure	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, replace the EAXA, EAXB board. Save the CMOS.BIN before replacing the board to be safe.	Messag
				Software operation error occurred	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).	ie List
		305	Error code received (The first digit shows the converter No)	Connection failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, check the connection and insertion of the following cables and connectors.</li> <li>EAXA01-CN507,510</li> <li>EAXB01-CN531,532,533</li> <li>Converter-CN551,553</li> <li>EX1SV(External axis servo pack)-CN591,592</li> </ul>	
				Module failure (converter)	<ul><li>(1)Turn the power OFF then back ON.</li><li>(2)If the alarm occurs again, replace the converter.</li></ul>	
				Servo control circuit board failure	<ul><li>(1)Turn the power OFF then back ON.</li><li>(2)If the alarm occurs again, replace the EAXA, EAXB board. Save the CMOS.BIN before replacing the board to be safe.</li></ul>	
				Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy
Number		Code			
		405	Error code received (The first digit shows the converter No)	Connection failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, check the connection and insertion of the following cables and connectors.</li> <li>EAXA01-CN507,510</li> <li>EAXB01-CN531,532,533</li> <li>Converter-CN551,553</li> <li>EX1SV(External axis servo pack)-CN591,592</li> </ul>
				Module failure (converter)	<ul><li>(1)Turn the power OFF then back ON.</li><li>(2)If the alarm occurs again, replace the converter.</li></ul>
				Servo control circuit board failure	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, replace the EAXA, EAXB board. Save the CMOS.BIN before replacing the board to be safe.
				Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		505	Error code received (The first digit shows the converter No)	Connection failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, check the connection and insertion of the following cables and connectors.</li> <li>EAXA01-CN507,510</li> <li>EAXB01-CN531,532,533</li> <li>Converter-CN551,553</li> <li>EX1SV(External axis servo pack)-CN591,592</li> </ul>
				Module failure (converter)	<ul><li>(1)Turn the power OFF then back ON.</li><li>(2)If the alarm occurs again, replace the converter.</li></ul>
				Servo control circuit board failure	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, replace the EAXA, EAXB board. Save the CMOS.BIN before replacing the board to be safe.
				Software operation error occurred	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).
		605	Error code received (The first digit shows the converter No)	Connection failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, check the connection and insertion of the following cables and connectors.</li> <li>EAXA01-CN507,510</li> <li>EAXB01-CN531,532,533</li> <li>Converter-CN551,553</li> <li>EX1SV(External axis servo pack)-CN591,592</li> </ul>
				Module failure (converter)	<ul><li>(1)Turn the power OFF then back ON.</li><li>(2)If the alarm occurs again, replace the converter.</li></ul>

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy
Number		Code			
				Servo control circuit board failure	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, replace the EAXA, EAXB board. Save the CMOS.BIN before replacing the board to be safe.
				Software operation error occurred	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).
		106	Received command error (The first digit shows the converter No.)	Connection failure	(1)Turn the power OFF then back ON.         (2)If the alarm occurs again, check the connection and insertion of the following cables and connectors.         • EAXA01-CN507,510         • EAXB01-CN531,532,533         • Converter-CN551,553         • EX1SV(External axis servo pack)-CN591,592
				Module failure (converter)	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, replace the converter.
				Servo control circuit board failure	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, replace the EAXA, EAXB board. Save the CMOS.BIN before replacing the board to be safe.
				Software operation error occurred	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).
		206	Received command error (The first digit shows the converter No.)	Connection failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, check the connection and insertion of the following cables and connectors.</li> <li>EAXA01-CN507,510</li> <li>EAXB01-CN531,532,533</li> <li>Converter-CN551,553</li> <li>EX1SV(External axis servo pack)-CN591,592</li> </ul>
				Module failure (converter)	<ul><li>(1)Turn the power OFF then back ON.</li><li>(2)If the alarm occurs again, replace the converter.</li></ul>
				Servo control circuit board failure	<ul><li>(1)Turn the power OFF then back ON.</li><li>(2)If the alarm occurs again, replace the EAXA, EAXB board. Save the CMOS.BIN before replacing the board to be safe.</li></ul>
				Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy
Number		Code			
		306	Received command error (The first digit shows the converter No.)	Connection failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, check the connection and insertion of the following cables and connectors.</li> <li>EAXA01-CN507,510</li> <li>EAXB01-CN531,532,533</li> <li>Converter-CN551,553</li> <li>EX1SV(External axis servo pack)-CN591,592</li> </ul>
				Module failure (converter)	<ul><li>(1)Turn the power OFF then back ON.</li><li>(2)If the alarm occurs again, replace the converter.</li></ul>
				Servo control circuit board failure	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, replace the EAXA, EAXB board. Save the CMOS.BIN before replacing the board to be safe.
				Software operation error occurred	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).
		406	Received command error (The first digit shows the converter No.)	Connection failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, check the connection and insertion of the following cables and connectors.</li> <li>EAXA01-CN507,510</li> <li>EAXB01-CN531,532,533</li> <li>Converter-CN551,553</li> <li>EX1SV(External axis servo pack)-CN591,592</li> </ul>
				Module failure (converter)	<ul><li>(1)Turn the power OFF then back ON.</li><li>(2)If the alarm occurs again, replace the converter.</li></ul>
				Servo control circuit board failure	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, replace the EAXA, EAXB board. Save the CMOS.BIN before replacing the board to be safe.
				Software operation error occurred	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).
		506	Received command error (The first digit shows the converter No.)	Connection failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, check the connection and insertion of the following cables and connectors.</li> <li>EAXA01-CN507,510</li> <li>EAXB01-CN531,532,533</li> <li>Converter-CN551,553</li> <li>EX1SV(External axis servo pack)-CN591,592</li> </ul>
				Module failure (converter)	<ul><li>(1)Turn the power OFF then back ON.</li><li>(2)If the alarm occurs again, replace the converter.</li></ul>

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy	
Number		Code				
				Servo control circuit board failure	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, replace the EAXA, EAXB board. Save the CMOS.BIN before replacing the board to be safe.	
				Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		606	Received command error (The first digit shows the converter No.)	Connection failure	(1)Turn the power OFF then back ON.         (2)If the alarm occurs again, check the connection and insertion of the following cables and connectors.         • EAXA01-CN507,510         • EAXB01-CN531,532,533         • Converter-CN551,553         • EX1SV(External axis servo pack)-CN591,592	9. Al 9.4 Al
				Module failure (converter)	<ul><li>(1)Turn the power OFF then back ON.</li><li>(2)If the alarm occurs again, replace the converter.</li></ul>	arm arm l
				Servo control circuit board failure	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, replace the EAXA, EAXB board. Save the CMOS.BIN before replacing the board to be safe.	Messag
				Software operation error occurred	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).	ye List
1349	POWER LOST DETECTION (SERVO)			Instant power failure	Check if the primary power supply voltage is dropping.	
1352	SERIAL ENCODER CORRECTION ERROR		subcode: Signifies the axis in which the alarm occurred	Connection failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, check the connection and insertion of the following cables and connectors.</li> <li>EAXA01-CN508</li> <li>EAXB01-CN534,535,536</li> </ul>	
				Module failure (encoder)	<ul><li>(1)Turn the power OFF then back ON.</li><li>(2)If the alarm occurs again, replace the encoder.</li></ul>	
				Servo control circuit board failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the EAXA, EAXB board. Save the CMOS.BIN before replacing the board to be safe.</li> </ul>	

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy	
Number		Code				
1355	SERIAL ENC MULTITURN LIMIT ERR		subcode: Signifies the axis in which the alarm occurred	Connection failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, check the connection and insertion of the following cables and connectors.</li> <li>[Robot axis]</li> <li>Cable between encoders</li> <li>EAXA-CN508</li> <li>[External axis]</li> <li>Cable between encoders</li> <li>EAXB-CN0534,535,536</li> </ul>	
				Module failure (encoder)	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, replace the encoder.	<u>ي</u> و
				Servo control circuit board failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the EAXA,EAXB board. Save the CMOS.BIN before replace the board to be safe.</li> </ul>	4 Ala
1400	ENCODER ERROR (CONVEYOR)	1	An error occurred at conveyor encoder 1.	Cable (defect), Module failure (encoder)	Replace the encoder cable or encoder of the conveyor encoder 1.	arm
		2	An error occurred at conveyor encoder 2.	Cable (defect), Module failure (encoder)	Replace the encoder cable or encoder of the conveyor encoder 2.	/less
		3	An error occurred at conveyor encoder 3.	Cable (defect), Module failure (encoder)	Replace the encoder cable or encoder of the conveyor encoder 3.	aqe I
1401	CANNOT CHANGE CONVEYOR MODE			Input error	Do not switch "Encoder / Virtual encoder" with the general signal while performing the conveyor synchronized function.	ist
1402	WORK IN/NOT DATA CNT. LMT. OVER			Work status error	Check the work in/not shift data and actual the work status within the shift area.	
1403	WORK IN/NOT SHIFT DATA POS LMT.			Work status error	Check the work in/not shift data and actual the work status within the shift area.	
1404	WORK ID. DATA CNT. LMT. OVER			Work status error	Check the work in/not shift data and actual the work status within the shift area.	
1405	WORK ID. SHIFT DATA POS LMT.			Work status error	Check the work in/not shift data and actual the work status within the shift area.	
1406	START SHIFT DATA CNT. LMT. OVER			Work status error	Check the start shift data and actual the work status within the shift area.	
1407	START SHIFT DATA POS LMT.			Work status error	Check the start shift data and actual the work status within the shift area.	
1514	OVERHEAT (AMPLIFIER)			The temperature of amplifier rose.	Turn the power OFF then back ON after cooling the amplifier.	

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy
Number		Code			
				Connection failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, check the connection and inserting state of the following cables and connectors.</li> <li>EAXA01-CN507,510</li> <li>EAXB01-CN531,532,533</li> <li>converter-CN551,553</li> <li>EX1SV(External axis servo pack)-CN591,592</li> </ul>
				Converter unit failure	<ul><li>(1)Turn the power OFF then back ON.</li><li>(2)If the alarm occurs again, replace the converter.</li></ul>
				Servo control circuit board failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the EAXA, EAXB board. Save the CMOS.BIN before replacing the board to be safe.</li> </ul>
1547	CURRENT FEEDBACK ERROR			Connection failure	Check if a ground fault has not occurred in the U-, V-, and W-phase of motor power line, or short circuit has not occurred between these phases.
				Connection failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, check the connection and inserting state of the following cables and connectors.</li> <li>EAXA01-CN501-506</li> <li>EAXB01-CN531,532,533</li> <li>Amplifier-CN581,582</li> <li>EX1SV(External axis servo pack)-CN591,592,595</li> </ul>
				Module failure (amplifier)	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, replace the amplifier.
				Module failure (motor)	<ul><li>(1)Turn the power OFF then back ON.</li><li>(2)If the alarm occurs again, replace the motor.</li></ul>
				Servo control circuit board failure	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, replace the EAXA, EAXB board. Save the CMOS.BIN before replacing the board to be safe.
1650	FILE TRANSFER DATA ERROR (SV)	1	An error occurred when the last data was not received during the first data communication at execution of motion command.	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
				Servo control circuit board failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the EAXA board. Save the CMOS.BIN before replace the board to be safe.</li> </ul>
				Main CPU board failure	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, replace the CPU-201R board. Save the CMOS.BIN before replace the board to be safe. Replace the CPU-201R board, and then Please execute the update. And, please load CMOS.BIN.

9. Alarm 9.4 Alarm Message List

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy	
Number		Code				
		2	An error occurred when the first data was not received during on the way data communication at execution of motion command.	Servo control circuit board failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the EAXA board. Save the CMOS.BIN before replace the board to be safe.</li> </ul>	
		3	An error occurred when the first data was not received during the last data communication at execution of motion command.	Servo control circuit board failure	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, replace the EAXA board. Save the CMOS.BIN before replace the board to be safe.	
1651	FILE TRANSFER DATA SIZE ERR (SV)	1	The data size for the file transfer does not agree with the received buffer size.	Servo control circuit board failure	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, replace the EAXA board. Save the CMOS.BIN before replace the board to be safe.	9 9
		2	Buffer size over	Servo control circuit board failure	(1)Turn the power OFF then back ON.       1         (2)If the alarm occurs again, replace the EAXA board. Save the CMOS.BIN before replace the board to be safe.       2	4 . <u>A A</u>
1652	DB ON ERROR (SERVO)			Servo control circuit board failure	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, replace the EAXA, EAXB board. Save the CMOS.BIN before replacing the board to be safe.	arm arm Me
				Software operation error occurred	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).	essade Li
1653	BASE BLOCK SIGNAL ERROR (SERVO)			Servo control circuit board failure	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, replace the EAXA, EAXB board. Save the CMOS.BIN before replacing the board to be safe.	st
				Software operation error occurred	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).	
				Module failure (amplifier)	<ul><li>(1)Turn the power OFF then back ON.</li><li>(2)If the alarm occurs again, replace the amplifier.</li></ul>	
1655	CONVERTER COMMAND ERROR (SV)			Software operation error occurred	<ul><li>(1)Turn the power OFF then back ON.</li><li>(2)If the error occurs again, contact your Yaskawa representative.</li></ul>	
1656	AXIS ENDLESS INFO NOT GENERATED (SV)			Setting error	<ul><li>(1)Turn the power OFF then back ON.</li><li>(2)If the error occurs again, contact your Yaskawa representative.</li></ul>	
1657	AXIS ENDLESS SPECIFIC. ERR (SV)	1	The home position detecting function was used for the axis for which the axis endless function was enabled. The home position detecting function cannot be used for the axis which the axis endless function was enabled.	Setting error	Disable the corresponding axis endless function.	

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy	
Number		Code				
		2	The servo float function was used for the axis for which the axis endless function was enabled. The servo float function cannot be used for the axis which the axis endless function was enabled.	Setting error	Disable either the axis endless function or the servo float function of corresponding axis.	-
		3	The encoders manufactured by Tamagawa Seiki Co., Ltd. was used for the axis for which the axis endless function was enabled. The encoders manufactured by Tamagawa Seiki Co., Ltd. cannot be used for the axis which the axis endless function was enabled.	Setting error	Disable the corresponding axis endless function.	9.4
		4	The general servo function was used for the axis for which the axis endless function was enabled. The general servo function cannot be used for the axis which the axis endless function was enabled.	Setting error	Disable the corresponding axis endless function.	Alarm Messa
1658	REDUCTION STOP SPECIFIC. ERR (SV)	1	The servo float function was used for the axis for which the deceleration stop function was enabled. The servo float function cannot be used for the axis which the deceleration stop function was enabled.	Setting error	Check the JOB.	ge List
		2	The specified axis speed control function was executed for the axis which the deceleration stop function was enabled. Specified axis speed control function cannot be used for the axis which the deceleration stop function was enabled.	Setting error	Check the JOB.	-
1664	MICRO PRG EXECUTE TIME OVER (SV)		subcode: specifies the axis that alarm occurred.	Servo control circuit board failure	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, replace the EAXA,EAXB board. Save the CMOS.BIN before replace the board to be safe.	
1665	MICRO PROGRAM SYNC. ERROR (SV)		subcode: specifies the axis that alarm occurred.	Servo control circuit board failure	<ul><li>(1)Turn the power OFF then back ON.</li><li>(2)If the alarm occurs again, replace the EAXA,EAXB board. Save the CMOS.BIN before replace the board to be safe.</li></ul>	

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy
Number		Code			
1666	FILE RECEIVE INCOMPLETE (SERVO)		subcode: specifies the axis that alarm occurred.	Servo control circuit board failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the EAXA board. Save the CMOS.BIN before replace the board to be safe.</li> </ul>
1667	RESOLUTION CONVERSE CONST ERR (SV)			Servo control circuit board failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the EAXA,EAXB board. Save the CMOS.BIN before replace the board to be safe.</li> </ul>
1674	CTRL LAW SWITCHING ORDER ERR (SV)		subcode: specifies the axis that alarm occurred.	Servo control circuit board failure	<ul><li>(1)Turn the power OFF then back ON.</li><li>(2)If the alarm occurs again, replace the EAXA,EAXB board. Save the CMOS.BIN before replace the board to be safe.</li></ul>
1675	BASE BLOCK READ SIGNAL ERR (SV)		subcode: specifies the axis that alarm occurred.	Servo control circuit board failure	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, replace the EAXA,EAXB board. Save the CMOS.BIN before replace the board to be safe.
1676	BASE BLOCK WRITE SIGNAL ERR (SV)			Servo control circuit board failure	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, replace the EAXA,EAXB board. Save the CMOS.BIN before replace the board to be safe.
1678	MOTOR CMD POSITION ERROR (SV)		subcode: specifies the axis that alarm occurred.	Servo control circuit board failure	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, replace the EAXA,EAXB board. Save the CMOS.BIN before replace the board to be safe.
1679	EXTERNAL BRAKE FUSE BROWN (SV)			YBK board failure	Replace the YBK01 fuse.
1680	GENERAL I/O FUSE BROWN (SV)			Servo control circuit board failure	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, replace the EAXA board. Save the CMOS.BIN before replace the board to be safe.
				Ground fault or short circuit	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, check whether neither a short circuit nor a ground fault have occurred in the I/O cables from the external devices.</li> </ul>
				Connection failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, check the connection and insertion of the following cables and connectors.</li> <li>AXA-CN509</li> <li>YPS-CN155</li> </ul>
1681	BRAKE POWER ERROR (SV)			YBK board failure	Check the power source of YBK01, and then if no fault is found, replace the brake unit.
				Ground fault or short circuit	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, check whether neither a short circuit nor a ground fault have occurred in the brake cables.</li> </ul>

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy
Number		Code			
				Connection failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, check the connection and insertion of the following cables and connectors.</li> <li>YBK-CN403,CN405</li> <li>YPS-CN153</li> <li>EAXA01-CN513</li> </ul>
1682	EXTERNAL BRAKE POWER ERROR (SV)			YBK board failure	Check the external axis brake of YBK01 in the power source, and then if no fault is found, replace the brake unit.
				Ground fault or short circuit	<ul><li>(1)Turn the power OFF then back ON.</li><li>(2)If the alarm occurs again, check whether neither a short circuit nor a ground fault have occurred in the brake cables.</li></ul>
				Connection failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, check the connection and insertion of the following cables and connectors.</li> <li>YBK-CN403CN404, CN405</li> <li>YPS-CN153</li> <li>EAXA01-CN513</li> </ul>
1684	INSTANT POWER FAILURE (TRQ) (SV)		The instant power failure occurred and then the torque was saturated.	Voltage failure	Check if the primary power supply voltage is dropping.
				Power failure	Check if the instant power failure has occurred.
1685	INSTANT POWER FAILURE (TIME) (SV)		The instant power failure occurred for longer than the certain time period.	Voltage failure	Check if the primary power supply voltage is dropping.
				Power failure	Check if the instant power failure has occurred.
1686	POS.DEVITATION SATURATING ERR (SV)			Setting error	Check the settings for manipulator motion condition (influence by external force, load condition).
				Connection failure	Check if a ground fault has not occurred in the U-, V-, and W-phase of motor power line, or short circuit has not occurred between these phases.
				Connection failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, check the connection and inserting state of the following cables and connectors.</li> <li>EAXA01-CN501-506</li> <li>EAXB01-CN531,532,533</li> <li>Amplifier-CN581,582</li> <li>EX1SV(External axis servo pack)-CN591,592,595</li> </ul>
				Module failure (motor)	<ul><li>(1)Turn the power OFF then back ON.</li><li>(2)If the alarm occurs again, replace the motor.</li></ul>
				Servo control circuit board failure	<ul><li>(1)Turn the power OFF then back ON.</li><li>(2)If the alarm occurs again, replace the EAXA, EAXB board. Save the CMOS.BIN before replace the board to be safe.</li></ul>

9. 9.4
| Alarm  | Alarm Name                         | Sub  | Meaning | Cause                                | Remedy  |           |
|--------|------------------------------------|------|---------|--------------------------------------|---|-----------|
| Number |                                    | Code |         |                                      |   |           |
|        |                                    |      |         | Module failure (amplifier)           | <ul><li>(1)Turn the power OFF then back ON.</li><li>(2)If the alarm occurs again, replace the amplifier.</li></ul>  |           |
| 1830   | CONTACTOR FB ERROR<br>(PLD1)       |      |         | Machine safety board failure         | <ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, execute the following operation.</li> <li>·Replace the machine safety board.</li> </ul>   |           |
|        |                                    |      |         | Power unit board failure             | <ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the power unit board (YPU board). Save the CMOS.BIN before replace the board to be safe.</li> </ul>   |           |
| 1831   | CONTACTOR FB ERROR<br>(PLD2)       |      |         | Machine safety board failure         | (1)Turn the power OFF then back ON.(2)If the alarm occurs again, execute the following operation.•Replace the machine safety board.   | 9         |
|        |                                    |      |         | Power unit board failure             | <ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the power unit board (YPU board). Save the CMOS.BIN before replace the board to be safe.</li> </ul>   | 4<br>Ala  |
| 1832   | ESP_OUT FB ERROR<br>(PLD1)         |      |         | Machine safety board failure         | <ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, execute the following operation.</li> <li>·Replace the machine safety board.</li> </ul>   | ırm<br>Me |
|        | ESP_OUT FB ERROR<br>(PLD2)         |      |         | Machine safety board failure         | <ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, execute the following operation.</li> <li>•Replace the machine safety board.</li> </ul>   | ssage     |
| 1834   | M-SAFETY WATCHDOG<br>ERROR (PLD1)  |      |         | Machine safety board failure         | <ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, execute the following operation.</li> <li>•Replace the machine safety board.</li> </ul>   | List      |
| 1835   | M-SAFETY WATCHDOG<br>ERROR (PLD2)  |      |         | Machine safety board failure         | <ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, execute the following operation.</li> <li>•Replace the machine safety board.</li> </ul>   |           |
| 1836   | M-SAFETY WATCHDOG<br>ERROR (PLD3)  |      |         | Machine safety board failure         | <ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, execute the following operation.</li> <li>•Replace the machine safety board.</li> </ul>   |           |
|        |                                    |      |         | Main CPU board failure               | <ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again after replacing the machine safety module, save the CMOS. BIN in the maintenance mode, then replace the main CPU board.</li> </ul>                     |           |
|        |                                    |      |         | Software operation error<br>occurred | <ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and<br/>then contact your Yaskawa representative about occurrence status (operating<br/>procedure).</li> </ul> |           |
| 1837   | M-SAFETY 24V POWER<br>SUPPLY ERROR |      |         | Connection failure                   | <ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and<br/>then contact your Yaskawa representative about occurrence status (operating<br/>procedure).</li> </ul> |           |

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy	
Number		Code				
				Machine safety board failure	<ul><li>(1)Turn the power OFF then back ON.</li><li>(2)If the alarm occurs again, execute the following operation.</li><li>•Replace the machine safety board.</li></ul>	
				Ground fault or a short circuit	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again after replacing the machine safety board, execute the following operation.</li> <li>Check the occurrence of short-circuit or ground fault to the external IO wiring if the alarm for DC24V power failure occurs simultaneously.</li> </ul>	
1838	M-SAFETY DC 24V FUSE BROKEN			Blown fuse	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, check if the fuse of the machine safety module is blown. If it is blown, replace it with the new one.</li> </ul>	.9 .9
				Ground fault or a short circuit	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again after replacing the fuse, execute the following operation.</li> <li>Check the occurrence of short-circuit or ground fault to the external IO wiring if the alarm for DC24V power failure occurs simultaneously.</li> </ul>	4 Alarm
				Machine safety board failure	<ul><li>(1)Turn the power OFF then back ON.</li><li>(2)If the alarm occurs again after the above mentioned operation, replace the machine safety board.</li></ul>	Messa
1839	M-SAFETY 5V POWER SUPPLY ERROR			Blown fuse	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, check if the fuse of the machine safety module is blown. If it is blown, replace it with the new one.</li> </ul>	ge List
				Machine safety board failure	<ul><li>(1)Turn the power OFF then back ON.</li><li>(2)If the alarm occurs again after checking the fuse to be safe, replace the machine safety board.</li></ul>	
1840	M-SAFETY 3.3V LOW VOLTAGE			Machine safety board failure	<ul><li>(1)Turn the power OFF then back ON.</li><li>(2)If the alarm occurs again, replace the machine safety board.</li></ul>	
1841	COMMUNICATION ERROR (LOOP BACK)			Connection failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)if the alarm occurs again, check the M III cable connecting the servo control circuit board and the main control circuit board.</li> </ul>	
				Servo control circuit board failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the EAXA board. Save the CMOS.BIN before replace the board to be safe.</li> </ul>	
1860	I/O MODULE ERR (OSCILLATOR STOP)		subcode: I/O Board slot (BIT) For example slot3 case: (0000_0100), slot4 case:(0000_1000). If multiple I/O boards detecting the error, multiple bits are set. (Standard shipping of FS100L, An I/O board is in slot3.)	I/O BOARD (LIO08R09R) ERROR	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, replace the I/O board(LIO08R/09R).	

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy	
Number		Code				
1861	I/O MODULE ERR (WATCHDOG ERROR)		subcode: I/O Board slot (BIT) For example slot3 case: (0000_0100), slot4 case:(0000_1000). If multiple I/O boards detecting the error, multiple bits are set. (Standard shipping of FS100L, An I/O board is in slot3.)	I/O BOARD (LIO08R/09R) ERROR	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, replace the I/O board(LIO08R/09R).	
4000	MEMORY ERROR (TOOL FILE)		subcode: Tool number	Data error	(1)Reset the alarm. (2)If the alarm occurs again, initialize the tool file in maintenance mode, and then load the tool file saved in the external memory device.	<u>9</u> 9
				Main CPU board failure	(1)Reset the alarm. (2)If the alarm occurs again, replace the Main CPU board. Save the CMOS.BIN before replace the board to be safe. Replace the Main CPU board, and then Please execute the update. And, please load CMOS.BIN.	Alarm
4001	MEMORY ERROR (USER COORD FILE)		subcode: User coordinate number	Data error	(1)Reset the alarm. (2)If the alarm occurs again, initialize the user coordinates file in maintenance mode, and then load the user coordinates file saved in the external memory device.	Messad
				Main CPU board failure	(1)Reset the alarm. (2)If the alarm occurs again, replace the Main CPU board. Save the CMOS.BIN before replace the board to be safe. Replace the Main CPU board, and then Please execute the update. And, please load CMOS.BIN.	₽ I ist
4002	MEMORY ERROR (SV MON SIGNAL FILE)			Data error	<ul> <li>(1)Reset the alarm.</li> <li>(2)If the alarm occurs again, initialize the servo monitor signal file in maintenance mode, and then load the servo monitor signal file saved in the external memory device.</li> </ul>	
				Main CPU board failure	<ul> <li>(1)Reset the alarm.</li> <li>(2)If the alarm occurs again, replace the Main CPU board. Save the CMOS.BIN before replace the board to be safe. Replace the Main CPU board, and then Please execute the update. And, please load CMOS.BIN.</li> </ul>	
4004	MEMORY ERROR (HOME POS FILE)			Data error	<ul> <li>(1)Reset the alarm.</li> <li>(2)If the alarm occurs again, initialize the home positioning file in maintenance mode, and then load the home positioning file saved in the external memory device.</li> </ul>	
				Main CPU board failure	<ul> <li>(1)Reset the alarm.</li> <li>(2)If the alarm occurs again, replace the Main CPU board. Save the CMOS.BIN before replace the board to be safe. Replace the Main CPU board, and then Please execute the update. And, please load CMOS.BIN.</li> </ul>	

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy
Number		Code			
4005	MEMORY ERROR (SECOND HOME POS)			Data error	<ul> <li>(1)Reset the alarm.</li> <li>(2)If the alarm occurs again, initialize the second home positioning file in maintenance mode, and then load the second home positioning file saved in the external memory device.</li> </ul>
				Main CPU board failure	<ul> <li>(1)Reset the alarm.</li> <li>(2)If the alarm occurs again, replace the Main CPU board. Save the CMOS.BIN before replace the board to be safe. Replace the Main CPU board, and then Please execute the update. And, please load CMOS.BIN.</li> </ul>
4012	MEMORY ERROR (LINK SERVOFLOAT)		subcode: Condition file number	Data error	(1)Reset the alarm. (2)If the alarm occurs again, initialize the link servo float condition file in maintenance mode, and then load the link servo float condition file saved in the external memory device.
				Main CPU board failure	<ul> <li>(1)Reset the alarm.</li> <li>(2)If the alarm occurs again, replace the Main CPU board. Save the CMOS.BIN before replace the board to be safe. Replace the Main CPU board, and then Please execute the update. And, please load CMOS.BIN.</li> </ul>
4013	MEMORY ERROR (LINEAR SERVOFLOAT)		subcode: Condition file number	Data error	<ul> <li>(1)Reset the alarm.</li> <li>(2)If the alarm occurs again, initialize the linear servo float condition file in maintenance mode, and then load the linear servo float condition file saved in the external memory device.</li> </ul>
				Main CPU board failure	(1)Reset the alarm. (2)If the alarm occurs again, replace the Main CPU board. Save the CMOS.BIN before replace the board to be safe. Replace the Main CPU board, and then Please execute the update. And, please load CMOS.BIN.
4014	MEMORY ERROR (ROBOT CALIB FILE)		subcode: Page number	Data error	<ul> <li>(1)Reset the alarm.</li> <li>(2)If the alarm occurs again, initialize the file for calibration between manipulators in maintenance mode, and then load the file for calibration between manipulators saved in the external memory device.</li> </ul>
				Main CPU board failure	<ul> <li>(1)Reset the alarm.</li> <li>(2)If the alarm occurs again, replace the Main CPU board. Save the CMOS.BIN before replace the board to be safe. Replace the Main CPU board, and then Please execute the update. And, please load CMOS.BIN.</li> </ul>
4018	MEMORY ERR (LADDER PRG FILE)			Data error	<ul> <li>(1)Reset the alarm.</li> <li>(2)If the alarm occurs again, initialize the ladder program file in maintenance mode, and then load the ladder program file saved in the external memory device.</li> </ul>
				Main CPU board failure	<ul> <li>(1)Reset the alarm.</li> <li>(2)If the alarm occurs again, replace the Main CPU board. Save the CMOS.BIN before replace the board to be safe. Replace the Main CPU board, and then Please execute the update. And, please load CMOS.BIN.</li> </ul>

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy	
Number		Code				
4020	MEMORY ERROR (OPERATION ORIGIN)			Data error	<ul> <li>(1)Reset the alarm.</li> <li>(2)If the alarm occurs again, initialize the work home position file in maintenance mode, and then load the work home position file saved in the external memory device.</li> </ul>	
				Main CPU board failure	<ul> <li>(1)Reset the alarm.</li> <li>(2)If the alarm occurs again, replace the Main CPU board. Save the CMOS.BIN before replace the board to be safe. Replace the Main CPU board, and then Please execute the update. And, please load CMOS.BIN.</li> </ul>	
4021	MEMORY ERROR (CONVEYOR COND FILE)			Data error	<ul> <li>(1)Reset the alarm.</li> <li>(2)If the alarm occurs again, initialize the conveyor condition file in maintenance mode, and then load the conveyor condition file saved in the external memory device.</li> </ul>	9. 9.4
				Main CPU board failure	<ul> <li>(1)Reset the alarm.</li> <li>(2)If the alarm occurs again, replace the Main CPU board. Save the CMOS.BIN before replace the board to be safe. Replace the Main CPU board, and then Please execute the update. And, please load CMOS.BIN.</li> </ul>	Alarm Alarm
4022	MEMORY ERROR (PAINT SPECIAL FILE)		subcode: Page number	Data error	<ul><li>(1)Reset the alarm.</li><li>(2)If the alarm occurs again, initialize the paint special file in maintenance mode, and then load the paint special file saved in the external memory device.</li></ul>	Messa
				Main CPU board failure	<ul> <li>(1)Reset the alarm.</li> <li>(2)If the alarm occurs again, replace the Main CPU board. Save the CMOS.BIN before replace the board to be safe. Replace the Main CPU board, and then Please execute the update. And, please load CMOS.BIN.</li> </ul>	ge List
4023	MEMORY ERROR (PAINT COND FILE)		subcode: Page number	Data error	<ul> <li>(1)Reset the alarm.</li> <li>(2)If the alarm occurs again, initialize the paint condition file in maintenance mode, and then load the paint condition file saved in the external memory device.</li> </ul>	
				Main CPU board failure	<ul> <li>(1)Reset the alarm.</li> <li>(2)If the alarm occurs again, replace the Main CPU board. Save the CMOS.BIN before replace the board to be safe. Replace the Main CPU board, and then Please execute the update. And, please load CMOS.BIN.</li> </ul>	
4025	MEMORY ERROR (INTERRUPT JOB FILE)			Data error	<ul><li>(1)Reset the alarm.</li><li>(2)If the alarm occurs again, initialize the interrupt job file in maintenance mode, and then load the interrupt job file saved in the external memory device.</li></ul>	
				Main CPU board failure	<ul> <li>(1)Reset the alarm.</li> <li>(2)If the alarm occurs again, replace the Main CPU board. Save the CMOS.BIN before replace the board to be safe. Replace the Main CPU board, and then Please execute the update. And, please load CMOS.BIN.</li> </ul>	
4028	MEMORY ERR (SENSOR MON COND FILE)			Data error	<ul> <li>(1)Reset the alarm.</li> <li>(2)If the alarm occurs again, initialize the sensor monitoring condition file in maintenance mode, and then load the sensor monitoring condition file saved in the external memory device.</li> </ul>	

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy	
Number		Code				
				Main CPU board failure	<ul> <li>(1)Reset the alarm.</li> <li>(2)If the alarm occurs again, replace the Main CPU board. Save the CMOS.BIN before replace the board to be safe. Replace the Main CPU board, and then Please execute the update. And, please load CMOS.BIN.</li> </ul>	
4034	MEMORY ERR (ANTICIPATION OT FILE)			Data error	<ul> <li>(1)Reset the alarm.</li> <li>(2)If the alarm occurs again, initialize the anticipation output (OT) file in maintenance mode, and then load the anticipation output (OT) file saved in the external memory device.</li> </ul>	
				Main CPU board failure	<ul> <li>(1)Reset the alarm.</li> <li>(2)If the alarm occurs again, replace the Main CPU board. Save the CMOS.BIN before replace the board to be safe. Replace the Main CPU board, and then Please execute the update. And, please load CMOS.BIN.</li> </ul>	9. 9.4
4035	MEMORY ERR (ANTICIPATION OG FILE)			Data error	<ul> <li>(1)Reset the alarm.</li> <li>(2)If the alarm occurs again, initialize the anticipation output (OG) file in maintenance mode, and then load the anticipation output (OG) file saved in the external memory device.</li> </ul>	Alarm Alarm
				Main CPU board failure	<ul> <li>(1)Reset the alarm.</li> <li>(2)If the alarm occurs again, replace the Main CPU board. Save the CMOS.BIN before replace the board to be safe. Replace the Main CPU board, and then Please execute the update. And, please load CMOS.BIN.</li> </ul>	Message
4039	MEMORY ERROR (FORM CUT FILE)		subcode: File number	Data error	<ul> <li>(1)Reset the alarm.</li> <li>(2)If the alarm occurs again, initialize the form cut file in maintenance mode, and then load the form cut file saved in the external memory device.</li> </ul>	List
				Main CPU board failure	<ul> <li>(1)Reset the alarm.</li> <li>(2)If the alarm occurs again, replace the Main CPU board. Save the CMOS.BIN before replace the board to be safe. Replace the Main CPU board, and then Please execute the update. And, please load CMOS.BIN.</li> </ul>	
4040	MEMORY ERROR (SHOCK LEVEL FILE)		subcode: File number	Data error	<ul><li>(1)Reset the alarm.</li><li>(2)If the alarm occurs again, initialize the shock level file in maintenance mode, and then load the shock level file saved in the external memory device.</li></ul>	
				Main CPU board failure	<ul> <li>(1)Reset the alarm.</li> <li>(2)If the alarm occurs again, replace the Main CPU board. Save the CMOS.BIN before replace the board to be safe. Replace the Main CPU board, and then Please execute the update. And, please load CMOS.BIN.</li> </ul>	
4042	MEMORY ERROR (VISION FILE)		subcode: Page number	Data error	<ul> <li>(1)Reset the alarm.</li> <li>(2)If the alarm occurs again, initialize the vision condition file in maintenance mode, and then load the vision condition file saved in the external memory device.</li> </ul>	
				Main CPU board failure	<ul> <li>(1)Reset the alarm.</li> <li>(2)If the alarm occurs again, replace the Main CPU board. Save the CMOS.BIN before replace the board to be safe. Replace the Main CPU board, and then Please execute the update. And, please load CMOS.BIN.</li> </ul>	

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy	
Number		Code				
4043	MEMORY ERROR (VISION CALIBRATION)		subcode: Page number	Data error	<ul> <li>(1)Reset the alarm.</li> <li>(2)If the alarm occurs again, initialize the vision calibration file in maintenance mode, and then load the vision calibration file saved in the external memory device.</li> </ul>	
				Main CPU board failure	<ul> <li>(1)Reset the alarm.</li> <li>(2)If the alarm occurs again, replace the Main CPU board. Save the CMOS.BIN before replace the board to be safe. Replace the Main CPU board, and then Please execute the update. And, please load CMOS.BIN.</li> </ul>	
4046	MEMORY ERR (CONVEYOR CALIB FILE)		subcode: File number	Data error	<ul> <li>(1)Reset the alarm.</li> <li>(2)If the alarm occurs again, initialize the conveyor calibration file in maintenance mode, and then load the conveyor calibration file saved in the external memory device.</li> </ul>	9. 9.4
				Main CPU board failure	<ul> <li>(1)Reset the alarm.</li> <li>(2)If the alarm occurs again, replace the Main CPU board. Save the CMOS.BIN before replace the board to be safe. Replace the Main CPU board, and then Please execute the update. And, please load CMOS.BIN.</li> </ul>	Alarm Alarm
4047				Data error	<ul> <li>(1)Reset the alarm.</li> <li>(2)If the alarm occurs again, initialize the macro definition file in maintenance mode, and then load the macro definition file saved in the external memory device.</li> </ul>	Message
				Main CPU board failure	<ul> <li>(1)Reset the alarm.</li> <li>(2)If the alarm occurs again, replace the Main CPU board. Save the CMOS.BIN before replace the board to be safe. Replace the Main CPU board, and then Please execute the update. And, please load CMOS.BIN.</li> </ul>	9 List
4050	MEMORY ERR (AXIS I/O ALLOC FILE)			Data error	<ul> <li>(1)Reset the alarm.</li> <li>(2)If the alarm occurs again, initialize the axis motion I/O allocation file in maintenance mode, and then load the axis motion I/O allocation file saved in the external memory device.</li> </ul>	
				Main CPU board failure	<ul> <li>(1)Reset the alarm.</li> <li>(2)If the alarm occurs again, replace the Main CPU board. Save the CMOS.BIN before replace the board to be safe. Replace the Main CPU board, and then Please execute the update. And, please load CMOS.BIN.</li> </ul>	
4052	MEMORY ERROR (TOOL INTERFERENCE)		subcode: File number	Data error	<ul> <li>(1)Reset the alarm.</li> <li>(2)If the alarm occurs again, initialize the tool interference file in maintenance mode, and then load the tool interference file saved in the external memory device.</li> </ul>	
				Main CPU board failure	<ul> <li>(1)Reset the alarm.</li> <li>(2)If the alarm occurs again, replace the Main CPU board. Save the CMOS.BIN before replace the board to be safe. Replace the Main CPU board, and then Please execute the update. And, please load CMOS.BIN.</li> </ul>	

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy
Number		Code			
4063	MEMORY ERR (CONVEYOR COND SUPP.)		subcode: File number	Data error	<ul> <li>(1)Reset the alarm.</li> <li>(2)If the alarm occurs again, initialize the conveyor condition auxiliary file in maintenance mode, and then load the conveyor condition auxiliary file saved in the external memory device.</li> </ul>
				Main CPU board failure	<ul> <li>(1)Reset the alarm.</li> <li>(2)If the alarm occurs again, replace the Main CPU board. Save the CMOS.BIN before replace the board to be safe. Replace the Main CPU board, and then Please execute the update. And, please load CMOS.BIN.</li> </ul>
4065	MEMORY ERROR (I/F PANEL FILE)			Data error	<ul> <li>(1)Reset the alarm.</li> <li>(2)If the alarm occurs again, initialize the I/F panel file in maintenance mode, and then load the I/F panel file saved in the external memory device.</li> </ul>
				Main CPU board failure	(1)Reset the alarm.       +         (2)If the alarm occurs again, replace the Main CPU board. Save the CMOS.BIN       +         before replace the board to be safe. Replace the Main CPU board, and then       +         Please execute the update. And, please load CMOS.BIN.       +
4072	MEMORY ERROR (LASER TRACKING TRACK START FILE)			Data error	(1)Reset the alarm.       ∃         (2)If the alarm occurs again, initialize the laser tracking track start file in maintenance mode, and then load the laser tracking track start file saved in the external memory device.       ∃
				Main CPU board failure	(1)Reset the alarm. (2)If the alarm occurs again, replace the Main CPU board. Save the CMOS.BIN before replace the board to be safe. Replace the Main CPU board, and then Please execute the update. And, please load CMOS.BIN.
4074	MEMORY ERROR (LASER TRACKING TRACK SET FILE)			Data error	<ul> <li>(1)Reset the alarm.</li> <li>(2)If the alarm occurs again, initialize the laser tracking track set file in maintenance mode, and then load the laser tracking track set file saved in the external memory device.</li> </ul>
				Main CPU board failure	<ul> <li>(1)Reset the alarm.</li> <li>(2)If the alarm occurs again, replace the Main CPU board. Save the CMOS.BIN before replace the board to be safe. Replace the Main CPU board, and then Please execute the update. And, please load CMOS.BIN.</li> </ul>
4075	MEMORY ERROR (CONDITION FILE OF CORRESPONDING TO LASER TRACKING GAP)			Data error	<ul> <li>(1)Reset the alarm.</li> <li>(2)If the alarm occurs again, initialize the condition file of corresponding to laser tracking gap in maintenance mode, and then load the condition file of corresponding to laser tracking gap saved in the external memory device.</li> </ul>
				Main CPU board failure	<ul> <li>(1)Reset the alarm.</li> <li>(2)If the alarm occurs again, replace the Main CPU board. Save the CMOS.BIN before replace the board to be safe. Replace the Main CPU board, and then Please execute the update. And, please load CMOS.BIN.</li> </ul>
4099	DC 24V POWER SUPPLY FAILURE (YPS)			Power supply failure	<ul> <li>(1)Reset the alarm.</li> <li>(2)If the alarm occurs again, turn the power OFF then back ON.</li> <li>(3)If the alarm occurs again, replace the following unit.</li> <li>YPS unit</li> </ul>

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy	
Number		Code				
				Ground fault or a short circuit	<ul> <li>(1)Reset the alarm.</li> <li>(2)If the alarm occurs again, check whether neither the short circuit nor the ground fault have occurred in the I/O cables from the external device or the brake connection.</li> </ul>	
4103	PARALLEL START INSTRUCTION ERROR	1	Sub task being executed: Although a job is being executed by instructed sub task, an attempt was made to execute another job by the sub task.	Setting error	<ul><li>(1)Check the following settings.</li><li>The sub task is completed by the PWAIT instruction.</li></ul>	
		2	Group axis being used: The job operated by another sub task uses the same group axis.	Setting error	<ul><li>(1)Check the following settings.</li><li>The job to be started</li><li>The execution timing for start command</li></ul>	9. 9.4
		3	Multiple start of same job: The job that was tried to be started was executed by another sub task.	Setting error	<ul><li>(1)Check the following settings.</li><li>The same job is not used in the another task</li></ul>	Alarm Alarm
		4	Unregistered master job: Although the master job was not registered, an attempt was made to execute PSTART SUB (job name omitted).	Setting error	<ul><li>(1)Check the following settings.</li><li>The master job of the sub task is registered</li></ul>	Message L
		5	Synchronization instruction error: When restarted by PSTART, synchronization instruction status of the sub task under interruption was different from the status to restart.	Setting error	<ul> <li>(1)Check the following settings.</li> <li>The job to be started</li> <li>The execution timing for start command</li> </ul>	IST
		6	Stopped by an alarm: An attempt was made to start the sub task which is stopped by an alarm.	Setting error	<ul><li>(1)Check the following settings.</li><li>Alarm occurrence status</li></ul>	
		7	Synchronization task specification of SYNC instruction omit error	Setting error	<ul><li>(1)Check the following settings.</li><li>Synchronization task specification of SYNC instruction</li></ul>	
		8	The task is specified by synchronization task of SYNC instruction.	Setting error	<ul> <li>(1)Check the following settings.</li> <li>Synchronization task specification of SYNC instruction</li> </ul>	
		9	I/O jog being executed	Setting error	<ul> <li>(1)Check the following settings.</li> <li>I/O jog executing status</li> <li>Complete the I/O jog executing status, and then restart.</li> </ul>	
		10	Separate group axis being used	Setting error	<ul> <li>(1)Check the following settings.</li> <li>Usage status of separation use axis</li> <li>Complete the use of separation use axis, and then restart.</li> </ul>	

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy
Number		Code			
		11	The servo power supply is OFF.	Setting error	<ul><li>(1)Check the following settings.</li><li>Servo power</li><li>Turn ON servo power.</li></ul>
		12	Twin synchronous task ID error	Setting error	<ul><li>(1)Check the following settings.</li><li>Twin synchronous task specification of SYNC instruction</li></ul>
		16	PSTART instruction is the old specification.	Setting error	<ul> <li>(1)Check the following settings.</li> <li>The specifications of PSTART instruction Register the PSTART instruction as new specification.</li> </ul>
		17	PWAIT instruction is the old specification.	Setting error	<ul><li>(1)Check the following settings.</li><li>The specifications of PWAIT instruction Register the PWAIT instruction as new specification.</li></ul>
4104	WRONG EXECUTION OF LOAD INST		subcode1 to 245: Signifies the data transmission error.	Setting error	* Refer to the instruction manual for Data Transmission Function for details.
4105	WRONG EXECUTION OF SAVE INST		subcode1 to 245: Signifies the data transmission error.	Setting error	* Refer to the instruction manual for Data Transmission Function for details.
4106	WRONG EXECUTION OF DELETE INST		subcode1 to 245: Signifies the data transmission error.	Setting error	* Refer to the instruction manual for Data Transmission Function for details.
4107	OUT OF RANGE (ABSO DATA)		subcode: Signifies the axis in which the alarm occurred	Setting error	<ul> <li>(1)Check the following settings.</li> <li>Move the manipulator or station to the zero position by the axis operation and check the home position alignment marks (the arrow).</li> </ul>
4112	DATA SENDING ERROR	1	Retry over of NAK	Communication error	<ul> <li>(1)Reset the alarm.</li> <li>(2)If the alarm occurs again, check the communication setting and communication wiring is correct.</li> </ul>
		2	Retry over for time-out in timer A	Communication error	<ul> <li>(1)Reset the alarm.</li> <li>(2)If the alarm occurs again, check the communication setting and communication wiring is correct.</li> </ul>
		3	Retry over for mutual response error	Communication error	<ul> <li>(1)Reset the alarm.</li> <li>(2)If the alarm occurs again, check the communication setting and communication wiring is correct.</li> </ul>
4113	DATA RECEIVING ERROR	1	Reception time-out (timer A)	Communication error	<ul> <li>(1)Reset the alarm.</li> <li>(2)If the alarm occurs again, check the communication setting and communication wiring is correct.</li> </ul>
		2	Reception time-out (timer B)	Communication error	<ul><li>(1)Reset the alarm.</li><li>(2)If the alarm occurs again, check the communication setting and communication wiring is correct.</li></ul>
		3	Heading length is too short.	Setting error	<ul> <li>(1)Reset the alarm.</li> <li>(2)If the alarm occurs again, send EOT code to release the data link and then check that the sending side data is correctly set.</li> <li>(3)Check that the communication setting is correct.</li> </ul>

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy	
Number		Code				
		4	Heading length is too long.	Setting error	<ul> <li>(1)Reset the alarm.</li> <li>(2)If the alarm occurs again, send EOT code to release the data link and then check that the sending side data is correctly set.</li> <li>(3)Check that the communication setting is correct.</li> </ul>	
		5	The header No. error	Setting error	<ul> <li>(1)Reset the alarm.</li> <li>(2)If the alarm occurs again, send EOT code to release the data link and then check that the sending side data is correctly set.</li> <li>(3)Check that the communication setting is correct.</li> </ul>	
		6	The text length exceeded 256 characters.	Setting error	<ul> <li>(1)Reset the alarm.</li> <li>(2)If the alarm occurs again, send EOT code to release the data link and then check that the sending side data is correctly set.</li> <li>(3)Check that the communication setting is correct.</li> </ul>	9. 9.4
		7		Setting error	<ul> <li>(1)Reset the alarm.</li> <li>(2)If the alarm occurs again, send EOT code to release the data link and then check that the sending side data is correctly set.</li> <li>(3)Check that the communication setting is correct.</li> </ul>	Alarm Alarm
4114	TRANSMISSION HARDWARE ERROR	1	Overrun error	Communication error	<ul><li>(1)Reset the alarm.</li><li>(2)If the alarm occurs again, check the communication setting and communication wiring is correct.</li></ul>	Messa
		2	Parity error	Communication error	<ul><li>(1)Reset the alarm.</li><li>(2)If the alarm occurs again, check the communication setting and communication wiring is correct.</li></ul>	ge List
		3	Framing error	Communication error	<ul> <li>(1)Reset the alarm.</li> <li>(2)If the alarm occurs again, check the communication setting and communication wiring is correct.</li> </ul>	
		4	Transmission time-out (timer A)	Communication error	<ul> <li>(1)Reset the alarm.</li> <li>(2)If the alarm occurs again, check the communication setting and communication wiring is correct.</li> </ul>	
		5	Transmission time-out (timer B)	Communication error	<ul><li>(1)Reset the alarm.</li><li>(2)If the alarm occurs again, check the communication setting and communication wiring is correct.</li></ul>	
4115	TRANSMISSION SYSTEM BLOCK	1	Received EOT while waiting ACK.	Communication error	<ul><li>(1)Reset the alarm.</li><li>(2)If the alarm occurs again, check the setting of communication or transmission side data is correctly set.</li></ul>	
		2	Received EOT while waiting ENQ.	Communication error	<ul> <li>(1)Reset the alarm.</li> <li>(2)If the alarm occurs again, check the setting of communication or transmission side data is correctly set.</li> </ul>	
		3	Received EOT before last block reception.	Communication error	<ul><li>(1)Reset the alarm.</li><li>(2)If the alarm occurs again, check the setting of communication or transmission side data is correctly set.</li></ul>	

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy
Number		Code			
		4	Received codes other than EOT after last block reception.	Communication error	<ul><li>(1)Reset the alarm.</li><li>(2)If the alarm occurs again, check the setting of communication or transmission side data is correctly set.</li></ul>
4116	TRANSMISSION SYSTEM ERROR	1	Transmission data contents error	Communication error	<ul><li>(1)Reset the alarm.</li><li>(2)If the alarm occurs again, check the setting of communication or transmission side data is correctly set.</li></ul>
		100	Trans error or protocol error	Communication error	<ul><li>(1)Reset the alarm.</li><li>(2)If the alarm occurs again, check the setting of communication or transmission side data is correctly set.</li></ul>
4117	BRAKE POWER ERROR		subcode: Signifies the LIO-08RT1 board No. in which the alarm occurred	Connection failure	<ul><li>(1)Reset the alarm.</li><li>(2)If the alarm occurs again, check the brake connection if there is a ground fault or short circuit.</li></ul>
				Fuse failure	<ul><li>(1)Reset the alarm.</li><li>(2)If the alarm occurs again, check the brake connection and then replace the fuse.</li></ul>
4118	FAN CIRCUIT PROTECTOR TRIPPED		subcode: Signifies the LIO-08RT1 board No. in which the alarm occurred	Connection failure	<ul><li>(1)Reset the alarm.</li><li>(2)If the alarm occurs again, check fan power line if there is a ground fault or short circuit.</li></ul>
				Short circuit or ground fault	<ul><li>(1)Turn the power OFF then back ON.</li><li>(2)If the alarm occurs again, check a short circuit or ground fault has not occurred in external 24V power line.</li></ul>
				Cooling fan failure	Replace the in-panel cooling fan.
4119	FAN ERROR(IN CONTROL BOX)		subcode: Signifies the LIO-08RT1 board No. in which the alarm occurred	Cooling fan failure	<ul><li>(1)Reset the alarm.</li><li>(2)If the alarm occurs again, replace the YPS unit. Save the CMOS.BIN before replacing the unit to be safe.</li></ul>
4121	COOLING FAN1 ERROR		subcode: Signifies the LIO-08RT1 board No. in which the alarm occurred	Cooling fan failure	Replace the cooling fan of manipulator. Check the wiring from a manipulator to a LIO-08RT1 board. * Move the manipulator to the safe position in the teach mode.
4122	COOLING FAN2 ERROR		subcode: Signifies the LIO-08RT1 board No. in which the alarm occurred	Cooling fan failure	Replace the cooling fan of manipulator. Check the wiring from a manipulator to a LIO-08RT1 board. * Move the manipulator to the safe position in the teach mode.
4124	WRONG EXECUTION OF VISION INST	1	The specified file number is incorrect.	Setting error	<ul><li>(1)Check the following settings.</li><li>File No.</li><li>Specify the correct file number.</li></ul>
		2	The specified file set value is incorrect.	Setting error	<ul><li>(1)Check the following settings.</li><li>File set value</li><li>Specify the set value.</li></ul>

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy
Number		Code			
		3	Calibration could not be executed.	Setting error	<ul> <li>(1)Check the following settings.</li> <li>The robot coordinate data or the pixel coordinate data used for the calibration</li> <li>The user variable number in the calibration file</li> <li>Set the robot coordinate data and the pixel coordinate data used for the calibration to the user variable.</li> <li>Correctly set the user variable number in the calibration file.</li> </ul>
		4	The communication port for the vision system could not be initialized.	Setting error	<ul><li>(1)Check the following settings.</li><li>The Parameter for communication port</li></ul>
		5	Time-out occurred during data transmission.	Setting error	(1)Check the following settings.         • The communication setting of vision system         • The Ethernet protocol address setting of vision system
				Connection failure	(1)Reset the alarm.         (2)If the alarm occurs again, check the connection of the following cables.         • Cable between vision system and FS100L system
		6	Time-out occurred during data reception.	Setting error	<ul> <li>(1)Check the following settings.</li> <li>The communication setting of vision system</li> <li>The Ethernet protocol address setting of vision system</li> </ul>
				Connection failure	(1)Reset the alarm.       Go         (2)If the alarm occurs again, check the connection of the following cables.       Go         • Cable between vision system and FS100L system       Image: Cable between vision system and FS100L system
		7	The data received from the vision system is incorrect.	Setting error	<ul> <li>(1)Check the following settings.</li> <li>The communication setting of vision system</li> <li>The detection setting of vision system</li> </ul>
				Connection failure	<ul> <li>(1)Reset the alarm.</li> <li>(2)If the alarm occurs again, check the connection of the following cables.</li> <li>Cable between vision system and F S 100 system</li> </ul>
		8	The pixel coordinates value was not able to be converted into the robot coordinates.	Setting error	<ul><li>(1)Check the following settings.</li><li>The communication setting of vision system</li><li>Calibration file for use</li></ul>
		9	Failed to read or write the position type variable (P variable).	Setting error	<ul> <li>(1)Check the following settings.</li> <li>Usage status of the specified position type variable Don't use the specified positional type variable at the same time in other jobs.</li> </ul>
		10	Use memory is lacking and the area could not be obtained.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		11	The setting value of measurement item (FT) is incorrect.		Correct the setting value of a measurement item.

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy
Number		Code			
		12	The data for the vision execution command is incorrect.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		48	The number of waiting commands sent by Vision sensor exceeded the limit.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)Check the command sent by Vision sensor</li> <li>(3)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
4126	CANNOT EXECUTE AUTO PMT	1	System error	Software operation error occurred	(1)Reset the alarm, and then try again. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).
		2	PBOX cannot be edited.	Setting error	(1)Check the following settings.          • I/O status of the edit prohibit signal          The edit prohibit signal cannot input.
		3	The source job cannot be edited.	Setting error	(1)Check the following settings.       Image: Comparison of the prohibit status of source job         • The prohibit status of source job       Image: Comparison of the prohibit status of source job         If the source job is protected from editing, it cannot be edited.       Image: Comparison of the prohibit status of source job
		4	The converted job cannot be edited.	Setting error	(1)Check the following settings.       •         • The prohibit status of converted job       •         If the converted job is protected from editing, it cannot be edited.       •
		5	The memory area for job area is insufficient.	Software operation error occurred	<ul> <li>(1)Reset the alarm.</li> <li>(2)If the error occurs again, delete unused jobs.</li> <li>(3)If the error occurs again after the previous measures were executed, initialize the job file in the maintenance mode, and then load the saved job file. In that case, delete the unused jobs.</li> <li>(4)If the error occurs again though the previous measures were executed, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		6	The source job is not exist.	Setting error	<ul> <li>(1)Check the following settings.</li> <li>Presence of the specified source job</li> <li>The job which does not exist cannot be set to the source job.</li> </ul>
		7	The memory area for position data of the job is insufficient.	Software operation error occurred	<ul> <li>(1)Reset the alarm.</li> <li>(2)when the error occurs again, if there is an unnecessary teaching position, delete it.</li> <li>(3)If the error occurs again after the previous measures were executed, initialize the job file in the maintenance mode, and then load the saved job file. In that case, delete the unused jobs.</li> <li>(4)If the error occurs again though the previous measures were executed, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy
Number		Code			
		8	The job under execution is specified as the conversion job.	Setting error	<ul> <li>(1)Check the following settings.</li> <li>Execution status of the source job</li> <li>Execution status of the converted job</li> <li>The job under execution is specified for the source / converted job. Execute conversion operation after ending the job execution.</li> </ul>
4127	U-AXIS TIMING BELT BLOWN		subcode: XY X : Servo control circuit board (SV#X) Y : Power-ON unit (TU#Y)	Belt blown	Replace the timing belt of the manipulator. Check the connection between manipulator and Servo control circuit board. * Move the manipulator to safety place in teach mode.
4129	TWIN DRIVE OUT OF RANGE (START)		subcode: Corresponding master- axes and slave-axes are displayed by the bit.	Setting error	<ul> <li>(1)Check the following settings.</li> <li>Pulse error of the master-axes and the slave-axes</li> <li>Switch to independent movement mode so that the pulse error of the master-axes and the slave-axes is settled within allowable range.</li> </ul>
4130	NETWORK APPLICATION PROCESS ERROR	1	An error occurred when the notification of the APP task re- initialization was processed in the Ethernet function.	Software operation error occurred	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).
				Main CPU board failure	(1)Turn the power OFF then back ON.       (2)If the alarm occurs again, replace the CPU-201R board. Save the CMOS.BIN before replace the board to be safe. Replace the CPU-201R board, and then Please execute the update. And, please load CMOS.BIN.       (2)
		2	An error occurred when the re- initialization response was received in the Ethernet function.	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
				Main CPU board failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the CPU-201R board. Save the CMOS.BIN before replace the board to be safe. Replace the CPU-201R board, and then Please execute the update. And, please load CMOS.BIN.</li> </ul>
		3	The incomplete task of re- initialization was unsuccessfully completed in the Ethernet function.	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
				Main CPU board failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the CPU-201R board. Save the CMOS.BIN before replace the board to be safe. Replace the CPU-201R board, and then Please execute the update. And, please load CMOS.BIN.</li> </ul>
		4	An error occurred when the semaphore for re-initialization was received in the Ethernet function.	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy
Number		Code			
				Main CPU board failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the CPU-201R board. Save the CMOS.BIN before replace the board to be safe. Replace the CPU-201R board, and then Please execute the update. And, please load CMOS.BIN.</li> </ul>
		5	An error occurred when the re- initialization mail was sent in the Ethernet function.	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
				Main CPU board failure	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, replace the CPU-201R board. Save the CMOS.BIN before replace the board to be safe. Replace the CPU-201R board, and then Please execute the update. And, please load CMOS.BIN.
		6	An error occurred in the exclusive process of the storage area control table of the Ethernet function.	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
				Main CPU board failure	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, replace the CPU-201R board. Save the CMOS.BIN before replace the board to be safe. Replace the CPU-201R board, and then Please execute the update. And, please load CMOS.BIN.
		7	Time-out occurred in the re- initialization response receiving process of the Ethernet function.	Software operation error occurred	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).
				Main CPU board failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the CPU-201R board. Save the CMOS.BIN before replace the board to be safe. Replace the CPU-201R board, and then Please execute the update. And, please load CMOS.BIN.</li> </ul>
		8	An error occurred in the re- initialization response receiving process of the Ethernet function.	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
				Main CPU board failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the CPU-201R board. Save the CMOS.BIN before replace the board to be safe. Replace the CPU-201R board, and then Please execute the update. And, please load CMOS.BIN.</li> </ul>
		9	Receiving data size error occurred in the re-initialization response receiving process of the Ethernet function.	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy	
Number		Code				
				Main CPU board failure	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, replace the CPU-201R board. Save the CMOS.BIN before replace the board to be safe. Replace the CPU-201R board, and then Please execute the update. And, please load CMOS.BIN.	
		30	An error occurred in the Web server task mail receiving process of the Ethernet function.	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
				Main CPU board failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the CPU-201R board. Save the CMOS.BIN before replace the board to be safe. Replace the CPU-201R board, and then Please execute the update. And, please load CMOS.BIN.</li> </ul>	9. 9.4
		31	An error occurred in the FTP server task mail receiving process of the Ethernet function.	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	Alarm Alarm
				Main CPU board failure	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, replace the CPU-201R board. Save the CMOS.BIN before replace the board to be safe. Replace the CPU-201R board, and then Please execute the update. And, please load CMOS.BIN.	Message
		32	An error occurred in the FTP client task mail receiving process of the Ethernet function.	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	Elist
				Main CPU board failure	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, replace the CPU-201R board. Save the CMOS.BIN before replace the board to be safe. Replace the CPU-201R board, and then Please execute the update. And, please load CMOS.BIN.	
		40	Illegal e-mail data were received in the Web server task of the Ethernet function.	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
				Main CPU board failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the CPU-201R board. Save the CMOS.BIN before replace the board to be safe. Replace the CPU-201R board, and then Please execute the update. And, please load CMOS.BIN.</li> </ul>	
		41	Illegal e-mail data were received in the FTP server task of the Ethernet function.	Software operation error occurred	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).	

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy	
Number		Code				
				Main CPU board failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the CPU-201R board. Save the CMOS.BIN before replace the board to be safe. Replace the CPU-201R board, and then Please execute the update. And, please load CMOS.BIN.</li> </ul>	
		42	Illegal e-mail data were received in the FTP client task of the Ethernet function.	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
				Main CPU board failure	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, replace the CPU-201R board. Save the CMOS.BIN before replace the board to be safe. Replace the CPU-201R board, and then Please execute the update. And, please load CMOS.BIN.	9.9 9.4
		50	An error occurred in the data size written to PCI of the Ethernet function.	Software operation error occurred	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).	Alarm Alarm
				Main CPU board failure	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, replace the CPU-201R board. Save the CMOS.BIN before replace the board to be safe. Replace the CPU-201R board, and then Please execute the update. And, please load CMOS.BIN.	Message
		51	An error occurred when the request to write PCI data was received in the Ethernet function.	Software operation error occurred	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).	- ist
				Main CPU board failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the CPU-201R board. Save the CMOS.BIN before replace the board to be safe. Replace the CPU-201R board, and then Please execute the update. And, please load CMOS.BIN.</li> </ul>	
		52	The request of the undefined transmission was received in the Ethernet function.	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
				Main CPU board failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the CPU-201R board. Save the CMOS.BIN before replace the board to be safe. Replace the CPU-201R board, and then Please execute the update. And, please load CMOS.BIN.</li> </ul>	
		53	An error occurred in the transmission request of the Ethernet function.	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy	
Number		Code				
				Main CPU board failure	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, replace the CPU-201R board. Save the CMOS.BIN before replace the board to be safe. Replace the CPU-201R board, and then Please execute the update. And, please load CMOS.BIN.	
		54	The transmission request without data was received in the Ethernet function.	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
				Main CPU board failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the CPU-201R board. Save the CMOS.BIN before replace the board to be safe. Replace the CPU-201R board, and then Please execute the update. And, please load CMOS.BIN.</li> </ul>	9. 9.4
		55	The transmission request of illegal data length was received in the Ethernet function.	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	Alarm Alarm
				Main CPU board failure	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, replace the CPU-201R board. Save the CMOS.BIN before replace the board to be safe. Replace the CPU-201R board, and then Please execute the update. And, please load CMOS.BIN.	Message
		100	An error occurred in storing process of memory which is used in the Ethernet function.	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	Elist
				Main CPU board failure	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, replace the CPU-201R board. Save the CMOS.BIN before replace the board to be safe. Replace the CPU-201R board, and then Please execute the update. And, please load CMOS.BIN.	
		101	An error occurred in the buffer for request to write PCI getting process of the Ethernet function.	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
				Main CPU board failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the CPU-201R board. Save the CMOS.BIN before replace the board to be safe. Replace the CPU-201R board, and then Please execute the update. And, please load CMOS.BIN.</li> </ul>	
		200	The socket of the Ethernet function was full and was not able to create a socket.	Software operation error occurred	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).	

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy	
Number		Code				
				Main CPU board failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the CPU-201R board. Save the CMOS.BIN before replace the board to be safe. Replace the CPU-201R board, and then Please execute the update. And, please load CMOS.BIN.</li> </ul>	
		201	An error occurred in the semaphore of socket control table of the Ethernet function.	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
				Main CPU board failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the CPU-201R board. Save the CMOS.BIN before replace the board to be safe. Replace the CPU-201R board, and then Please execute the update. And, please load CMOS.BIN.</li> </ul>	9.4
4131	UDP PROCESS ERROR	1	An error occurred in the creation of receiving socket during the UDP process of the Ethernet function.	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	Alarm Alarm
				Main CPU board failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the CPU-201R board. Save the CMOS.BIN before replace the board to be safe. Replace the CPU-201R board, and then Please execute the update. And, please load CMOS.BIN.</li> </ul>	Message
		2	An error occurred in the creation of transmission socket during the UDP process of the Ethernet function.	Software operation error occurred	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).	List
				Main CPU board failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the CPU-201R board. Save the CMOS.BIN before replace the board to be safe. Replace the CPU-201R board, and then Please execute the update. And, please load CMOS.BIN.</li> </ul>	
		3	Illegal data were received in the UDP process of the Ethernet function.	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
				Main CPU board failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the CPU-201R board. Save the CMOS.BIN before replace the board to be safe. Replace the CPU-201R board, and then Please execute the update. And, please load CMOS.BIN.</li> </ul>	
		4	Transmission error occurred in the UDP process of the Ethernet function.	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy	
Number		Code				
				Main CPU board failure	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, replace the CPU-201R board. Save the CMOS.BIN before replace the board to be safe. Replace the CPU-201R board, and then Please execute the update. And, please load CMOS.BIN.	
		5	The SELECT operation was not successfully completed in the UDP process of the Ethernet function.	Software operation error occurred	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).	
				Main CPU board failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the CPU-201R board. Save the CMOS.BIN before replace the board to be safe. Replace the CPU-201R board, and then Please execute the update. And, please load CMOS.BIN.</li> </ul>	9. 9.4
		100	The re-initialization notification of illegal data length was received in the UDP process of the Ethernet function.	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, check the connection and insertion of the following cables and connectors.</li> <li>The M II communications cable which I/O module of the corresponding subcode</li> <li>(In case of M II communications last station) Terminator</li> <li>24V power of the corresponding I/O module</li> </ul>	Alarm Alarm Messa
				Main CPU board failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the CPU-201R board. Save the CMOS.BIN before replace the board to be safe. Replace the CPU-201R board, and then Please execute the update. And, please load CMOS.BIN.</li> </ul>	ige List
		101	The re-initialization notification of illegal data was received in the UDP process of the Ethernet function.	Software operation error occurred	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).	
				Main CPU board failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the CPU-201R board. Save the CMOS.BIN before replace the board to be safe. Replace the CPU-201R board, and then Please execute the update. And, please load CMOS.BIN.</li> </ul>	
		102	The PCI write process was not successfully completed in the UDP process of the Ethernet function.	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
				Main CPU board failure	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, replace the CPU-201R board. Save the CMOS.BIN before replace the board to be safe. Replace the CPU-201R board, and then Please execute the update. And, please load CMOS.BIN.	
		103	The transmission request of illegal data length was received in the UDP process of the Ethernet function.	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy
Number		Code			
				Main CPU board failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the CPU-201R board. Save the CMOS.BIN before replace the board to be safe. Replace the CPU-201R board, and then Please execute the update. And, please load CMOS.BIN.</li> </ul>
		104	The transmission request of illegal data was received in the UDP process of the Ethernet function.	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
				Main CPU board failure	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, replace the CPU-201R board. Save the CMOS.BIN before replace the board to be safe. Replace the CPU-201R board, and then Please execute the update. And, please load CMOS.BIN.
4132	TCP PROCESS ERROR	1	The socket table was not successfully created in the TCP process of the Ethernet function.	Software operation error occurred	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).
				Main CPU board failure	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, replace the CPU-201R board. Save the CMOS.BIN before replace the board to be safe. Replace the CPU-201R board, and then Please execute the update. And, please load CMOS.BIN.
		2	An error occurred in the process of the TCP server initialization of the Ethernet function.	Software operation error occurred	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).
				Main CPU board failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the CPU-201R board. Save the CMOS.BIN before replace the board to be safe. Replace the CPU-201R board, and then Please execute the update. And, please load CMOS.BIN.</li> </ul>
		3	An error occurred in connection detecting process of TCP server of the Ethernet function.	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
				Main CPU board failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the CPU-201R board. Save the CMOS.BIN before replace the board to be safe. Replace the CPU-201R board, and then Please execute the update. And, please load CMOS.BIN.</li> </ul>
		4	An error occurred in the connection detection checking process of TCP server of the Ethernet function.	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>

Alarm Number	Alarm Name	Sub Code	Meaning	Cause	Remedy	
				Main CPU board failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the CPU-201R board. Save the CMOS.BIN before replace the board to be safe. Replace the CPU-201R board, and then Please execute the update. And, please load CMOS.BIN.</li> </ul>	
4134	COOLING FAN SET ABNORMAL	0		Setting error	<ul> <li>(1)Check the following settings.</li> <li>Confirm parameter SVS and S2C for the cooling fan.</li> <li>Open the front panel to refer to the parameter list on the back.</li> </ul>	
4137	WRONG EXECUTION OF SETUALM INST	1	Alarm code specification error	Setting error	<ul><li>(1)Check the following settings.</li><li>Alarm code</li><li>Specify the alarm in the range 8000 to 8999.</li></ul>	
		2	Task specification error	Setting error	<ul> <li>(1)Check the following settings.</li> <li>Task specification</li> <li>Specify the task in the range 0 to 4 (7 at expansion).</li> </ul>	9.4 24
		3	Motion mode specification error	Setting error	(1)Check the following settings.         • Motion mode specification         Set the motion mode to 0 or 1.	vlarm Vlarm M
4138	WRONG EXECUTION OF SVON INST			Connection failure	(1)Check the following settings.       •         • Short-circuit the external servo ON (EXSVON) of MXT terminal block.       •	essa
				Setting error	(1)Check the following settings.(1)Check the following settings.• The concurrent I/O signal #80031 (servo ON condition1) ON(1)Check the following settings.• The concurrent I/O signal #80033 (servo ON condition2) ON(2)Check the following settings.	ae List
4139	WRONG EXECUTION OF PRINT INST			Setting error	<ul> <li>(1)Check the following settings.</li> <li>The setting of the PRINT output conversion spec (character string specification)</li> <li>If there is no problem in the setting, delete the corresponding PRINT instruction and register again.</li> </ul>	
4140	WRONG EXECUTION OF DIALOG INST	1	DIALOG instruction control error	Setting error	<ul> <li>(1)Check the following settings.</li> <li>The tag setting of DIALOG instruction If no fault is found, delete corresponding DIALOG instruction, and then register again.</li> </ul>	
		2	Messages and buttons are not registered.	Setting error	<ul><li>(1)Check the following settings.</li><li>The information of DIALOG instruction message and button</li></ul>	
		3	Buttons are not registered.	Setting error	<ul><li>(1)Check the following settings.</li><li>The information of DIALOG instruction button</li></ul>	
4152	TIMING BELT BLOWN		Servo control circuit board number (SV#) from which an error was detected.	Manipulator timing belt is blown.	Move the manipulator in teach mode to the position where there is no torque on the driving belt. (1) Check the timing belt tension.	
4160	BRAKE FB ERROR			Loose fuse	(1)Check the fuse(F1) in the YBK01-2 unit is not disconnected.	
				Blown fuse	Replace the fuse(F1) in the YBK01-2 unit.	
				Unit failure (YBK01-2)	Replace the YBK01-2 unit.	

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy
Number		Code			
				Unit failure (MAKER LIO board)	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, replace the MAKER LIO board.
4200	SYSTEM ERROR (FILE DATA)		subcode 01 to 50: Signifies the internal software error	Data error	<ul> <li>(1)Reset the alarm.</li> <li>(2)If the alarm occurs again, turn the controller power OFF and then ON to check the operation.</li> <li>(3)If the alarm occurs again, initialize the appropriate data in maintenance mode, and then load the data saved in the external memory device.</li> </ul>
4201	SYSTEM ERROR (JOB)	-1	An error occurred during the access to a job in parameter specifications.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
				Main CPU board failure	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, replace the CPU-201R board. Save the CMOS.BIN and then replace the board. After replacing the board, upgrade the software with the version which is same as the one saved in the former CPU-201R board.</li> </ul>
		-3	The access to a job could not be performed with the specified job name.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
				Main CPU board failure	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, replace the CPU-201R board. Save the CMOS.BIN and then replace the board. After replacing the board, upgrade the software with the version which is same as the one saved in the former CPU-201R board.</li> </ul>
		-4	A job was newly created with the same name of the job already specified in the memory.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
				Main CPU board failure	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, replace the CPU-201R board. Save the CMOS.BIN and then replace the board. After replacing the board, upgrade the software with the version which is same as the one saved in the former CPU-201R board.</li> </ul>
		-5	A job was newly created with the same name of the job already specified in the memory.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
				Main CPU board failure	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, replace the CPU-201R board. Save the CMOS.BIN and then replace the board. After replacing the board, upgrade the software with the version which is same as the one saved in the former CPU-201R board.</li> </ul>
		-6	The allowable job registration area (memory) was exceeded.	Setting error	<ul><li>(1)Check the following settings.</li><li>Delete unused jobs.</li></ul>

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy	
Number		Code				
		-7	A job that did not exist in the memory was specified.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
				Main CPU board failure	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, replace the CPU-201R board. Save the CMOS.BIN and then replace the board. After replacing the board, upgrade the software with the version which is same as the one saved in the former CPU-201R board.</li> </ul>	
		-8	An attempt was made to change the contents for the job prohibited from being edited.	Setting error	<ul><li>(1)Check the following settings.</li><li>Release the prohibition.</li></ul>	ပ္ပ
		-9	An error occurred during the access to a job in handle value.	Software operation error occurred	(1)Reset the alarm, and then try again. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).	4 Alar Alar
				Main CPU board failure	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, replace the CPU-201R board. Save the CMOS.BIN and then replace the board. After replacing the board, upgrade the software with the version which is same as the one saved in the former CPU-201R board.</li> </ul>	m m Messa
		-10	An error occurred in job data control system.	Software operation error occurred	(1)Reset the alarm, and then try again. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).	ne List
				Main CPU board failure	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, replace the CPU-201R board. Save the CMOS.BIN and then replace the board. After replacing the board, upgrade the software with the version which is same as the one saved in the former CPU-201R board.</li> </ul>	
		-11	An error occurred in sequence number of the accessed job.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
				Main CPU board failure	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, replace the CPU-201R board. Save the CMOS.BIN and then replace the board. After replacing the board, upgrade the software with the version which is same as the one saved in the former CPU-201R board.</li> </ul>	
		-12	An error occurred in step number of the accessed job.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
				Main CPU board failure	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, replace the CPU-201R board. Save the CMOS.BIN and then replace the board. After replacing the board, upgrade the software with the version which is same as the one saved in the former CPU-201R board.</li> </ul>	

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy
Number		Code			
		-13	A job specified at job search did not exist in the memory.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
				Main CPU board failure	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, replace the CPU-201R board. Save the CMOS.BIN and then replace the board. After replacing the board, upgrade the software with the version which is same as the one saved in the former CPU-201R board.</li> </ul>
		-16	Unused handles were lacking when an attempt was made to open a job.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
				Main CPU board failure	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, replace the CPU-201R board. Save the CMOS.BIN and then replace the board. After replacing the board, upgrade the software with the version which is same as the one saved in the former CPU-201R board.</li> </ul>
		-18	The number of instructions added to a job exceeded 9999.	Setting error	<ul><li>(1)Check the following settings.</li><li>Delete unnecessary instructions and add new instructions again.</li></ul>
		-19	The number of steps added to a job exceeded 999.	Setting error	(1)Check the following settings. Delete unnecessary steps and add new steps again.
		-22	Job information was not able to be expanded.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
				Main CPU board failure	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, replace the CPU-201R board. Save the CMOS.BIN and then replace the board. After replacing the board, upgrade the software with the version which is same as the one saved in the former CPU-201R board.</li> </ul>
		-23	Job information was not able to be acquired.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
				Main CPU board failure	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, replace the CPU-201R board. Save the CMOS.BIN and then replace the board. After replacing the board, upgrade the software with the version which is same as the one saved in the former CPU-201R board.</li> </ul>
		-24	An error occurred in cluster control.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy	
Number		Code				
				Main CPU board failure	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, replace the CPU-201R board. Save the CMOS.BIN and then replace the board. After replacing the board, upgrade the software with the version which is same as the one saved in the former CPU-201R board.</li> </ul>	
		-25	Failed to read the cluster information.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
				Main CPU board failure	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, replace the CPU-201R board. Save the CMOS.BIN and then replace the board. After replacing the board, upgrade the software with the version which is same as the one saved in the former CPU-201R board.</li> </ul>	9. 9.4
		-26	Heap area could not be obtained.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	Alarm Alarm
				Main CPU board failure	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, replace the CPU-201R board. Save the CMOS.BIN and then replace the board. After replacing the board, upgrade the software with the version which is same as the one saved in the former CPU-201R board.</li> </ul>	Message
		-90	The configuration data is damaged.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	List
				Main CPU board failure	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, replace the CPU-201R board. Save the CMOS.BIN and then replace the board. After replacing the board, upgrade the software with the version which is same as the one saved in the former CPU-201R board.</li> </ul>	
		-91	The FAT area is damaged.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
				Main CPU board failure	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, replace the CPU-201R board. Save the CMOS.BIN and then replace the board. After replacing the board, upgrade the software with the version which is same as the one saved in the former CPU-201R board.</li> </ul>	
		-92	A job data in the memory was destroyed.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy
Number		Code			
				Main CPU board failure	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, replace the CPU-201R board. Save the CMOS.BIN and then replace the board. After replacing the board, upgrade the software with the version which is same as the one saved in the former CPU-201R board.</li> </ul>
4202	SYSTEM ERROR (JOB)	1	An error occurred in parameter specifications for the access to a job.	Software operation error occurred	<ul> <li>(1)Reset the alarm.</li> <li>(2)If the error occurs again, delete the job where the alarm occurred.</li> <li>(3)If the error occurs again after the previous measures were executed, initialize the job file in the maintenance mode, and then load the saved job file.</li> <li>(4)If the error occurs again though the previous measures were executed, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		2	Access time exceeded the limit during the access to a job.	Software operation error occurred	<ul> <li>(1)Reset the alarm.</li> <li>(2)If the error occurs again, delete the job where the alarm occurred.</li> <li>(3)If the error occurs again after the previous measures were executed, initialize the job file in the maintenance mode, and then load the saved job file.</li> <li>(4)If the error occurs again though the previous measures were executed, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		3	Unapproved characters are used for a job name.	Software operation error occurred	<ul> <li>(1)Reset the alarm.</li> <li>(2)If the error occurs again, delete the job where the alarm occurred.</li> <li>(3)If the error occurs again after the previous measures were executed, initialize the job file in the maintenance mode, and then load the saved job file.</li> <li>(4)If the error occurs again though the previous measures were executed, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		4	A job was newly created with the same name of the job already specified in the memory.	Software operation error occurred	<ul> <li>(1)Reset the alarm.</li> <li>(2)If the error occurs again, delete the job where the alarm occurred.</li> <li>(3)If the error occurs again after the previous measures were executed, initialize the job file in the maintenance mode, and then load the saved job file.</li> <li>(4)If the error occurs again though the previous measures were executed, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		5	A job was newly created with the same name of the job already specified in the memory.	Software operation error occurred	<ul> <li>(1)Reset the alarm.</li> <li>(2)If the error occurs again, delete the job where the alarm occurred.</li> <li>(3)If the error occurs again after the previous measures were executed, initialize the job file in the maintenance mode, and then load the saved job file.</li> <li>(4)If the error occurs again though the previous measures were executed, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy	
Number		Code				
		6	The allowable job registration area (memory) was exceeded.	Software operation error occurred	<ul> <li>(1)Reset the alarm.</li> <li>(2)If the error occurs again, delete unused jobs.</li> <li>(3)If the error occurs again after the previous measures were executed, initialize the job file in the maintenance mode, and then load the saved job file. In that case, delete the unused jobs.</li> <li>(4)If the error occurs again though the previous measures were executed, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		7	A job that did not exist in the memory was specified.	Software operation error occurred	<ul> <li>(1)Reset the alarm.</li> <li>(2)If the error occurs again, delete the job where the alarm occurred.</li> <li>(3)If the error occurs again after the previous measures were executed, initialize the job file in the maintenance mode, and then load the saved job file.</li> <li>(4)If the error occurs again though the previous measures were executed, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	9. Ala 9.4 Ala
		8	An attempt was made to change the contents for the job prohibited from being edited.	Setting error	<ul> <li>(1)Check the following settings.</li> <li>Setting of EDIT LOCK in JOB header screen</li> <li>If the job is protected from editing, release the prohibition.</li> </ul>	arm Me
				Software operation error occurred	<ul> <li>(1)Reset the alarm.</li> <li>(2)If you edit this job, release the prohibition.</li> <li>(3)If the error occurs again, delete the job where the alarm occurred.</li> <li>(4)If the error occurs again after the previous measures were executed, initialize the job file in the maintenance mode, and then load the saved job file.</li> <li>(5)If the error occurs again though the previous measures were executed, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	ssage List
		9	An attempt was made to change the contents for the job prohibited from being edited.	Setting error	<ul> <li>(1)Check the following settings.</li> <li>Setting of EDIT LOCK in JOB header screen</li> <li>If the job is protected from editing, release the prohibition.</li> </ul>	
				Software operation error occurred	<ul> <li>(1)Reset the alarm.</li> <li>(2)If you edit this job, release the prohibition.</li> <li>(3)If the error occurs again, delete the job where the alarm occurred.</li> <li>(4)If the error occurs again after the previous measures were executed, initialize the job file in the maintenance mode, and then load the saved job file.</li> <li>(5)If the error occurs again though the previous measures were executed, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		10	An error occurred in job data control system.	Software operation error occurred	<ul> <li>(1)Reset the alarm.</li> <li>(2)If the error occurs again, delete the job where the alarm occurred.</li> <li>(3)If the error occurs again after the previous measures were executed, initialize the job file in the maintenance mode, and then load the saved job file.</li> <li>(4)If the error occurs again though the previous measures were executed, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy
Number		Code			
		11	An error occurred in sequence number of the accessed job.	Software operation error occurred	<ul> <li>(1)Reset the alarm.</li> <li>(2)If the error occurs again, delete the job where the alarm occurred.</li> <li>(3)If the error occurs again after the previous measures were executed, initialize the job file in the maintenance mode, and then load the saved job file.</li> <li>(4)If the error occurs again though the previous measures were executed, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		12	An error occurred in step number of the accessed job.	Software operation error occurred	<ul> <li>(1)Reset the alarm.</li> <li>(2)If the error occurs again, delete the job where the alarm occurred.</li> <li>(3)If the error occurs again after the previous measures were executed, initialize the job file in the maintenance mode, and then load the saved job file.</li> <li>(4)If the error occurs again though the previous measures were executed, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		13	A job specified at job search did not exist in the memory.	Software operation error occurred	<ul> <li>(1)Reset the alarm.</li> <li>(2)If the error occurs again, delete the job where the alarm occurred.</li> <li>(3)If the error occurs again after the previous measures were executed, initialize the job file in the maintenance mode, and then load the saved job file.</li> <li>(4)If the error occurs again though the previous measures were executed, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		14	There was an instruction that did not exist in a job because of inconsistency of the system software.	Software operation error occurred	<ul> <li>(1)Reset the alarm.</li> <li>(2)If the error occurs again, delete the job where the alarm occurred.</li> <li>(3)If the error occurs again after the previous measures were executed, initialize the job file in the maintenance mode, and then load the saved job file.</li> <li>(4)If the error occurs again though the previous measures were executed, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		16	Unused handles were lacking when an attempt was made to open a job.	Setting error	<ul> <li>(1)Check the following settings.</li> <li>The number of call job stacks</li> <li>Set the job configuration that decreases the number of call job stacks.</li> </ul>
				Software operation error occurred	<ul> <li>(1)Reset the alarm.</li> <li>(2)If the error occurs again, delete the job where the alarm occurred.</li> <li>(3)If the error occurs again after the previous measures were executed, initialize the job file in the maintenance mode, and then load the saved job file.</li> <li>(4)If the error occurs again though the previous measures were executed, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		18	The number of instructions added to a job exceeded 9999.	Setting error	<ul> <li>(1)Check the following settings.</li> <li>The number of steps in job</li> <li>Delete unnecessary instructions in job and add new instructions.</li> </ul>

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy
Number		Code			
				Software operation error occurred	<ul> <li>(1)Reset the alarm.</li> <li>(2)If the error occurs again, delete the job where the alarm occurred.</li> <li>(3)If the error occurs again after the previous measures were executed, initialize the job file in the maintenance mode, and then load the saved job file.</li> <li>(4)If the error occurs again though the previous measures were executed, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		19	The number of steps added to a job exceeded 9999.	Setting error	<ul> <li>(1)Check the following settings.</li> <li>The number of steps in job</li> <li>Delete unnecessary steps in job and add new steps.</li> </ul>
				Software operation error occurred	<ul> <li>(1)Reset the alarm.</li> <li>(2)If the error occurs again, delete the job where the alarm occurred.</li> <li>(3)If the error occurs again after the previous measures were executed, initialize the job file in the maintenance mode, and then load the saved job file.</li> <li>(4)If the error occurs again though the previous measures were executed, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		20	A job was newly created with the same name of the undefined job already specified in the memory.	Software operation error occurred	<ul> <li>(1)Reset the alarm.</li> <li>(2)If the error occurs again, delete the job where the alarm occurred.</li> <li>(3)If the error occurs again after the previous measures were executed, initialize the job file in the maintenance mode, and then load the saved job file.</li> <li>(4)If the error occurs again though the previous measures were executed, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		22	Failed to expand job information during the access to a job.	Software operation error occurred	<ul> <li>(1)Reset the alarm.</li> <li>(2)If the error occurs again, delete the job where the alarm occurred.</li> <li>(3)If the error occurs again after the previous measures were executed, initialize the job file in the maintenance mode, and then load the saved job file.</li> <li>(4)If the error occurs again though the previous measures were executed, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		23	The accessed job was not opened.	Software operation error occurred	<ul> <li>(1)Reset the alarm.</li> <li>(2)If the error occurs again, delete the job where the alarm occurred.</li> <li>(3)If the error occurs again after the previous measures were executed, initialize the job file in the maintenance mode, and then load the saved job file.</li> <li>(4)If the error occurs again though the previous measures were executed, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy
Number		Code			
		24	An error occurred in the cluster control process of the accessed job.	Software operation error occurred	<ul> <li>(1)Reset the alarm.</li> <li>(2)If the error occurs again, delete the job where the alarm occurred.</li> <li>(3)If the error occurs again after the previous measures were executed, initialize the job file in the maintenance mode, and then load the saved job file.</li> <li>(4)If the error occurs again though the previous measures were executed, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		25	An error occurred when reading the cluster information of the accessed job.	Software operation error occurred	<ul> <li>(1)Reset the alarm.</li> <li>(2)If the error occurs again, delete the job where the alarm occurred.</li> <li>(3)If the error occurs again after the previous measures were executed, initialize the job file in the maintenance mode, and then load the saved job file.</li> <li>(4)If the error occurs again though the previous measures were executed, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		26	Failed to acquire the necessary memory area during the access to a job.	Software operation error occurred	<ul> <li>(1)Reset the alarm.</li> <li>(2)If the error occurs again, delete the job where the alarm occurred.</li> <li>(3)If the error occurs again after the previous measures were executed, initialize the job file in the maintenance mode, and then load the saved job file.</li> <li>(4)If the error occurs again though the previous measures were executed, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		90	The configuration information for job data control is damaged.	Software operation error occurred	<ul> <li>(1)Reset the alarm.</li> <li>(2)If the error occurs again, delete the job where the alarm occurred.</li> <li>(3)If the error occurs again after the previous measures were executed, initialize the job file in the maintenance mode, and then load the saved job file.</li> <li>(4)If the error occurs again though the previous measures were executed, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		91	The FAT information for job data is damaged.	Software operation error occurred	<ul> <li>(1)Reset the alarm.</li> <li>(2)If the error occurs again, delete the job where the alarm occurred.</li> <li>(3)If the error occurs again after the previous measures were executed, initialize the job file in the maintenance mode, and then load the saved job file.</li> <li>(4)If the error occurs again though the previous measures were executed, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		92	A job data was destroyed.	Software operation error occurred	<ul> <li>(1)Reset the alarm.</li> <li>(2)If the error occurs again, delete the job where the alarm occurred.</li> <li>(3)If the error occurs again after the previous measures were executed, initialize the job file in the maintenance mode, and then load the saved job file.</li> <li>(4)If the error occurs again though the previous measures were executed, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy	
Number		Code				
		99	A job data in the memory was destroyed.	Software operation error occurred	<ul> <li>(1)Reset the alarm.</li> <li>(2)If the error occurs again, delete the job where the alarm occurred.</li> <li>(3)If the error occurs again after the previous measures were executed, initialize the job file in the maintenance mode, and then load the saved job file.</li> <li>(4)If the error occurs again though the previous measures were executed, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
4203	SYSTEM ERROR(POSITION DATA)	-1	The memory area for position data is lacking at the initialization of the position data control process.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
				Main CPU board failure	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, replace the CPU-201R board. Save the CMOS.BIN and then replace the board. After replacing the board, upgrade the software with the version which is same as the one saved in the former CPU-201R board.</li> </ul>	Ala 4 Ala
		-3	The number of axes for position data is zero.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	rm rm Messa
				Main CPU board failure	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, replace the CPU-201R board. Save the CMOS.BIN and then replace the board. After replacing the board, upgrade the software with the version which is same as the one saved in the former CPU-201R board.</li> </ul>	age List
		-6	Unused position data file is destroyed.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
				Main CPU board failure	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, replace the CPU-201R board. Save the CMOS.BIN and then replace the board. After replacing the board, upgrade the software with the version which is same as the one saved in the former CPU-201R board.</li> </ul>	
		-7	Unused position data file does not exist.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
				Main CPU board failure	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, replace the CPU-201R board. Save the CMOS.BIN and then replace the board. After replacing the board, upgrade the software with the version which is same as the one saved in the former CPU-201R board.</li> </ul>	
		-8	Position data file is destroyed.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy	
Number		Code				
				Main CPU board failure	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, replace the CPU-201R board. Save the CMOS.BIN and then replace the board. After replacing the board, upgrade the software with the version which is same as the one saved in the former CPU-201R board.</li> </ul>	
		-9	Position data control information is destroyed.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
				Main CPU board failure	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, replace the CPU-201R board. Save the CMOS.BIN and then replace the board. After replacing the board, upgrade the software with the version which is same as the one saved in the former CPU-201R board.</li> </ul>	9. 9.4
		-10	An error occurred in specified position data number.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	Alarm Alarm
				Main CPU board failure	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, replace the CPU-201R board. Save the CMOS.BIN and then replace the board. After replacing the board, upgrade the software with the version which is same as the one saved in the former CPU-201R board.</li> </ul>	Message
		-11	Position data is not registered.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	List
				Main CPU board failure	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, replace the CPU-201R board. Save the CMOS.BIN and then replace the board. After replacing the board, upgrade the software with the version which is same as the one saved in the former CPU-201R board.</li> </ul>	
		-12	An attempt was made to access the undefined position data.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
				Main CPU board failure	(1)Reset the alarm, and then try again. (2)If the alarm occurs again, replace the CPU-201R board. Save the CMOS.BIN and then replace the board. After replacing the board, upgrade the software with the version which is same as the one saved in the former CPU-201R board.	
		-13	An attempt was made to access the position data for the undefined control group.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy	
Number		Code				
				Main CPU board failure	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, replace the CPU-201R board. Save the CMOS.BIN and then replace the board. After replacing the board, upgrade the software with the version which is same as the one saved in the former CPU-201R board.</li> </ul>	
		-20	Inconsistency of data.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
				Main CPU board failure	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, replace the CPU-201R board. Save the CMOS.BIN and then replace the board. After replacing the board, upgrade the software with the version which is same as the one saved in the former CPU-201R board.</li> </ul>	9. 9.4
4204	SYSTEM ERROR (POSITION DATA)	1	The number of axes for all the control groups is zero at the initialization of the position data control process	Software operation error occurred	<ul> <li>(1)Reset the alarm.</li> <li>(2)If the error occurs again, delete the job where the alarm occurred.</li> <li>(3)If the error occurs again after the previous measures were executed, initialize the job file in the maintenance mode, and then load the saved job file.</li> <li>(4)If the error occurs again though the previous measures were executed, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	Alarm Alarm Messa
		3	The number of axes for position data is zero.	Software operation error occurred	<ul> <li>(1)Reset the alarm.</li> <li>(2)If the error occurs again, delete the job where the alarm occurred.</li> <li>(3)If the error occurs again after the previous measures were executed, initialize the job file in the maintenance mode, and then load the saved job file.</li> <li>(4)If the error occurs again though the previous measures were executed, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	age List
		6	Unused position data file is destroyed.	Software operation error occurred	<ul> <li>(1)Reset the alarm.</li> <li>(2)If the error occurs again, delete the job where the alarm occurred.</li> <li>(3)If the error occurs again after the previous measures were executed, initialize the job file in the maintenance mode, and then load the saved job file.</li> <li>(4)If the error occurs again though the previous measures were executed, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		7	Unused position data file does not exist.	Setting error	<ul> <li>(1)Check the following settings.</li> <li>The number of steps in job (position data)</li> <li>Delete unnecessary position data in job and add new position data.</li> </ul>	
				Software operation error occurred	<ul> <li>(1)Reset the alarm.</li> <li>(2)If the error occurs again, delete the job where the alarm occurred.</li> <li>(3)If the error occurs again after the previous measures were executed, initialize the job file in the maintenance mode, and then load the saved job file.</li> <li>(4)If the error occurs again though the previous measures were executed, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy	
Number		Code				
		8	Position data file is destroyed.	Software operation error occurred	<ul> <li>(1)Reset the alarm.</li> <li>(2)If the error occurs again, delete the job where the alarm occurred.</li> <li>(3)If the error occurs again after the previous measures were executed, initialize the job file in the maintenance mode, and then load the saved job file.</li> <li>(4)If the error occurs again though the previous measures were executed, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		9	Position data control information is destroyed.	Software operation error occurred	<ul> <li>(1)Reset the alarm.</li> <li>(2)If the error occurs again, delete the job where the alarm occurred.</li> <li>(3)If the error occurs again after the previous measures were executed, initialize the job file in the maintenance mode, and then load the saved job file.</li> <li>(4)If the error occurs again though the previous measures were executed, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		10	An error occurred in specified position data number.	Software operation error occurred	<ul> <li>(1)Reset the alarm.</li> <li>(2)If the error occurs again, delete the job where the alarm occurred.</li> <li>(3)If the error occurs again after the previous measures were executed, initialize the job file in the maintenance mode, and then load the saved job file.</li> <li>(4)If the error occurs again though the previous measures were executed, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		11	Position data is not registered.	Setting error	<ul> <li>(1)Check the following settings.</li> <li>Teaching of alarm occurred point Teaching the point where alarm occurred.</li> </ul>	
				Software operation error occurred	<ul> <li>(1)Reset the alarm.</li> <li>(2)If the error occurs again, delete the job where the alarm occurred.</li> <li>(3)If the error occurs again after the previous measures were executed, initialize the job file in the maintenance mode, and then load the saved job file.</li> <li>(4)If the error occurs again though the previous measures were executed, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		12	An attempt was made to access the undefined position data.	Software operation error occurred	<ul> <li>(1)Reset the alarm.</li> <li>(2)If the error occurs again, delete the job where the alarm occurred.</li> <li>(3)If the error occurs again after the previous measures were executed, initialize the job file in the maintenance mode, and then load the saved job file.</li> <li>(4)If the error occurs again though the previous measures were executed, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
Alarm	Alarm Name	Sub	Meaning	Cause	Remedy	
--------	--------------------------------	------	---	--------------------------------------	--	------------------------
Number		Code				
		13	An attempt was made to access the position data for the undefined control group.	Software operation error occurred	<ul> <li>(1)Reset the alarm.</li> <li>(2)If the error occurs again, delete the job where the alarm occurred.</li> <li>(3)If the error occurs again after the previous measures were executed, initialize the job file in the maintenance mode, and then load the saved job file.</li> <li>(4)If the error occurs again though the previous measures were executed, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		17	An error occurred in exceptional control during the position data control process.	Software operation error occurred	<ul> <li>(1)Reset the alarm.</li> <li>(2)If the error occurs again, delete the job where the alarm occurred.</li> <li>(3)If the error occurs again after the previous measures were executed, initialize the job file in the maintenance mode, and then load the saved job file.</li> <li>(4)If the error occurs again though the previous measures were executed, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	9. 9.4
		20	Undefined position exists.	Software operation error occurred	<ul> <li>(1)Reset the alarm.</li> <li>(2)If the error occurs again, delete the job where the alarm occurred.</li> <li>(3)If the error occurs again after the previous measures were executed, initialize the job file in the maintenance mode, and then load the saved job file.</li> <li>(4)If the error occurs again though the previous measures were executed, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	Alarm Alarm Message
4206	SYSTEM ERROR (TRANSMISSION)		subcode 1 to 4: Signifies the internal software error during data transmission.	Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	List
4207	SYSTEM ERROR (MOTION)	1	An interrupt undefined in the main command from the system control section occurred.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		2	An interrupt undefined in the sub command from the system control section occurred.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		3	The interrupt command that was sent previously from the system control section is being processed.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		4	An error was detected in the interrupt command data from the system control section.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy
Number		Code			
		5	An undefined command was detected in the sub segment task of MOTION section.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		6	An undefined command was detected in the servo-related processing of MOTION section.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		7	An undefined command was detected in the offline processing task of MOTION section.	Software operation error occurred	(1)Reset the alarm, and then try again. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).
		8	An undefined command was detected in the utility task of MOTION section.	Software operation error occurred	(1)Reset the alarm, and then try again. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).
		10	Task Token is not generated.	Software operation error occurred	(1)Reset the alarm, and then try again. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).
		11	Mail-box Token is not generated.	Software operation error occurred	(1)Reset the alarm, and then try again. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).
		12	Semaphore Token is not generated.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		14	RMS receiving data error	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		15	RMS sending data error	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		16	RMS receiving unit error	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy	
Number		Code				
		18	Task generation error	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		19	Mail-box generation error	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		20	Semaphore generation error	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	9.4
		22	TCB area overflow	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	Alarm Alarm
		23	Stack area overflow	Software operation error occurred	(1)Reset the alarm, and then try again. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).	Message
		24	Mail-box area overflow	Software operation error occurred	(1)Reset the alarm, and then try again. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).	List
		25	Semaphore area overflow	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		30	Interrupt main command error	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		33	Incorrect control group designation	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		34	Offline bank semaphore reception error	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy
Number		Code			
		35	m_gen_area semaphore reception error	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		36	Offline HA processing time-out	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		37	DM_BANK flag error (DM_BANK conversion processing)	Software operation error occurred	(1)Reset the alarm, and then try again. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).
		38	S -> M offline processing command type error	Software operation error occurred	(1)Reset the alarm, and then try again. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).
		39	Function specification error in the data transmission to the sensor board	Software operation error occurred	(1)Reset the alarm, and then try again. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).
		40	Error in designation of application in the request of general-purpose data preset for each application.	Software operation error occurred	(1)Reset the alarm, and then try again. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).
		45	Mail-box of sequence task is not ready.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		46	Control-group usage undefined	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		47	Segment task polling command error	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		48	Physical axis number error	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy	
Number		Code				
		49	The control group impossible to release the brake	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		50	Sub-segment request FULL	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		51	Sub-segment process time-out	Software operation error occurred	(1)Reset the alarm, and then try again. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).	2 .0 2
		52	Data latch request FULL	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	Alarm
		53	Data latch process time-out	Software operation error occurred	(1)Reset the alarm, and then try again. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).	• • • • • • • • • • • • • • • • • • • •
		54	AXIS command request FULL	Software operation error occurred	(1)Reset the alarm, and then try again. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).	
		55	AXIS command process time-out	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		56	Positioning monitor request FULL	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		57	Positioning monitor process time- out	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		58	Failed AXIS servo OFF command request during category1 emergency stop	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy
Number		Code			
		59	AXIS servo OFF command execution system not set during category1 emergency stop	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		61	Conversion primary expression for Power Source command <-> EW command not prepared	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		62	Duplicated request error during master control-group tracking	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		63	GVM shared resource semaphore error	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		64	Job queue DEQUE error	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		66	Execution system decision table not set	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		67	Unknown mode data (Without TEACH/PLAY mode data)	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		68	Shift-value output time-out of the general-purpose sensor	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		69	Interrupt main status set	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		71	System number error at the master side in twin synchronous system	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy	
Number		Code				
		72	No data link added to the command	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		73	Setting status error of the user coordinates file	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		75	Previous path data reference error	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	0 <u>9</u>
		79	Inner track zone status error	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	Alarm
		80	Instruction queue and instruction system data area overflow	Software operation error occurred	(1)Reset the alarm, and then try again. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).	
		81	Offline answer bank flag error	Software operation error occurred	(1)Reset the alarm, and then try again. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).	<u>-</u> 
		82	Path and trace queue ENQUE BANK error	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		83	Pending and block end request FULL	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		84	Base axis file type error	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		85	Output buffer SYSCON for automatic test data in use	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy
Number		Code			
		86	Conversion completion status for AXIS section feedback latch data not established	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		88	File C1 through C3 for calibration between manipulators not set	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		89	File C1 through C3 for conveyor calibration not set	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		90	HA function error (conv_pos_data())	Setting error	<ul> <li>(1)Check the following settings.</li> <li>Correct the job so that the target position data is within the motion range.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		91	HA function error (conv_shift_data())	Setting error	<ul> <li>(1)Check the following settings.</li> <li>Correct the job so that the target position data is within the motion range.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		94	HA function error (conv_pulse_to_angle())	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		100	Control-group axis configuration information parameter error	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		101	Error in the parameter for the table for physical axes	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		102	Error in the parameter for the table for physical TU	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		103	Excessive number of control group axes in use	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy	
Number		Code				
		104	JOG and PLAY maximum speed setting parameter error	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		121	Job argument stack overflow	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		122	Job argument stack underflow	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	9.4 9.4
		123	Designation error of the fetched feedback pulse area at preparation of current value	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	Alarm Alarm
		128	Time-out for waiting permission to modify the number of averaging times	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	Message
		129	Object undefined for CLEAR instruction	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	- ist
		130	No space in RT_BANK setting area for correction-amount data	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		131	Queue operation error for variable write-in history at pre-reading (at ENQUE)	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		132	Queue operation error for variable write-in history at pre-reading (at DEQUE)	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		133	Queue operation error for variable write-in history at pre-reading (undefined operation)	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy
Number		Code			
		134	Queue operation error for variable write-in history at pre-reading (data length too long)	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		135	Queue operation error for score- board setting history (at ENQUE)	Software operation error occurred	<ul><li>(1)Reset the alarm, and then try again.</li><li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li></ul>
		136	Queue operation error for score- board setting history (at DEQUE)	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		137	Queue operation error for score- board setting history (undefined operation)	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		138	Queue operation error for score- board setting history (data length too long)	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		139	Queue operation error for instruction execution (at ENQUE)	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		140	Queue operation error for instruction execution (at DEQUE)	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		141	Queue operation error for instruction execution (undefined operation)	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		142	Queue operation error for instruction execution (data length too long)	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		143	Queue operation error for WORK ID conveyor (at ENQUE)	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy	
Number		Code				
		144	Queue operation error for WORK ID conveyor (at DEQUE)	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		145	Queue operation error for WORK ID conveyor (undefined operation)	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		146	Queue operation error for WORK ID conveyor (data length too long)	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	9. 9.4
		147	Queue operation error for WORK IN/OUT checking convey or (at ENQUE)	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	Alarm Alarm
		148	Queue operation error for WORK IN/OUT checking convey or (at DEQUE)	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	Message
		149	Queue operation error for WORK IN/OUT checking conveyor (undefined operation)	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	List
		150	Queue operation error for WORK IN/OUT checking conveyor (data length too long)	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		151	Queue operation error for waiting for semaphore for LOCK instruction (at ENQUE)	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		152	Queue operation error for waiting for semaphore for LOCK instruction (at DEQUE)	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		153	Queue operation error for waiting for semaphore for LOCK instruction (undefined operation)	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy	
Number		Code				
		154	Queue operation error for waiting for semaphore for LOCK instruction (data length too long)	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		221	Transfer data overflow in offline data bank	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		222	Impossible to execute system exclusive for system job	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	9.4 9.4
		223	Event queue number range exceeded	Software operation error occurred	(1)Reset the alarm, and then try again. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).	Alarm Alarm
		225	The number of WORK ID data and the MAX. WORK FIND COUNT unmatched (MOTION ≠ CV)	Software operation error occurred	(1)Reset the alarm, and then try again. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).	Message
		226	The number of WORK IN/OUT data and the MAX. WORK FIND COUNT unmatched (MOTION ≠ CV)	Software operation error occurred	(1)Reset the alarm, and then try again. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).	List
		227	Excessive number of scheduling for execution of instructions	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		228	Instruction execution scheduling impossible	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		229	Illegal 1st-line move instruction at execution of +SMOV instruction	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		230	Impossible to execute the slave circular interpolation and the master circular interpolation at the same time	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy	
Number		Code				
		232	Illegal index value for a +MOVx instruction	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		233	No xth-line move instruction exists where the master control group belongs.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		234	Marking error for WORK ID conveyor queue (empty queue)	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	9. 9.4
		235	Marking error for WORK IN/OUT conveyor queue (empty queue)	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	Alarm Alarm
		236	Data error 1 at restarting after an emergency stop (actual status and the data status unmatched)	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	Message
		237	Data error 2 at restarting after an emergency stop (actual status and the data status unmatched)	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	List
		238	Data error 3 at restarting after an emergency stop (actual status and the data status unmatched)	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		239	Time-out for receiving segment data output request	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		240	The number which designates the setting area of correction amount in RT_BANK exceeded the limit value.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		241	Task error of the function calling source (cv_sync_intr ( ))	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy
Number		Code			
		244	GETTOOLW manipulator designation error	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		245	Overflow of entry number for instruction execution	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		246	Data latch processing (function number overflow)	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		247	Data latch processing (real-time status number overflow)	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		248	Failed to set a timer unit. (No allocation space for timer unit setting)	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		250	GETS instruction internal error	Software operation error occurred	(1)Reset the alarm, and then try again. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).
		251	SETFILE undefined file	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		252	GETFILE undefined file	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		253	The parameter was destroyed when a GETPRM instruction was executed.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		254	Null pointer assignment detected	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy	
Number		Code				
		255	Function or other processing parameter error	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		260	Arithmetic answer is not set at pre-reading (ADV_HA_ANS.flag == OFF)	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		261	Heap area obtainment failure (A_BANK)	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	9.4
		262	Heap area obtainment failure (C_BANK)	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	Alarm Alarm
		263	Heap area obtainment failure (Instruction queue)	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	Message
		264	Heap area obtainment failure (Path/trace queue)	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	List
		278	MEASON TRQ Instruction control axis specification error	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		279	Specified MSS system instance is not generated.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		280	API error (HDAS_get_alias_name())	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		500	SL undefined interrupt command (main command)	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy
Number		Code			
		501	SL undefined interrupt command (sub command)	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		502	Previous SL interrupt command processing	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		503	SL interrupt command data error	Software operation error occurred	(1)Reset the alarm, and then try again. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).
		999	Arithmetic section error (segment data all zero time-out)	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		1000	System clock (RTC) setting error	Software operation error occurred	(1)Reset the alarm, and then try again. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).
		1001	System task priority arrangement error	Software operation error occurred	(1)Reset the alarm, and then try again. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).
		1002	VxWorks primitive error (msgQCreate)	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		1003	VxWorks primitive error (msgQSend)	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		1005	VxWorks primitive error (semBCreate)	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		1007	VxWorks primitive error (semTake)	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy	
Number		Code				
		1100	Failed system job environment configuration	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		1101	MotoPlus environment setup error	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
4208	SYSTEM ERROR(ARITH)	1	pre-reading task is not completed.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	9.4
		6	No previous bank exists.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	Alarm Alarm
		7	The answer bank flag is ON.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	Message
		8	An error occurred in preparation of current position.	Software operation error occurred	(1)Reset the alarm, and then try again. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).	List
		11	The previous bank's pre-reading conversion could not correctly be completed.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		12	A manipulator designation error occurred at JOG operation using the external reference point.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		13	Designation error of cubic interference coordinates	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		14	Path control position data error of pre-reading bank	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy
Number		Code			
		16	Station/base axis motion command error	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		18	User coordinates number error	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		20	pre-reading task not completed at master in twin synchronous system	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		23	Dynamic model arithmetic error	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		24	Speed limit control error (excessive moment of gravity)	Setting error	<ul> <li>(1)Check the following settings.</li> <li>The allowable breaking torque was exceeded only by the gravity moment. Set the gravity value of the tool within payload of the manipulator.</li> <li>Teach the manipulator orientation that does not become the overload for each-axes of the manipulator.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		25	Square root of a negative number	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		26	The system number is not set at master in twin synchronous system.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		29	FORMCUT internal control error	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		35	No master-group is designated at preparation of master-tool user coordinates.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy	
Number		Code				
		41	Pulse linked JOG function error	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		42	Special JOG operation error	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		57	Arithmetic error occurred when calculating the acceleration and deceleration time (Function acceleration and deceleration control)	Software operation error occurred	(1)Reset the alarm, and then try again. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).	0. 9.
		59	Arithmetic error occurred when calculating PL control (Function acceleration and deceleration control)	Software operation error occurred	(1)Reset the alarm, and then try again.(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).	Alarm ∆larm M
		60	Arithmetic error occurred when calculating Function acceleration and deceleration dry run.	Software operation error occurred	(1)Reset the alarm, and then try again. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).	ALCODA
		61	Arithmetic error occurred when calculating current path of continuous motion stop operation	Software operation error occurred	(1)Reset the alarm, and then try again. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).	<u>č</u>
		62	Arithmetic error occurred when calculating next path of continuous motion stop operation	Software operation error occurred	(1)Reset the alarm, and then try again. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).	
		63	Arithmetic error occurred when calculating acceleration time when continuous motion in the pre- reading processing	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		64	Arithmetic error occurred when calculating deceleration time when continuous motion in the pre- reading processing	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		65	Arithmetic error occurred when calculating acceleration and deceleration time when teaching.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy	
Number		Code				
		66	Arithmetic error occurred when calculating acceleration and deceleration time for plucking in pre-reading processing 1	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		67	Arithmetic error occurred when calculating acceleration and deceleration time for plucking in pre-reading processing 2	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		68	Arithmetic error occurred when calculating acceleration and deceleration time for plucking in pre-reading processing 3	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	9. 9.4
		69	Arithmetic error occurred when calculating acceleration and deceleration time for plucking in pre-reading processing 4	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	Alarm Alarm
		70	Arithmetic error occurred when calculating acceleration and deceleration for PL control plucking in pre-reading processing 1	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	Message L
		71	Arithmetic error occurred when calculating acceleration and deceleration for PL control plucking in pre-reading processing 2	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	ist
		72	Arithmetic error occurred when calculating acceleration and deceleration for plucking	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		73	Arithmetic error occurred when calculating acceleration and deceleration for PL control in pre- reading processing 1	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		74	Arithmetic error occurred when calculating acceleration and deceleration for PL control in pre- reading processing 2	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy	
Number		Code				
		75	Arithmetic error occurred when calculating acceleration and deceleration for PL control in pre- reading processing 3	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		76	Arithmetic error occurred when calculating acceleration and deceleration for PL control in pre- reading processing 4	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		77	Arithmetic error occurred when calculating acceleration and deceleration for PL control in pre- reading processing 5	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	9. Ala 9.4 Ala
		85	Arithmetic error occurred when acceleration and deceleration for canceling PL control of station were recalculated.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	rm rm Messa
		86	PL during current → Arithmetic error occurred when calculating acceleration time for CONT	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	age List
		87	Arithmetic error occurred when calculating acceleration and deceleration for PL control in pre- reading processing	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		88	Arithmetic error occurred when acceleration and deceleration for moving to the different conveyer coordinate were calculated.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		89	Operation command group which pre-reading is not completed detection error	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		65535	For HA debug use	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
4209	OFFLINE SYSTEM ERROR (ARITH)	100	Data setting error in offline data bank	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy
Number		Code			
		101	Data setting error in offline answer bank	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		102	OFF_USER_POS occupation control error	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		103	OFF_USER_POS valid control error	Software operation error occurred	(1)Reset the alarm, and then try again. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).
		104	Mail-receiving error of offline task	Software operation error occurred	(1)Reset the alarm, and then try again. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).
		105	Offline occupation control error	Software operation error occurred	(1)Reset the alarm, and then try again. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).
		107	OFF_USER_ROT_POS occupation control error	Software operation error occurred	(1)Reset the alarm, and then try again. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).
		108	OFF_USER_ROT_POS valid control error	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		109	OFF_CV_CALIB_POS occupation control error	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		110	OFF_CV_CALIB_POS valid control error	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		111	Incorrect teaching for offline conveyor tracking turntable function	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy	
Number		Code				
		112	No manipulator is designated for offline conveyor tracking turntable function.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
4210	SYSTEM ERROR (LOCAL VARIABLE)	-1	Local variable is not used.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		-2	Memory area for local variable could not be obtained.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	9. 9.4
		-3	No unused handle value exists when local variable area is created.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	Alarm Alarm
		-4	An error occurred in exclusive control.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	Message
		-5	Handle value is invalid for specified local variable.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	List
		-6	Handle value is incorrect for specified local variable.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		-7	An error occurred when memory area for local variable was released.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		-8	An error occurred when memory area for local variable was registered.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		-9	Local variable control process is not initialized.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy
Number		Code			
		-10	Local variable area shared heap area.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		-11	An error occurred in exclusive control.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		-12	An error occurred in exclusive control when control of the local variable was processed.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
4220	SERVO POWER OFF FOR JOB		subcode: Control group	Setting error	<ul> <li>(1)Check the following settings.</li> <li>Turn OFF the servo power supply, and then turn ON the servo power supply for the group axis to be operated.</li> </ul>
4221	SERVO POWER OFF FOR JOB		subcode: Control group	Setting error	• Turn OFF the servo power supply, and then turn ON the servo power supply for the group axis to be operated.
4226	COMMUNICATION SERVICE ERROR	1	The communication channel could not be opened/closed at OPEN/ CLOSE instruction execution.	Setting error	<ul><li>(1)Check the following settings.</li><li>Setting of the RS (transmission) parameter</li></ul>
		100	The communication port is already opened.	Setting error	(1)Check the following settings. The serial port setting
		101	The communication port is not opened.	Setting error	(1)Check the following settings. The serial port setting
		102	No space was found in data sent buffer.	Setting error	(1)Check the following settings. The serial port setting
		103	The setting value for the event queue designation parameter is incorrect.	Setting error	<ul> <li>(1)Check the following settings.</li> <li>• RS157 • • • Set to 1 to 4</li> </ul>
		105	The type of output data is incorrect.	Setting error	(1)Check the following settings. The serial port setting

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy	
Number		Code				
4228	WRONG DATA			Software operation error occurred	<ul> <li>(1)Reset the alarm, and then execute following operation.</li> <li>Select a sub menu [WRONG DATA LOG] under main menu [SETUP].</li> <li>Execute "RESTORE" by selecting "UTILITY" from the pull-down menu.</li> <li>*Occurrence date changes to restoration date after it is restored.</li> <li>Turn the power OFF and then ON to check the factor of the inconsistency 1 and 2, on the data inconsistency screen in maintenance mode . The factor 1: Check the position of the corresponding file again</li> <li>*The factor 3: Just turn the power OFF and then ON again.</li> <li>(2)If it would not restore, select "RE CHECK" from the pull-down menu.</li> <li>(3)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	9. 9.4
				Data error	<ul> <li>(1) If different axes configuration data is loaded, the system data becomes incorrect status, which causes this alarm. In this case, execute the following operations.</li> <li>Select a sub menu [WRONG DATA LOG] under main menu [SETUP].</li> <li>Select "UTILITY" from the pull-down menu to execute "RESTORE".</li> <li>Load correct axes configuration data</li> <li>(2)If it would not restore, select "RE CHECK" from the pull-down menu, and then load correct axes configuration data.</li> <li>(3)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	Alarm Alarm Message List
4229	ETHERNET PROCESS ERROR	1	An error occurred in the acquisition process of the IP address during the IP address monitoring process of the Ethernet function.	Setting error	<ul> <li>(1)Check the following settings.</li> <li>The DHCP server operation (If the DHCP is used)</li> <li>The network status (If the DHCP is used)</li> </ul>	
				Main CPU board failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the CPU-201R board. Save the CMOS.BIN before replace the board to be safe. Replace the CPU-201R board, and then Please execute the update. And, please load CMOS.BIN.</li> </ul>	
		2	An error occurred in the acquisition process of sub net mask during the network service data creation process of the Ethernet function.	Setting error	<ul> <li>(1)Check the following settings.</li> <li>The DHCP server operation (If the DHCP is used)</li> <li>The network status (If the DHCP is used)</li> </ul>	
				Main CPU board failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the CPU-201R board. Save the CMOS.BIN before replace the board to be safe. Replace the CPU-201R board, and then Please execute the update. And, please load CMOS.BIN.</li> </ul>	

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy	
Number		Code				
		3	An error occurred in the acquisition process of gateway during the network service data creation process of the Ethernet function.	Setting error	<ul> <li>(1)Check the following settings.</li> <li>The DHCP server operation (If the DHCP is used)</li> <li>The network status (If the DHCP is used)</li> </ul>	
				Main CPU board failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the CPU-201R board. Save the CMOS.BIN before replace the board to be safe. Replace the CPU-201R board, and then Please execute the update. And, please load CMOS.BIN.</li> </ul>	
		4	An error occurred in the conversion process of gateway address during the network service data creation process of the Ethernet function.	Setting error	<ul> <li>(1)Check the following settings.</li> <li>The DHCP server operation (If the DHCP is used)</li> <li>The network status (If the DHCP is used)</li> </ul>	9.4 A
				Main CPU board failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the CPU-201R board. Save the CMOS.BIN before replace the board to be safe. Replace the CPU-201R board, and then Please execute the update. And, please load CMOS.BIN.</li> </ul>	larm Iarm Mes
		6	An error occurred in the acquisition process of domain during the network service data creation process of the Ethernet function.	Setting error	<ul> <li>(1)Check the following settings.</li> <li>The DHCP server operation (If the DHCP is used)</li> <li>The network status (If the DHCP is used)</li> </ul>	sage List
				Main CPU board failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the CPU-201R board. Save the CMOS.BIN before replace the board to be safe. Replace the CPU-201R board, and then Please execute the update. And, please load CMOS.BIN.</li> </ul>	
		8	An error occurred in the acquisition process of host name during the network service data creation process of the Ethernet function.	Setting error	<ul> <li>(1)Check the following settings.</li> <li>The DHCP server operation (If the DHCP is used)</li> <li>The network status (If the DHCP is used)</li> </ul>	
				Main CPU board failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the CPU-201R board. Save the CMOS.BIN before replace the board to be safe. Replace the CPU-201R board, and then Please execute the update. And, please load CMOS.BIN.</li> </ul>	
4300	VERIFY ERROR (SERVO PARAMETER)			Setting error	<ul> <li>(1)Reset the alarm</li> <li>(2)If the alarm occurs again, check the parameter setting if there were any parameters which were modified before the alarm.</li> <li>(3)If the alarm occurs again or when it occurs other than above mentioned (2) case, contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy	
Number		Code				
				Servo control circuit board failure	<ul><li>(1)Reset the alarm</li><li>(2)If the alarm occurs again, replace the EAXA, EAXB board. Save the CMOS.BIN before replacing the board to be safe.</li></ul>	
4301	CONTACTOR ERROR		subcode: Signifies the physical No. of contactor in which the alarm occurred Before performing a connection check of the wiring, turn OFF the controller power. Make sure that all the LEDs of SERVOPACK and converter are OFF, then verify that no electricity is charged using equipment such as a tester. This process may take a few minutes after shutting off the power.	Module failure (contactor)	<ul> <li>(1)Reset the alarm.</li> <li>(2)Check the insertion and connection of the followings.</li> <li>SF2300-CN4</li> <li>YPU-CN607, CN611</li> <li>(3)Check if the contactors (1KM and 2KM) are open, and not damaged by melting or sticking.</li> <li>(4)If the alarm occurs again, replace the YPU01unit. Save the CMOS.BIN before replacing the unit to be safe.</li> </ul>	9. Ala 9.4 Ala
				Servo control circuit board failure	<ul><li>(1)Reset the alarm.</li><li>(2)If the alarm occurs again, replace the EAXA, EAXB board. Save the CMOS.BIN before replacing the board to be safe.</li></ul>	arm Arm Me
4302	BRAKE CIRCUIT ERROR			Software operation error occurred	<ul> <li>(1)Reset the alarm</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	ssage Lis
				Servo control circuit board failure	<ul><li>(1)Reset the alarm.</li><li>(2)If the alarm occurs again, replace the EAXA, EAXB board. Save the CMOS.BIN before replacing the board to be safe.</li></ul>	st
4303	CONVERTER READY SIGNAL ERROR		subcode: Signifies the physical No. of converter in which the alarm occurred	Connection failure	<ul> <li>(1)Reset the alarm</li> <li>(2)If the alarm occurs again, check the connection and inserting state of the following cables and connectors.</li> <li>EAXA01-CN507,510</li> <li>EAXB01-CN531,532,533</li> <li>converter-CN551,553</li> <li>EX1SV (External axis servo pack) -CN591,592</li> </ul>	
				Module failure (converter)	<ul> <li>(1)Reset the alarm</li> <li>(2)Check if the contactors (1KM and 2KM) are open, and not damaged by melting or sticking.</li> <li>(3)If the alarm occurs again, replace the YPU01 unit. Save the CMOS.BIN before replacing the board to be safe.</li> </ul>	
				Servo control circuit board failure	<ul><li>(1)Reset the alarm</li><li>(2)If the alarm occurs again, replace the EAXA, EAXB board. Save the CMOS.BIN before replacing the board to be safe.</li></ul>	
				Module failure (converter)	<ul><li>(1)Reset the alarm</li><li>(2)If the alarm occurs again, replace the converter.</li></ul>	

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy
Number		Code			
4304	CONVERTER INPUT POWER ERROR		subcode: Signifies the physical No. of converter in which the alarm occurred	Module failure (converter)	<ul> <li>(1)Reset the alarm</li> <li>(2)Check if the contactors (1KM and 2KM) are open, and not damaged by melting or sticking.</li> <li>(3)If the alarm occurs again, replace the YPU01 unit. Save the CMOS.BIN before replacing the board to be safe.</li> </ul>
				Connection failure	<ul> <li>(1)Reset the alarm</li> <li>(2)If the alarm occurs again, check the connection and inserting state of the following cables and connectors.</li> <li>EAXA01-CN507,510</li> <li>EAXB01-CN08</li> <li>Converter CN551,553</li> <li>YPU-CN602</li> </ul>
				Module failure (converter)	<ul><li>(1)Reset the alarm</li><li>(2)If the alarm occurs again, replace the converter.</li></ul>
4305	CONVERTER CIRCUIT CHARGE ERROR		subcode: Signifies the physical No. of converter in which the alarm occurred	Module failure (converter)	<ul><li>(1)Reset the alarm</li><li>(2)If the alarm occurs again, replace the converter.</li></ul>
				Module failure (Regenerative resistor)	Check if there is no ground fault in the regeneration resistors.
4306	AMPLIFIER READY SIGNAL ERROR		subcode: Signifies the axis in which the alarm occurred	Connection failure	<ul> <li>(1)Reset the alarm</li> <li>(2)If the alarm occurs again, check the connection and inserting state of the following cables and connectors.</li> <li>EAXA-CN501 ~ 506,CN510</li> <li>EAXB-CN531,532,533</li> <li>Amplifier-CN581,582</li> <li>Converter-CN551,552A,552B</li> </ul>
				Module failure (converter)	<ul> <li>(1)Reset the alarm</li> <li>(2)If the alarm occurs again, check if the LED (green) for amplifier is lighted up when servo power is ON.</li> <li>(3) If it is lighted, replace the converter.</li> </ul>
				Module failure (amplifier)	<ul><li>(1)Reset the alarm</li><li>(2)If the alarm occurs again, replace the corresponding amplifier.</li></ul>
				EAXA board failure	(1)Reset the alarm (2)If the alarm occurs again, replace the EAXA/EAXB board. Save the CMOS.BIN before replacing the board to be safe.
4307	SERVO ON DEFECTIVE SPEED		subcode: Signifies the axis in which the alarm occurred	Movement of axis when the SERVO ON process	Turn ON the servo power after 5 or more seconds from the alarm occurrence.
		1		Mechanical failure	Check that the manipulator is not moving when the servo turned ON.
				YBK board failure	Check that the brake has not been released because the brake relay is broken.

Alarm Alarm Messag

.9

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy	
Number		Code				
				Connection failure	<ul> <li>(1)Reset the alarm</li> <li>(2)If the alarm occurs again, check the connection and inserting state of the following cables and connectors.</li> <li>Amplifier-CN584</li> <li>The power cable connection of the manipulator cable.</li> </ul>	
				Connection failure	<ul> <li>(1)Reset the alarm</li> <li>(2)If the alarm occurs again, check the connection and inserting state of the following cables and connectors.</li> <li>EAXA01-CN501-506</li> <li>EAXB01-CN531,532,533</li> <li>Amplifier-CN581,582</li> <li>EX1SV(External axis servo pack) -CN591,592</li> </ul>	9. 9.4
				Module failure (motor)	(1)Reset the alarm (2)If the alarm occurs again, replace the motor.	Ala Ala
				Servo control circuit board failure	<ul><li>(1)Reset the alarm.</li><li>(2)If the alarm occurs again, replace the EAXA、EAXB board. Save the CMOS.BIN before replace the board to be safe.</li></ul>	arm Me
4308	VOLTAGE DROP (CONVERTER)		subcode: Signifies the physical No. of converter in which the alarm occurred	Voltage failure	Check if the primary power supply voltage is dropping.	ssage l
				Connection failure	<ul> <li>(1)Reset the alarm</li> <li>(2)If the alarm occurs again, check the connection and inserting state of the following cables and connectors.</li> <li>EAXA01-CN507,510</li> <li>EAXB01-CN531,532,533</li> <li>converter-CN551,553</li> <li>EX1SV(External axis servo pack)-CN591,592</li> </ul>	∟ist
				Module failure (converter)	(1)Reset the alarm (2)If the alarm occurs again, replace the converter.	
				Servo control circuit board failure	(1)Reset the alarm. (2)If the alarm occurs again, replace the EAXA, EAXB board. Save the CMOS.BIN before replace the board to be safe.	
4310	ENCODER OVERHEAT		subcode: Signifies the axis in which the alarm occurred	Overheated encoder	Turn OFF the FS100L power for approx. 10 minutes, then turn it ON again.	
				High ambient temperature	Adjust the ambient temperature to 40°C or less.	
				Module failure (encoder)	(1)Reset the alarm (2)If the alarm occurs again, replace the encoder.	
				Servo control circuit board failure	<ul><li>(1)Reset the alarm.</li><li>(2)If the alarm occurs again, replace the EAXA、EAXB board. Save the CMOS.BIN before replace the board to be safe.</li></ul>	

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy
Number		Code			
4311	ENCODER BACK-UP ERROR		subcode: Signifies the axis in which the alarm occurred	Module failure (encoder battery)	<ul> <li>[AL-4314 occurred]</li> <li>Replace the battery of the axis in which the error occurred.</li> <li>[AL-1327 occurred]</li> <li>Replace the battery of the axis in which the alarm occurred. If the home position of the corresponding axis is displayed as "***", register the home position again.</li> <li>AL-1327 occurs due to the unconnected battery (weak battery), causing undefined alarm data.</li> <li>If the alarm doesn't occur after turning the power OFF and then ON, there is no problem.</li> </ul>
				Connection failure	<ul> <li>(1)Reset the alarm</li> <li>(2)If the alarm occurs again, check the connection and inserting state of the following cables and connectors.</li> <li>EAXA01-CN508</li> <li>EAXB01-CN534,535,536</li> </ul>
				Module failure (encoder)	<ul><li>(1)Reset the alarm</li><li>(2)If the alarm occurs again, replace the encoder.</li></ul>
				Servo control circuit board failure	<ul> <li>(1)Reset the alarm.</li> <li>(2)If the alarm occurs again, replace the EAXA、EAXB board. Save the CMOS.BIN before replace the board to be safe.</li> </ul>
4312	ENCODER BATTERY ERROR			Module failure (encoder battery)	Replace the battery.
				Connection failure	<ul> <li>(1)Reset the alarm</li> <li>(2)If the alarm occurs again, check the connection and inserting state of the following cables and connectors.</li> <li>Manipulator cable</li> </ul>
4315	COLLISION DETECT		subcode: Signifies the axis in which the alarm occurred	Setting error	Check the following settings. <ul> <li>The tool information</li> <li>The selection tap of the transfer</li> <li>The collision detection level</li> <li>JOB</li> <li>Work</li> <li>The speed of JOB</li> <li>The acceleration/deceleration speed of ACC and DEC</li> <li>Length of the power cables</li> <li>Diameter of the power cables</li> </ul>
				Interference error	<ul> <li>Remove the following interferences.</li> <li>The interferences to the jigs of Robot.</li> <li>The interferences to the jigs of workpieces.</li> <li>If there is no interference between robot and workpieces, set the shock detection level to more than maximum eternal value. Up to 500% can be set.</li> </ul>

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy	
Number		Code				
				Acceleration limit over	This alarm occurs when excessive load is applied to the motor upon the satisfactions of all the following conditions;	
					The acceleration/deceleration is automatically calculated by the manipulator's position at start/end point	
					The JOB is stopped by category 1 stop or HOLD stop	
					Compared to the start/end point, excessive load is applied to the motor according to the position	
					<remedy>Adjust the acceleration/deceleration by ACC and DEC for the teaching position.</remedy>	
					Also, make sure to run the machine enough before operation when this alarm	ം ര
					(ambient temperature: 10 $^{\circ}$ C)	4
				Connection failure	<ul> <li>(1)Reset the alarm.</li> <li>(2)If the alarm occurs again, check the connection and inserting state of the following cables and connectors.</li> <li>EAXA01- CN501 to 506,CN510</li> <li>EAXB01- CN531,532,533</li> <li>Amplifier - CN581,582</li> <li>Converter - CN551,552A,552B</li> <li>EX1SV(External axis servo pack) -CN591,592,595</li> </ul>	Alarm Alarm Message
				Connection failure	<ul> <li>(1) If the alarm occurs again, check the wiring of phase-U, -V, and -W isn't disconnected.</li> <li>(2) If disconnected, replace the motor power wire.</li> </ul>	<u>,</u>
				Connection failure	<ul> <li>(1) Check that the motor brake wire is not disconnected.</li> <li>(2) If disconnected, replace the motor brake wire.</li> </ul>	
				YBK01 board failure	(1)Reset the alarm (2)If the alarm occurs again, replace the YBK01 board.	
				Module failure (amplifier)	<ul><li>(1)Reset the alarm</li><li>(2)If the alarm occurs again, replace the amplifier.</li></ul>	
				Module failure (motor)	<ul><li>(1)Reset the alarm</li><li>(2)If the alarm occurs again, replace the motor.</li></ul>	
				Maintenance failure	Measure the density of grease iron powder in the speed reducer and do the maintenance.	
				Defective speed reducer	Replace the speed reducer or the grease of it.	
4318	SERIAL ENCODER CORRECTION LIMIT		subcode: Signifies the axis in which the alarm occurred	Connection failure	<ul> <li>(1)Reset the alarm</li> <li>(2)If the alarm occurs again, check the connection and inserting state of the following cables and connectors.</li> <li>EAXA01-CN508</li> <li>EAXB01-CN534,535,536</li> </ul>	

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy
Number		Code			
				Module failure (encoder)	<ul><li>(1)Reset the alarm.</li><li>(2)If the alarm occurs again, replace the encoder.</li></ul>
				Servo control circuit board failure	<ul><li>(1)Reset the alarm.</li><li>(2)If the alarm occurs again, replace the EAXA、EAXB board. Save the CMOS.BIN before replace the board to be safe.</li></ul>
4320	OVERLOAD (CONTINUE)		subcode: Signifies the axis in which the alarm occurred	Setting error	Check the following settings.  • The tools or the mass of the workpieces
				Interference with peripheral devices	Remove interference with the workpiece and peripheral device.
				Setting error	Review the JOB to check if the load factor doesn't exceed 100%.
				Module failure (brake)	<ul> <li>(1)Check if the power (24V) is supplied the following terminals to release the brakes. Check that the brakes are not been locked due to malfunction of the contactor.</li> <li>YBK01-CN400</li> <li>Motor brake terminal         <ul> <li>(2) If any error is found, replace the YBK01 unit.</li> </ul> </li> </ul>
				Connection failure	(1)Reset the alarm.       000000000000000000000000000000000000
				Module failure (motor)	(1)Reset the alarm. (2)If the alarm occurs again, replace the motor.
				Servo control circuit board failure	<ul><li>(1)Reset the alarm.</li><li>(2)If the alarm occurs again, replace the EAXA, EAXB board. Save the CMOS.BIN before replacing the board to be safe.</li></ul>
				Module failure (converter)	<ul><li>(1)Reset the alarm.</li><li>(2)If the alarm occurs again, replace the converter unit. Save the CMOS.BIN before replacing the unit to be safe.</li></ul>
4321	OVERLOAD (MOMENT)		subcode: Signifies the axis in which the alarm occurred	Setting error	Check the following settings. • The tools or the mass of the workpieces
				Interference with peripheral devices	Remove interference with the workpiece and peripheral device.
				Setting error	Review the JOB to check if the load factor doesn't exceed 100%.
				Module failure (brake)	<ul> <li>(1)Check if the power has been applied to the brake voltage of the following terminal.</li> <li>Check that the brake has not been locked due to malfunction of the contactor.</li> <li>YBK01-CN400</li> <li>Motor brake terminal</li> <li>(2) If any error is found, replace the YBK01 unit.</li> </ul>

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy	
Number		Code				
				Connection failure	<ul><li>(1)Reset the alarm.</li><li>(2)If the alarm occurs again, replace the following cables.</li><li>The wire harness in the robot.</li></ul>	
				Module failure (motor)	<ul><li>(1)Reset the alarm.</li><li>(2)If the alarm occurs again, replace the motor.</li></ul>	
				Servo control circuit board failure	<ul><li>(1)Reset the alarm.</li><li>(2)If the alarm occurs again, replace the EAXA, EAXB board. Save the CMOS.BIN before replacing the board to be safe.</li></ul>	
				Module failure (converter)	<ul><li>(1)Reset the alarm.</li><li>(2)If the alarm occurs again, replace the converter unit. Save the CMOS.BIN before replacing the unit to be safe.</li></ul>	9.2 9.2
4322	AMPLIFIER OVERLOAD (CONTINUE)		subcode: Signifies the axis in which the alarm occurred	Setting error	Check the following settings.  • The tools or the mass of the workpieces	- > >
				Interference with peripheral devices	Remove interference with the workpiece and peripheral device.	larm
				Setting error	Review the JOB to check if the load factor doesn't exceed 100%.	≤
				Module failure (brake)	<ul> <li>(1)Check if the power has been applied to the brake voltage of the following terminal.</li> <li>Check that the brake has not been locked due to malfunction of the contactor.</li> <li>YBK01-CN400</li> <li>Motor brake terminal</li> <li>(2) If any error is found, replace the YBK01 unit.</li> </ul>	essage List
				Connection failure	<ul> <li>(1)Reset the alarm.</li> <li>(2)If the alarm occurs again, replace the following cables.</li> <li>The wire harness in the robot.</li> </ul>	
				Module failure (amplifier)	<ul><li>(1)Reset the alarm</li><li>(2)If the alarm occurs again, replace the amplifier.</li></ul>	
				Module failure (converter)	<ul><li>(1)Reset the alarm.</li><li>(2)If the alarm occurs again, replace the converter unit. Save the CMOS.BIN before replacing the unit to be safe.</li></ul>	
4323	AMPLIFIER OVERLOAD (MOMENT)		subcode: Signifies the axis in which the alarm occurred	Setting error	Check the following settings.  • The tools or the mass of the workpieces	
				Interference with peripheral devices	Remove interference with the workpiece and peripheral device.	
				Setting error	Review the JOB to check if the load factor doesn't exceed 100%.	
				Module failure (brake)	<ul> <li>(1)Check if the power has been applied to the brake voltage of the following terminal.</li> <li>Check that the brake has not been locked due to malfunction of the contactor.</li> <li>YBK01-CN400</li> <li>Motor brake terminal</li> <li>(2) If any error is found, replace the YBK01 unit.</li> </ul>	

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy
Number		Code			
				Connection failure	<ul><li>(1)Reset the alarm.</li><li>(2)If the alarm occurs again, replace the following cables.</li><li>The wire harness in the robot.</li></ul>
				Module failure (amplifier)	(1)Reset the alarm (2)If the alarm occurs again, replace the amplifier.
				Module failure (converter)	(1)Reset the alarm. (2)If the alarm occurs again, replace the converter unit. Save the CMOS.BIN before replacing the unit to be safe.
4324	CONVERTER OVERLOAD			Setting error	Check the settings of the following. If the tool or the workpiece used has exceeded the allowable load.
				Setting error	Adjust the job speed. Adjust the acceleration/deceleration of ACC and DEC instructions.
				Module failure (converter)	<ul><li>(1)Reset the alarm.</li><li>(2)If the alarm occurs again, replace the converter.</li></ul>
				Servo control circuit board failure	(1)Reset the alarm. (2)If the alarm occurs again, replace the EAXA, EAXB board. Save the CMOS.BIN before replacing the board to be safe.
4326	OVER SPEED		subcode: Signifies the axis in which the alarm occurred	Setting error	If the alarm occurs at the same site, check the following setting. <ul> <li>Set the lower motion speed around the site where the alarm occurs.</li> <li>If the alarm occurs for the motor gun, check the following settings.</li> <li>Setting of the touch speed</li> <li>Setting of the touch pressure</li> </ul>
				Connection failure	(1)Reset the alarm. (2)If the alarm occurs again, check the wiring of phase-U, -V, and -W is correct.
				Module failure (motor)	<ul><li>(1)Reset the alarm.</li><li>(2)If the alarm occurs again, replace the motor.</li></ul>
				Servo control circuit board failure	<ul><li>(1)Reset the alarm.</li><li>(2)If the alarm occurs again, replace the EAXA, EXAB board. Save the CMOS.BIN before replacing the board to be safe.</li></ul>
4327	WRONG MOTOR ROTATION		subcode: Signifies the axis in which the alarm occurred	Connection failure	<ul> <li>(1Reset the alarm.</li> <li>(2)If the alarm occurs again, check the connection and insertion of the following cables and connectors.</li> <li>Motor power cable</li> <li>Amplifier-CN584</li> <li>EX1SV(External axis servo pack)-CN595</li> <li>Power supply cable (Power cable)</li> <li>Encoder cable</li> <li>EAXA01-CN508</li> <li>EAXB01-CN534,535,536</li> </ul>

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy	
Number		Code				
				Servo control circuit board failure	(1)Reset the alarm. (2)If the alarm occurs again, replace the EAXA, EAXB board. Save the CMOS.BIN before replacing the board to be safe.	
4328	SERVO TRACKING ERROR		subcode: Signifies the axis in which the alarm occurred	Setting error	Check the settings of the followings. •Tool file setting •The tools or the mass of the workpieces	
				Interference error	Check if the manipulator interferes with any objects such as workpieces or peripheral devices. If interferes, remove the object.	
				Acceleration limit over	<ul> <li>This alarm occurs when excessive load is applied to the motor upon the satisfactions of all the following conditions;</li> <li>The acceleration/deceleration is automatically calculated by the manipulator's position at start/end point</li> <li>The JOB is stopped by category 1 stop or HOLD stop</li> <li>Compared to the start/end point, excessive load is applied to the motor according to the position</li> <li><remedy>Adjust the acceleration/deceleration by ACC and DEC for the teaching position.</remedy></li> <li>Also, make sure to run the machine enough before operation when this alarm occurs at low temperature environment (ambient temperature: 10 °C )</li> </ul>	9. Alarm 9.4 Alarm Message List
				Connection failure	<ul> <li>(1Reset the alarm.</li> <li>(2)If the alarm occurs again, check the connection and insertion of the following cables and connectors.</li> <li>Amplifier-CN584</li> <li>EX1SV(External axis servo pack)-CN595</li> <li>Motor power wiring</li> <li>Power supply cable (Power cable)</li> </ul>	-
				Module failure (brake)	<ul> <li>(1)Check if the power has been supplied to the brake voltage of the following terminal.</li> <li>Check that the brake has not been locked due to malfunction of the contactor.</li> <li>YBK01-CN400</li> <li>Motor brake terminal</li> <li>(2) If any error is found, replace the YBK01 unit.</li> </ul>	
				Module failure (amplifier)	<ul><li>(1)Reset the alarm.</li><li>(2)If the alarm occurs again, replace the amplifier.</li></ul>	
				Module failure (motor)	<ul><li>(1)Reset the alarm.</li><li>(2)If the alarm occurs again, replace the motor.</li></ul>	
				Servo control circuit board failure	<ul><li>(1)Reset the alarm.</li><li>(2)If the alarm occurs again, replace the EAXA, EAXB board. Save the CMOS.BIN before replacing the board to be safe.</li></ul>	

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy
Number		Code			
				YPU unit board failure	(1)Reset the alarm. (2)If the alarm occurs again, replace the YPU unit. Save the CMOS.BIN before replacing the board to be safe.
4329	SAFETY SPEED ERROR (SERVO)	11	The motion speed at the center of the flange exceeded the specified max. speed.	Setting error	Check the following settings. •Reduction in the motion speed
				Setting error	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
				Connection failure	(1)Reset the alarm. (2)If the alarm occurs again, check that U-, V- and W-phase are appropriately connected.
				Module failure (motor)	<ul><li>(1)Reset the alarm.</li><li>(2)If the alarm occurs again, replace the motor.</li></ul>
				Servo control circuit board failure	(1)Reset the alarm. (2)If the alarm occurs again, replace the EAXA、EAXB board. Save the CMOS.BIN before replace the board to be safe.
		12	The motion speed at the center of the flange exceeded the specified max. speed.	Setting error	Check the following settings. •Reduction in the motion speed
				Setting error	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
				Connection failure	(1)Reset the alarm. (2)If the alarm occurs again, check that U-, V- and W-phase are appropriately connected.
				Module failure (motor)	<ul><li>(1)Reset the alarm.</li><li>(2)If the alarm occurs again, replace the motor.</li></ul>
				Servo control circuit board failure	<ul><li>(1)Reset the alarm.</li><li>(2)If the alarm occurs again, replace the EAXA、EAXB board. Save the CMOS.BIN before replace the board to be safe.</li></ul>
		21	The motion speed at the center of the control point exceeded the specified max. speed.	Setting error	Check the following settings. •Reduction in the motion speed
				Setting error	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
Alarm	Alarm Name	Sub	Meaning	Cause	Remedy
--------	----------------------------	------	--	---	---
Number		Code			
				Connection failure	(1)Reset the alarm. (2)If the alarm occurs again, check that U-, V- and W-phase are appropriately connected.
				Module failure (motor)	<ul><li>(1)Reset the alarm.</li><li>(2)If the alarm occurs again, replace the motor.</li></ul>
				Servo control circuit board failure	<ul><li>(1)Reset the alarm.</li><li>(2)If the alarm occurs again, replace the EAXA、EAXB board. Save the CMOS.BIN before replace the board to be safe.</li></ul>
		22	The motion speed at the center of the control point exceeded the specified max. speed.	Setting error	Check the following settings. •Reduction in the motion speed
				Setting error	(1)Reset the alarm, and then try again. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).
				Connection failure	(1)Reset the alarm. (2)If the alarm occurs again, check that U-, V- and W-phase are appropriately connected.
				Module failure (motor)	(1)Reset the alarm. (2)If the alarm occurs again, replace the motor.
				Servo control circuit board failure	(1)Reset the alarm. (2)If the alarm occurs again, replace the EAXA、EAXB board. Save the CMOS.BIN before replace the board to be safe.
4334	OVERVOLTAGE (CONVERTER)		subcode: Signifies the physical No. of converter in which the alarm occurred	Connection failure	<ul> <li>(1)Reset the alarm.</li> <li>(2)If the alarm occurs again, check the connection and inserting state of the following cables and connectors.</li> <li>EAXA01-CN507,510</li> <li>EAXB01-CN531,532,533</li> <li>Converter -CN551,553</li> </ul>
				Setting error	Check the following settings. • The tools or the mass of the workpieces
				Voltage failure	Modify the primary breaker voltage to the specified voltage 200V (+10%~ 15%).
-				Module failure (Regenerative resistor)	<ul><li>(1)Disconnect the converter CN557 to check if there is no cable disconnection.</li><li>(2)If disconnected, replace the regenerative resistor.</li></ul>
				Module failure (converter)	<ul><li>(1)Reset the alarm.</li><li>(2)If the alarm occurs again, replace the converter.</li></ul>
				Servo control circuit board failure	<ul><li>(1)Reset the alarm.</li><li>(2)If the alarm occurs again, replace the EAXA, EAXB board. Save the CMOS.BIN before replacing the board to be safe.</li></ul>

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy
Number		Code			
4335	GROUND FAULT		subcode: Signifies the axis in which the alarm occurred (If the alarm occurred at an axis which is driven by a common converter, all the subject axes are indicated.)	Connection failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, check the connection and inserting state of the following cables and connectors.</li> <li>EAXA01-CN507,510</li> <li>Converter -CN551,553,555</li> <li>EX1SV(External axis servo pack) -CN592</li> </ul>
				Connection failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the following cables.</li> <li>Check the axis in which earth fault occurs in the alarm history screen.</li> <li>If both robot axes and external axes use the same type converter, the earth fault may occur on the external axis not the robot axis. (There is also a possibility that it is stained by water)</li> <li>(1) External axis cables (Power wire)</li> <li>(2) Traveling axis cable (Power wire)</li> <li>(3) Power supply cable (Robot axis, external axis) (Power wire)</li> <li>(4) Internal cables (Robot axis, external axis) (Power wire)</li> </ul>
				Module failure (Regenerative resistor)	Check if there is no ground fault in the regeneration resistors.
				GND wiring failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2) If the alarm repeats, check the voltage of the primary power and GND. If the voltage amount on each RST varies more than 100V, review the GND setting.</li> </ul>
				Module failure (motor)	<ul><li>(1)Turn the power OFF then back ON.</li><li>(2)If the alarm occurs again, replace the motor.</li></ul>
				Module failure (amplifier)	<ul><li>(1)Turn the power OFF then back ON.</li><li>(2)If the alarm occurs again, replace the amplifier.</li></ul>
				Module failure (contactor)	<ul><li>(1)Turn the power OFF then back ON.</li><li>(2)If the alarm occurs again, replace the contactor.</li></ul>
				Servo control circuit board failure	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, replace the EAXA, EAXB board. Save the CMOS.BIN before replacing the board to be safe.
				YPU unit failure	(1)Turn the power OFF then back ON. (2)If the alarm occurs again, replace the YPU unit. Save the CMOS.BIN before replacing the YPU unit to be safe.
4336	OPEN PHASE (CONVERTER)		subcode: Signifies the physical No. of converter in which the alarm occurred	Connection failure	<ul> <li>(1)Reset the alarm.</li> <li>(2)If the alarm occurs again, check the connection and inserting state of the following cables and connectors.</li> <li>EAXA01-CN507,510</li> <li>EAXB01-CN531,532,533</li> <li>Converter CN551,553</li> </ul>
				Voltage failure	Modify the primary breaker voltage to the specified voltage 200V (+10%~ 15%).

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy
Number		Code			
				YPU unit failure	(1)Reset the alarm. (2)If the alarm occurs again, replace the YPU unit. Save the CMOS.BIN before replacing the YPU unit to be safe.
				Module failure (converter)	(1)Reset the alarm (2)If the alarm occurs again, replace the converter.
				Servo control circuit board failure	<ul><li>(1)Reset the alarm.</li><li>(2)If the alarm occurs again, replace the EAXA, EAXB board. Save the CMOS.BIN before replacing the board to be safe.</li></ul>
4337	OVER CURRENT (AMP)		subcode: Signifies the axis in which the alarm occurred	Connection failure	(1)Reset the alarm.         (2)If the alarm occurs again, check the connection and inserting state of the following cables and connectors.         • EAXA-CN501 ~ 506,CN510         • EAXB-CN531,532,533         • Amplifier-CN581,582         • Converter-CN551,552A,552B
				Connection failure	(1)Reset the alarm.       3         (2)If the alarm occurs again, replace the following cables.       5         • Manipulator cable       5         • Supply cable       6
				Module failure (amplifier)	(1)Reset the alarm. (2)If the alarm occurs again, replace the amplifier.
				Module failure (motor)	<ul><li>(1)Reset the alarm.</li><li>(2)If the alarm occurs again, replace the motor.</li></ul>
				Servo control circuit board failure	<ul><li>(1)Reset the alarm.</li><li>(2)If the alarm occurs again, replace the EAXA, EAXB board. Save the CMOS.BIN before replacing the board to be safe.</li></ul>
4338	REGENERATIVE TROUBLE (CONVERTER)		subcode: Signifies the axis in which the alarm occurred	Connection failure	<ul> <li>(1)Reset the alarm.</li> <li>(2)If the alarm occurs again, check the connection and inserting state of the following cables and connectors.</li> <li>EAXA01 board</li> <li>EAXB01 board</li> <li>Converter-CN557</li> <li>Cable between the regenerative resistors</li> </ul>
				Module failure (Regenerative resistor)	Replace the regenerative resistor.
-				Module failure (converter)	<ul><li>(1)Reset the alarm.</li><li>(2)If the alarm occurs again, replace the converter unit.</li></ul>
				Servo control circuit board failure	(1)Reset the alarm. (2)If the alarm occurs again, replace the EAXA, EAXB board. Save the CMOS.BIN before replace the board to be safe.

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy
Number		Code			
				Overloading	Check that the load does not exceed the allowable limit.
4339	INPUT POWER OVER VOLTAGE (CONV)		subcode: Signifies the physical No. of converter in which the alarm occurred	Voltage failure	Modify the primary breaker voltage to the specified voltage 200V(+10%~ 15%).
				Connection failure	<ul> <li>(1)Reset the alarm.</li> <li>(2)If the alarm occurs again, check the connection and inserting state of the following cables and connectors.</li> <li>EAXA01-CN507,510</li> <li>EAXB01-CN531,532,533</li> <li>Converter -CN551,553</li> <li>EX1SV(External axis servo pack) -CN591,592</li> </ul>
				Module failure (converter)	(1)Reset the alarm.
					(2)If the alarm occurs again, replace the converter.
				Servo control circuit board failure	<ul><li>(1)Reset the alarm.</li><li>(2)If the alarm occurs again, replace the EAXA, EAXB board. Save the CMOS.BIN before replacing the board to be safe.</li></ul>
4340	TEMPERATURE ERROR (CONVERTER)		subcode: Signifies the physical No. of converter in which the alarm occurred	Voltage failure	Modify the primary breaker voltage to the specified voltage 200V(+10% $\sim$ 15%).
				Connection failure	<ul> <li>(1)Reset the alarm.</li> <li>(2)If the alarm occurs again, check the connection and inserting state of the following cables and connectors.</li> <li>EAXA01-CN507,510</li> <li>EAXB01-CN531,532,533</li> <li>Converter -CN551,553</li> <li>EX1SV(External axis servo pack) -CN591,592</li> </ul>
				Module failure (converter)	<ul><li>(1)Reset the alarm.</li><li>(2)If the alarm occurs again, replace the converter.</li></ul>
				Servo control circuit board failure	(1)Reset the alarm. (2)If the alarm occurs again, replace the EAXA, EAXB board. Save the CMOS.BIN before replacing the board to be safe.
				High ambient temperature	Adjust the ambient temperature to 40°C or less.
				Install failure	Check that the air inlet or outlet is not blocked.
4344	LINEAR SERVOFLOAT TRACKING ERROR			Setting error	Confirm the job settings so that excess load would not be applied to the axis in the linear servo float.
4345	LNK SERVOFLOAT EXECUTE ERROR			Setting error	Check the job settings so that the link servo float would not be executed while the linear servo float is executed.
4346	LNK SERVOFLOAT TRQ LIMIT ERROR			Setting error	Check the limit torque of the link servo float condition file.

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy
Number		Code			
4347	LNR SERVOFLOAT TRQ LIMIT ERROR			Setting error	Check the limit torque of the linear servo float condition file.
4348	LNR SERVOFLOAT COORD TYPE ERROR			Setting error	Check the setting file of the job and the linear servo float.
4349	LNR SERVOFLOAT TOOL POSE ERROR			Setting error	Check the setting file of the job and the linear servo float.
4350	LNR SERVOFLOAT EXECUTE ERROR			Setting error	Check the job settings so that the linear servo float would not be executed while the link servo float is executed.
4351	DRIVE BELT SNAP DETECT		subcode: Signifies the axis in which the alarm occurred	Connection failure	Check that the driving belt is not broken.
				Driving belt failure	Check the driving belt.
4352	TWIN DRIVE OVER DEVIATION		subcode: Signifies the axis in which the alarm occurred	Connection failure	<ul> <li>(1)Reset the alarm</li> <li>(2)If the alarm occurs again, check the connection and inserting state of the following cables and connectors.</li> <li>EAXA01-CN507,510</li> <li>EAXB01-CN531,532,533</li> <li>converter-CN551,553</li> <li>EX1SV(External axis servo pack) -CN591,592</li> </ul>
				Cable (failure) (motor power cable)	(1)Check U-, V- and W-phase of the motor power cable disconnection.       (2)If disconnection is found, replace the motor power cable.
				Cable (failure) (motor brake cable)	<ul><li>(1) Check that the motor brake wire is not disconnected.</li><li>(2) If disconnected, replace the motor brake wire.</li></ul>
				Module failure (brake)	<ul><li>(1)Reset the alarm.</li><li>(2)If the alarm occurs again, replace the YBK01 board.</li></ul>
				Module failure (amplifier)	<ul><li>(1)Reset the alarm.</li><li>(2)If the alarm occurs again, replace the amplifier.</li></ul>
				Module failure (motor)	<ul><li>(1)Reset the alarm.</li><li>(2)If the alarm occurs again, replace the motor.</li></ul>
4353	DEFECTIVE TAUGHT POINT (ENDLESS)		subcode: Signifies the axis in which the alarm occurred	Setting error	Check the following settings. • Setting of the command soft (JOB) • MRESET instruction to corresponding axis
				Servo control circuit board failure	<ul><li>(1)Reset the alarm.</li><li>(2)If the alarm occurs again, replace the EAXA, EAXB board. Save the CMOS.BIN before replacing the board to be safe.</li></ul>
4355	EXTERNAL PRES DETECT (SERVOFLOAT)			Setting error	Check the settings for jobs.

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy
Number		Code			
4359	CONVERTER ERROR		subcode: Signifies the physical No. of converter in which the alarm occurred	Connection failure	<ul> <li>(1)Reset the alarm.</li> <li>(2)If the alarm occurs again, check the connection and inserting state of the following cables and connectors.</li> <li>EAXA01-CN507,510</li> <li>EAXB01-CN531,532,533</li> <li>Converter -CN551,553</li> <li>EX1SV(External axis servo pack) -CN591,592</li> </ul>
				Module failure (converter)	<ul><li>(1)Reset the alarm.</li><li>(2)If the alarm occurs again, replace the converter.</li></ul>
				Servo control circuit board failure	(1)Reset the alarm. (2)If the alarm occurs again, replace the EAXA, EAXB board. Save the CMOS.BIN before replacing the board to be safe.
4400	NOT READY (ARITH)	1	The arithmetic process for motion control did not complete within regulated time. No motion command was prepared.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		2	The arithmetic processing section is not ready for JOG operation.	Software operation error occurred	(1)Reset the alarm, and then try again. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).
		3	The arithmetic processing section is not ready for the playback operation.	Software operation error occurred	(1)Reset the alarm, and then try again. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).
		4	The pre-reading processing in the arithmetic processing section has not completed.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		5	The arithmetic processing section is not ready for the timer follow-up of the conveyor tracking function.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
4401	SEQUENCE TASK CONTR ERROR	1	Unused A_BANK does not exist in the pre-reading processing of move instruction.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		2	Unused bank priority does not exist in the pre-reading processing of move instruction.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy
Number		Code			
		5	A_BANK pointer is not set.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		6	A_BANK conversion could not be performed.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		7	The specified A_BANK number does not exist.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		20	An error occurred when system number (MSS) was obtained.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		21	An error occurred in RMS960 system call.	Software operation error occurred	(1)Reset the alarm, and then try again. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).
		22	Undefined interrupt command was received.	Software operation error occurred	(1)Reset the alarm, and then try again. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).
		23	Job start condition is not defined.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		24	An error occurred in instruction pre-fetch queue operation.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		26	Intermediate code is not defined.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		29	Instruction pre-reading processing has not been completed normally.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy
Number		Code			
		30	An error occurred in job data change.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		31	The specified sequence number at job execution start is incorrect.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		32	The added area for interruption command is incorrect.	Software operation error occurred	(1)Reset the alarm, and then try again. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).
		33	System number (MSS) for interruption command is incorrect.	Software operation error occurred	(1)Reset the alarm, and then try again. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).
		38	An error occurred at start of twin synchronous operation.	Software operation error occurred	(1)Reset the alarm, and then try again. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).
		39	An error occurred when SYNC specification was reset.	Software operation error occurred	(1)Reset the alarm, and then try again. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).
		41	An error occurred in occupation control group setting in MOTION section.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		45	An error occurred in path/trace control.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		47	An error occurred when waiting for a completion of main system task (job) in SYNC specification.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		48	An attempt was made to execute an instruction that could not be executed at line sequence execution.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy
Number		Code			
		49	An error occurred while obtaining the instruction information.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		80	An exceptional error occurred in job execution process.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		100	Main processing command is incorrect in pre-reading processing.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		101	Sub processing command is incorrect in pre-reading processing.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		102	pre-reading processing has not been completed at job execution.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		103	A_BANK conversion has not been completed.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		104	System number (MSS) is incorrect in pre-reading processing.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		105	An error occurred in instruction pre-fetch queue operation in pre- reading processing.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		106	An error occurred at IES switching in pre-reading processing.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
4402	UNDEFINED COMMAND (ARITH)			Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)Check the following settings.</li> <li>the base-axis position must be registered for the system with base-axis MOVL P00001 BP00001</li> <li>(3)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy
Number		Code			
4404	ARITHMETIC ERROR	8	Interpolation such as linear and circular interpolation cannot be performed with this manipulator.	Setting error	<ul><li>(1)Check the following settings.</li><li>Change the step (move instruction), where the alarm occurred, to MOVJ.</li></ul>
		10	The setting of the form data for Flip/No Flip is not "B-axis Angle."	Setting error	<ul><li>(1)Check the following settings.</li><li>Set "1" to "S2C658: Type data detail settings".</li></ul>
		11	An attempt was made to pass the B-axis zero degree position (singular area).	Setting error	<ul> <li>(1)Check the following settings.</li> <li>Check the teaching position of the job so that the manipulator does not pass the B-axis zero degree position (singular area).</li> </ul>
4406	GROUP AXIS CONTROL ERROR	1	Designation error for master and slave	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		2	Slave designation error	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		3	Slave interpolation error	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		4	No designation of master axis	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		6	Master-axis designation error for JOG motion	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		7	Slave-axis designation error for JOG motion	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		8	Occupation control error	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		9	Designation error of occupation control for JOG motion	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy	
Number		Code				
		10	Designation error of occupation control for Bank position	Software operation error occurred	(1)Reset the alarm, and then try again. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).	
		11	Designation error of occupation control group for tracking motion	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		12	No master and slave designated for tracking motion	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	9. 9.4
4407	TWO STEPS SAME POSITION (CIRC)			Setting error	<ul> <li>(1)Check the following settings.</li> <li>Check the settings for teaching position of circular interpolation steps so that each point is different.</li> </ul>	Aları Aları
4409	TWO STEPS SAME POSITION (3 STEPS)			Setting error	<ul> <li>(1)Check the following settings.</li> <li>Check the settings for three taught points to create an user coordinate system so that each point is different.</li> </ul>	n n Mess
4414	EXCESSIVE SEGMENT (LOW/HIGH)		subcode: Control group and axis	Setting error	<ul> <li>(1)Reduce the speed in the step where the alarm occurred.</li> <li>(2)Change the move instruction to joint interpolation (MOVJ).</li> <li>* Be careful to the peripheral interference since its movement changes.</li> </ul>	age Lis
4416	PULSE LIMIT (MIN./MAX.)		subcode: Control group and axis	Setting error	<ul> <li>(1)Check the following settings.</li> <li>Perform the teaching again to correct positions for manipulators so that the step where the alarm occurred is within the motion range.</li> </ul>	st
4418	CUBE LIMIT (MIN./MAX.)		subcode: Control group and XYZ	Setting error	<ul> <li>(1)Check the following settings.</li> <li>Perform the teaching again to correct positions for manipulators so that the step where the alarm occurred is within the motion range.</li> </ul>	
4420	SPECIAL SOFTLIMIT (MIN./MAX.)		subcode: Control group and axis	Setting error	<ul> <li>(1)Check the following settings.</li> <li>Perform the teaching again to correct positions for manipulators so that the step where the alarm occurred is within the motion range.</li> </ul>	
4422	MECHANICAL INTERFERENCE (MIN./MAX.)		subcode: Control group and axis	Setting error	<ul> <li>(1)Check the following settings.</li> <li>Perform the teaching again to correct positions for manipulators so that the step where the alarm occurred is within the motion range.</li> </ul>	
4424	SPECIAL MECHANICAL INTRF (MIN./MAX.)		subcode: Control group and axis	Setting error	<ul> <li>(1)Check the following settings.</li> <li>Perform the teaching again to correct positions for manipulators so that the step where the alarm occurred is within the motion range.</li> </ul>	
4426	PULSE MECHANICAL LIMIT (MIN./MAX.)		subcode: Control group and axis	Setting error	<ul> <li>(1)Check the following settings.</li> <li>Perform the teaching again to correct positions for manipulators so that the step where the alarm occurred is within the motion range.</li> </ul>	

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy
Number		Code			
4428	SEGMENT CONTROL ERROR	1	RT-buffer control command error	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		2	Segment-receiving control command error	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		3	No bank priority	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		4	Answer error at MOVE simulating	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		5	The value of bank_refresh_flag (x) exceeded its limit.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		8	RT-buffer tracking option error	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		9	The segment was received although the previous segment had not been sent.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		10	The segment was received although the previous segment had not been sent.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
4429	WRONG SPECIFIED CONTROL GROUP	1	Control group not designated	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		2	Slave control-group error	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy	
Number		Code				
		3	Master control-group error	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		4	Master and Slave control-group error	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		5	Control-group error for a job file	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	9 <u>4</u>
		6	Control-group error for a user coordinate file	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	Alarm Alarm
		7	Control-group error for a calibration file between manipulators	Software operation error occurred	(1)Reset the alarm, and then try again. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).	Message
		8	Control-group error for a tool calibration file	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	L ist
		10	Control-group error for pre- reading-calculation start point (for adv_st_pos)	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		11	Control-group error for the current-value preset position	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		12	Control-group error for the conveyor pre-reading-calculation start point	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		13	Occupation control-group error	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy
Number		Code			
		18	Control-group error for the pre- reading-calculation start point (for dm_st_pos)	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		19	Control-group error for pre- reading-calculation start point (for dm_st_pos)	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
4430	CPU COMMUNICATION ERROR	1	Interrupt processing error between MOTION section and system control section	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		2	Interrupt processing error between MOTION section and SL#1	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		3	Interrupt processing error between MOTION section and SL#2	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		4	Interrupt processing error between MOTION section and SL#3	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		5	Interrupt processing error between MOTION section and SL#4	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		6	Interrupt processing error between MOTION section and CV#1	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		7	Interrupt processing error between MOTION section and CV#2	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
4431	JHM ERROR	1	An error occurred in JMS system call when an attempt was made to open a job.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy	
Number		Code				
		2	No space was found in job handle value storage area when an attempt was made to open a job.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		3	No job handle was found.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		4	Job control proprietary is incorrect.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	9.4
		5	Job control proprietary could not be changed.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	Alarm Alarm
		6	An error occurred in exclusive control.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	Message
	INSTRUCTION INTERPRETER ERROR	1	The intermediate code of the instruction that is to be executed is incorrect.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	list
		3	Destination (variable) tag arrangement is incorrect.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		4	Tag data type is incorrect.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		5	Box number is incorrect.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		6	An error occurred in block separation processing of intermediate code.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy
Number		Code			
		8	Box number definition is duplicated.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		9	Undefined instruction was found at block separation of intermediate code.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		10	IPRM is not set.	Software operation error occurred	(1)Reset the alarm, and then try again. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).
		11	An error occurred in tag data search process.	Software operation error occurred	(1)Reset the alarm, and then try again. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).
		12	An error occurred move instruction search process.	Software operation error occurred	(1)Reset the alarm, and then try again. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).
		14	Variable information does not exist.	Software operation error occurred	(1)Reset the alarm, and then try again. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).
		16	An error occurred at position file data reading.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		17	Variable data type is not defined.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		18	An instruction is included with incorrect intermediate code in expression instruction.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		19	The syntax in expression instruction is incorrect.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy	
Number		Code				
		20	The tag data length is zero when tag data is read.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		22	The object to be processed was secret variable in position file control process, so it could not be processed.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		23	The object to be processed was position type variable in position file control process, so it could not be processed.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	9. 9.4
		24	Job argument settings do not match when a variable is given and/or taken between jobs.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	Alarm Alarm
		25	An attempt was made to perform undefined operation at four-rule operation instruction.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	Message
		26	Arithmetic stack used for expression operation exceeded.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	List
		27	Arithmetic stack used for expression operation is empty.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		28	Operation items are lacking in expression operation and operation processing cannot be performed.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		29	Sub instruction which has EXEC process exceeded the maximum number.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		254	Access mechanism for old parameters is used.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy
Number		Code			
		255	An exceptional error occurred.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
4433	UNDEFINED GLOBAL VARIABLE	0	The set data for byte type variable area is incorrect.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		1	The set data for integer type variable area is incorrect.	Software operation error occurred	(1)Reset the alarm, and then try again. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).
		2	The set data for double-precision integer-type variable area is incorrect.	Software operation error occurred	(1)Reset the alarm, and then try again. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).
		3	The set data for real type variable area is incorrect.	Software operation error occurred	(1)Reset the alarm, and then try again. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).
		4	The set data for character-string type variable area is incorrect.	Software operation error occurred	(1)Reset the alarm, and then try again. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).
		5	The set data for robot-axis position-type variable area is incorrect.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		6	The set data for base-axis position-type variable (S1D parameter) area is incorrect.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		7	The set data for station-axis position-type variable (S1D parameter) area is incorrect.	Software operation error occurred	(1)Reset the alarm, and then try again. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).
4435	UNDEFINED LOCAL- VARIABLE	0	The byte type variable is not defined.	Setting error	<ul><li>(1)Check the following settings.</li><li>Set the number of local variables to be used in the job header.</li></ul>
		1	The integer type variable is not defined.	Setting error	<ul><li>(1)Check the following settings.</li><li>Set the number of local variables to be used in the job header.</li></ul>

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy	
Number		Code				
		2	The double-precision integer-type variable is not defined.	Setting error	<ul><li>(1)Check the following settings.</li><li>Set the number of local variables to be used in the job header.</li></ul>	
		3	The real-number type variable is not defined.	Setting error	<ul><li>(1)Check the following settings.</li><li>Set the number of local variables to be used in the job header.</li></ul>	
		4	The character-string type variable is not defined.	Setting error	<ul><li>(1)Check the following settings.</li><li>Set the number of local variables to be used in the job header.</li></ul>	
		5	The robot-axis position-type variable is not defined.	Setting error	<ul><li>(1)Check the following settings.</li><li>Set the number of local variables to be used in the job header.</li></ul>	
		6	The base-axis position-type variable is not defined.	Setting error	<ul><li>(1)Check the following settings.</li><li>Set the number of local variables to be used in the job header.</li></ul>	9. 9.4
		7	The station-axis position-type variable is not defined.	Setting error	<ul><li>(1)Check the following settings.</li><li>Set the number of local variables to be used in the job header.</li></ul>	Ala Ala
4436	LESS THAN 3 STEPS (CIRCULAR)			Setting error	<ul> <li>(1)Check the following settings.</li> <li>Perform teaching so that circulation interpolation steps are continuous three points or more.</li> </ul>	ırm Irm Mes
4438	UNDEFINED JOB			Setting error	<ul> <li>(1)Check the following settings.</li> <li>Check if the CALL/JUMP destination job is registered. If the job is not registered, delete the JUMP instruction where an alarm occurred.</li> </ul>	ssage L
4439	UNDEFINED LABEL			Setting error	<ul> <li>(1)Check the following settings.</li> <li>Check if the JUMP destination label is registered. If the label is not registered, delete the JUMP instruction where alarm occurred.</li> </ul>	ist
4440	UNDEFINED RETURN JOB			Setting error	<ul> <li>(1)Check the following settings.</li> <li>If there is an illegal RET instruction in the start job, delete the RET instruction.</li> <li>Check if RET instruction is not executed under the condition that there is no job in the job call stack. In that case, execute it from master (start) job.</li> </ul>	
4441	LACK OF LOCAL- VARIABLE AREA			Setting error	<ul><li>(1)Check the following settings.</li><li>Reduce the number of local variables to be used.</li></ul>	
4444	UNSUCCESSFUL FINE POSITIONING		subcode: Bit specification of axis where error occurred	Effect of external force	<ul> <li>(1)Check the following settings.</li> <li>Move the manipulator by the axis operation, etc. to remove the external force of axis where alarm occurred.</li> </ul>	
4445	DATA PRESET ERROR		The token for pre-reading processing could not be obtained.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
			The pre-reading processing has not been completed within the time, and the waiting time for completion exceeded the limit.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy
Number		Code			
		3	The pre-reading operation processing has not been completed within the time, and the waiting time for completion exceeded the limit.	Software operation error occurred	(1)Reset the alarm, and then try again. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).
		4	An error occurred in pre-reading operation process.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		5	A_BANK conversion has not been completed.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		255	An exceptional error occurred in job execution process.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
4446	OVER VARIABLE LIMIT	0	The variable value exceeded the limit.	Setting error	<ul> <li>(1)Check the following settings.</li> <li>Check the settings for variable, and then correct the job to fall within the input range of the tag.</li> </ul>
		1	The value for the binary (0/1) data type variable exceeded the limit.	Setting error	<ul> <li>(1)Check the following settings.</li> <li>Check the settings for variable, and then correct the job to fall within the input range of the tag.</li> </ul>
		2	The value for the signed 1-byte data type variable is less than the minimum value.	Setting error	<ul> <li>(1)Check the following settings.</li> <li>Check the settings for variable, and then correct the job to fall within the input range of the tag.</li> </ul>
		3	The value for the unsigned 1-byte data type variable is less than the minimum value.	Setting error	<ul> <li>(1)Check the following settings.</li> <li>Check the settings for variable, and then correct the job to fall within the input range of the tag.</li> </ul>
		4	The value for the signed 2-byte data type variable is less than the minimum value.	Setting error	<ul> <li>(1)Check the following settings.</li> <li>Check the settings for variable, and then correct the job to fall within the input range of the tag.</li> </ul>
		5	The value for the unsigned 2-byte data type variable is less than the minimum value.	Setting error	<ul> <li>(1)Check the following settings.</li> <li>Check the settings for variable, and then correct the job to fall within the input range of the tag.</li> </ul>
		6	The value for the signed 4-byte data type variable is less than the minimum value.	Setting error	<ul> <li>(1)Check the following settings.</li> <li>Check the settings for variable, and then correct the job to fall within the input range of the tag.</li> </ul>

Alarm Alarm Message I

<u>9</u>.

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy	
Number		Code				
		7	The value for the unsigned 4-byte data type variable is less than the minimum value.	Setting error	<ul> <li>(1)Check the following settings.</li> <li>Check the settings for variable, and then correct the job to fall within the input range of the tag.</li> </ul>	
		8	The value for the real-number 4- byte data type variable is less than the minimum value.	Setting error	<ul><li>(1)Check the following settings.</li><li>Check the settings for variable, and then correct the job to fall within the input range of the tag.</li></ul>	
		14	The value for the character-string type variable is less than the minimum value.	Setting error	<ul> <li>(1)Check the following settings.</li> <li>Check the settings for variable, and then correct the job to fall within the input range of the tag.</li> </ul>	(O ((
		32770	The value for the signed 1-byte data type variable exceeded the maximum value.	Setting error	<ul> <li>(1)Check the following settings.</li> <li>Check the settings for variable, and then correct the job to fall within the input range of the tag.</li> </ul>	9.4 Ala
		32771	The value for the unsigned 1-byte data type variable exceeded the maximum value.	Setting error	<ul> <li>(1)Check the following settings.</li> <li>Check the settings for variable, and then correct the job to fall within the input range of the tag.</li> </ul>	arm Mes
		32772	The value for the signed 2-byte data type variable exceeded the maximum value.	Setting error	<ul> <li>(1)Check the following settings.</li> <li>Check the settings for variable, and then correct the job to fall within the input range of the tag.</li> </ul>	sage Lis
		32773	The value for the unsigned 2-byte data type variable exceeded the maximum value.	Setting error	<ul> <li>(1)Check the following settings.</li> <li>Check the settings for variable, and then correct the job to fall within the input range of the tag.</li> </ul>	Ŧ
		32774	The value for the signed 4-byte data type variable exceeded the maximum value.	Setting error	<ul> <li>(1)Check the following settings.</li> <li>Check the settings for variable, and then correct the job to fall within the input range of the tag.</li> </ul>	
		32775	The value for the unsigned 4-byte data type variable exceeded the maximum value.	Setting error	<ul><li>(1)Check the following settings.</li><li>Check the settings for variable, and then correct the job to fall within the input range of the tag.</li></ul>	
		32776	The value for the real-number 4- byte data type variable exceeded the maximum value.	Setting error	<ul> <li>(1)Check the following settings.</li> <li>Check the settings for variable, and then correct the job to fall within the input range of the tag.</li> </ul>	
		32782	The value for the character-string type variable exceeded the maximum value.	Setting error	<ul> <li>(1)Check the following settings.</li> <li>Check the settings for variable, and then correct the job to fall within the input range of the tag.</li> </ul>	

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy
Number		Code			
4447	DEFECTIVE TAUGHT POINT (CIRC)			Setting error	<ul> <li>(1)Check the following settings.</li> <li>Check the settings for three teaching points so that circular interpolation steps do not lie in a straight line.</li> </ul>
4449	UNMATCHED POSN VAR DATA TYPE			Setting error	<ul><li>(1)Check the following settings.</li><li>Match the data type of position type variable.</li></ul>
4450	FILE NO. ERROR	1	An error occurred in tool file number check.	Setting error	<ul><li>(1)Check the following settings.</li><li>Confirm that the specified tool file number is 0 to 63.</li></ul>
		2	An error occurred in user coordinate file number check.	Setting error	<ul><li>(1)Check the following settings.</li><li>Confirm that the specified user coordinate file number is 1 to 63.</li></ul>
		3	An error occurred in calibration file number check between the manipulators.	Setting error	<ul><li>(1)Check the following settings.</li><li>Confirm that the specified robot calibration file number is 1 to 32.</li></ul>
		4	An error occurred in tool calibration file number check.	Setting error	<ul><li>(1)Check the following settings.</li><li>Confirm that the specified tool file number is 0 to 63.</li></ul>
		5	An error occurred in reference point number check.	Setting error	<ul><li>(1)Check the following settings.</li><li>Confirm that the specified robot calibration file number is 1 to 8.</li></ul>
		9	An error occurred in conveyor characteristic file number check.	Setting error	<ul><li>(1)Check the following settings.</li><li>Confirm that the specified conveyor condition file number is 1 to 6.</li></ul>
		10	An error occurred in press characteristic file number check.	Setting error	<ul><li>(1)Check the following settings.</li><li>Confirm that the specified press characteristic file number is 0 to 3.</li></ul>
		12	An error occurred in conveyor calibration file number check.	Setting error	<ul><li>(1)Check the following settings.</li><li>Confirm that the specified conveyor calibration file number is 1 to 6.</li></ul>
		13	An error occurred in argument number check.	Setting error	<ul><li>(1)Check the following settings.</li><li>Confirm that the argument number is 1 to 16.</li></ul>
		15	An error occurred while checking the link (linear) servo float condition file number.	Setting error	<ul><li>(1)Check the following settings.</li><li>Confirm that the link (linear) servo float condition file number is within the range of 1 t 8.</li></ul>
4451	UNDEFINED REFERENCE POINT		subcode: Reference point number in binary	Setting error	<ul><li>(1)Check the following settings.</li><li>Set the reference point.</li></ul>
4452	STACK MORE THAN 10 (JOB CALL)			Setting error	<ul> <li>(1)Check the following settings.</li> <li>Change the job configuration so that the number of nests for CALL instruction is twelve or less.</li> </ul>
4453	OVER VARIABLE NO.		The variable number is out of range. subcode: The variable number which an attempt was made to use	Setting error	<ul><li>(1)Check the following settings.</li><li>Correct the job using the variable number within the range.</li></ul>

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy	
Number		Code				
4459	EXCESSIVE INSTRUCTION EQUATION			Setting error	<ul> <li>(1)Check the following settings.</li> <li>Separate the operation expression, shorten the expression, and then check the settings for the job.</li> </ul>	
4460	ZERO DIVIDED OCCURRENCE			Setting error	<ul><li>(1)Check the following settings.</li><li>Do not divide by zero.</li></ul>	
4463	PARITY ERROR			Setting error	<ul><li>(1)Check the following settings.</li><li>Check the settings for the parity data of the user I/O group.</li></ul>	
4464	OVER BCD RANGE			Setting error	<ul><li>(1)Check the following settings.</li><li>Correct the BCD data so that it is within the limit.</li></ul>	
4465	OVER BINARY RANGE (PARITY CHECK)			Setting error	(1)Check the following settings.O• Correct the binary data so that it is within the limit.•	ي د ۲
4466	OFFLINE UNDEFINED COMMAND(ARITH)	0	An undefined command was issued to the offline position-data preparation section.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	Alarm
4467	USER COORD STEP NOT ENOUGH			Setting error	(1)Check the following settings.         • Correct the JOB that the number of steps will be three or more.	<b>N</b> )))))
4468	ROBOT CALIBRATION DATA ERROR	1	The calibration between manipulators cannot be executed for this model.	Setting error	(1)Check the following settings. • Do not use a coordinated motion with this manipulator.	) 2) 
		2	The master group and the slave group are set to the same group.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	F
		3	Incorrect designation of the control group for master group	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		4	Incorrect designation of the control group for slave group	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		5	Incorrect designation of the occupation control group for calibration data	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		6	Incorrect designation of the enabling control group for calibration data	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy
Number		Code			
		7	Among three points in the master- group's calibration data, two or three points are on the same point.	Setting error	<ul><li>(1)Check the following settings.</li><li>Teach the data for calibration so that each point is different.</li></ul>
		8	Among three points in the slave- group's calibration data, two or three points are on the same point.	Setting error	<ul><li>(1)Check the following settings.</li><li>Teach the data for calibration so that each point is different.</li></ul>
		9	The number of the teaching points for calibration data is insufficient.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
4469	ROBOT CALIBRATION FRAME ERROR	1	The calibration between manipulators cannot be executed for this model.	Setting error	<ul><li>(1)Check the following settings.</li><li>The calibration function between manipulators cannot be used for this model.</li></ul>
		2	The master group and the slave group are set to the same group.	Setting error	<ul><li>(1)Check the following settings.</li><li>Set the different groups for the master group and the slave group.</li></ul>
		3	Incorrect designation of the control group for master group	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		4	Incorrect designation of the control group for slave group	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		5	Calibration data setting error	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
4470	ROBOT CARIB STEP NOT ENOUGH			Setting error	<ul><li>(1)Check the following settings.</li><li>Check the settings for number of the job steps</li></ul>
4471	ROBOT CALIBRATION DATA ERROR	1	Incorrect number of teaching points for tool calibration	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		2	Incorrect designation of the occupation control group for calibration data	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy
Number		Code			
		3	Incorrect designation of the enabling control group for calibration data	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		4	Incorrect designation of the control group for calibration data	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
4473	ARITHMETIC ALARM RESET ERROR			Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
4474	WRONG CONTROL GROUP AXIS		subcode: The related control- group	Setting error	<ul> <li>(1)Check the following settings.</li> <li>Make the setting in advance so that the control group of the CALL/JUMP designation job is included in that of the CALL/JUMP source job.</li> <li>Don't start the job which including control group under already operation by "PSTART" instruction.</li> </ul>
4475	CANNOT EXECUTE JOB (NO ROBOT)			Setting error	<ul> <li>(1)Check the following settings.</li> <li>Add the robot axis to the control-group of the job.</li> <li>A robot which executed SKILLSND is not defined as using MotoPlus sensor related API. Check the combination of the robot and MotoPlus application. If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
4476	CANNOT EDIT (EDIT LOCK JOB)	0	An attempt was made to change the tag data.	Setting error	<ul><li>(1)Check the following settings.</li><li>Release the prohibition.</li></ul>
		1	An attempt was made to change the speed tag data.	Setting error	<ul><li>(1)Check the following settings.</li><li>Release the prohibition.</li></ul>
		2	An attempt was made to change the board thickness tag data.	Setting error	<ul><li>(1)Check the following settings.</li><li>Release the prohibition.</li></ul>
4477	SELECT ERROR (APPLICATION)		subcode: Application number	Setting error	<ul> <li>(1)Check the following settings.</li> <li>Set the application to a specified robot by the application selection of maintenance mode.</li> </ul>
4478	MotoPlus MM task no response			Software operation error occurred	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, replace the CPU-201R board. Save the CMOS.BIN before replace the board to be safe. Replace the CPU-201R board, and then Please execute the update. And, please load CMOS.BIN.</li> </ul>
4479	MotoPlus MM Task watch dog error			Software operation error occurred	Check if there is high priority task of MotoPlus application running long time. Especially, check if there may be the process which waits for a special condition without executing mpTaskDelay in loop process. If such process exists, suitable remedy should be done like putting mpTaskDelay in the loop process.

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy	
Number		Code				
4480	SELECT ERROR (SENSOR 1)		subcode: Sensor number	Setting error	<ul> <li>(1)Check the following settings.</li> <li>Select the option function for the specified robot in the option function selection of maintenance mode.</li> </ul>	
4482	MotoPlus MEMORY PROTECT ERR (RTP)	1	Memory protection exception	Software operation error occurred	<ul><li>(1)Check following point in the application source code</li><li>Unsuitable Pointer handling</li></ul>	
		2	Stack or heap memory over flow	Software operation error occurred	<ul> <li>(1)Check following point in the application source code</li> <li>Stack overflow</li> <li>Bigger local memory array element number than designed size</li> </ul>	
				Software operation error occurred	<ul> <li>(1)Check following point in the application source code         <ul> <li>Heap memory overflow</li> <li>MotoPlus application gets 1Mbyte memory for user memory pool at starting up.</li> <li>Then the error might happen because of insufficient of the memory space.</li> <li>MotoPlus application can use maximum 8Mbye memory. Thus check if code and data exceed more than approximately 7Mbyte (8Mb - 1Mb(user memory pool))</li> </ul> </li> </ul>	9. Alarn
4485	WRONG SELECTION (SENSOR)			Software operation error occurred	(1)Reset the alarm, and then try again. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).	
4487	WRONG MECH PARAMETER FILE			Software operation error occurred	(1)Reset the alarm, and then try again. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).	
4490	DEFECTIVE TAUGHT POINT (ENDLESS)	1	After the Endless rotation completed, an attempt was made to execute an interpolation instruction such as MOVL and MOVC before executing an MRESET instruction.	Setting error	<ul> <li>(1)Check the following settings.</li> <li>To perform an interpolation motion such as MOVL and MOVC after an Endless rotation, execute an MRESET instruction beforehand.</li> </ul>	
		2	The base axis is set as an Endless rotation axis. The Endless function cannot be used with the base axis.	Setting error	<ul> <li>(1)Check the following settings.</li> <li>Check the parameter setting that designates the Endless rotation axis.</li> </ul>	
		3	An attempt was made to execute the Endless function although the endless axis was not designated.	Setting error	<ul><li>(1)Check the following settings.</li><li>Check the parameter setting that designates the Endless rotation axis.</li></ul>	
		4	The Endless axis exceeded the maximum pulse value (±536870911).	Setting error	<ul> <li>(1)Check the following settings.</li> <li>Set the rotation amount so that the Endless axis does not exceed the maximum pulse value.</li> </ul>	

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy
Number		Code			
4491	CORRECTIONAL DIRECTION ERROR	1	Control-group designation error for correcting-direction preparation	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		2	Designation error for the correcting-direction coordinates	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		3	When "any direction" is set for the correcting direction, the correction coordinates is not prepared.	Setting error	(1)Check the following settings. •Check the settings for the correcting direction with the reference point (REFP).
		4	When "any direction" is set for the correcting direction, the reference points (REFP) are taught on the same point.	Setting error	(1)Check the following settings. • Check the settings for the reference points (REFP) so that each point is different.
		5	Designation error for the coordinated motion control axis at the reference point	Setting error	<ul> <li>(1)Check the following settings.</li> <li>Match the control group designation of the wall point and weaving execution.</li> </ul>
4492	POSITION CORRECTION ERROR	1	Data unmatched between the correction amount data and the job data: The information about the control groups designated for the series of jobs, which is added to the correction amount data, does not include the valid control-group for the job.	Software operation error occurred	(1)Reset the alarm, and then try again. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).
		2	Data unmatched between the correction amount data and the job data: The valid control-group information that is added to the correction amount data disagrees with the valid control-group for the job.	Software operation error occurred	(1)Reset the alarm, and then try again. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).
4493	OVER TOOL FILE NO.			Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
4495	UNDEFINED ROBOT CALIBRATION		subcode: Control group which calibration is not completed	Setting error	<ul> <li>(1)Check the following settings.</li> <li>Before using the coordinated motion, execute the calibration between manipulators.</li> </ul>

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy
Number		Code			
4496	PARAMETER ERROR	1	The setting of the manipulator number is incorrect.	Setting error	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		2	Zero is set for the resolution.	Setting error	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		3	Zero is set in the feedback pulse parameter.	Setting error	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		4	The setting of L-axis ball-screw data is incorrect.	Setting error	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		5	The setting of U-axis ball-screw data is incorrect.	Setting error	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		6	Zero or a negative value is set for MAXPPS.	Setting error	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		7	Zero or a negative value is set for the maximum acceleration speed.	Setting error	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		8	Zero or a negative value is set for the maximum deceleration speed.	Setting error	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		9	Zero or a negative value is set for the play-mode servo averaging time.	Setting error	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		10	The setting of the manipulator number is incorrect. An undefined type is designated.	Setting error	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy	
Number		Code				
		11	The incorrect coordinate system is designated for the cubic interference. An undefined coordinate system is set.	Setting error	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		12	The designation of the user coordinates number is incorrect. A number out of the setting range is set.	Setting error	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		13	The reduction ratio <= 0 is output.	Setting error	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	9. 9.4
		14	Zero or a negative value is set for the spring constant.	Setting error	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	Alarm Alarm
		15	Zero or a negative value is set for the motor inertia.	Setting error	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	Message
		16	Zero or a negative value is set for the speed calculation constant.	Setting error	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	List
		17	Dividing number setting error	Setting error	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		18	The setting of allowable torque for the speed reducer is incorrect.	Setting error	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		19	The setting of allowable torque for the motor is incorrect.	Setting error	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		21	Zero or a negative value is set for the balancer.	Setting error	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy
Number		Code			
		22	The angle of hexagon set for the CUT instruction is out of the range "0 degree < angle < 60 degrees."	Setting error	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		33	Zero is set for the response time constant.	Setting error	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		35	Zero is set for the averaging time constant.	Setting error	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		36	Torque limit ratio data error	Setting error	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		39	The setting in the optimized acceleration/deceleration designation parameter is incorrect.	Setting error	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		41	The dynamics-model calculation at the optimized acceleration/ deceleration is invalid.	Setting error	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		42	Zero is set for the inertia of dynamics fixed model.	Setting error	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		43	Designation error for dynamics- model calculation type	Setting error	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		44	The optimized acceleration/ deceleration control of speed limit function is disabled.	Setting error	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		45	The axis designation parameter for the speed limit function is not set.	Setting error	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy	
Number		Code				
		46	The setting in the mode designation parameter for the speed limit function is incorrect.	Setting error	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		47	Zero or negative value is set in the allowable braking torque parameter for the speed limit function.	Setting error	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		48	Zero or a negative value is set in the speed adjustment ratio parameter for the speed limit function.	Setting error	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	9. 9.4
		49	Zero or a negative value is set in the torque limit adjustment ratio parameter for the acceleration/ deceleration tuning.	Setting error	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	Alarm Alarm
		50	Zero or a negative value is set in the parameter that sets the shortest acceleration/deceleration time for when the excessive torque is applied at the optimized acceleration/deceleration.	Setting error	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	Message Lis
		51	Zero is set for the dimension information "a3" for the SKR manipulator.	Setting error	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	ť
		53	The parameter setting for the Cartesian manipulator X-axis data is incorrect.	Setting error	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		54	The parameter setting for the Cartesian manipulator Y-axis data is incorrect.	Setting error	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		56	Zero or a negative value is set in the FORMCUT maximum acceleration/deceleration time parameter.	Setting error	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		85	The setting of wrist axis angle for tube-incorporated wrist type manipulators or three-roll wrist type manipulators is incorrect.	Setting error	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy
Number		Code			
		86	The special link JOG operation cannot be used with this manipulator.	Setting error	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		87	The setting in the parameter for special angle limit check designation is incorrect.	Setting error	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		92	A negative value is set in the roundness parameter for the path- priority control.	Setting error	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		93	The link parameter for the cutting device is not set.	Setting error	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		95	The real-time bending correction function is enabled for a control- group other than robot axis.	Setting error	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		97	Zero is set for the deceleration ratio for double T-axis unit of the V-shaped double T-axis manipulator.	Setting error	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		103	" $\alpha$ " is replaced with "0" in SKR1-5 type robot.	Setting error	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		118	Wrong value in set for backlash correction function.	Setting error	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		121	Incorrect parameter setting to inertia speed control function.	Setting error	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		122	Incorrect acceleration/ deceleration time setting at tool mass acceleration/deceleration speed correction function.	Setting error	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy	
Number		Code				
		123	Incorrect coefficient/item settings at tool mass acceleration/ deceleration speed correction function.	Setting error	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		124	No tool mas as the minimum acceleration/deceleration time at tool mass acceleration/ deceleration speed correction function.	Setting error	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		125	Incorrect speed setting at tool mass acceleration/deceleration speed correction function.	Setting error	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	9 9 4
		126	Incorrect coefficient/item settings at tool mass acceleration/ deceleration speed control function.	Setting error	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	Alarm M
		127	No tool mass as the maximum acceleration/deceleration time at tool mass acceleration/ deceleration speed control function.	Setting error	(1)Reset the alarm, and then try again. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).	essage Lis
		129	An error in the standard arithmetical axis number setting for approximation model.	Setting error	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	+
		130	An error in the standard expanding point number setting for approximation model.	Setting error	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		131	An error in the radius setting for approximation model.	Setting error	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		132	setting error of arithmetical axis number in D-H method.	Setting error	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		133	setting error of choosing no / wrong connection base arithmetical axis number in D-H method.	Setting error	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy
Number		Code			
		135	Base axis control point $\rightarrow$ Robot coordinate system of f set g setting prohibited	Setting error	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		136	Pulse linked JOG function specification error	Setting error	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		137	Dual drive control specification error	Setting error	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		138	Notch filter supported acceleration and deceleration tuning: Notch filter function setting error	Setting error	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		139	Notch filter supported acceleration and deceleration tuning: Notch filter (z2) setting error	Setting error	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
4497	DEFECTIVE TAUGHT POINT (CALIB)	1	Some of the teaching points for master-group are on the same point.	Setting error	<ul><li>(1)Check the following settings.</li><li>Perform the teaching again so that the teaching points are different from one another.</li></ul>
		2	Some of the teaching points for slave-group are on the same point.	Setting error	<ul><li>(1)Check the following settings.</li><li>Perform the teaching again so that the teaching points are different from one another.</li></ul>
		3	The 2nd-axis positions of C3, C4, and C5 of station axes are not the same.	Setting error	<ul> <li>(1)Check the following settings.</li> <li>Perform the teaching again so that the 2ndaxis positions of C3, C4, and C5 of the station axes are the same.</li> </ul>
		4	The 1st-axis positions of C1, C2, and C3 of station axes are not the same.	Setting error	<ul> <li>(1)Check the following settings.</li> <li>Perform the teaching again so that the 1staxis positions of C1, C2, and C3 of station axes are the same.</li> </ul>
		5	The 2nd-axis positions of C1, C2, and C3 of station axes are the same.	Setting error	<ul><li>(1)Check the following settings.</li><li>Perform the teaching again so that the teaching positions are different from one another.</li></ul>
		6	The 1st-axis rotation direction of C3, C4, and C5 of station axes are not the same.	Setting error	<ul> <li>(1)Check the following settings.</li> <li>Perform the teaching again so that the 1staxis rotation direction of C3, C4, and C5 of station axes are the same.</li> </ul>
		7	The 1st-axis (elevation axis) positions of C1, C2, and C3 of station axes are not the same.	Setting error	<ul> <li>(1)Check the following settings.</li> <li>Perform the teaching again so that the 1staxis (elevation axis) positions of C1, C2, and C3 of station axes are the same.</li> </ul>

Alarm Number	Alarm Name	Sub Code	Meaning	Cause	Remedy
		8	The 1st-axis (elevation axis) positions of C3, C4, and C5 of station axes are not the same.	Setting error	<ul> <li>(1)Check the following settings.</li> <li>Perform the teaching again so that the 1staxis (elevation axis) positions of C3, C4, and C5 of station axes are the same.</li> </ul>
4498	CANNOT EXECUTE JOB (NO GRP AXIS)		An attempt was made to execute an instruction that could not be executed in a job without control group.	Setting error	<ul><li>(1)Check the following settings.</li><li>Check the settings for the job instruction with control group.</li></ul>
4499	UNDEFINED POSITION VARIABLE		subcode: The variable number	Setting error	<ul><li>(1)Check the following settings.</li><li>Check the settings for the position type variable.</li></ul>
4500	UNDEFINED USER FRAME		subcode: User coordinate number	Setting error	<ul><li>(1)Check the following settings.</li><li>Check the settings for the user coordinate.</li></ul>
4501	OUT OF RANGE (PARALLEL PROCESS)		subcode: Task number	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
4502	SL BOARD ON-LINE ERROR		The option board was detected not to operate normally at power ON.	Software operation error occurred	(1)Reset the alarm, and then try again. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).
4507	REFP POS ERROR (SEARCH MOTION)			Setting error	<ul> <li>(1)Check the following settings.</li> <li>Perform the teaching again so that the search start point and the motion target point are not the same.</li> <li>Increase the distance between the search start point and the motion target point.</li> </ul>
4508	SPECIFIED ERROR (COORDINATE)	0	The specified coordinate system does not exist.	Setting error	<ul><li>(1)Check the following settings.</li><li>Check the settings for the coordinate system which can be used.</li></ul>
		1	Designation error of the master tool coordinate system. This coordinate system cannot be used.	Setting error	<ul><li>(1)Check the following settings.</li><li>Check the settings for the coordinate system which can be used.</li></ul>
		2	Designation error of the tool coordinate system. This coordinate system cannot be used.	Setting error	<ul><li>(1)Check the following settings.</li><li>Check the settings for the coordinate system which can be used.</li></ul>
		3	Designation error of the direction of travel coordinate system (for a shared function). This coordinate system cannot be used.	Setting error	<ul><li>(1)Check the following settings.</li><li>Check the settings for the coordinate system which can be used.</li></ul>
		4	Designation error of the any direction coordinate system (for a shared function). This coordinate system cannot be used.	Setting error	<ul> <li>(1)Check the following settings.</li> <li>Check the settings for the coordinate system which can be used.</li> </ul>

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy
Number		Code			
		6	Designation error of the conveyor coordinate system. This coordinate system cannot be used.	Setting error	<ul><li>(1)Check the following settings.</li><li>Check the settings for the coordinate system which can be used.</li></ul>
		10	Designation error of the cylindrical coordinate system. This coordinate system cannot be used.	Setting error	<ul><li>(1)Check the following settings.</li><li>Check the settings for the coordinate system which can be used.</li></ul>
		11	Designation error of the coordinate system for the external reference point. This coordinate system cannot be used.	Setting error	<ul><li>(1)Check the following settings.</li><li>Check the settings for the coordinate system which can be used.</li></ul>
4509	MFRAME ERROR	1	The master-tool user coordinates could not be prepared.	Setting error	<ul> <li>(1)Check the following settings.</li> <li>Execute the MFRAME instruction in coordinated job when you make the master tool user coordinate.</li> </ul>
4510	CANNOT EXECUTE INSTRUCTION (SQRT)			Setting error	<ul> <li>(1)Check the following settings.</li> <li>Check the job settings so that the second argument of SQRT instruction does not become negative.</li> </ul>
4511	OUT OF RANGE (DROP-VALUE)		subcode: Control group exceeding the allowable value	Setting error	<ul><li>(1)Check the following settings.</li><li>Confirm the load setting to the robot.</li></ul>
4512	TWO STEPS SAME LINE (3 STEPS)			Setting error	<ul><li>(1)Check the following settings.</li><li>Check the settings so that the teaching points are not aligned in a straight line.</li></ul>
4513	EXCESSIVE SEGMENT (SAFETY 1): LOW/HIGH		subcode: Control group and axis	Setting error	<ul> <li>(1)Check the following settings.</li> <li>Reduce the speed of the step where the alarm occurred.</li> <li>Change the move instruction to joint interpolation (MOVJ).</li> <li>* Be careful to the peripheral interference since its movement changes.</li> </ul>
4515	EXCESSIVE SEGMENT (SAFETY 2): LOW/HIGH		subcode: Control group and axis	Setting error	<ul> <li>(1)Check the following settings.</li> <li>Reduce the speed of the step where the alarm occurred.</li> <li>Change the move instruction to joint interpolation (MOVJ).</li> <li>* Be careful to the peripheral interference since its movement changes.</li> </ul>
4517	SEARCH MONITOR SET ERROR (SERVO)		subcode: The related control- group	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
4518	SEARCH MON RELEASE ERR (SERVO)		subcode: The related control- group	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
Alarm	Alarm Name	Sub	Meaning	Cause	Remedy
--------	-------------------------------------	------	---	--------------------------------------	---
Number		Code			
4521	WRONG JOB TYPE		subcode 0000_0001: A robot job was started from the concurrent job at CALL/JUMP instruction execution. 0000_1001: A concurrent job was started from the robot job at CALL/ JUMP instruction execution. 1000_0001: A system job was started from the robot job at CALL/ JUMP instruction execution.	Setting error	<ul> <li>(1)Check the following settings.</li> <li>Check the settings for the job to be started.</li> </ul>
4522	TAG DATA CHANGE PROCESS ERROR	0	An attempt was made to change the contents of variable tag data.	Setting error	(1)Check the following settings. • The variable tag cannot be changed. Correct the job so as not to use the variable tag.
		1	An attempt was made to change the tag data for the job prohibited from being edited.	Setting error	(1)Check the following settings.     • Release the prohibition.
		2	An error occurred at instruction read-in.	Software operation error occurred	(1)Reset the alarm, and then try again. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).
		3	The tag is not registered.	Software operation error occurred	(1)Reset the alarm, and then try again. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).
		4	The tag data was variable specification.	Setting error	<ul><li>(1)Check the following settings.</li><li>The variable tag cannot be changed. Correct the job so as not to use the variable tag.</li></ul>
		5	The value which it was made to change exceeded the limit of tag data.	Setting error	<ul><li>(1)Check the following settings.</li><li>Check the contents of changing data.</li></ul>
		7	An error occurred at tag data change.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
4523	SHARED AXES CONTROL ERROR		subcode: Internal control error in software	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
4524	CANNOT EXECUTE INST (COUCUR JOB)			Setting error	<ul> <li>(1)Check the following settings.</li> <li>Delete an instruction that cannot be executed such as move instruction in the concurrent job.</li> </ul>

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy
Number		Code			
4525	CANNOT EXECUTE SPECIFIED JOB	1	An interrupt job (user setting) is started up during the back operation.	Setting error	(1)Check the following settings. ·Check the job so that the interrupt job will not start-up during the back operation.
		2	An interrupt macro job is started up during the back operation.	Setting error	(1)Check the following settings. •Check the job so that the interrupt macro job will not start-up during the back operation.
		3	An interrupt job (inside the system) is started up during the back operation.	Setting error	(1)Check the following settings. •Check the job so that the interrupt job will not start-up during the back operation.
4527	UNDEFINED PORT NO. (AOUT)			Setting error	<ul><li>(1)Check the following settings.</li><li>Check the settings for the specified analog output port number.</li></ul>
4528	SYNTAX ERROR	1	A syntax error was found in the IF sentence.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
4529	TWIN COORDINATED ERROR	1	A job without control group was started by SYNC instruction.	Setting error	<ul><li>(1)Check the following settings.</li><li>Check the control group setting of the job to be started by SYNC.</li></ul>
		2	A job only with robot axes was started by SYNC instruction.	Setting error	<ul><li>(1)Check the following settings.</li><li>Check the control group setting of the job to be started by SYNC.</li></ul>
		3	A job only with master control group axes was started by SYNC instruction.	Setting error	<ul><li>(1)Check the following settings.</li><li>Check the control group setting of the job to be started by SYNC.</li></ul>
		4	At full synchronization, the completion timings of move instructions for the master and the slave disagreed.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		5	At full synchronization, no operation request from the master was sent.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		6	At full synchronization, the execution timings of move instructions for the master and the slave disagreed.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		7	The twin synchronous ID number is incorrect.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		8	An attempt was made to execute triple synchronization when specified Sub-master for the master was different.	Setting error	<ul> <li>(1)Check the following settings.</li> <li>Match the system number specification of the master between the job to be started by SYNC.</li> </ul>

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy
Number		Code			
4530	CONVEYOR TRACKING ERROR	1	The base axis specification is other than 1 or 2 for conveyor characteristic file.	Setting error	<ul> <li>(1)Check the following settings.</li> <li>Set the base axis specification of conveyor characteristic file to either 0, 1, or 2.</li> </ul>
		2	No robot axis in the job for robot axis tracking	Setting error	<ul> <li>(1)Check the following settings.</li> <li>Correct the job setting so that the robot axis tracking is executed in the job where robot axis exists.</li> </ul>
		3	No base axis in the job for base axis tracking	Setting error	<ul> <li>(1)Check the following settings.</li> <li>Correct the job settings so that the base axis tracking is executed in the job where base axis exists.</li> </ul>
		4	The conveyor board number and conveyor characteristic file number used are incorrect.	Setting error	(1)Check the following settings. • Check the specification of conveyor condition file number for use.
		5	There was no conveyor start position data at pre-reading processing.	Software operation error occurred	(1)Reset the alarm, and then try again. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).
		10	No base axis in the job for arc tracking	Setting error	(1)Check the following settings. • Correct the job setting so that the arc tracking is executed in the job where robot axis exists.
4531	UNDEFINED CONVEYOR COND FILE		subcode: Conveyor characteristic file number	Setting error	(1)Check the following settings.         • Set "Use state" of conveyor characteristic file to "1: Use."
4532	CONVEYOR SPEED DOWN		subcode: Conveyor number	Setting error	<ul><li>(1)Check the following settings.</li><li>Correct the "Convey or Lowest Speed" set in the conveyor characteristic file.</li></ul>
4533	ARITHMETIC ERROR (CV TRACKING)	1	Designation error of the conveyor tracking control-group	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		2	Designation error of the user coordinates for the conveyor tracking	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		3	An attempt was made to use the conveyor tracking function with the slave manipulator at coordinate motion.	Setting error	<ul> <li>(1)Check the following settings.</li> <li>The conveyor tracking cannot be executed to the slave manipulator of the coordinate system. Correct the job so that the conveyor tracking perform by the robot unit or without coordinated motion.</li> </ul>
		4	Zero is set for the resolution for the turn-table synchronization.	Setting error	<ul><li>(1)Check the following settings.</li><li>Check the settings for the resolution.</li></ul>
		5	Base axis tracking application error at the control whose conveyor coordinates are different.	Setting error	<ul> <li>(1)Check the following settings.</li> <li>Set the tracking system to "robot axis tracking".</li> <li>Do not operate between different conveyors while it is set to "base-axis tracking".</li> </ul>

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy
Number		Code			
		6	Turn table tracking application error at the control whose conveyor coordinates are different.	Setting error	(1)Check the following settings. •Do not operate between different conveyors while it is set to turn table synchronization.
		7	I interpolation error of the control whose conveyor coordinates are different.	Setting error	(1)Check the following settings. •Teach interpolation method to SYMOVL when operating between different conveyors.
4534	TORQUE INTERFERENCE			Setting error	<ul> <li>(1)Check the following settings.</li> <li>Correctly set the weight information in the tool file. (Are the weight: W and the number set to the load value of either Xg, Yg or Zg?)</li> <li>Reduce the speed in the step where the alarm occurred.</li> </ul>
4535	TARGET VARIABLE TYPE UNMATCHED	0	An attempt was made to obtain the byte type system variable by the other type variable.	Setting error	<ul><li>(1)Check the following settings.</li><li>Obtain as the byte type variable.</li></ul>
		1	An attempt was made to obtain the integer type system variable by the other type variable.	Setting error	<ul><li>(1)Check the following settings.</li><li>Obtain as the integer type variable.</li></ul>
		2	An attempt was made to obtain the double-precision integer-type system variable by the other type variable.	Setting error	<ul><li>(1)Check the following settings.</li><li>Obtain as the double-precision integer-type variable.</li></ul>
		3	An attempt was made to obtain the real-number type system variable by the other type variable.	Setting error	<ul><li>(1)Check the following settings.</li><li>Obtain as the real-number type variable.</li></ul>
		4	An attempt was made to obtain the character-string type system variable by the other type variable.	Setting error	<ul><li>(1)Check the following settings.</li><li>Obtain as the character-string type variable.</li></ul>
4538	ROBOT AXIS TRACKING INVALID	0	"SYMOVJ" instruction is executed at robot-axis tracking.	Setting error	(1)Check the following settings. •Do not use "SYMOVJ" instruction in robot axis tracking.
4539	CORNER R CONTROL ERROR	1	The Corner-R motion cannot be used for coordinated motion.	Setting error	<ul><li>(1)Check the following settings.</li><li>Do not use the Corner-R motion for coordinated motion.</li></ul>
		2	An attempt was made to execute the Corner-R motion for the same point.	Setting error	<ul><li>(1)Check the following settings.</li><li>Check the settings for the teaching so that the start step and end step are not on the same point.</li></ul>
		3	The Corner-R zone is taught on a straight line.	Setting error	<ul> <li>(1)Check the following settings.</li> <li>Check the settings for teaching so that the Corner-R zone is not on a strait line.</li> </ul>

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy
Number		Code			
		4	The start position or end position for the Corner-R motion could not be calculated inside the start zone or the end zone.	Setting error	<ul> <li>(1)Check the following settings.</li> <li>Make the setting for the Corner-R radius small.</li> <li>Make the moving amount of the Corner-R start step long.</li> <li>Make the moving amount of the Corner-R start end long.</li> </ul>
		5	The Corner-R motion cannot be used for coordinated motion (with master manipulators).	Setting error	<ul> <li>(1)Check the following settings.</li> <li>Do not use the Corner-R motion for master manipulators at coordinated motion.</li> </ul>
		6	The Corner-R motion cannot be used for MOVC, MOVS, and EIMOVC instructions.	Setting error	<ul> <li>(1)Check the following settings.</li> <li>• Use a MOVL instruction when using the Corner-R motion.</li> </ul>
		8	Different tool numbers are set in a Corner-R zone (for the Corner-R middle step and end step).	Setting error	(1)Check the following settings.       •         • Use the same tool number in a Corner-R zone.       •
		17	The Corner-R motion is disabled during conveyor tracking.	Setting error	<ul><li>(1)Check the following settings.</li><li>Do not perform the conveyor tracking when using the Corner-R motion.</li></ul>
		18	Arithmetic error occurred when calculating the acceleration and deceleration time for the Corner-R operation	Setting error	<ul> <li>(1)Check the following settings.</li> <li>Do not perform the conveyor tracking when using the Corner-R motion.</li> </ul>
		20	The Corner-R motion is disabled to start during continuous motion.	Setting error	(1)Check the following settings.       •         • Make the setting for the Corner-R radius small.       •         • set Timer or PL=0 to a previous line.       •
4540	JOB QUE EMPTY ERROR			Setting error	<ul> <li>(1)Check the following settings.</li> <li>Use "CALL QUE" under the condition that the job data is set to the job queue.</li> </ul>
4541	INVALID INPUT STRING (VAL)	1	There was no character string representing a constant in character string to be extracted at VAL instruction execution.	Setting error	<ul><li>(1)Check the following settings.</li><li>Check the settings for the data of the character string to be extracted.</li></ul>
4542	MRESET ERROR	1	An MRESET instruction was executed while no endless axis was designated.	Setting error	<ul><li>(1)Check the following settings.</li><li>Set the endless axis.</li></ul>
4543	STACK LESS THAN 0 (JOB CALL)		At job return, an attempt was made to fetch a data from an empty job call stack or to stack a data in the job call stack that is full.	Software operation error occurred	(1)Reset the alarm, and then try again. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy	
Number		Code				
4544	MID\$ INST ERROR	1	The first character of character string to be extracted is null at MID\$ instruction execution.	Setting error	<ul><li>(1)Check the following settings.</li><li>Check the settings for the data of the character string to be extracted.</li></ul>	
		2	The extraction start position exceeds the character string length at MID\$ instruction execution.	Setting error	<ul><li>(1)Check the following settings.</li><li>Check the settings for the data of the character string to be extracted.</li></ul>	
4546	CANNOT EXCUTE SYSTEM JOB		subcode: System number	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	9.4
4547	PRIMITIVE ERROR		subcode: Error code	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	Alarm
4548	CANNOT OPERATE SPECIFIED EVENT		subcode: System number	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	ı Messag
4549	NOT EXECUTION OF INIEVNT		subcode: System number	Setting error	<ul><li>(1)Check the following settings.</li><li>Execute an INIEVNT instruction before executing an event related instruction.</li></ul>	e Lis
4550	CANNOT EXECUTE INST (USER JOB)		subcode: System number	Setting error	<ul> <li>(1)Check the following settings.</li> <li>This instruction cannot be executed in the system job. Correct the job so that the instruction is executed in the user job.</li> </ul>	-
4565	SOFTWARE UNMATCH	1	The multi-layer welding function is not used.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		3	The TURBO function is not used.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		5	The conveyor/press synchronization function is not used.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		6	The shared motion function is not used.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy	
Number		Code				
		7	The layer motion function is not used.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		8	The general sensor function is not used.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		9	The servo float function is not used.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	9. 9.4
		10	The laser cutting function (with small circle cutter) is not used.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	Alarm Alarm
		11	The motor gun function (for spot welding application) is not used.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	Message
		12	The speed control function (VCON/VCOF) is not used.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	List
		14	The laser cutting function (for form cutting operation) is not used.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		15	The series communication function between the systems (PSEND/PRECV) is not used.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		16	The motion extension function is not used.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		17	The bending function is not used.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy
Number		Code			
		18	The ME-NET function is not used.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		19	The MEMO-PLAY function is not used.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		20	The 3D-SHIFT function is not used.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		255	An attempt was made to execute an undefined instruction.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
4566	USER FRAME MAKING ERROR	1	The teaching points are incorrect.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		2	The teaching points for user- coordinate turning are incorrect.	Setting error	<ul> <li>(1)Check the following settings.</li> <li>Among three taught points in the teaching position. Teach the three points again so that they do not lie in the straight line.</li> </ul>
		3	The robot axis is not specified for the control group of the job to prepare the user coordinates.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		5	Position data error	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		6	Setting error of the slave group for user coordinate conversion	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
4568	UNDEFINED PRESS COND DATA FILE		subcode: Press characteristic file number	Setting error	<ul><li>(1)Check the following settings.</li><li>Set the status of press characteristic file to be used in the job to "Used State."</li></ul>
4569	UNDEFINED PRESS RESOLUTION DATA		subcode: Press characteristic file number	Setting error	<ul><li>(1)Check the following settings.</li><li>Set the press resolution data to be used in the job.</li></ul>

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy	
Number		Code				
4571	SERVO FLOAT MODE RELEASE ERR			Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
4579	ANTICIPATION CONTROL ERROR	1	No availability in anticipation control	Setting error	<ul> <li>(1)Check the following settings.</li> <li>Maximum simultaneous execution number of anticipation control is five.</li> <li>Correct the settings for the job so that it is within five.</li> </ul>	
		2	The anticipation data exceeded the maximum length.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	.9 .9
4581	DEFECTIVE ANTICIPATION OT FILE	1	Incorrect setting of OT output number for anticipation output file	Setting error	<ul><li>(1)Check the following settings.</li><li>Check the setting value of OT output number.</li></ul>	4
		2	Incorrect setting of OG output number for anticipation output file	Setting error	<ul><li>(1)Check the following settings.</li><li>Check the setting value of OG output number.</li></ul>	Alarm
4585	SERVO PG ON ERROR			Connection failure	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, check the connection and inserting state of the following cables and connectors.</li> <li>Each axes encoder cable</li> </ul>	i Messag
4591	SPEED CTRL MODE SET ERR (SERVO)			Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	e List
4592	SPEED CTRL MODE CANCEL ERR (SV)			Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
4595	CAN'T DO FIXED FORM CUT MOTION	1	The setting for radius is incorrect. (1) For a circle, it is incorrectly set as: radius <= 0, radius < minimum radius value, or radius > maximum radius value. (2) For an ellipse, it is incorrectly set as: radius <= 0, radius < minimum radius value/2, or radius > (maximum radius/2 - width/2).	Setting error	<ul> <li>(1)Check the following settings.</li> <li>Setting of the radius data</li> </ul>	

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy	
Number		Code				
		2	The setting for width is incorrect. (1) For a rectangle, it is incorrectly set as: width < 1.0, width > sqrt (maximum diameter2 - height2), or width > maximum diameter. (2) It is incorrectly set as: width < 0, width > maximum diameter -2 * radius.	Setting error	<ul> <li>(1)Check the following settings.</li> <li>Setting of the width data</li> </ul>	
		3	The setting for height is incorrect. (1) For a rectangle, it is incorrectly set as: height > maximum diameter, height < minimum diameter/2, or height > sqrt (maximum diameter <sup>2</sup> - width <sup>2</sup> ).	Setting error	<ul><li>(1)Check the following settings.</li><li>Setting of the height data</li></ul>	9.4 A
		4	The setting for the corner radius is incorrect. (1) For a rectangle, it is incorrectly set as: corner radius > width/2 or corner radius > height/2.	Setting error	<ul><li>(1)Check the following settings.</li><li>Setting of the corner radius</li></ul>	larm Mess
		5	The setting for overlap is incorrect. (1) For a rectangle, it is incorrectly set as overlap > width/2. (2) For a circle, it is incorrectly set as overlap > ABS ( $2\pi$ * radius). (3) For an ellipse, it is incorrectly set as overlap > $\pi$ * radius +ABS (width/2).	Setting error	<ul> <li>(1)Check the following settings.</li> <li>Setting of the overlap data</li> </ul>	age List
		6	The setting for the cutting speed is incorrect. It is set as the cutting speed > maximum linear speed.	Setting error	<ul><li>(1)Check the following settings.</li><li>Setting of the cutting speed</li></ul>	
		7	Coordinated motion cannot be used with the Form Cutting motion.	Setting error	<ul><li>(1)Check the following settings.</li><li>Do not use the coordinated motion.</li></ul>	
		8	Zero or a negative value is set in the minimum diameter parameter (S1CxG063) for the Form Cutting motion.	Setting error	<ul> <li>(1)Check the following settings.</li> <li>The setting of the minimum diameter parameter (S1CxG063) for the Form Cutting motion.</li> </ul>	
		9	Zero or a negative value is set in the maximum diameter parameter (S1CxG064) for the Form Cutting motion.	Setting error	<ul> <li>(1)Check the following settings.</li> <li>The setting of the maximum diameter parameter (S1CxG064) for the Form Cutting motion.</li> </ul>	

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy
Number		Code			
		10	Although "PLACEMENT" or "AUTO" is set for the start point designation on the FORM CUT SETTING window, the FORMAPR instruction was not executed.	Setting error	<ul><li>(1)Check the following settings.</li><li>Execute the FORMAPR instruction.</li></ul>
		11	The Cut file setting of the FORMAPR instruction is different from that of the FORMCUT instruction.	Setting error	<ul><li>(1)Check the following settings.</li><li>The Cut file settings of FORMAPR and FORMCUT instructions must be same.</li></ul>
4596	FORMCUT ERROR	1	An attempt was made to re- execute the FORMCUT instruction after interrupting it.	Execute condition failure	<ul> <li>(1)Check the following settings.</li> <li>Re-execute the move instruction executed before the FORMCUT instruction, and then execute the FORMCUT instruction again.</li> </ul>
4597	OFFLINE POSITION DATA CONVERT ERR	1	Incorrect information of reference position data for offline position data conversion	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		3	Incorrect reference-point data for offline position data conversion	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		4	The standard position data for offline position data conversion could not correctly be calculated.	Setting error	<ul> <li>(1)Check the following settings.</li> <li>The variable position may be out of the robot motion range. Check if the variable position is within the robot motion range.</li> </ul>
		5	Incorrect pulse incremental value for offline position data conversion	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		6	The position data could not correctly be added by the pulse incremental value at the offline position data conversion.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		7	Incorrect Cartesian incremental value for offline position data conversion	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		8	The position data could not correctly be added by the Cartesian incremental value at the offline position data conversion.	Setting error	<ul> <li>(1)Check the following settings.</li> <li>The variable position may be out of the robot motion range. Check if the variable position is within the robot motion range.</li> </ul>

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy
Number		Code			
		9	The position conversion could not be done in the designated coordinate system at the offline position data conversion.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		10	Incorrect incremental value of angle for offline position data conversion	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		11	The position data could not correctly be added by the incremental value of angle at the offline position data conversion.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		14	The reverse shift value could not correctly be calculated at the offline position data conversion.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		15	The reverse shift value could not correctly be calculated at the offline position data conversion.	Software operation error occurred	(1)Reset the alarm, and then try again. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).
		17	The shift value could not correctly be added at the offline position data conversion.	Software operation error occurred	(1)Reset the alarm, and then try again. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).
		19	The positions for the mirror shift function could not correctly be calculated at the offline position data conversion.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		20	The positions could not correctly be converted for the mirror shift function at the offline position data conversion.	Setting error	<ul> <li>(1)Check the following settings.</li> <li>The variable position may be out of the robot motion range. Check if the variable position is within the robot motion range.</li> </ul>
		22	Incorrect designation of coordinates for a new mirror-shift conversion function at the offline position data conversion	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
4599	SERVO COMMAND ERROR		An attempt was made to issue the command while the servo control processing has not completed. subcode: Servo CPU bit number	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
4604	SPECIFIED ERR (ABSO RECOVER AXIS)			Setting error	<ul><li>(1)Check the following settings.</li><li>Registration for the home position correction data.</li></ul>

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy
Number		Code			
4605	SETTOOL ERROR	1	The difference between the current tool constant and a new set value exceeded the allowable range (parameter set value).	Setting error	<ul> <li>(1)Check the following settings.</li> <li>Correct the job so that the setting value of tag is allowable value.</li> <li>Set the allowance amount of the tool data automatic setting function maximum deviation (S3C1192) to large value.</li> </ul>
4606	LACK OF GLOBAL VARIABLE AREA			Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
4607	WRONG EXECUTION OF MACRO INST	1	The execution macro job is not set.	Setting error	<ul><li>(1)Check the following settings.</li><li>Check the settings for execution macro job.</li></ul>
		2	The interrupt macro job is not set.	Setting error	<ul><li>(1)Check the following settings.</li><li>Check the settings for interrupt macro job.</li></ul>
		3	An attempt was made to start the job that could not be started by the macro instruction.	Setting error	<ul><li>(1)Check the following settings.</li><li>Check the settings for macro job.</li></ul>
		5	An error occurred in the operation process of job call stack when the execution of macro instruction was cancelled.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		6	Incorrect macro number	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
4608	WRONG EXECUTION OF GETARG INST	1	The job argument is not set.	Setting error	<ul><li>(1)Check the following settings.</li><li>Check the settings for jobs.</li></ul>
		2	No number of the specified job argument	Setting error	<ul><li>(1)Check the following settings.</li><li>Check the settings for jobs.</li></ul>
		3	The data types of job argument disagreed.	Setting error	<ul><li>(1)Check the following settings.</li><li>Check the settings for jobs.</li></ul>
4611	OVER OPTON INST EXECUTION LIMIT			Setting error	<ul> <li>(1)Check the following settings.</li> <li>Check the settings for the OPTON instruction. OPTON instruction can use only the function to five simultaneously.</li> </ul>
4612	TSYNC ERROR		subcode: the number of synchronizations of the first executed TSYNC	Setting error	<ul> <li>(1)Check the following settings.</li> <li>Check the settings for the number of synchronizations of the TSYNC instruction.</li> </ul>

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy
Number		Code			
4615	I/O AXIS OPERATING		An attempt was made to command a job whose control group was in I/O axis motion.	Setting error	<ul> <li>(1)Check the following settings.</li> <li>Does not the I/O axis motion executed for the control group that executing the job?</li> <li>Does not the job executed for the control group that operating by the I/O axis motion?</li> <li>The control group where the I/O axis is operating cannot execute the job. Moreover, the I/O axis motion cannot perform for the control group where the job is executing.</li> </ul>
4619	UNDEFINED JOB ENTRY TABLE		subcode: Designated registration number	Setting error	<ul><li>(1)Check the following settings.</li><li>Check the settings for the job registration table.</li></ul>
4620	ARM (TOOL) INTERFERENCE		subcode: Bit specification of interfered axis	Setting error	<ul> <li>(1)Check the following settings.</li> <li>Modify the teaching so that the robots indicated by the subcode would not interfere each other.</li> <li>Confirm the tool mode (tool interference file) of the robots indicated by the subcode would not interfere each other.</li> <li>Confirm the settings of the calibration between the robots.</li> </ul>
4622	SELF-INTERFERENCE		subcode: Manipulator number	Setting error	<ul> <li>(1)Check the following settings.</li> <li>Modify the teaching so that the robots indicated by the subcode would not interfere each other</li> <li>Confirm the tool mode (tool interference file) of the robots indicated by the subcode would not interfere each other</li> <li>(2) If the manipulator is stopped near the interference area by servo OFF, it may interfere with the interference area.</li> <li>In this case, execute the following operations to disable the self interference check</li> <li>and move each part out of the interference area.</li> <li>Change the mode to "TEACH"</li> <li>To display LIMIT RELEASE window, select the main menu [ROBOT] and then [LIMIT RELEASE]</li> <li>Change the setting for SELF INTERFERENCE RELEASE from "INVALID" to "VALID" by [SELECT] key</li> <li>NOTE) Be sure to check the operation direction since the above operations enable manipulator's parts to interfere with each other.</li> </ul>
4623	WRONG EXECUTION OF GETPOS INST	1	An attempt was made to obtain the step that used a local position type variable. (The step with local position type variable cannot be fetched. Example: MOVJ LP000 VJ=25.00)	Setting error	<ul> <li>(1)Check the following settings.</li> <li>Check the settings for the GETPOS instruction.</li> </ul>

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy	
Number		Code				
		2	An attempt was made to obtain the step that used a local position type variable. (The step with local position type variable cannot be fetched. Example: MOVJ LP000 VJ=25.00)	Setting error	<ul> <li>(1)Check the following settings.</li> <li>Check the settings for the GETPOS instruction.</li> </ul>	
		3	The specified step did not exist.	Setting error	<ul><li>(1)Check the following settings.</li><li>Check the settings for the GETPOS instruction.</li></ul>	
4628	WRITE VARIABLE NO. MULTI SETTING		subcode: Duplicated variable number	Setting error	<ul><li>(1)Check the following settings.</li><li>Check the settings for the written destination variable numbers.</li></ul>	
4629	GROUP CHANGE ERROR	1	The group change parameter was invalid.	Setting error	<ul><li>(1)Check the following settings.</li><li>Validate the group change parameter.</li></ul>	9. 9.4
		2	The GRPCHG instruction was executed while the external axis motor was servo ON.	Setting error	<ul> <li>(1)Check the following settings.</li> <li>Execute the GRPCHG instruction when the external axis motor was servo OFF.</li> </ul>	Alarm Alarm
		3	The GRPCHG instruction was executed in unchucking status.	Setting error	<ul><li>(1)Check the following settings.</li><li>Execute the GRPCHG instruction in chucking status.</li></ul>	Mes
		4	The group identification signal was not received.	Setting error	<ul><li>(1)Check the following settings.</li><li>Check the settings for group identification signal.</li></ul>	sage
		5	The specified control group number and the group identification number were unmatched.	Setting error	<ul><li>(1)Check the following settings.</li><li>Check the settings for the specified control group number.</li></ul>	List
		6	The encoder PG power supply was OFF when the GRPCHG was ON.	Setting error	<ul><li>(1)Check the following settings.</li><li>Turn ON the encoder PG power supply when GRPCHG is ON.</li></ul>	
		7	The encoder PG power supply was ON when the GRPCHG was OFF.	Setting error	<ul><li>(1)Check the following settings.</li><li>Turn OFF the encoder PG power supply when GRPCHG is OFF.</li></ul>	
		8	The control group that corresponded to the received group identification signal did not exist.	Setting error	<ul><li>(1)Check the following settings.</li><li>Check the settings for group identification signal.</li></ul>	
4632	UNDEFINED LNR SCALE FILE		subcode: Linear scale characteristic file number	Setting error	<ul><li>(1)Check the following settings.</li><li>Complete the settings for the linear scale condition file.</li></ul>	
4635	CANNOT EXECUTE COMMON JOB		subcode: The related control- group	Setting error	<ul><li>(1)Check the following settings.</li><li>Check the settings for control group specified by the CALL instruction.</li></ul>	
4637	TRACK CHG WORK IN/ NOT NOT FOUND		subcode: Conveyor characteristic file number	Setting error	<ul> <li>(1)Check the following settings.</li> <li>Check the workpiece presence/absence and data settings for the synchronization section.</li> </ul>	

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy
Number		Code			
4638	TRACKING CHG WORK ID NOT FOUND		subcode: Conveyor characteristic file number	Setting error	<ul><li>(1)Check the following settings.</li><li>Check the workpiece presence/absence and data settings for the synchronization section.</li></ul>
4639	SYMOVJ INST EXECUTE ERROR	2	The conveyor moving amount is not specified for the SYMOVJ motion.	Setting error	<ul><li>(1)Check the following settings.</li><li>Set the conveyor moving amount for the SYMOVJ motion.</li></ul>
		3	An error occurred in the preparation process of the manipulator motion start position for the SYMOVJ motion.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		4	An error occurred in the preparation process of the manipulator motion end position for the SYMOVJ motion.	Software operation error occurred	(1)Reset the alarm, and then try again. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).
4640	WRONG EXECUTION OF PSTART INST	1	No axis data of control group to be disconnected	Setting error	<ul><li>(1)Check the following settings.</li><li>Check the settings for PSTART instruction.</li></ul>
		2	An attempt was made to disconnect a control group other than the occupation control group during pre-reading processing.	Setting error	(1)Check the following settings.         • Check the settings for PSTART instruction.
		3	An attempt was made to disconnect a control group other than the occupation control group when executing a PSTART instruction.	Setting error	<ul> <li>(1)Check the following settings.</li> <li>Check the settings for PSTART instruction.</li> </ul>
4641	CANNOT EXECUTE JOB (SEPARATE GRP)		subcode: The disconnected control group used by a move instruction	Setting error	<ul> <li>(1)Check the following settings.</li> <li>Correct the teaching so that the control group disconnected by itself is not to operate for move instruction of own system.</li> </ul>
4649	PARTIAL MOTION RANGE INTRF.		subcode: Interference control group number & interference axis & interference area number.	Setting error	<ul><li>(1)Check the following settings.</li><li>Check the teaching position setting of manipulators.</li></ul>
4650	TRQ CLEAR ERROR			Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
4651	PALLETIZING EXECUTE ERROR	1	The setting of the palletizing condition configuration file is incomplete.	Setting error	<ul><li>(1)Check the following settings.</li><li>Set the palletizing condition setting file to "Completed."</li></ul>
		4	Palletize completion universal output number range exceeds the limit.	Setting error	<ul> <li>(1)Check the following settings.</li> <li>Change the palletize completion universal output signal number of the palletizing condition setting file in the user output signal point of contact number.</li> </ul>

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy
Number		Code			
		5	During the palletize start instruction execution, the palletize start instruction is executed again (double execution).	Setting error	<ul><li>(1)Check the following settings.</li><li>Delete the palletize start instruction in the palletize section.</li></ul>
		6	The value of the palletizing number present value output register (or I variable) is more than the total number output register (or I variable).	Setting error	<ul> <li>(1)Check the following settings.</li> <li>Check if the palletizing number of current position output register (or I variable) and total number of output register (or I variable) is not changed by another function.</li> </ul>
		7	Palletize completion universal output signal is turned ON at palletize start instruction execution.	Setting error	<ul><li>(1)Check the following settings.</li><li>Reset the palletize completion universal output signal.</li></ul>
		8	Palletize end instruction is not registered.	Setting error	<ul><li>(1)Check the following settings.</li><li>Register the palletizing end instruction.</li></ul>
4652	TRQ MEASURE MODE SET ERR (SV)			Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
4653	TRQ MEASURE MODE CANCEL ERR (SV)			Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
4654	WRONG EXECUTION OF SETREG INST	1	An attempt was made to change the value of the register currently used by TMR/CNT.	Setting error	<ul> <li>(1)Check the following settings.</li> <li>The SETREGM instruction cannot change the register values used in TMR/ CNT. Correct the setting of tag that specifies register number of SETREG instruction.</li> </ul>
4655	WRONG EXECUTION OF GETREG INST	1	An attempt was made to acquire the value of the register not existing.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
4656	WRONG EXECUTION OF SETPRM INST	1	An attempt was made to change a parameter other than the cube- related parameter.	Setting error	<ul> <li>(1)Check the following settings.</li> <li>The SETPRM instruction cannot change the parameter values other than the parameter related to the cube. Correct the setting of tag that specifies parameter number of SETPRM instruction.</li> </ul>
		2	The SETPRM instruction was executed while another system was in execution.	Setting error	<ul> <li>(1)Check the following settings.</li> <li>The SETPRM instruction cannot execute while another system is operating. Correct the job.</li> </ul>
4670	INSUFFICIENT NUM OF SAMPLE DATA		subcode: Signifies the axis in which the alarm occurred	Setting error	Lengthen the measurement section.

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy
Number		Code			
4671	SAMPLE BUFFER OVER FLOW		subcode: Signifies the axis in which the alarm occurred	Setting error	Shorten the measurement section.
4672	BASIC SPEED UNREACHED		subcode: Signifies the axis in which the alarm occurred	Setting error	Increase the speed specification value of a measurement job or set a small value for BASICV. Or set a small value for BASICT, or lengthen the measurement section.
4673	MAX TRQ UNDETECTED		subcode: Signifies the axis in which the alarm occurred	Setting error	Set a large value for the BASICT, and then check again.
4676	BROKEN FAN FUSE		subcode: Signifies the LIO-08RT1 board No. in which the alarm occurred	Connection failure	<ul><li>(1)Reset the alarm.</li><li>(2)If the alarm occurs again, check if there is a ground fault or short circuit in the fan power line.</li></ul>
				Fuse failure	(After cancellation of the short-circuit and ground fault) Replace the fuse.
4677	IMPOSSIBLE LINEAR MOTION		subcode: Control group and axis	Setting error	<ul> <li>(1)Check the following settings.</li> <li>If the subcode display is L- and U-axes, perform the teaching again to make the form (arm folded direction) of L- and U-axes same at start point and end point.</li> <li>If the subcode display is S- and L-axes, perform the teaching again to make the form (arm folded direction) of S- and L-axes same at start point and end point.</li> <li>Change the teaching move instruction to MOVJ instruction.</li> <li>* Be careful to the peripheral interference since its movement changes.</li> </ul>
4681	OVER SPEED (MainCPU)		subcode: Control group and axis	Setting error	<ul> <li>(1)Check the following settings.</li> <li>Reduce the speed of the step where the alarm occurred.</li> <li>Change the move instruction to joint interpolation (MOVJ).</li> <li>* Be careful to the peripheral interference since its movement changes.</li> </ul>
4682	MOTION RANGE LIMIT INTERFERENCE		subcode: Manipulator number	Setting error	<ul> <li>(1)Check the following settings.</li> <li>Modify the teaching position or widen the operation area so that the robot would not interfere with the operation area.</li> <li>Confirm the setting of the robot operation area which is indicated by the subcode.</li> <li>Confirm the setting of the robot tool mode (tool interference file) a which is indicated by the subcode.</li> </ul>
4683	AXIS MOTION RANGE LIMIT OVER (MIN./MAX.)		subcode: Control group and axis	Setting error	<ul> <li>(1)Check the following settings.</li> <li>Modify the teaching position or widen the operation area so that the robot would not interfere with the operation area.</li> <li>Confirm the setting of the operation area which the control group is indicated by the subcode.</li> </ul>
4684	INTERPOLATION INVALID		subcode: Control group	Setting error	<ul> <li>(1)Check the following settings.</li> <li>At the cartesian jog operation, switch to each-axes jog operations, and then change the orientation of manipulator.</li> <li>Change the teaching position and orientation.</li> </ul>

9. Alarm 9.4 Alarm Message List

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy
Number		Code			
4696	TURN TABLE CALIBRATION ERROR	1	There was the same point in three points where the calibration had been executed.	Setting error	<ul><li>(1)Check the following settings.</li><li>Correct the calibration position so that each point is different.</li></ul>
		2	The three points where the calibration had been executed lie in a straight line.	Setting error	<ul> <li>(1)Check the following settings.</li> <li>Check the calibration position so that the three taught points are not aligned in a straight line.</li> </ul>
		3	The three points where the calibration had been executed lie in a straight line.	Setting error	<ul> <li>(1)Check the following settings.</li> <li>Check the calibration position so that the three taught points are not aligned in a straight line.</li> </ul>
4697	OFFLINE ARM BEND POS CONVERT ERR	1	Incorrect information of standard position data for offline arm bend position data conversion	Software operation error occurred	(1)Reset the alarm, and then try again. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).
		3	Incorrect reference-point data offline arm bend position data conversion	Software operation error occurred	(1)Reset the alarm, and then try again. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).
		4	The position data could not be converted correctly/conversely for the standard position data at the offline arm bend position data conversion.	Setting error	(1)Check the following settings. • The variable position may be out of the robot motion range. Check if the variable position is within the robot motion range.
		5	Incorrect pulse incremental value for offline arm bend position data conversion	Setting error	<ul> <li>(1)Check the following settings.</li> <li>The variable position may be out of the robot motion range. Check if the variable position is within the robot motion range.</li> </ul>
		6	The position data could not be converted correctly for the pulse incremental value at the offline arm bend position data conversion.	Setting error	<ul> <li>(1)Check the following settings.</li> <li>The variable position may be out of the robot motion range. Check if the variable position is within the robot motion range.</li> </ul>
		7	Incorrect Cartesian incremental value for offline arm bend position data conversion	Setting error	<ul> <li>(1)Check the following settings.</li> <li>The variable position may be out of the robot motion range. Check if the variable position is within the robot motion range.</li> </ul>
		8	The position data could not be converted correctly for the Cartesian incremental value at the offline arm bend position data conversion.	Setting error	<ul> <li>(1)Check the following settings.</li> <li>The variable position may be out of the robot motion range. Check if the variable position is within the robot motion range.</li> </ul>
		9	The position conversion could not be done in the conversion data for offline arm bend position data conversion.	Setting error	<ul> <li>(1)Check the following settings.</li> <li>The variable position may be out of the robot motion range. Check if the variable position is within the robot motion range.</li> </ul>

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy
Number		Code			
		10	Incorrect incremental value of angle for offline arm bend position data conversion	Setting error	<ul> <li>(1)Check the following settings.</li> <li>The variable position may be out of the robot motion range. Check if the variable position is within the robot motion range.</li> </ul>
		11	The position data could not be converted correctly for the incremental value of angle at the offline arm bend position data conversion.	Setting error	<ul> <li>(1)Check the following settings.</li> <li>The variable position may be out of the robot motion range. Check if the variable position is within the robot motion range.</li> </ul>
		14	The reverse shift value creation at the offline position data conversion failure	Setting error	<ul> <li>(1)Check the following settings.</li> <li>The variable position may be out of the robot motion range. Check if the variable position is within the robot motion range.</li> </ul>
		15	The reverse shift value adding failure at the offline position data conversion	Setting error	<ul> <li>(1)Check the following settings.</li> <li>The variable position may be out of the robot motion range. Check if the variable position is within the robot motion range.</li> </ul>
		17	The shift value adding failure at the offline position data conversion	Setting error	<ul> <li>(1)Check the following settings.</li> <li>The variable position may be out of the robot motion range. Check if the variable position is within the robot motion range.</li> </ul>
		19	Mirror shift correctly/conversely conversion for the offline position data conversion error	Setting error	<ul> <li>(1)Check the following settings.</li> <li>The variable position may be out of the robot motion range. Check if the variable position is within the robot motion range.</li> </ul>
		20	Mirror shift position conversion for the offline position data conversion error	Setting error	<ul> <li>(1)Check the following settings.</li> <li>The variable position may be out of the robot motion range. Check if the variable position is within the robot motion range.</li> </ul>
		22	Coordinate specification error in the new mirror shift conversion for the offline position data conversion	Setting error	<ul> <li>(1)Check the following settings.</li> <li>The variable position may be out of the robot motion range. Check if the variable position is within the robot motion range.</li> </ul>
4698	SHIFT VALUE MAKING ERROR	1	Reference position and target position occupation control-group error	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		2	Reference position and target position enabling control-group error	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		3	The position data type is not applicable.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy	
Number		Code				
		4	Coordinated control-group error	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		5	User coordinates number on the specified tag side error	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
4715	CIP MESSAGE SERVER FUNC ERROR	1	Failed in the generation of the CIP server task.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	9. 9.4
		2	Failed in the ID take of the CIP server task.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	Alarm Alarm
		3	Failed in the generation of the class entry table.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	Message
		4	Library initialize error.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	List
		5	Failed in the generation of the access process.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		10	Detect undefined error.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		20	Detect sever function started processing.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		30	Detect request error.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy
Number		Code			
		31	Detect memory error.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		32	Detect mail send error.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		33	Detect CIP answer error.	Software operation error occurred	(1)Reset the alarm, and then try again. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).
		40	Detect CIP server task mail receive error.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		41	Detect CIP server task request data error.	Software operation error occurred	(1)Reset the alarm, and then try again. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).
		50	Detect CIP server task send error.	Software operation error occurred	(1)Reset the alarm, and then try again. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).
4716	BINARY ETHERNET SERVER FUNC ERR	1	Detect message library initialize error.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		2	Failed in the generation of the RC connect management task.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		3	Failed in the generation of the RC server task.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		4	Failed in the generation of the file server task.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy
Number		Code			
		1040	Failed in the request take of the RC connect management task.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		1041	Failed in the conversion-endian.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		1042	Received data area overflow.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		1043	Failed in the request error.	Software operation error occurred	(1)Reset the alarm, and then try again. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).
		1044	Failed in the request error.	Software operation error occurred	(1)Reset the alarm, and then try again. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).
		1059	In a RC connect management task, undefined error detected.	Software operation error occurred	(1)Reset the alarm, and then try again. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).
		1060	Failed in the ID take of the RC server task.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		1061	Failed in the mail take of the RC server task.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		1062	In a RC server task, request mail data error detected.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		1063	Answer data area overflow.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy
Number		Code			
		1064	In a RC server task, receive data area overflow.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		1079	In a RC server task, undefined error detected.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		1080	In a file server task, mail receive error detected.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		1081	In a file server task, request mail data error detected.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		1082	In a file server task, request error occurred.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		1083	Failed in the conversion-endian.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		1084	In a file server task, receive data area overflow.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		2045	In a RC connect management task, send error detected.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		2046	Failed in the conversion-endian.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		2065	Detect RC server task send error.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy	
Number		Code				
		2066	Failed in the conversion-endian.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		2085	Detect file server task send error.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		2086	Failed in the conversion-endian.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	9. 9.4
		2087	In a file server task, answer data error detected.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	Alarm Alarm
		2088	Failed in the conversion-endian.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	Message
		2089	In a file server task, answer data area overflow.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	e List
		2098	Failed in the status error occurred.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		2099	In a file server task, undefined error detected.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		3090	In a file sever task, file close error.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy
Number		Code			
4718	I/O MODULE 24V POWER ERROR		subcode: I/O Board slot(BIT) For example slot3 case: (0000_0100), slot4 case:(0000_1000). If multiple I/O boards detecting the error, multiple bits are set. (Standard shipping of FS100L, An I/O board is in slot3.)	Fuse failure	<ul> <li>I/O board (LIO08R/09R) detected 24V power failure. Check the following items.</li> <li>(1) Check the fuse in the robot controller of FS100L(F13, F14), and replace it if it was cut.</li> <li>(2) Check the CN3 connector and the cable of the I/O board.</li> <li>(3) If the alarm occurs again, replace controller. Save the CMOS.BIN before replace controller to be safe.</li> </ul>
				Ground fault or a short circuit	<ul> <li>(1)Reset the alarm.</li> <li>(2)If the alarm occurs again, check whether neither the short circuit nor the ground fault have occurred in the I/O cables from the external device or the brake connection.</li> </ul>
4719	BINARY ETHERNET CLIENT FUNC ERR	1	Detect message library initialize error.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		2	Failed in the generation of the file function task.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		3	Failed in the generation of the RC function task.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		4	Detect I/F data error.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		10	Detect undefined error.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		110	In a file task, undefined error detected.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		510	In a RC task, undefined error detected.	Software operation error occurred	(1)Reset the alarm, and then try again. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy	
Number		Code				
		511	In a RC task, request command error detected.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		512	In RC task, there is not the class entry of the request command.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		513	In RC task, there is not the service entry of the request command.	Software operation error occurred	(1)Reset the alarm, and then try again. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).	, o o
		1130	In a high speed ethernet task, request mail error detected.	Software operation error occurred	(1)Reset the alarm, and then try again. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).	Alarm
		1131	In a high speed ethernet task, request command error detected.	Software operation error occurred	(1)Reset the alarm, and then try again. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).	
		1132	In a file task, mail receive error occurred.	Software operation error occurred	(1)Reset the alarm, and then try again. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).	-
		2140	In a file task, file reading error occurred.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		2141	In a file task, file writing error occurred.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		3150	In a file task, request send error occurred.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		3151	Failed in the conversion-endian.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy
Number		Code			
		3160	In a file task, reply packet clear error occurred.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		3161	Failed in the take of the reply packet data error.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		3162	Failed in the conversion-endian.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		3163	In a file task, time out occurred.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		3164	In a file task, receive data area overflow occurred.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		3165	In a file task, received data unmatched.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		3166	In a file task, receive data size overflow occurred.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		3167	In a file task, received data size set to zero occurred.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		3168	In a file task, reply head error occurred.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		3169	In a file task, reply status error occurred.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>

9. Alarm
 9.4 Alarm Message List

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy	
Number		Code				
		5530	In a RC task, interface request error occurred.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		5531	In a RC task, interface answer error occurred.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		5532	In a RC task, interface data area overflow occurred.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	ہ ق
		5533	In a RC task, interface data writing error occurred.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	Alarm
		6540	In a RC task, time out occurred.	Software operation error occurred	(1)Reset the alarm, and then try again. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).	
		6541	Detect data error.	Software operation error occurred	(1)Reset the alarm, and then try again. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).	
		6542	Detect exclusive process error.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		6543	Detect time out.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		6544	Setting error	Setting error	<ul> <li>(1)Reset the alarm, and confirm whether the following parameter is set to zero.</li> <li>S2C541</li> <li>S2C542</li> </ul>	
			Detect data error.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy
Number		Code			
		6545	Detect exclusive process error.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		7550	In a RC task, request send error occurred.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		7551	Failed in the conversion-endian.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		7560	In a RC task, reply packet error detected.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		7561	In a RC task, reply take error detected.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		7562	Failed in the conversion-endian.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		7563	Detect time out.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		7564	In a RC task, receive data area overflow detected.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		7565	In a RC task, received data unmatched.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		7566	In a RC task, receive data size over.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy
Number		Code			
		7567	In a RC task, receive data size zero detected.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		7568	In a RC task, reply head error error detected.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
		7569	In a RC task, reply status error detected.	Software operation error occurred	<ul> <li>(1)Reset the alarm, and then try again.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
4720	MotomanSync CLIENT DISCONNECTION	1	Connection to the client device has been cut off.	Connection failure	Check the connection and insertion of the cables and connectors on the client device.
		-1	Failed in connecting to the client device	Connection failure	Check the connection and insertion of the cables and connectors on the client device.
		-2	Incompatible Motoman Syncl/F	Data error	Use the compatible MotomanSyncl/F.
		-3	Failed in communication rate command.	Data error	Check the application and confirm the following contents: (1) Use correct function codes. (2) Confirm that the transmission data has no errors.
		-4	Controller failed in data transmission.	Software operation error occurred	Check the connection and insertion of the cables and connectors on the client device.
		-5	Client failed in data receiving.	Software operation error occurred	Check the connection and insertion of the cables and connectors on the client device.
		-6	Failed in connecting to client device. (MotomanSync-PLC)	Connection failure	<ul> <li>(1)Check the connection and insertion of the cables and connectors on the client device.</li> <li>(2)Check the client device and FS100L communication settings (instance number, I/O data size).</li> </ul>
4721	SYSTEM ERROR (MotomanSync)			Software operation error occurred	<ul> <li>(1)Reset the alarm and execute again.</li> <li>(2))If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
4722	MotomanSync OPERATION ERROR	100000	Undefined command ID has been set.	Setting error	Input correct data.
		100100	Failed in servo power control. Un defined servo power control command has been set.	Setting error	Input correct data.
		100101	Failed in servo power control. Tried to control servo power without resetting alarms and errors.	Software operation error occurred	Reset alarms and errors.

Alarm

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy	
Number		Code				
		100102	Failed in servo power control.	Software operation error occurred	Check following items; (1)Release emergency stop switch. (2)Reset servo power ON prohibited status. (3)Close the safety fence. (4)Reset the external servo OFF request. (5)Complete external device operations. (6)Complete the data transmission.	
		100200	Failed in writing files. Undefined file type has been set.	Setting error	Input correct data.	
		100201	Failed in writing files. The number of files is out of range.	Setting error	Input correct data.	9. 9.4
		100202	Failed in writing files. Incorrect control group number has been set.	Setting error	Input correct data.	Alar Alar
		100203	Failed in writing files. Undefined coordinate system has been set.	Setting error	Input correct data.	m m Mess
		100204	Failed in writing files. The user coordinate number is out of range.	Setting error	Input correct data.	sage Li
		100205	Failed in writing files. executing playback operation.	Setting error	End the playback operation.	st
		100206	Failed in writing files. Use memory is lacking.	Setting error	<ul> <li>(1)Reset the alarm.</li> <li>(2)when the error occurs again, if there is an unnecessary teaching position, delete it.</li> <li>(3)If the error occurs again after the previous measures were executed, initialize the job file in the maintenance mode, and then load the saved job file. In that case, delete the unused jobs.</li> <li>(4)If the error occurs again though the previous measures were executed, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
		100207	Failed in writing files.	Setting error	<ul><li>(1) Reset the alarm and execute again.</li><li>(2) End the playback operation.</li></ul>	
		100300	Failed in writing variables. Undefined variable type has been set.	Setting error	Input correct data.	
		100301	Failed in writing variables. The number of variables is out of range.	Setting error	Input correct data.	

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy	
Number		Code				
		100302	Failed in writing variables. Undefined coordinate system has been set.	Setting error	Input correct data.	
		100303	Failed in writing variables. The user coordinate number is out of range.	Setting error	Input correct data.	_
		100304	Failed in writing variables. The tool number is out of range.	Setting error	Input correct data.	
		100305	Failed in writing B/I/D/R variables.	Setting error	<ul><li>(1)Input correct data.</li><li>(2)Don't set the number exceeding maximum number.</li><li>(3)Don't use the same variables same as other functions.</li></ul>	
		100306	Failed in writing S variable.	Setting error	<ul><li>(1)Input correct data.</li><li>(2)Don't set the number exceeding maximum number.</li><li>(3)Don't use the same variables same as other functions.</li></ul>	- 4 Ala
		100307	Failed in writing P/BP/EX variables.	Setting error	<ul><li>(1)Input correct data.</li><li>(2)Don't set the number exceeding maximum number.</li><li>(3)Don't use the same variables same as other functions.</li></ul>	ırm Me
		110000	Undefined monitor command ID has been set.	Setting error	Input correct data.	ssag
		110100	Failed in reading files. Undefined file type has been set.	Setting error	Input correct data.	e List
		110101	Failed in reading files. The file number is out of range.	Setting error	Input correct data.	
		110102	Failed in reading files.	Setting error	<ul><li>(1)Reset the alarm, and then try again.</li><li>(2)End the playback operation.</li></ul>	_
		110200	Failed in reading variables. Undefined variable type has been set.	Setting error	Input correct data.	
		110201	Failed in reading B/I/D/R variables.	Setting error	<ul><li>(1)Input correct data.</li><li>(2)Don't set the number exceeding maximum number.</li><li>(3)Don't use the same variables same as other functions.</li></ul>	
		110202	Failed in reading S variable.	Setting error	<ul><li>(1)Input correct data.</li><li>(2)Don't set the number exceeding maximum number.</li><li>(3)Don't use the same variables same as other functions.</li></ul>	
		110203	Failed in reading P/BP/EX variables.	Setting error	<ul> <li>(1)Input correct data.</li> <li>(2)Don't set the number exceeding maximum number.</li> <li>(3)Don't use the same variables same as other functions.</li> </ul>	_
		300000	Failed in monitoring current value. (Control group1) Undefined coordinate system has been set.	Setting error	Input correct data.	

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy	
Number		Code				
		300001	Failed in monitoring current value. (Control group1) The user coordinate number is out of range.	Setting error	Input correct data.	
		300002	Failed in monitoring current value. (Control group1) Undefined user coordinate number has been set.	Setting error	Input correct data.	
		300003	Failed in monitoring current value. (Control group1) The control group number set in the tool coordinate specification is out of range.	Setting error	Input correct data.	9.9 4
		300004	Failed in monitoring current value. (Control group1) The coordinate system other than pulse or angle has been set for the external axis control group.	Setting error	Input correct data.	Alarm Mes
		300005	Failed in monitoring current value. (Control group1) The detail setting is out of range.	Setting error	Input correct data.	ssage L
		301000	Failed in monitoring current value. (Control group2) Undefined coordinate system has been set.	Setting error	Input correct data.	list
		301001	Failed in monitoring current value. (Control group2) The user coordinate number is out of range.	Setting error	Input correct data.	
		301002	Failed in monitoring current value. (Control group2) Undefined user coordinate number has been set.	Setting error	Input correct data.	
		301003	Failed in monitoring current value. (Control group2) The control group number set in the tool coordinate specification is out of range.	Setting error	Input correct data.	
		301004	Failed in monitoring current value. (Control group2) The coordinate system other than pulse or angle has been set for the external axis control group.	Setting error	Input correct data.	

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy	
Number		Code				
		301005	Failed in monitoring current value. (Control group2) The detail setting is out of range.	Setting error	Input correct data.	
		302000	Failed in monitoring current value. (Control group3) Undefined coordinate system has been set.	Setting error	Input correct data.	
		302001	Failed in monitoring current value. (Control group3) The user coordinate number is out of range.	Setting error	Input correct data.	ې ې
		302002	Failed in monitoring current value. (Control group3) Undefined user coordinate number has been set.	Setting error	Input correct data.	4 Alar
		302003	Failed in monitoring current value. (Control group3) The control group number set in the tool coordinate specification is out of range.	Setting error	Input correct data.	m Message
		302004	Failed in monitoring current value. (Control group3) The coordinate system other than pulse or angle has been set for the external axis control group.	Setting error	Input correct data.	List
		302005	Failed in monitoring current value. (Control group3) The detail setting is out of range. 。	Setting error	Input correct data.	
		303000	Failed in monitoring current value. (Control group4) Undefined coordinate system has been set.	Setting error	Input correct data.	
		303001	Failed in monitoring current value. (Control group4) The user coordinate number is out of range.	Setting error	Input correct data.	
		303002	Failed in monitoring current value. (Control group4) Undefined user coordinate number has been set.	Setting error	Input correct data.	

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy	
Number		Code				
		303003	Failed in monitoring current value. (Control group4) The control group number set in the tool coordinate specification is out of range.	Setting error	Input correct data.	
		303004	Failed in monitoring current value. (Control group4) The coordinate system other than pulse or angle has been set for the external axis control group.	Setting error	Input correct data.	
		303005	Failed in monitoring current value. (Control group4) The detail setting is out of range.	Setting error	Input correct data.	9. 9.4
		400000	Failed in setting MOVE command attribute. (Control group1)Failed in setting MOVE command attribute. (Control group1) The task number is out of range.	Setting error	Input correct data.	Alarm Alarm Mes
		400001	Failed in setting MOVE command attribute. (Control group1) The synchronization specification is out of range.	Setting error	Input correct data.	sage Lis
		400002	Failed in setting MOVE command attribute. (Control group1) The coordinate is out of range.	Setting error	Input correct data.	-
		400003	Failed in setting MOVE command attribute. (Control group1) The tool number is out of range.	Setting error	Input correct data.	
		400004	Failed in setting MOVE command attribute. (Control group1) The acceleration and deceleration rate is out of range.	Setting error	Input correct data.	
		400099	Failed in setting MOVE command attribute. (Control group1) Undefined MOVE command attribute.	Setting error	Input correct data.	
		400100	Failed in active command. (Control group1) The speed level setting is out of range.	Setting error	Input correct data.	
Alarm	Alarm Name	Sub	Meaning	Cause	Remedy	
--------	------------	--------	--	---------------	---------------------	----------------
Number		Code				
		400101	Failed in active command. (Control group1) Incorrect speed level has been set.	Setting error	Input correct data.	
		400102	Failed in active command. (Control group1) Incorrect coordinate system has been set.	Setting error	Input correct data.	
		400103	Failed in active command. (Control group1) The tool number is out of range.	Setting error	Input correct data.	م م
		400104	Failed in active command. (Control group1) The arbitrarily-set speed is out of range.	Setting error	Input correct data.	4 Alar Alar
		400105	Failed in active command. (Control group1) Incorrect destination has been set.	Setting error	Input correct data.	m m Mes:
		400106	Failed in active command. (Control group1) The mode is out of range.	Setting error	Input correct data.	sage
		400107	Failed in active command. (Control group1) Shared base axes setting is unmatch.	Setting error	Input correct data.	्र रा
		400108	Failed in active command. (Control group1) Incorrect all axis active command request has been set.	Setting error	Input correct data.	
		400200	Failed in setting MOVE command. (Control group1) Incorrect interpolation method has been set.	Setting error	Input correct data.	
		400201	Failed in setting MOVE command. (Control group1) Target Position of Robot axis and Traveling axis is undefined.	Setting error	Input correct data.	
		400202	Failed in setting MOVE command. (Control group1) The task number of Robot and Traveling axis are unmatch.	Setting error	Input correct data.	

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy	
Number		Code				
		400203	Failed in setting MOVE command. (Control group1) Incorrect interpolation method of slave robot has been set.	Setting error	Input correct data.	
		400204	Failed in setting MOVE command. (Control group1) Incorrect interpolation method of master robot has been set.	Setting error	Input correct data.	
		400205	Failed in setting MOVE command. (Control group1) Target Position of master robot is undefined.	Setting error	Input correct data.	9.4
		400206	Failed in setting MOVE command. (Control group1) The task number of Master Robot and Slave Robot are unmatch.	Setting error	Input correct data.	Alarm
		400207	Failed in setting MOVE command. (Control group1) The multiple Master/Slave Robot has been set.	Setting error	Input correct data.	Message
		400208	Failed in setting MOVE command. Undefined user coordinate number has been set.	Setting error	Input correct data.	List
		401000	Failed in setting MOVE command attribute. (Control group2) The task number is out of range.	Setting error	Input correct data.	
		401001	Failed in setting MOVE command attribute. (Control group2) The synchronization specification is out of range.	Setting error	Input correct data.	
		401002	Failed in setting MOVE command attribute. (Control group2) The coordinate is out of range.	Setting error	Input correct data.	
		401003	Failed in setting MOVE command attribute. (Control group2) The tool number is out of range.	Setting error	Input correct data.	
		401004	Failed in setting MOVE command attribute. (Control group2) The acceleration and deceleration rate is out of range.	Setting error	Input correct data.	

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy	
Number		Code				
		401099	Failed in setting MOVE command attribute. (Control group2) Undefined MOVE command attribute.	Setting error	Input correct data.	
		401100	Failed in active command. (Control group2) The speed level setting is out of range.	Setting error	Input correct data.	
		401101	Failed in active command. (Control group2) Incorrect speed level has been set.	Setting error	Input correct data.	9. 9.4
		401102	Failed in active command. (Control group2) Incorrect coordinate system has been set.	Setting error	Input correct data.	Alarm
		401103	Failed in active command. (Control group2) The tool number is out of range.	Setting error	Input correct data.	Messa
		401104	Failed in active command. (Control group2) The arbitrarily-set speed is out of range.	Setting error	Input correct data.	ge List
		401105	Failed in active command. (Control group2) Incorrect destination has been set.	Setting error	Input correct data.	
		401106	Failed in active command. (Control group2) The mode is out of range.	Setting error	Input correct data.	
		401107	Failed in active command. (Control group2) Shared base axes setting is unmatch.	Setting error	Input correct data.	
		401108	Failed in active command. (Control group2) Incorrect all axis active command request has been set.	Setting error	Input correct data.	
		401200	Failed in setting MOVE command. (Control group2) Incorrect interpolation method has been set.	Setting error	Input correct data.	

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy	
Number		Code				
		401201	Failed in setting MOVE command. (Control group2) Target Position of Robot axis and Traveling axis is undefined.	Setting error	Input correct data.	
		401202	Failed in setting MOVE command. (Control group2) The task number of Robot and Traveling axis are unmatch.	Setting error	Input correct data.	
		401203	Failed in setting MOVE command. (Control group2) Incorrect interpolation method of slave robot has been set.	Setting error	Input correct data.	9.4
		401204	Failed in setting MOVE command. (Control group2) Incorrect interpolation method of master robot has been set.	Setting error	Input correct data.	Alarm
		401205	Failed in setting MOVE command. (Control group2) Target Position of master robot is undefined.	Setting error	Input correct data.	Message
		401206	Failed in setting MOVE command. (Control group2) The task number of Master Robot and Slave Robot are unmatch.	Setting error	Input correct data.	List
		401207	Failed in setting MOVE command. (Control group2) The multiple Master/Slave Robot has been set.	Setting error	Input correct data.	
		402000	Failed in setting MOVE command attribute. (Control group3) The task number is out of range.	Setting error	Input correct data.	
		4020001	Failed in setting MOVE command attribute. (Control group3) The synchronization specification is out of range.	Setting error	Input correct data.	
		402002	Failed in setting MOVE command attribute. (Control group3) The coordinate is out of range.	Setting error	Input correct data.	
		402003	Failed in setting MOVE command attribute. (Control group3) The tool number is out of range.	Setting error	Input correct data.	

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy	
Number		Code				
		402004	Failed in setting MOVE command attribute. (Control group3) The acceleration and deceleration rate is out of range.	Setting error	Input correct data.	
		402099	Failed in setting MOVE command attribute. (Control group3) Undefined MOVE command attribute.	Setting error	Input correct data.	
		402100	Failed in active command. (Control group3) The speed level setting is out of range.	Setting error	Input correct data.	9. 9.
		402101	Failed in active command. (Control group3) Incorrect speed level has been set.	Setting error	Input correct data.	Alarm
		402102	Failed in active command. (Control group3) Incorrect coordinate system has been set.	Setting error	Input correct data.	Message
		402103	Failed in active command. (Control group3) The tool number is out of range.	Setting error	Input correct data.	
		402104	Failed in active command. (Control group3) The arbitrarily-set speed is out of range.	Setting error	Input correct data.	
		402105	Failed in active command. (Control group3) Incorrect destination has been set.	Setting error	Input correct data.	
		402106	Failed in active command. (Control group3) The mode is out of range.	Setting error	Input correct data.	
		402107	Failed in active command. (Control group3) Shared base axes setting is unmatch.	Setting error	Input correct data.	
		402108	Failed in active command. (Control group3) Incorrect all axis active command request has been set.	Setting error	Input correct data.	

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy	
Number		Code				
		402200	Failed in setting MOVE command. (Control group3) Incorrect interpolation method has been set.	Setting error	Input correct data.	
		402201	Failed in setting MOVE command. (Control group3) Target Position of Robot axis and Traveling axis is undefined.	Setting error	Input correct data.	
		402202	Failed in setting MOVE command. (Control group3) The task number of Robot and Traveling axis are unmatch.	Setting error	Input correct data.	9. 4.
		402203	Failed in setting MOVE command. (Control group3) Incorrect interpolation method of slave robot has been set.	Setting error	Input correct data.	Alarm
		402204	Failed in setting MOVE command. (Control group3) Incorrect interpolation method of master robot has been set.	Setting error	Input correct data.	Message
		402205	Failed in setting MOVE command. (Control group3) Target Position of master robot is undefined.	Setting error	Input correct data.	List
		402206	Failed in setting MOVE command. (Control group3) The task number of Master Robot and Slave Robot are unmatch.	Setting error	Input correct data.	
		402207	Failed in setting MOVE command. (Control group3) The multiple Master/Slave Robot has been set.	Setting error	Input correct data.	
		403000	Failed in setting MOVE command attribute. (Control group4) The task number is out of range.	Setting error	Input correct data.	
		403001	Failed in setting MOVE command attribute. (Control group4) The synchronization specification is out of range.	Setting error	Input correct data.	
		403002	Failed in setting MOVE command attribute. (Control group4) The coordinate is out of range.	Setting error	Input correct data.	

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy		
Number		Code					
		403003	Failed in setting MOVE command attribute. (Control group4) The tool number is out of range.	Setting error	Input correct data.		
		403004	Failed in setting MOVE command attribute. (Control group4) The acceleration and deceleration rate is out of range.	Setting error	Input correct data.		
		403099	Failed in setting MOVE command attribute. (Control group4) Undefined MOVE command attribute.	Setting error	Input correct data.		9
		403100	Failed in active command. (Control group4) The speed level setting is out of range.	Setting error	Input correct data.	4 Alar	Alar
		403101	Failed in active command. (Control group4) Incorrect speed level has been set.	Setting error	Input correct data.	m Messa	З
		403102	Failed in active command. (Control group4) Incorrect coordinate system has been set.	Setting error	Input correct data.	ge List	
		403103	Failed in active command. (Control group4) The tool number is out of range.	Setting error	Input correct data.		
		403104	Failed in active command. (Control group4) The arbitrarily-set speed is out of range.	Setting error	Input correct data.		
		403105	Failed in active command. (Control group4) Incorrect destination has been set.	Setting error	Input correct data.		
		403106	Failed in active command. (Control group4) The mode is out of range.	Setting error	Input correct data.		
		403107	Failed in active command. (Control group4) Shared base axes setting is unmatch.	Setting error	Input correct data.		

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy	
Number		Code				
		403108	Failed in active command. (Control group4) Incorrect all axis active command request has been set.	Setting error	Input correct data.	
		403200	Failed in setting MOVE command. (Control group4) Incorrect interpolation method has been set.	Setting error	Input correct data.	
		403201	Failed in setting MOVE command. (Control group4) Target Position of Robot axis and Traveling axis is undefined.	Setting error	Input correct data.	9. 9.4
		403202	Failed in setting MOVE command. (Control group4) The task number of Robot and Traveling axis are unmatch.	Setting error	Input correct data.	Alarm Alarm
		403203	Failed in setting MOVE command. (Control group4) Incorrect interpolation method of slave robot has been set.	Setting error	Input correct data.	Message
		403204	Failed in setting MOVE command. (Control group4) Incorrect interpolation method of master robot has been set.	Setting error	Input correct data.	List
		403205	Failed in setting MOVE command. (Control group4) Target Position of master robot is undefined.	Setting error	Input correct data.	
		403206	Failed in setting MOVE command. (Control group4) The task number of Master Robot and Slave Robot are unmatch.	Setting error	Input correct data.	
		403207	Failed in setting MOVE command. (Control group4) The multiple Master/Slave Robot has been set.	Setting error	Input correct data.	
4730	MOTION RANGE LIMIT OVER		subcode: Control group	Setting error	<ul> <li>(1)Check the following settings.</li> <li>Perform the teaching again to correct positions for manipulators so that the step where the alarm occurred is within the motion range.</li> </ul>	
4731	DEST MOTION RANGE LIMIT OVER		subcode: Control group	Setting error	<ul><li>(1)Check the following settings.</li><li>Check the position setting for the step (move instruction) where the alarm occurred.</li></ul>	

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy
Number		Code			
4732	ACCELERATION LIMIT OVER		subcode: Control group	Setting error	<ul> <li>(1)Adjust the CTP position to close the teaching position and the actual target position when this alarm occurred.</li> <li>(2)Adjust the OL to limit the operating range of the robot or add TRAP instruction to the JOB to operate without the alarm when this alarm occurred.</li> <li>(3) Set the teaching speed in slow in the step which causes occurring the alarm. Please pay attention to the robot interfering around the area because the trajectory of the robot might change.</li> </ul>
4800	WDT ERROR (CONVERTER)		subcode: Signifies the physical No. of converter in which the alarm occurred	Connection failure	<ul> <li>(1)Reset the alarm.</li> <li>(2)If the alarm occurs again, check the connection and inserting state of the following cables and connectors.</li> <li>EAXA01-CN507,510</li> <li>EAXB01-CN531,532,533</li> <li>Converter -CN551,553</li> <li>EX1SV(External axis servo pack) -CN591,592</li> </ul>
				Module failure (converter)	<ul><li>(1)Reset the alarm.</li><li>(2)If the alarm occurs again, replace the converter.</li></ul>
				Servo control circuit board failure	<ul><li>(1)Reset the alarm.</li><li>(2)If the alarm occurs again, replace the EAXA, EAXB board. Save the CMOS.BIN before replacing the board to be safe.</li></ul>
4830	PP E-STOP SIGNAL ERROR			Connection failure	<ul> <li>(1)Reset the alarm.</li> <li>(2)If the alarm occurs again, check the followings.</li> <li>Check the loose of the connector to the programming pendant and cables.</li> <li>Check the connection or insertion of the machine safety module CN2 connector.</li> <li>If other errors occur with this alarm, check a short circuit or ground fault has not occurred in 24V power line for safety signal.</li> </ul>
				programming pendant failure	<ul><li>(1)Reset the alarm.</li><li>(2)If the alarm occurs again, execute the following.</li><li>Replacement of the programming pedant</li></ul>
				Machine safety board failure	<ul><li>(1)Reset the alarm.</li><li>(2)If the alarm occurs again, execute the following.</li><li>Replacement of the machine safety board</li></ul>
4831	PANEL E-STOP SIGNAL ERROR			Machine safety board failure	<ul> <li>(1)Reset the alarm.</li> <li>(2)If the alarm occurs again, execute the following.</li> <li>Replacement of the machine safety board</li> </ul>
				Connection failure	<ul> <li>(1)Reset the alarm.</li> <li>(2)If the alarm occurs again, check the following s.</li> <li>Check the connection or insertion of the machine safety module CN1 connector.</li> <li>If other errors occur with this alarm, check a short circuit or ground fault has not occurred in 24V power line for safety signal.</li> </ul>

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy
Number		Code			
4832	EXT E-STOP SIGNAL ERROR			Connection failure	<ul> <li>(1)Reset the alarm.</li> <li>(2)If the alarm occurs again, check the following s.</li> <li>Replace the connecting cable</li> <li>Check the connection or insertion of the machine safety module CN3 connector.</li> <li>If other errors occur with this alarm, check a short circuit or ground fault has not occurred in 24V power line for safety signal.</li> </ul>
				Hardware failure	<ul> <li>(1)Reset the alarm.</li> <li>(2)If the alarm occurs again, execute the following operation.</li> <li>·Replacement of the external emergency stop button or the corresponding parts.</li> <li>(3)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
4833	ENABLE SW SIGNAL ERROR			Enable signal unmatched error	<ul> <li>(1)Reset the alarm.</li> <li>(2)Check the followings.</li> <li>There are two point of contact enable switch, and only one might be turned on by how to squeeze. Moreover, only one might be turned on when putting it on the place where it is not a plane on the knee etc. Check how to squeeze or put the programming pendant on flat.</li> </ul>
				Connection failure	(1)Reset the alarm.         (2) If the alarm occurs again, execute the following operation.         • Replace the programming pendant cable
				programming pendant failure	<ul><li>(1)Reset the alarm.</li><li>(2)If the alarm occurs again, execute the following operation.</li><li>·Replacement of programming pendant</li></ul>
				Machine safety board failure	<ul><li>(1)Reset the alarm.</li><li>(2)If the alarm occurs again, check the followings.</li><li>Replace the machine safety board</li></ul>
4834	SAFETY PLUG SIGNAL ERROR			Connection failure	<ul> <li>(1)Reset the alarm.</li> <li>(2)If the alarm occurs again, check the following s.</li> <li>Replace the connecting cable</li> <li>Check the connection or insertion of the machine safety module CN3 connector.</li> </ul>
				Hardware failure	<ul> <li>(1)Reset the alarm.</li> <li>(2)If the alarm occurs again, check the followings.</li> <li>Replace the machine safety module</li> <li>Replace the switches used to the safeguard or a corresponding parts</li> </ul>
				Hardware failure	<ul> <li>(1)Reset the alarm.</li> <li>(2)If the alarm occurs again after replacing the machine safety board, check the followings.</li> <li>Replace the switch used for protective stop signal or a corresponding parts.</li> </ul>

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy
Number		Code			
				Machine safety board failure	(1)Reset the alarm. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).
4835	SERVO ON ENABLE SIGNAL ERROR			Connection failure	<ul> <li>(1)Reset the alarm.</li> <li>(2)If the alarm occurs again, check the following s.</li> <li>Replace the connecting cable</li> <li>Check the connection or insertion of the machine safety module CN3 connector.</li> </ul>
				Machine safety board failure	(1)Reset the alarm.         (2)If the alarm occurs again, check the followings.         • Replace the machine safety board
				Hardware failure	<ul> <li>(1)Reset the alarm.</li> <li>(2)If the alarm occurs again after replacing the machine safety board, check the followings.</li> <li>Replace the SERVO ON ENABLE SIGNAL switch.</li> </ul>
4836	OVERRUN SIGNEAL ERROR (OT1)		subcode: Control group	Enable signal unmatched error	(1)Reset the alarm. (2)If the alarm occurs again, confirm the followings. ·Select "OVERRUN & S-SENSOR"from "ROBOT" menu to display OVERRUN & S-SENSOR window. The alarm can be released on this window.
				Connection failure	<ul> <li>(1)Reset the alarm.</li> <li>(2)If the alarm occurs again, check the following s.</li> <li>Replace the connecting cable</li> <li>Check the connection or insertion of the machine safety module CN5 connector.</li> </ul>
				Hardware failure	<ul> <li>(1)Reset the alarm.</li> <li>(2)If the alarm occurs again after replacing the machine safety board, check the followings.</li> <li>Replace the limit switch or a corresponding parts.</li> </ul>
				Machine safety board failure	(1)Reset the alarm. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).
4837	OVERRUN SIGNEAL ERROR (OT2)		subcode: Control group	Enable signal unmatched error	<ul> <li>(1)Reset the alarm.</li> <li>(2)If the alarm occurs again, confirm the followings.</li> <li>·Select "OVERRUN &amp; S-SENSOR"from "ROBOT" menu to display OVERRUN &amp; S-SENSOR window. The alarm can be released on this window.</li> </ul>

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy	
Number		Code				
				Connection failure	<ul> <li>(1)Reset the alarm.</li> <li>(2)If the alarm occurs again, check the following s.</li> <li>Replace the connecting cable</li> <li>Check the connection or insertion of the machine safety module CN5 connector.</li> </ul>	
				Hardware failure	<ul> <li>(1)Reset the alarm.</li> <li>(2)If the alarm occurs after the replacement of the machine safety module, execute the following operation.</li> <li>·Replacement of the limit switch or corresponding parts.</li> </ul>	
				Machine safety board failure	<ul> <li>(1)Reset the alarm.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	9.4
4838	OVERRUN DETECT		subcode: Control group	Overrun limit switch released	Select "OVERRUN & S-SENSOR" from "ROBOT" menu to display the     OVERRUN & S-SENSOR screen. The alarm can be released on this screen.	Alarn Alarn
				Connection failure	<ul> <li>(1)Reset the alarm.</li> <li>(2)If the alarm occurs again, check the following s .</li> <li>Replace the connecting cable</li> <li>Check the connection or insertion of the machine safety module CN5 connector.</li> </ul>	n Message I
				Machine safety board failure	<ul> <li>(1)Reset the alarm.</li> <li>(2)If the alarm occurs again, execute the following.</li> <li>Replacement of the machine safety board</li> </ul>	ist
				Hardware failure	<ul> <li>(1)Reset the alarm.</li> <li>(2)If the alarm occurs again after replacing the machine safety module, check the followings.</li> <li>Replace the limit switch or a corresponding parts.</li> </ul>	
4839	MODE SIGNAL CUT			Connection failure	<ul> <li>(1)Reset the alarm.</li> <li>(2)If the alarm occurs after above mentioned operation, execute the following operation.</li> <li>·Confirm the looseness of the connectors connecting the programming pendant and the cable.</li> <li>·Replace the programming pendant cable.</li> </ul>	
				programming pendant failure	<ul> <li>(1)Reset the alarm.</li> <li>(2)If the alarm occurs again, execute the following operation.</li> <li>·Replacement of the programming pendant</li> </ul>	
				MAKER LIO board failure	<ul> <li>(1)Reset the alarm.</li> <li>(2)If the error occurs again, save the CMOS.BIN in maintenance mode, replace the following board.</li> <li>MAKER LIO board</li> </ul>	

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy	
Number		Code				
4901	CUBE/AXIS INTERFERENCE		subcode; Group, axis, and interference area number	Setting error	<ul> <li>(1)Check the following settings.</li> <li>Perform the teaching again to correct positions for manipulators so that the step where the alarm occurred is out of interference area.</li> <li>Change the settings for interference area.</li> </ul>	
4902	CUBE INTERFERENCE (TCP)		subcode: Control group & Area number	Setting error	<ul> <li>(1)Check the following settings.</li> <li>Perform the teaching again to correct positions for manipulators so that the step where the alarm occurred is out of interference area.</li> <li>Change the settings for interference area.</li> </ul>	
4903	CUBE INTERFERENCE (ENTIRE)		subcode: Control group & Interference axis & Area number	Setting error	<ul> <li>(1)Check the following settings.</li> <li>Perform the teaching again to correct positions for manipulators so that the step where the alarm occurred is out of interference area.</li> <li>Change the settings for interference area.</li> </ul>	9. 9.4
4904	CUBE INTERFERENCE AREA SET ERR	0	Maximum number of the cube interference area exceeds the allowable range.	Setting error	<ul> <li>(1)Reset the alarm.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	Alarm Alarm N
		1	The number of cube interference area whose monitoring part is "whole" exceeds the limit.	Setting error	Reduce the number of cube interference area whose monitoring part is "whole".	Messag
		2	Detect the cube whose interference area are extremely big or small.	Setting error	<ul> <li>(1)Among the cube interference areas already values are entered, modify as follows.</li> <li>1.Change the extremely big values to smaller ones.</li> <li>2.Change the extremely small values to bigger ones.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	je List
		3	Detect the cube interference area whose monitoring part is set to "whole" despite the invalid status of cube arm interference check function.	Setting error	<ul> <li>(1)Reset the alarm.</li> <li>(2)If the alarm occurs just after loading the cube interference area setting function, execute the following measures.</li> <li>1.Among the cube interference areas to be loaded, change the monitoring part setting from "whole" to "control point".</li> <li>2.Load the modified cube interference area.</li> <li>3.Confirm the settings if the alarm occurs again after the loading operation.</li> <li>(3)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	
4940	MOTION COMMAND CODE ERROR (SV)			Software operation error occurred	<ul> <li>(1)Reset the alarm.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>	

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy
Number		Code			
4941	CANNOT EXECUTE MOTION CMD (SV)			Software operation error occurred	<ul> <li>(1)Reset the alarm.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
4942	AVERAGING TIME CHANGE ERR (SV)			Software operation error occurred	<ul> <li>(1)Reset the alarm.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
4943	AVERAGING TIME ERROR (SERVO)			Software operation error occurred	<ul> <li>(1)Reset the alarm.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
4944	POSITION LOOP GAIN ERROR (SV)			Software operation error occurred	<ul> <li>(1)Reset the alarm.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
4945	MOTION COMMAND DATA ERROR (SV)			Software operation error occurred	<ul> <li>(1)Reset the alarm.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
4946	PG POWER ON INCOMPLETE (SV)			Software operation error occurred	<ul> <li>(1)Reset the alarm.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
4947	SERVO ON MULTIPLE REQUEST (SV)			Software operation error occurred	<ul> <li>(1)Reset the alarm.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
4948	ENCODER ALARM (SERVO)			Software operation error occurred	<ul> <li>(1)Reset the alarm.</li> <li>(2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).</li> </ul>
4953	ENCODER COUNTER DIFF. ERR (SV)		subcode: Signifies the axis in which the alarm occurred	Software operation error occurred	<ul> <li>(1)Reset the alarm</li> <li>(2)If the alarm occurs again, check the connection and inserting state of the following cables and connectors.</li> <li>EAXA01-CN508</li> <li>EAXB01-CN534,535,536</li> </ul>
				Servo control circuit board failure	(1)Reset the alarm. (2)If the alarm occurs again, replace the EAXA, EAXB board. Save the CMOS.BIN before replacing the board to be safe.

9. Alarm
 9.4 Alarm Message List

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy	
Number		Code				
4955	AVERAGING DATA ERROR (SERVO)			Software operation error occurred	(1)Reset the alarm. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).	
4956	AVERAGING SUMERROR (SERVO)			Software operation error occurred	(1)Reset the alarm. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).	
4958	HIGH RESOLUTION PRM UNDEFINED (SV)			Software operation error occurred	(1)Reset the alarm. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).	9.4
4960	BELT SNAP DETECT PRM ERROR (SV)			Setting error	(1)Reset the alarm. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).	Alarm Alarm
4962	BRAKE LOCK ERROR (SERVO)		subcode: Signifies the axis in which the alarm occurred	Software operation error occurred	(1)Reset the alarm. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).	Message
4963	BRAKE RELEASE ERROR (SERVO)		subcode: Signifies the axis in which the alarm occurred	Software operation error occurred	(1)Reset the alarm. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).	List
4964	CONST.SPD MEASURE MULTI REQ (SV)		subcode: Signifies the axis in which the alarm occurred	Software operation error occurred	(1)Reset the alarm. (2)If the alarm occurs again, save the CMOS.BIN in maintenance mode, and then contact your Yaskawa representative about occurrence status (operating procedure).	
4965	DIN SIGNAL SPECIFIC. ERROR (SV)		subcode: Signifies the axis in which the alarm occurred	Setting error	Confirm the DIN signal settings.	
4966	DB REGIST NOT INSTALLED (SV)			Connection failure	<ul> <li>(1)Reset the alarm.</li> <li>(2)If the alarm occurs again, check the connection and inserting state of the following cables and connectors.</li> <li>DB resist of CN585 amplifier</li> <li>Short-circuit connector CN585 amplifier</li> <li>Amplifier-CN583</li> <li>Converter-CN556,CN558</li> </ul>	
				DB resist board failure	The DB resist may be fired. Replace the DB resist.	
				Module failure (SERVOPACK)	<ul><li>(1)Reset the alarm.</li><li>(2)If the alarm occurs again, replace the SERVOPACK.</li></ul>	
4969	CONVTR POWER ERR (FREQUENCY) (SV)		subcode: Signifies the axis in which the alarm occurred	Primary power supply failure	Confirm that appropriate primary voltage is applied to the breaker. Prescribed voltage: 200V (+10% to 15%)	

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy
Number		Code			
				Connection failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, check the connection and insertion of the following cables and connectors.</li> <li>EAXA01-CN507,510</li> <li>EAXB01-CN531,532,533</li> <li>Converter-CN551,553</li> <li>EX1SV(External axis servo pack)-CN591,592</li> </ul>
				Module failure (converter)	<ul><li>(1)Turn the power OFF then back ON.</li><li>(2)If the alarm occurs again, replace the SERVOPACK.</li></ul>
				Servo control circuit board failure	<ul> <li>(1)Reset the alarm.</li> <li>(In case of major alarm, turn the power OFF then back ON.)</li> <li>(2)If the alarm occurs again, replace the EAXA and EAXB boards. Save the CMOS.BIN before replacing the board to be safe.</li> </ul>
4970	CONVTR POWER ERR (PHASE SEQ.) (SV)		subcode: Signifies the axis in which the alarm occurred	Primary power supply failure	Confirm that appopriate primary voltage is applied to the breaker. Prescribed voltage: 200V (+10% to 15%)
				Connection failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, check the connection and insertion of the following cables and connectors.</li> <li>EAXA01-CN507,510</li> <li>EAXB01-CN531,532,533</li> <li>Converter-CN551,553</li> <li>EX1SV (External axis servo pack) -CN591,592</li> </ul>
				Module failure (converter)	<ul><li>(1)Turn the power OFF then back ON.</li><li>(2)If the alarm occurs again, replace the SERVOPACK.</li></ul>
				Servo control circuit board failure	<ul> <li>(1)Reset the alarm.</li> <li>(In case of major alarm, turn the power OFF then back ON.)</li> <li>(2)If the alarm occurs again, replace the EAXA and EAXB boards. Save the CMOS.BIN before replacing the board to be safe.</li> </ul>
4971	CONVTR POWER ERR (PEAK) (SV)		subcode: Signifies the axis in which the alarm occurred	Primary power supply failure	Confirm that appopriate primary voltage is applied to the breaker. Prescribed voltage: 200V (+10% to 15%)
				Connection failure	<ul> <li>(1)Turn the power OFF then back ON.</li> <li>(2)If the alarm occurs again, check the connection and insertion of the following cables and connectors.</li> <li>EAXA01-CN507,510</li> <li>EAXB01-CN531,532,533</li> <li>Converter-CN551,553</li> <li>EX1SV (External axis servo pack) -CN591,592</li> </ul>
				Module failure (converter)	<ul><li>(1)Turn the power OFF then back ON.</li><li>(2)If the alarm occurs again, replace the SERVOPACK.</li></ul>

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy
Number		Code			
				Servo control circuit board failure	<ul> <li>(1)Reset the alarm.(In case of major alarm, turn the power OFF then back ON.)</li> <li>(2)If the alarm occurs again, replace the EAXA and EAXB boards. Save the CMOS.BIN before replacing the board to be safe.</li> </ul>
4972	CONVTR REGENERATE OVERLOAD (SV)			Primary power supply failure	Correct the converter primary power supply.
				Setting error	Check the following settings.    The tool information   JOB   Work  The speed of JOB  The acceleration/deceleration speed of ACC and DEC
				Connection failure	(1)Reset the alarm         (2)If the alarm occurs again, check the connection and inserting state of the following cables and connectors.         • EAXA01-CN507,510         • EAXB01-CN531,532,533         • converter-CN551,553         • EX1SV (External axis servo pack) -CN591,592
				Module failure (Regenerative resistor)	(1)Disconnect the converter CN104 to check if it is disconnected.(2)If it is disconnected, replace the generative resistor.
				Module failure (converter)	(1)Reset the alarm (2)If the alarm occurs again, replace the converter.
				Servo control circuit board failure	<ul><li>(1)Reset the alarm.</li><li>(2)If the alarm occurs again, replace the EAXA board. Save the CMOS.BIN before replace the board to be safe.</li></ul>
4973	POSITION ERROR (COLLISION DETECT)			Setting error	Confirm the settings of the followings. •The tool information •Workpiece
4980	DESTINATION PULSE LIMIT			Setting error	<ul> <li>(1)Check the following settings.</li> <li>Check the position setting for the step (move instruction) where the alarm occurred.</li> </ul>
4981	DEST PULSE MECHANICAL LIMIT			Setting error	<ul><li>(1)Check the following settings.</li><li>Check the position setting for the step (move instruction) where the alarm occurred.</li></ul>

Alarm	Alarm Name	Sub	Meaning	Cause	Remedy
Number		Code			
4982	DEST MECHANICAL INTRF			Setting error	<ul><li>(1)Check the following settings.</li><li>Check the position setting for the step (move instruction) where the alarm occurred.</li></ul>
4983	DEST MECHANICAL INTRF			Setting error	<ul> <li>(1)Check the following settings.</li> <li>Check the position setting for the step (move instruction) where the alarm occurred.</li> </ul>
4984	DESTINATION SELF- INTERFERENCE			Setting error	<ul><li>(1)Check the following settings.</li><li>Check the position setting for the step (move instruction) where the alarm occurred.</li></ul>

- 10 Error
- 10.1 Error Message

## 10.1 Error Message

Error warns the operator not to advance to the next operation caused by a wrong operation or the access method when using the programming pendant or an external equipment (computer, PLC, etc.).

When an error occurs, confirm the content of the error then release the error.

To release the error, perform either of the following operations:

- Press [CANCEL] on programming pendant.
- Input alarm/error reset signal (system input).



When two or more errors occur, appears in the message display area. Activate the message display area and press [SELECT] to view the list of current errors.

## 10.1 Error Message

## 10.1.1 System and General Operation

Error No.	Data	Error Message	Contents
10			
10	-	corrective action	is ON.
20	-	Depress TEACH	Out of specified operation mode
30	-	Illegal setting for number of variables	Parameter setting error
31	-	Illegal setting for number of variable- names	
32	-	Illegal setting for number of SUB task.	
40	-	Undefined robot position variables	Position variable cannot be used.
50	-	Depress MODIFY	
60	-	Undefined points (ORG, XX, XY)	Not registered user coordinates basic 3 points (ORG, XX, XY)
70	-	Program and current tool different	The tool number registered with teaching position data does not match the tool number selected at the programing pendant.
80	-	Same position in the 3 points	
90	-	Set robot exactly to taught position	
100	-	On overrun recovery status	
110	-	Turn ON servo power	
120	-	Set to PLAY mode	
130	-	No start using external signal	
140	-	No start using P.P.	
150	-	TEACH-LOCK mode ON	
160	-	ENABLE LED ON	
170	-	Servo OFF signal ON	
180	-	TEACH mode select signal ON	
190	-	Set variable number	
200	-	Defined group axis	
210	-	Undefined coordinated robots	
211	-	Cannot register between stations	
212	-	Cannot register at this combination	
220	-	Taught by other robot	
230	-	While releasing soft limit	
240	-	Undefined robot	
250	-	Defined condition No.	
260	-	Undefined file	
280	-	Lack of number of I/O points	
290	-	Cannot set same No.	
300	-	Undefined user frame	
310	-	Cannot register Master JOB	
320	-	Cannot operate CHECK-RUN	
330	-	Cannot operate MACHINE LOCK	
340	-	Cannot operate Master JOB	

10.1 Error Message

Error No.	Data	Error Message	Contents
350	-	Cannot initialize	
360	-	Teach point not specified	
370	-	No SYNCRO operation	
380	-	Position not checked	Second home position was not checked
383	-	Select joint coordinate system and	
		perform forward operation	
390	-	Can specify servo OFF by safety relay	
400	-	Wrong specification of measure interval	
410	-	Time could not be measured	Time could not be measured for TRT function.
420	-	Incorrect number of taught points	The number of the taught points for tool calibration is incorrect.
430	-	Register start reserved JOB	
440	-	Clear data to teach at the tool because other tool is set	
450	-	Wrong JOB for measuring	
460	-	Excess time for measuring	
470	-	Calibrated at another file	
480	-	Calibrated at another robot combination	
490	-	Cannot calibrate at this combination	
500	-	Undefined robot calibration data	
510	-	Undefined axis	
520	-	Cannot select two coordinated combination	
530	-	Start reservation mode	
540	-	Not start reservation mode	
550	-	Start reserved JOB change prohibit is set	
560	-	Cannot teach position while soft limit released	
590	-	Register group axis combination	[SYNCHRO] was pressed for coordinated job which was not registered as group.
600	-	Out of setting data range	
610	-	Cannot use the user coordinate	
620	-	Select JOB (robot)	
630	-	Not completed to load original tool file	
640	-	Not specified Tool File	
650	-	Incorrect measured data	
660	-	Wrong data type of position variable	
670	-	Enter path number	
680	-	Defined data	
	XXX		File no.
690	-	Illegal path number	
700	-	Wrong CMOS memory board type	
710	-	Canceled pelletizing shift value	
720	-	Defined name	

Error No.	Data	Error Message	Contents
721	-	It is already registered for IN/OUT signal name.	
722	-	It is already registered for Variable name.	
723	-	It is already registered for Local variable name.	
724	-	The existing names cannot be overwritten	
730	-	Undefined Name Position file	
750	-	This name cannot be defined	
760	-	Error in start condition set	
770	-	During robot or station operation	
790	-	FWD/BWD don't work in the handle operation	
810	-	Servo power supply is limited	
820	-	Modification range over	
830	-	Cannot move while modifying speed	
840	-	Unregistered key	
850	-	Cannot register instruction	
860	-	Please release key registration mode	
870	-	This key cannot be allocated	
880	-	Same relay cannot be set	
890	-	This key has already been registered. Cannot register them once	
900	-	Relay No. not set	
910	-	Cannot be registered because job control group not same	
920	-	Cannot modify this setting	
930	-	Undefined conveyor calibration data	
960	-	I/O axis mode requesting	
971	-	ERRCPU signal error	

- 10 Error
- 10.1 Error Message

# 10.1.2 Editing

Error No.	Data	Error Message	Contents
1010	-	EDIT LOCK mode	
1020	-	Enter correct value	
1030	-	Unauthorized ID No.	
1050	-	Enter correct date	
1060	-	Enter correct clock	
1070	-	Enter an ID number in 4-8 figures	
1080	-	Negative value can't be set	
1090	-	Enter correct value (START-END signal no)	

## 10.1 Error Message

### 10.1.3 Job Defined Data

Error No.	Data	Error Message	Contents
2010	-	Incorrect character	
2020	-	Name not entered	
2030	-	Undefined JOB name	
2040	-	Defined JOB name	
2050	-	Address not found	
2060	-	Select master	
2070	-	Set robot exactly to taught position	
2080	-	Press INSERT or MODIFY	
2090	-	Only modifying move instruction possible	
2100	-	JOB cannot be edited.	
2110	-	Over soft limit	
2111	-	Over soft limit. Adjust center position or pulse width.	
2111	-	Cannot insert/alter/delete with servo OFF	
2130	-	Only modifying move instruction possible	
2140	-	Must press ENABLE to modify	
2150	-	Inserting is not possible from this point	
2160	-	Cannot modify or delete this position	
2170	-	Press INSERT to record same step as previous step	
2180	-	Cannot insert data	
2190	-	Cannot delete data	
2200	-	Cannot modify data	
2210	-	Illegal data setting	
2220	-	Display edit instruction	
2230	-	Illegal instruction equation	
2240	-	Excessive instruction equation	
2250	-	Unmatched number of parentheses in equation	
2260	-	Wrong group axis selection	
2270	-	Cannot insert any more instruction in JOB	
2280	*	JOB memory is full	
	1		Lack of position file memories
	2		Lack of JOB registering memories
	3		Lack of instruction file memories
	4		Lack of memory pool
	5		Lack of pass condition file for multi layer
2290	-	Undefined master JOB	

10.1 Error Message

Error No.	Data	Error Message	Contents
2291	*	Undefined SUB Master JOB	
	1		Sub-master 1
	2		Sub-master 2
	3		Sub-master 3
	4		Sub-master 4
	5		Sub-master 5
2292	-	Undefined MASTER START JOB	
2293	*	Undefined SUB START JOB	
	1		Sub-master 1
	2		Sub-master 2
	3		Sub-master 3
	4		Sub-master 4
	5		Sub-master 5
2300	-	Cannot teach JOB without group-axis specification	
2310	*	Same label exists	
	XXX		Line no.
2320	-	Cannot create coordinated JOB	
2330	-	Cannot edit coordinated instruction	
2350	-	Pasted data not found	
2340	-	Editing data not found	
2360	-	Cannot create editing area	
2370	-	Cannot cut/copy NOP and END instructions	
2380	-	Wrong JOB selection	
2390	-	Wrong group axis selection	
2400	-	Cannot move in cut & paste editing	
2410	-	When variable is used for speed setting, perform a line-edit	
2420	-	When variable is used for teach setting, perform a line-edit	
2430	-	Reverse data not found	
2450	-	Relative JOB not permitted	
2460	-	Specified JOB is already converted	
2470	-	Wrong JOB type	
2480	-	Wrong JOB coordinates setting	
2490	-	Execute FWD/BWD operation once	
2500	-	Cannot convert the JOB	
2501	-	Cannot convert positions as macro arguments	
2510	-	Cannot correct position in the JOB	
2520	-	Enter JOB name	
2530	-	Illegal step number	
2540	-	Enter step number	
2550	-	Duplicated step number	

Error No.	Data	Error Message	Contents
2551	-	Duplicated line number	
2560	-	Cannot correct steps of position variables and REFP	
2570	-	The step does not contain speed	
2580	-	The step dose not contain PL/CONT	
2590	-	Soft limit range over	
2600	-	Cannot teach position in concurrent JOB	
2610	-	Wrong JOB kind	
2620	-	Cannot correct play speed in the JOB	
2630	-	Conveyor position not reset	
2640	-	Incorrect JOB name	
2650	-	Defined JOB name	
2660	-	Register MOVL after circular block	
2670	-	Undefined target JOB	
2690	-	Defined same kind JOB	
2710	-	Relative job can't be shifted with pulse type	
2720	-	Cannot correct position variables	
2730	-	Cannot use robot macro JOB	
2740	-	Cannot use concurrent macro JOB	
2750	-	Cannot use JOB with group-axis specification	
2760	-	Cannot insert/modify/delete for group axis detachment	
2761	-	Cannot insert/modify/delete for axis detachment	
2780	-	Arithmetic error	
2790	-	Step exceeding operation range.	

10.1 Error Message

# 10.1.4 External Memory Equipment

Error No.	Data	Error Message	Contents
3021	-	CompactFlash not inserted into CompactFlash slot(PP)	
3022	-	USB media not inserted	
3040	-	File not saved on the media	
3050	-	File saved on the media	
3060	-	Out of memory on the media	
3070	-	Number of files on the media	
3080	-	I/O error on the media	
3090	-*	Transmission error with the media	
	1		Framing error
	2		Overrun error
	3		Parity error
	4		Data code error
	5		Data read error
	6		Data write error
	7		Data time out
	8		Serial I/O error
	9		Error other than described above
3100	-	Total checksum error	
3110	-	Syntax error	
3120	*	HEX code error	
	1		Specification error of data decode
	2		Specification error of EOF record
	3		Record type error
	4		Total check error of record
3130	-	Verify error	
3140	-	Wrong pseudo instruction	
3150	*	Concurrent I/O record error	
	1		Format error
	2		Ladder program is too long
	3		Exceed the range of the data
	4		Specification error of channel No.
	5		Specification error of relay No.
	6		Timer value error
3150	7		Specification error of timer No
3160	-	Cannot load illegal system data	
3170	*	Condition file data error	
	1		Format error
	2		Specified file No. is omitted
	3		Specified tool No. is omitted
	4		User file is not registered.
3180	-	Concurrent I/O data transmission error	

Error No.	Data	Error Message	Contents
3190	*	Error in JOB data record	
	1		Record on the number of position data (NPOS) is wrong for the format.
	2		Record on the user coordinate No. (USER) is wrong for the format.
	3		Record on the tool No. (TOOL) is wrong for the format.
	4		Record on the position data section is wrong for the format.
	5		Record on the robot type of XYZ data (RCONF) is wrong for the format.
	6		Date (DATE) record is wrong for the format.
	7		Comment (COMM) record is wrong for the format.
	8		Record on the JOB attribute data (ATTR) is wrong for the format.
	9		Control group (GROUP) record is wrong for the format.
	10		Local variable (LVARS) record is wrong for the format.
	11		JOB argument (JARGS) record is wrong for the format.
	12		Record on the teaching coordinates for relative job (FRAME) is wrong for the format.
	13		Position data coordinates do not match relative job coordinates.
3200	-	NOP or END instruction not found	
3210	-	Position No. storage area not found	
3220	*	Syntax error in instruction data	
	2		Interior control error
	3		Undefined instruction/tag
	4		Instruction/tag shortage
	5		Disuse instruction/tag
	6		Sub instruction

- 10 Error
- 10.1 Error Message

Error No.	Data	Error Message	Contents
3220	7		No instruction
	8		Invalid instruction
	9		Invalid tag
	10		Invalid character
	11		Undefined intermediate code
	12		Intermediate code shortage
	13		Syntax stack overflow
	14		Syntax stack underflow
	15		Array type tag uncompleted Tag [ARRAY]
	16		Element type tag uncompleted Tag [ELEMENT]
	17		Macro JOB unregistered
	18		Input format error
	19		Data size over
	20		MIN value over
	21		MAX value over
	22		Operation expression error
	23		Job call argument setting error
	24		Macro job call argument setting error
	25		Position vector setting error
	26		System error
	27		Soft key designate error
	28		Numerical input buffer overflow
	29		Real type data precision error
	30		Element format error
	35		BOOL TYPE data error
	36		CHAR data error
	37		BYTETYPE, BINARY / HEXADECIMAL BYTE TYPE data error
	38		INTEGER TYPE, DECIMAL WORD TYPE data error
	39		BINARY/HEXADECIMAL WORD TYPE data error
	40		DOUBLE PRECISION INTEGER TYPE, DECIMAL DWORD TYPE data error
	41		BINARY/HEXADECIMAL WORD TYPE data error
	42		REAL TYPE data error
	43		LADDER SPECIAL TYPE data error
	44		JCL text
	45		Invalid text
	46		LABEL NAME data error
	47		JOB NAME data error
	48		STRING data error
	49		COMMENT data error
	58		Invalid instruction/tag detection
3230	-	Syntax not matched	

Error No.	Data	Error Message	Contents
3240	-	Undefined application	
3250	-	Cannot load this file	
3260	-	Excess input data	
3270	-	Cannot verify this file	
3290	-	Serial port not defined	
3300	-	Serial port being used	
3310	-	Protocol being used	
3350	-	Not enough memory	
3360	-	Invalid folder	
3370	-	Incorrect folder name	
3380	-	Drive not ready	
3390	-	File not found	
3400	-	File already exists on the media	
3410	-	Out of memory on the media	
3420	-	Max number of files has been reached	
3430	-	I/O error on the drive	
3440	-	Wrong media type	
3450	-	Cannot load macro JOB at current security mode	Load in management mode.
3460	*	Cannot backup the media	
	1		Insufficient Compact Flash memory.
	2		Not accessible to Compact Flash.
3470	-	Database not found	
3480	-	Database access error	
3490	-	Same database exists	
3500	-	Check the media insertion	
3501	-	Check the media insertion	
3510	-	Cannot delete folder. Check attribute and inside file	
3520	-	Same folder exists	
3530	-	Cannot load at current security mode	
3540	-	CMOS not compatible	
3550	-	Under automatic backup operation. Operate after the backup is completed.	
3551	-	Under automatic backup operation. Operate "SORT FILE" after the backup is completed.	
3560	-	Failed in sorting backup file	
3570	-	Actuator data transmission error	
3580	-	Under backup file access. Operate after the access is completed.	
3581	-	Under backup file access. Operate "SORT FILE" after the access is completed.	

Error No.	Data	Error Message	Contents
3600	-	system configuration data not matched	
3610	-	Excessive path	
3620	-	Excess folders	

## 10.1 Error Message

### 10.1.5 Concurrent I/O

Error No.	Data	Error Message	Contents
4010	*	Illegal relay No.	
	XXX		Line no.
4020	-	Illegal block No.	
4030	*	Illegal instruction	
	XXX		Line no.
4040	*	Relay/register No. duplicated in OUT/ GOUT or arithmetic instruction	Multiple outputs are instructed to the relay or register.
	XXX		Line no.
4050	*	The relay is not used	
	XXX		Line no.
4060	*	Excess STR-[-NOT] instructions	
	XXX		Line no.
4070	*	Excess AND [OR] STR instructions	
	XXX		Line no.
4080	*	Syntax error in CRT instructions	
	XXX		Line no.
4090	*	Enter STR [-NOT] at head of block	Need STR [-NOT]
	XXX		Line no.
4100	-	Relay No. duplicated in TMR and CNT	
4110	-	Excessive ladder scan-time	
4120	-	Concurrent I/O memory is full	Exceeds memory capacity (10000 steps)
4130	-	END instruction not found	END instruction not found
4140	-	Wrong ladder program	Position and number of PART instruction are wrong.
4150	*	Wrong use of GSTR, GOUT commands	GSTR and GOUT is not used together.
	XXX		Line no.
4160	-	Cannot edit system section	
4170	-	Cannot modify/delete	
4180	-	Depress INSERT/MODIFY/DELETE keys	
4190	-	Ladder program not found	
4200	-	Cannot specify system variables(\$)	
4210	-	Cannot edit line	
4220	-	Excess TMR/CNT or arithmetic instructions	More than 100 TMR, CNT or arithmetic instruction used
4230	-	Syntax error in TMR/CNT instructions	

10.1 Error Message

## 10.1.6 Maintenance Mode

Error No.	Data	Error Message	Contents
8010	-	Too many axes	
8011	-	Choose the input of overrun	
8020	-	Too many I/O points	
8030	-	Too many boards (DEVICENET)	
8033	-	Too many boards	
8034	-	Too many channels	
8035	-	Invalid configuration	
8040	-	Memory error (ControlNet output condition)	
8041	-	Memory error (UNIWIRE CONNECT DAT	
8042	-	Memory error(IP Network Configuration data)	
8050	-	Robot model is not registered	
8051	-	Select model	
8060	-	Cannot get UNIWIRE connection data	
8070	-	DHCP is already set to use for another item	
8071	-	DNS is already set to use for another item	
8072	-	DHCP is not set to use	
8073	-	DNS is not set to use	
8074	-	Device Information not found	
8075	-	Unable to accept same type of boards simultaneously	
8076	-	Ethernet is being used by other function.	
8080	-	Non support function	
8205	-	ENABLE Unit over	
8206	-	FLASH access error	
8210	-	IO module configuration is not modified	
8211	-	OPTION, BOARD or MODULE SETUP is not completed.	
8212	-	Cannot change setting (Function conflict	
8213	-	Check EXTERNAL IO setup	

- 10 Error
- 10.2 Particular Error Message

## **10.2 Particular Error Message**

Apart from ordinary alarms or errors, some may display an error box message on the programming pendant. This message is displayed, when the system of the programming pendant becomes unauthorized.

#### 10.2.1 Message

10.2.1.1 Fatal Error

This message is displayed when the fatal error occurs.

The message is "Fatal application Error" although the content of the message box varies depending on the occurrence status.

The programming pendant becomes either of following states

- 1. The window becomes inoperable.
- 2. The window disappears and blue background appears.

JOB	EDIT	DISPLAY	UTILITY	12 🗹 🖬 🏍 🗃 🕞 👆
JOB CONTEL J:TEST01 CONTROL G	NT ROUP: R1		S:000 TOOL:	- 10 **
00000 NOP 0001 SET I 0002 SET I 0003 MOVJ 0004 MOVJ 0005 DOUT 0006 MOVJ 0007 MOVJ	3000 1 3001 0 Fatal Applica Owr Progr Excer	ation Error Lation NxPp1.ex In If the proble am: YppMain.ex Stion: 0x20000	e has performe m persists, con ce 105	OK × ad an illegal operation and will be shut tact the program vendor.
0008 MOVJ 0009 MOVJ 0010 END	Addri	ess: 0003e9fe		
W013 13-	0.70			
Main Men	u Simp	le Menu		

- 10 Error
- 10.2 Particular Error Message

#### 10.2.1.2 Application Transaction Error

This message is displayed when the system or the software of the programming pendant becomes unauthorized due to unexpected transaction or failure in software transaction, etc.

The message in the message box varies depending on the occurrence status.

JOB	EDIT	DISPLAY	UTILITY	12 🗹 🖬 🛸 🔞 🕞 👆
JOB CONTE J: TEST01 CONTROL G 0000 NOP 0001 SET 0002 SET 0003 MOVJ 0004 MOVJ 0005 DOUT 0006 MOVJ 0007 MOVJ 0008 MOVJ 0008 MOVJ 0009 MOVJ	NT ROUP: R1 B000 1 B001 0 VJ=80.00 VJ=80.00 OT#(10) OK VJ=80.00 VJ=100.00 VJ=100.00 VJ=100.00	(c	S:000 T00L: est01 ? Out of r	IO ***
MOVJ VJ=	0.78			
Main Men	u Simp	le Menu		

Followings are the messages possible to occur.

Message	Meaning
syntax error	There is an unauthorized part in internal processing description.
expression too complex (stack overflow)	Internal stack has overflowed.
function nesting depth exceeded	Nesting of internal processing is unauthorized.
bad radix	The cardinal number used is unauthorized.
divide by 0	Memory is running out.
out of memory	Memory is insufficient.
argument list does not match a function	The internal processing of the pendant program is unauthorized.
register is not available	Specified an unavailable system data.

The programming pendant becomes either of following states

- 1. The window becomes inoperable.
- 2. Press {OK} button to disappear the message box and it becomes operable.

#### 10.2.1.3 Other Errors

Other errors than mentioned above, some can trigger the message box.

10.2 Particular Error Message

#### 10.2.2 When the Error is Indicated

#### 10.2.2.1 Fatal Error

Programming pendant becomes inoperable when this message appears. Please restart the system.

#### 10.2.2.2 Application Transaction Error

It is possible to keep the operation after pressing {OK} button to disappear the message box. However, in this case, the system might be instable. Please restart the system if the window becomes inoperable.

#### 10.2.2.3 Other Errors

Most of the cases when an error occurs, it is possible to keep the operation after pressing {OK} button to disappear the message box. Please restart the system if the window becomes inoperable.

Sometimes the message appears due to a specific operation although unstable state of the programming pendant is the main cause of the error in most cases.

If the pendant becomes inoperable after the message due to a specific operation invariably, please report the displayed message to your Yaskaswa representative.
## 11 LED Indicator on Each Circuit Board

•

Before the check of LED indicator

In principle, the door must not be opened to prevent electric shock while power is ON. However, open the door with extreme care only if it is required to check the LED display on each circuit board for maintenance.





Failure to observe this warning may result in electric shock.

- 11 LED Indicator on Each Circuit Board
- 11.1 6 LED-Spot Indicator on the Main CPU Circuit Board (CPU201R)

# 11.1 6 LED-Spot Indicator on the Main CPU Circuit Board (CPU201R)

CPU201R board shows its operation status with 6 LED-spot indicator.

Indication	LED Color	Board Status when LED is lit
SV-ON	Green	While the SERVO power is turned ON.
RUN	Green	While in operation
ALM-1	Red	Occurrence of a major error
ALM-2	Red	Occurrence of a minor error
BAT	Red	Battery alarm
ERR	Red	Error



- 11 LED Indicator on Each Circuit Board
- 11.2 7-Segment LED Indicator on the Main CPU Circuit Board (CPU201R)

# 11.2 7-Segment LED Indicator on the Main CPU Circuit Board (CPU201R)

CPU201R board indicates its start-up status and error causes with 7-segment LED indicator.

Status	7-Segment LED Indicator
Immediately after the power is turned ON	All 7-SEG indicators light up. ('8' + '.' light up.)
During the start-up process	Count up from '0' toward 'd' or 'P'
Online normal start-up	'd' + '.' blink every one second
Maintenance mode start-up	'F' + '.' blink every one second
PP/SWP unconnected	'P' + '.' blink every one second
ERR	The error cause and the address where the error has occurred are indicated.



Error indication spec.:

- 11 LED Indicator on Each Circuit Board
- 11.2 7-Segment LED Indicator on the Main CPU Circuit Board (CPU201R)

#### 11.2.1 Status of 7-Segment LED Indicator at Error Occurrence

Error cause indication	Meaning
F0100	Critical Input
F0200	Machine Check
F0300	Data Storage
F0400	Instruction Storage
F0600	Alignment
F0700	Program
F0800	Floating Point Unavailable
F0900	Watchdog Timer Error (no address indication)
F0930	CPU Hung Up Error (no address indication)
F0a00	Auxiliary Processor Unavailable
F0c00	Fixed Interval Timer
F0d00	Watchdog Timer
F0e00	Data TLB Error
F0f00	Instruction TLB Error
F1000	Debug Exception
F1100	CPU Signal Process Engine
F1200	Floating Point Data
F1300	Floating Point Data Round
F1400	Performance Monitor

11 LED Indicator on Each Circuit Board

11.2 7-Segment LED Indicator on the Main CPU Circuit Board (CPU201R)

11.2.2 Status of 7-Segment LED Indicator at Control Power Start-up (one digit)

LED	Status
1	The system program has started.
2	Starts verifying the existence of other circuit boards. (Verifies the start-up of the booting program.)
3	Starts the system program transmission.
4	Sends the request of the system program start-up.
5	Starts verifying the existence of other circuit boards. (Verifies the start-up of the system program.)
6	Acquires hardware information, etc. of other circuit boards. (Verifies the IO board status, SERVO IF, and so on.)
7	Starts the CMOS data transmission.
8	Sends the pre-online request.
9	Waits for MIII communication synchronization.
А	
b	Sends the start-up request of on-line system.
С	The on-line system has started. (Starts up the initialization task.)
d	Processes of the system setup completion. (Servo ON enabled)
E	Alarm occurs at the system setup.
F	The maintenance mode is starting up.
Ρ	The system setup PP/SWP unconnected.

#### 11.2.3 Status of 7-Segment LED Indicator at Hardware Error Occurrence

When the hardware error is detected during the operation, the error is indicated with 4-digit numbers with the letter [H] at its head.

Indication spec.:

Repeat of  $[H] \rightarrow [0] \rightarrow [0] \rightarrow [0] \rightarrow [1] \rightarrow [.]$ 

Alarm No.	
H0001	MAC address error
H0002	Power lost error when start-up
H0003	Watchdog error when start-up
H0004	Interrupt clear impossible
H0005	Initialization of SERVO communication error

Turn the power supply OFF and ON again when the above mentioned numbered error is indicated by the 7-Segment.

Replacement of the controller is required if the error occurs again.

- 11 LED Indicator on Each Circuit Board
- 11.2 7-Segment LED Indicator on the Main CPU Circuit Board (CPU201R)

#### 11.2.4 Status of 7-Segment LED Indicator at Alarm Occurrence

Only when the PP is not connected the FS100L, the alarm number is indicated with 4-digit numbers with the letter [A] at its head.

If more than one alarm occurred, the first alarm numbers indicated.

Note that the number of the major alarm is indicated if major and minor alarms occurred at a time.

Indication spec.: when Alarm 1200 is occurred

Repeat of  $[-] \rightarrow [A] \rightarrow [1] \rightarrow [2] \rightarrow [0] \rightarrow [0]$ 

- 11 LED Indicator on Each Circuit Board
- 11.3 LED Indicator on Machine Safety Board (SF2300R)

### 11.3 LED Indicator on Machine Safety Board (SF2300R)

SF2300R board indicates its operation status with LED indicator.

Indication	LED Color	Board Status when LED is lit
RUN	Green	Access from the main CPU (CPU-201R)
ALM	Red	Error is being detected
HWBB1	Green	SERVO OFF
HWBB2	Green	SERVO OFF



- 11 LED Indicator on Each Circuit Board
- 11.4 7-Segment LED Indicator on SERVO control circuit board (EAXA)

# 11.4 7-Segment LED Indicator on SERVO control circuit board (EAXA)

EAXA board indicates its start-up status and error causes with 7-segment LED indicator.

Status	7-Segment LED Indicator
Immediately after the power is turned ON	All 7-SEG indicators light up. ( ' 8 '+ ' . ' light up )
During the start-up process	Count up from '0' toward 'd' Refer to <i>chapter 11.4.3</i>
Online normal start-up	'd'+'.' blink every one second
Error occurrence in the main CPU and SERVO control circuit board communication system or power supply system	The error cause is indicated at LED. Refer to <i>chapter 11.4.1</i>
Normal errors other than errors described above	'E'+'.' blink every one second
Fatal error occurrence	The error cause and the address where the error has occurred are indicated at LED. Refer to <i>chapter 11.4.2</i>

#### 11.4.1 Status of 7-Segment LED Indicator at Error Occurrence in the Main CPU and SERVO Control Board Communication System or Power Supply System

Error indication spec: Repeat of	[F] to [0] to [0] to [3] to [.]
(error caus	e)

Error cause indication	Meaning
F001	Communication error between main CPU board and servo control circuit board (Send incompletion)
F002	Communication error between main CPU board and servo control circuit board (Receive incompletion)
F003	Communication error between main CPU board and servo control circuit board (Communication WDG error)
F010	Communication error between main CPU board and servo control circuit board (Communication status error)
F101	Power failure detected Power lost detected
F103	Power failure detected Torque saturation occurred during detection of AC holdup.
F104	Power failure detected Detection of AC holdup continues for certain period time.

- 11 LED Indicator on Each Circuit Board
- 11.4 7-Segment LED Indicator on SERVO control circuit board (EAXA)

#### 11.4.2 Status of 7-Segment LED Indicator at Fatal Error Occurrence

Error indication spec: Repeat of

[-] to [F] to [0] to [2] to [0] to [0] (error cause)

[.] to [-] to [0] to [0] to [0] to [0] to [F] to [F] to [0] to [4]

(Address of occurrence)

0010ROM error in the boot section0020RAM error0030FP register error0040On-line communications command error0100Reset exception0200Machine check exception0210WDT error0300Data access error0400Instruction access exception050000600Alignment exception0700Program exception0800Unavailable floating point exception090000A00Undefined exception050000500	Error cause indication	Meaning
0020RAM error0030FP register error0040On-line communications command error0100Reset exception0200Machine check exception0210WDT error0300Data access error0400Instruction access exception050006000600Alignment exception0700Program exception0800Unavailable floating point exception0900040005000000500000050000005000000500000050000005000000500000050000005000000500000050000005000000500000050000005000000500000050000005000	0010	ROM error in the boot section
0030FP register error0040On-line communications command error0100Reset exception0200Machine check exception0210WDT error0300Data access error0400Instruction access exception050006000600Alignment exception0700Program exception0800Unavailable floating point exception090004000400Undefined exception0500<	0020	RAM error
0040On-line communications command error0100Reset exception0200Machine check exception0210WDT error0300Data access error0400Instruction access exception050006000600Alignment exception0700Program exception0800Unavailable floating point exception090009000A00Undefined exception0B00Undefined exception0C00System call exception0D00Trace exception	0030	FP register error
0100Reset exception0200Machine check exception0210WDT error0300Data access error0400Instruction access exception050006000600Alignment exception0700Program exception0800Unavailable floating point exception090004000800Undefined exception09000500<	0040	On-line communications command error
0200Machine check exception0210WDT error0300Data access error0400Instruction access exception050006000600Alignment exception0700Program exception0800Unavailable floating point exception090004000800Undefined exception090008000500Undefined exception050008000500Undefined exception050008000500Undefined exception0500Undefined exception0500Undefined exception0500Undefined exception0500Undefined exception0500Trace exception	0100	Reset exception
0210WDT error0300Data access error0400Instruction access exception050006000600Alignment exception0700Program exception0800Unavailable floating point exception090009000A00Undefined exception0B00Undefined exception0C00System call exception0D00Trace exception	0200	Machine check exception
0300Data access error0400Instruction access exception050006000600Alignment exception0700Program exception0800Unavailable floating point exception090004000A00Undefined exception0B00Undefined exception0C00System call exception0D00Trace exception	0210	WDT error
0400Instruction access exception050006000600Alignment exception0700Program exception0800Unavailable floating point exception090004000A00Undefined exception0B00Undefined exception0C00System call exception0D00Trace exception	0300	Data access error
0500Alignment exception0600Alignment exception0700Program exception0800Unavailable floating point exception090004000A00Undefined exception0B00Undefined exception0C00System call exception0D00Trace exception	0400	Instruction access exception
0600Alignment exception0700Program exception0800Unavailable floating point exception0900Undefined exception0A00Undefined exception0B00Undefined exception0C00System call exception0D00Trace exception	0500	
0700Program exception0800Unavailable floating point exception090004000A00Undefined exception0B00Undefined exception0C00System call exception0D00Trace exception	0600	Alignment exception
0800Unavailable floating point exception090004000A00Undefined exception0B00Undefined exception0C00System call exception0D00Trace exception	0700	Program exception
0900Undefined exception0A00Undefined exception0B00Undefined exception0C00System call exception0D00Trace exception	0800	Unavailable floating point exception
0A00Undefined exception0B00Undefined exception0C00System call exception0D00Trace exception	0900	
0B00 Undefined exception   0C00 System call exception   0D00 Trace exception	0A00	Undefined exception
0C00 System call exception   0D00 Trace exception	0B00	Undefined exception
0D00 Trace exception	0C00	System call exception
	0D00	Trace exception
0E00 Undefined exception	0E00	Undefined exception
0F00 Undefined exception	0F00	Undefined exception
1000 Instruction conversion error exception	1000	Instruction conversion error exception
1100     Data load conversion error exception	1100	Data load conversion error exception
1200 Data store conversion error exception	1200	Data store conversion error exception
1300 Instruction breakpoint exception	1300	Instruction breakpoint exception
1400 System management interruption	1400	System management interruption
1500 Undefined exception	1500	Undefined exception
1600 Undefined exception	1600	Undefined exception
1700 Undefined exception	1700	Undefined exception
1800 Undefined exception	1800	Undefined exception
1900 Undefined exception	1900	Undefined exception
1A00 Undefined exception	1A00	Undefined exception
1B00 Undefined exception	1B00	Undefined exception
1C00 Undefined exception	1C00	Undefined exception
1D00 Undefined exception	1D00	Undefined exception
1E00 Undefined exception	1E00	Undefined exception
1F00 Undefined exception	1F00	Undefined exception
2000 Undefined exception	2000	Undefined exception
2100 Undefined exception	2100	Undefined exception
2200 Undefined exception	2200	Undefined exception
2300 Undefined exception	2300	Undefined exception
2400 Undefined exception	2400	Undefined exception
2500 Undefined exception	2500	Undefined exception
2600 Undefined exception	2600	Undefined exception

11 LED Indicator on Each Circuit Board

## 11.4 7-Segment LED Indicator on SERVO control circuit board (EAXA)

Error cause indication	Meaning
2700	Undefined exception
2800	Undefined exception
2900	Undefined exception
2A00	Undefined exception
2B00	Undefined exception
2C00	Undefined exception
2D00	Undefined exception
2E00	Undefined exception
2F00	Undefined exception
3010	Receiving data size error
3020	Receiving data sum error
3030	Receiving data write address error
3040	All receiving data sum error

11 LED Indicator on Each Circuit Board

11.4 7-Segment LED Indicator on SERVO control circuit board (EAXA)

### 11.4.3 Status of 7-Segment LED Indicator at Control Power Start-up (One Digit)

LED	Status
0	The booting program has started. (ROM/RAM/FP register check)
1	Starts the booting system. (Completes initialization of various kinds.)
2	Completes the preparation for receiving the system program.
3	The system program has been received. (Waits for the request of system change.)
4	The system program has started. (Starts up hardware initialization of various kinds.)
5	Starts the system. (Completes initialization of various kinds.)
6	Starts the CMOS data transmission.
7	Receives the CMOS mapping. (Waits for pre-online)
8	Starts the servo system. (Starts the process of various initialization.)
9	Waits for CPU board communication synchronization. (Completes the process of various initialization.)
А	
В	Waits for the start-up of on-line system.
С	
D	Completes the setup process. (Servo ON enabled)

## 12 Troubleshooting Methods When an Alarm Massage Is Not Displayed

Turn the power supply OFF and then ON if FS100L does not start and also an alarm is not displayed on the programming pendant.

When FS100L still does not work after turning the power supply OFF and ON, perform the following procedures.



remove the back panel while the power supply is ON. Never touch the devices in the controller when checking the LED indicator lamp.

Failure to observe this caution may result in electric shock or injury.

Status of the Programing Pendant	7SEG LED of the Control Circuit Board (CPU-201R)	Possible Cause	Remedy
Not Displayed	Light is OFF	No control power supply from the CPS unit. (JZNC-YPS01-E)	Check if the voltage is low or there is a open phase in the primary power source.
			Check if the breaker is working.
			Check if there is no blown fuse (1FU, 2FU) in the power supply contactor unit. When the fuse has blown, research the cause and then replace it.
			Check the cable connection of the power sup- ply contactor unit (JZRCR-YPU31-1), CPS unit (JZNC-YPS01-E) and Power relay circuit board (JEPMC-PSD3007R-E).
			Check if the 5V red LED lights up on the CPS unit. (JZNC-YPS01-E) When the LED lights up, check a ground fault or short circuit of following connectors. •YPS-CN158 •PSD-CN3
	Others	No control power supply to the programming pendant, although CPS unit (JZNC- YPS01-E) is providing the power supply.	Check if the cable between programming pen- dant and FS100L is connected properly, and confirm that there is no abnormality. Also check the wiring of the following connec- tor. •YPS-CN154
			Check if the power supply fuse (F12) of the left side has blown. When the fuse has blown, research the cause and then replace it. There may be a ground fault or short circuit of the programming pendant cable.
			Check if the 24V red LED lights up on the CPS unit. (JZNC-YPS01-E) When the LED lights up, check the wiring of the following connectors. •YPS-CN154 YPS-CN155 •AXA-CN509

# 12 Troubleshooting Methods When an Alarm Massage Is Not Displayed

		I	
Status of the Programing Pendant	7SEG LED of the Control Circuit Board (CPU-201R)	Possible Cause	Remedy
Screen Display of the Programming Pendant Startup (Unable to con- firm the con- nection of the Programming Pendant)	Light is OFF	No control power supply to the CPU unit, although CPS unit (JZNC-YPS01-E) is pro- viding the power supply.	Check if the power supply fuse (F11) of the left side has blown. When the fuse has blown, research the cause and then replace it.
			Check the connection and insertion of the fol- lowing cables and connectors of CPS unit (JZNC-YPS01-E) and The power relay circuit board (JEPMC-PSD3007R-E). -YPS-CN158 -PSD-CN3
	H0002.	No status detection of CPS unit.	Check the wiring of following connectors. •YPS-CN159 •LIO-08RT1-CN1
			Check the LIO-08RT1 board is installed correctly.
	Others	Communication line error of the programming pendant.	Check the cable between programming pen- dant and FS100L. Also confirm the wiring of the following connec- tor. •CPU-201R-PP
		Unable to recognize the sig- nal of the enable switch.	Hold and release the enable switch by following the direction in the screen.
			Check the cable between programming pen- dant and FS100L. Also confirm the wiring of the following connec- tors. •SF2300R-CN2, CN3, CN6 •YPS-CN154
			Check if an alarm indication on the 7SEG LED of control circuit board (CPU-201R). When the alarm occurs, follow the remedy of the alarm.
			Check if the 24V red LED lights up on the CPS unit. (JZNC-YPS01-E) When the LED lights up, check the following 24V wirings. •SF2300R-CN6 •LIO-08R-CN1,CN2,CN3 •CN211 (Direct in connector) •YPS-CN154、CN155、CN156 •AXA-CN509

#### **Numerics**

6 LED-spot indicator		11-2
7-Segment LED	11-3, 11-8, 11-11,	12-1

## A

6-1
5-41, 6-1
5-41, 6-1, 6-4
2-3
8-19
9-1
8-19
2-3
10-17
2-3
2-4
9-3

### В

Battery	
Battery inspections	
binary data	
Brake	6-4, 6-6, 6-8, 6-10, 6-12
Brake control board	5-2, 5-31, 5-42
Brake power supply fuse	5-42, 6-1
Brake Power Supply Fuse for External Axis	5-42

# С

Cable clamp	
Cable inlet	6-14
Calibrating operation	
calibration	4-2
Carrier hood	6-1
CHANGE BUTTON	
CHANGE FONT	
CHANGE WINDOW PATTERN	
Changing the Absolute Data	
changing the monitor items	8-26
check point	4-3
Check program	4-3. 7-12
Circuit board rack	5-2. 5-13
Circuit Board Rack Replacement	
Clearing Absolute Data	
clearing the alarm history	
clearing the I/O message history	

Clearing the System Manitaring Time Diaplay	0.40
CMOS memory	3-5
COMMAND POSITION	2-3
Concurrent I/O	10-14
Control circuit board	5-2, 5-3
control group data	9-3
Control power time	8-16
Converter	5-2, 5-37
Converter cooling fan	5-2, 5-46
cooling	3-3
Cooling fan	3-2, 3-3
Cooling fan inside the controller	5-2
Cooling fan inspections	3-3
CPS unit	5-2, 5-27
CREATE NEW JOB	2-2
Creating a Check Program	4-3
CURRENT POSITION	2-3
Current Position	8-24
Current Position Window	8-24

## D

DATE/TIME	2-4
DC Control power supply connector	5-33
DC Control power supply fuse	6-1
DC control power supply fuse	Б Л2
desimal data	
DEVICE	2-3
DISPLAY SETUP	2-4
displaying and releasing alarm	
DISPLAYING COLOR COND	2-4
DROP AMOUNT	2-3

### Ε

EAXA	11-8
EAXA base	5-35
Editing	2-1
Editing mode	2-1
Emergency stop button	3-2
emergency stop button inspections	3-4
Enable switch	3-2
Enable switch inspections	3-4
ENCODER MAINTENANCE	2-4
ENCODER ROTATE SUM	8-25
ENCODER TEMPERATURE	8-25
ENERGY SAVING FUNCTION	2-4
Error message list	10-1
ERROR PULSE	8-25
External Memory Equipment	10-9

## F

FD/CF	<del>.</del>	2-3	3
-------	--------------	-----	---

FEEDBACK PULSE	
FEEDBACK SPEED	
Filter	
FOLDER	
FS100 controller	
FUNCTION COND	
FUNCTION ENABLE	
Fuse holder	

## G

GENERAL DIAG	
grounding wire	5-29, 5-31
GRP COMBINATION	

## Η

HAND VIBRATION CONTROL	2-3
HOME POSITION	2-3
home position	7-3
home position calibration	7-3
Home position data correction	7-13
how to replace converter	5-37

## I

I/O message history	8-21
I/O message history window	8-21
I/O MSG HISTORY	2-3
IN 1 TURN POSITION	8-25
IN/OUT	2-2
Independent control function (optional)	
Individual Window of the System Monitoring Time Display	8-17
INITIALIZE LAYOUT	2-4
Input/Output Status	8-2
Inspection for the Filter	3-6
INTERFERENCE	2-3

## J

JANCD-YBK01-2E	5-2
JAPMC-IO2308R-E	5-2, 5-18, 5-23
JAPMC-IO2308R-ET1	5-2, 5-18, 5-23
JAPMC-SF2300R-E	5-2, 5-20
JEPMC-BUB3008R-E	5-2, 5-13
JEPMC-CP3201R-E	5-2, 5-3
JEPMC-PSD3007R-E	5-2, 5-8, 12-1, 12-2
JOB	
JOB CAPACITY	2-2
Job Defined Data	10-6
JOG COND	
JOG KEY ALLOC	

JZNC-YPS01-E	
JZRCR-YBK01-2E	
JZRCR-YPU01-1	
JZRCR-YPU31-1	

## Κ

KEY ALLOCATION	2-4
----------------	-----

# L

LED	3-5
LED indicator on each circuit board	11-1
LIMIT RELEASE	2-3
LOAD	2-3

# Μ

Machine safety circuit board	5-2, 5-20
Maintenance Mode	10-15
major alarm	9-1
Major axes control circuit board	5-2, 5-39
Managememt mode	2-1
Manipulator	
Manipulator home position	
manipulator model	8-1
MANIPULATOR TYPE	2-3
MANUAL BRAKE RELEASE	2-3
MASTER JOB	2-2
MAX. TORQUE	8-25
Maximum torque data	8-28
minor alarm	
mode key	
Modification of the Signal Name	8-14
modifying the output status	
MONITORING TIME	2-3
MOTOR ABSOLUTE	8-25
Moving time	8-16
Multiple SERVOPACK system	
· · · · · · · · · · · · · · · · · · ·	

## Ν

NETWORK SERVICE	2-3	2
	~ `	,

# 0

OPERATE COND	2-4
OPERATE ENABLE	2-4
Operating time	8-16

Operation	. 2-1
Operation Mode	. 2-1
outline of alarm	. 9-1
OVERRUN	. 2-3

## Ρ

PARAMETER	2-4
PLAYBACK COND	2-4
Playback time	8-16
Position check operation	7-16
position data when power is turned ON/OFF	8-23
position deviation check using the check program	
power flow	1-2
POWER ON/OFF POS	2-3
power ON/OFF position window	8-23
Power relay circuit board	5-2, 5-8
Power supply cable	3-2
Power supply connector	6-1
Power supply contactor unit	5-2, 5-29
PP power supply fuse	5-43, 6-1

### R

Regenerative resistor cooling fan	5-2
regular inspections	3-1
Relay for a motor cooling fan	5-2
Relay number search	8-8, 8-11
replacing parts	5-1
RES. START (CNCT)	2-4
RESERVE JOB NAME	2-4
RIN input	8-7
RIN input window	8-7
ROBOT	2-3

## S

SAVE	
Screw in hood	
SECOND HOME POS	2-3
Second home position	
SECURITY	
Security	
Security mode	2-1, 2-5
Security System	
SELECT JOB	
Servo amplifier	5-2, 5-33
Servo cooling fan	5-2, 5-45
SERVO MONITOR	
servo monitor window	8-25
servo monitoring	
SERVO ON	
SERVO ON READY	
Servo power time	
SET SPEED	

I	n	d	e	х
	11	u	c	^

\_

SETUP	2-4
SHIFT VALUE	2-3
SHOCK SENS LEVEL	2-3
signal flow	1-3
Signal number search	8-8
Spare parts	6-3
Special alarm display	9-3
Specific Input Simple Window	8-5
Specific Input Window	8-5
Specific Output	8-6
Specific Output Simple Window	8-6
Specified Output Window	8-6
SPEED DEVIATION	8-25
SPEED INST	8-25
SRDA-COA30A01A-E	5-2
SRDA-EAXA01A	5-2, 5-39, 5-44
system diagnosis	8-1
System I/O board	5-23
System I/O circuit board	5-2
System I/O power supply fuse	5-43, 6-1
SYSTEM INFO	2-3
System Input	8-5
System Monitoring Time Display	8-16
System Monitoring Time Display Window	8-16
system version	8-1

# <u>T\_\_\_\_\_</u>

TEACHING COND	. 2-4
Thermal sheet	5-36
TOOL	. 2-3
TORQUE SPEC	8-25
Troubleshooting	12-1

# U\_\_\_\_\_

Universal Input	8-2
Universal Input Simple Window	8-2
Universal Input Window	
Universal Output Simple Window	8-3
Universal Output Window	8-3
User	5-43
USER COORDINATE	2-3
USER DEFINITION MENU	2-3
User I/O board	5-23
User I/O circuit board	
User I/O power supply fuse	5-43, 6-1
User ID	2-4, 2-6, 2-7

#### V

VARIABLE	2-2
VERIFY	2-3
VERSION	2-3

\_\_\_\_\_

## 

### Х

XYZ coordinate data	. 9-3
XYZ coordinate data	. 9-3

# FS100L MAINTENANCE MANUAL

HEAD OFFICE 2-1 Kurosakishiroishi, Yahatanishi-ku, Kitakyushu 806-0004, Japan Phone +81-93-645-7703 Fax +81-93-645-7802

YASKAWA America Inc. (Motoman Robotics Division) 100 Automation Way, Miamisburg, OH 45342, U.S.A. Phone +1-937-847-6200 Fax +1-937-847-6277

YASKAWA Europe GmbH (Robotics Divsion) Yaskawastrasse 1, 85391 Allershausen, Germany Phone +49-8166-90-100 Fax +49-8166-90-103

YASKAWA Nordic AB Bredbandet 1 vån. 3 varvsholmen 392 30 Kalmar, Sweden Phone +46-480-417-800 Fax +46-480-417-999

YASKAWA Electric (China) Co., Ltd. 22/F One Corporate Avenue No.222, Hubin Road, Huangpu District, Shanghai 200021, China Phone +86-21-5385-2200 Fax +86-21-5385-3299

YASKAWA SHOUGANG ROBOT Co. Ltd. No7 Yongchang North Road, Beijing E&T Development Area, China 100176 Phone +86-10-6788-2858 Fax +86-10-6788-2878

YASKAWA India Private Ltd. (Robotics Division) #426, Udyog Vihar, Phase- IV, Gurgaon, Haryana, India Phone +91-124-475-8500 Fax +91-124-475-8542

YASKAWA Electric Korea Co., Ltd 9F, Kyobo Securities Bldg., 26-4, Yeouido-dong, Yeongdeungpo-gu, Seoul 150-737, Korea Phone +82-2-784-7844 Fax +82-2-784-8495

YASKAWA Electric Taiwan Corporation 12F, No.207, Sec. 3, Beishin Rd., Shindian District, New Taipei City 23143, Taiwan Phone +886-2-8913-1333 Fax +886-2-8913-1513

YASKAWA Electric (Singapore) PTE Ltd. 151 Lorong Chuan, #04-02A, New Tech Park, Singapore 556741 Phone +65-6282-3003 Fax +65-6289-3003

YASKAWA Electric (Thailand) Co., Ltd. 252/125-126 27th Floor, Tower B Muang Thai-Phatra Complex Building, Rachadaphisek Road, Huaykwang, Bangkok 10320, Thailand Phone +66-2693-2200 Fax +66-2693-4200

PT. YASKAWA Electric Indonesia Menara Anugrah Lantai 1, Kantor Taman E.3.3, JI Mega Kuningan Lot 8.6-8.7, Kawasan Mega Kuningan, Jakarta, Indonesia Phone +62-21-57941845 Fax +62-21-57941843

Specifications are subject to change without notice for ongoing product modifications and improvements.

YASKAWA ELECTRIC CORPORATION



MANUAL NO. RE-CHO-A112 © Printed in Japan August 2014 13-02